Low-overshoot PI tuning · factory D fixed
Positive = short of target; negative = past target · Red line = overshoot limit

Joint 1 · accuracy 0.2°, overshoot ≤0.1°



Joint 2 · accuracy 0.2°, overshoot ≤0.1°



Joint 3 · accuracy 0.2°, overshoot ≤0.1°



Joint 4 · accuracy 1°, overshoot ≤0.1°



Joint 5 · accuracy 1°, overshoot ≤0.1°



Joint 6 · accuracy 1°, overshoot ≤0.1°