
Pixel Unit Cell
sensor
bump pad
sensor calib
calib
CalDel
VCal
FBPre
FBSh
Vsh
hold
send
PUC address
9 bit
Trim bits
trimming
comparator
hold delay
TrimScale
Vcomp
HoldDel
GlobalThr
Double column periphery
write
read
80×
Static FIFO 80×9 bit
Double column address
reset
PHOffset
Controller & interface block
FIFO
ADC
serializer
PHscale
ADCpower
sout –
sout +