

BUILDING INSPECTION REPORT

Official Compliance Record — AI-Assisted Analysis
Report ID RPT-2026-05-34DC
Project Name Building Inspection
Inspection Date May 22, 2026
Classification Electrical
Permit No. N/A

1.0 Compliance Summary

87%
⚠ REQUIRES REMEDIATION
8
Total Items
1
Violations
7
Compliant
0
Uncertain

AI-Powered Analysis | Generated: May 22, 2026 10:22
Confidential — For Authorized Personnel Only Page 1 of 4

SBC Inspection Report
RPT-2026-05-34DC

2.0 Violation Details

CRITICAL VIO-001 SBC Ref: SBC 712:51-4.102

Exposed Electrical Wiring

Bounding box detected at region
Description Electrical wiring running along ceiling without conduit protection.
SBC Code SBC 712:51-4.102 — All wiring must be enclosed in fire-rated conduit.
Remediation Install fire-rated EMT conduit for all exposed runs.
Priority CRITICAL
Confidential — For Authorized Personnel Only Page 2 of 4

SBC Inspection Report
RPT-2026-05-34DC

3.0 Media Evidence

No media evidence captured for this inspection.

4.0 SBCNC Code References

#	SBC Code	Requirement Summary	Status
1	SBC 712:51-4.102	All wiring must be enclosed in fire-rated conduit. Violation	

Confidential — For Authorized Personnel Only Page 3 of 4

SBC Inspection Report
RPT-2026-05-34DC

5.0 AI Analysis Methodology

Engine Saudi SBC Compliance AI
Analysis Type Multi-modal Vision + RAG-augmented Code Matching
Knowledge Base Saudi Building Code National Committee (SBCNC) Database

Rules Evaluated 8 items against 8 SBC code sections per item

Token Usage Observe: 1234 tokens | Judge: 5678 tokens

⚠ This AI-generated analysis is advisory only. Final compliance determination must be made by a certified SBC inspector in accordance with SBCNC regulations.

6.0 Sign-off & Authorization

Prepared By

SBC Compliance AI System

Automated Audit Engine

System Generated

May 22, 2026

Reviewed By

Chief Compliance Officer
Signature

Official

Stamp

End of Report — Confidential Page 4 of 4