
Held-out recovery RMSE (percentage points)
0
2
4
6
8
10
12
rejected
copper porphyry soft
copper porphyry hard
gold free milling
iron magnetite fine
nickel sulphide
phosphate clay
copper molybdenum
copper oxide
zinc sulfide
mixed ore high clay
low grade copper
refractory gold