Column C		CLUTCH INDIA	ĕ	OPERATI	N O	STANDARD	(B)			Doc. No. : FCC-APQP-QF Rev. No. : 01 Rev. Date : 21.02.2018	2P-QF0-04(b)
The color of the color of pictures Color of pictures Color of the color of pictures	OPERATION	ON N	논	OPERATION NAME		nm - CAULKING, MOVE TO FINAL	ASSY.			STEET 4:. OF 1.	.;
Control Statement	PREVIOUS	1.	MENT OF PLATE DRIVEN EAR SIDE & RIVET 4mm INSTALLATION	NEXT OPERATION	FITMENT OF OI WASHER THRUST MOVEMENT CKI WASHER CONF	UTER COMP. CLUT 7 17mm, CENTER A ECKING MARKING FIRMATION BY SLIT	TCH, SSY, & AND	मैटेरियल	पहचान	रखरखाव	नेर्देश
Contraction	M/C NAME			M/C NO.			本	टरियल स्टेट्स		रखरखाव	
Contention:	PART NAME		- 1	PART NO.	22100-K3C-D11C (M-23-E0028)	-M1 HRHSHA		🕻 मैटेरियल	करें या	बिन/ट्रोली में लोट	टैग के साध
Control Cont	MODEL		K3CA	SETTING PRESSURE	$52 \pm 2 \text{ kgf/cm}^2$	(Put Circle on applicable		ोक्शन		लाल बिन में रखे	
Procession Pro	TOOLS			JIG/FIX NAME			3. स्पर	₽		पीले बिन में रखे	<u></u>
100-001-001-001-001-001-001-001-001-001	VISUAL AID	SC		JIG/FIX NO.			4. शुह	द्वेकरण	ф	ोले बिन का प्रयोग	भू
CHEANIDA CONTROL CON								केवल	ंजीनियर / सुपरवाईज		अन
Particular Fig. Particular Particula	S. NO.	0	PERATION	POINTS & CONTROL II	TEMS	RESP	CHECKING	МЕТНОВ	ALTERNATE CONTROL	INSP. FRQY.	DATA ENTRY
Part	-	CLINCHING HI				OPERATOR & INSP.	HEIGHT		BACK UP HEIGHT GAUGE		N=5/SETUP & SHIFT
THE STATE OF THE S	7	CLINCHING DI	IAMETER	Ø5~Ø6 mm		OPERATOR & INSP.	VERNIER	CALIPER	BACK UP VERNIER CALIPER	5/SETUP SHIFT	I II
10 10 10 10 10 10 10 10	3	Axial Holding S		9800 N (1000 kgf) Minimum		INSPECTOR	TU		BACK UP FCC MNS	N=1/6 MONTH	N=1/6 MONTH
To see of the see of the shocks of the shock	4	कॉलकिंग जिग कॉम को रखें, पि	के निचले हिस्से में आउटर फेर स्टार्ट बटन दबाएँ।	कॉलकिंग जिग पर	सही प्रकार से	OPERATOR	VISL	JAL		100%	ON
The communion Making & Challedon (or of a ") represented by the communion making & Challedon (or of a ") represented by the communion making of a major service or part of a major serv	Ŋ	∕ 16	द पार्ट को सुनिश्चित करें।	पार्ट मिस तो नही, कॉलकिंग के या आउटर क्लच पर कोई कैक	बाद रिवेट तो नही।	OPERATOR & INSP.	NSL VISL	JAL		100%	=5/SETUP &
10 10 10 10 10 10 10 10	ω	Caulking Con Plate Driven C PUNCH Confin	rfirmation Marking & Sear Side पर 'DIMPLE' mation Marking करें।	Caulking OK पार्ट पर Permanent कनफॉरमेसन Rivet पर BLUE COLO। Plate Driven Gear side की "DIMI MARK पर BLUE COLOR मार्किंग क	ते प्रोसेस हरें। और CH	OPERATOR & INSP.	VISL	JAL		100%	≪
The pressure of the pressure o	7	Appearance		n Miss, Part Miss, tear,cra	hole etc.	OPERATOR & INSP.	VISL	JAL	,	100%	=5/SETUP &
Surface with referred with the control of the contr	ω	Caulking pres	ssure	52 ± 2 kgf/cm2		OPERATOR	Vist [Digital C	Jal Sauge]	,	5/START & FINISH	5/START & FINISH
A STOREY OFFI VEHICATION TO PRINCIPLY AS A STOREY OFFI AT	6	Caulking Jig ∤	4ppearance	No Tear, Wear, Dent, Damage etc		OPERATOR	Visual/	Sence	,	START & FINISH	START & FINISH
REV. NO. REVISOR RECORD DATE NEW ISSUE DATE CHECKING GAUGE SIDE PLATE CHECKING GAUGE SINDS REV. NO. REVISOR RECORD DATE NEW ISSUE DATE CHECKING GAUGE SINDS REV. NO. REVISOR RECORD DATE NEW ISSUE DATE CHECKING GAUGE SINDS REV. NO. REVISOR RECORD DATE NEW ISSUE DATE CHECKING GAUGE SINDS REV. NO. REVISOR RECORD DATE NEW ISSUE DATE CHECKING GAUGE SINDS REV. NO. REVISOR RECORD DATE NEW ISSUE DATE NEW IS	10	ं जीग भं करें	एसेम्बली	आउटर कॉम एसेम्बली स्लीट जिग में होनी चाहिए, और अगर डबल साइड प्लेर से पास नहीं होगा।	자 는 나 나 나 나 나 나 나 나 나 나 나 나 ا ا ا ا ا ا ا	OPERATOR	SLIT	SIG	,	100%	5/SETUP
: :	OUT CON FCC-OS-ASS)	SUB ASSY SUB ASSY CONTROL STATUS OL NO:: 17-K3CA-04	TINCHING DIA. 1) O REV. NO.	से पास नहीं होगा । CAULKING CAULKING SIDE PLATE CHECK REVISION RECORD NEW ISSUE	SAUGE DATE	APPROVE	1 - 14	PROCESS CLI CLI CLI CLI CLI CLI CLI C	मोल्झिंग म करें। ग करें। श CONFIMATI S CONFIMATI D BV	MARKING CON MARKIN	DIMPLE पंच कन्फर्मेशन माकिंग करे। NFIRM करे। SSUED BY