FCC CLUTCH INDIA

OPERATION STANDARD (B)

Doc. No.: FCC-APQP-QF0-04(b)
Rev. No.: 01 Rev. Date: 21.02.2018 SHEET ...11.. OF ...13.

OPERA	OPERATION NO.	7A	OPERATION NAME	AXIAL & ROTATIONAL MOVEMENT	EMENT				
PREVIC	PREVIOUS OPN.	TORQUE CONFIRMATION, SPRING DETECTION, MOVEMENT CHECK, SLIT JIG CONFIRMATION & LOT STAMPING	NEXT OPERATION	I.D. INSPECTION OF LIFTER & OUTER COMP CLUTCH BY AIR PLUG GAUGE & PACKING	JTER COMP & PACKING	मैटेरियल	कि पहचान औ	मैटेरियल कि पहचान और रखरखाव के निर्देश।	नेर्देश
M/C NAME	ME		M/C NO.			मैटरियल स्टेट्स		रखरखाव	
PART NAME	JAME	CLUTCH ASSY.	PART NO.	100-D6G01-05 (22100-AAH-F010)		1. OK मैटेरियल	प्रयोग करें या बि	प्रयोग करें या बिन⁄ट्रोली में लोट टैग के साथ रखें	टैग के साथ रखें।
MODEL		KST-VA	SETTING PRESSURE	0.4~0.6Mpa		2. रिजेक्शन		लाल बिन में रखें	
TOOLS			JIG/FIX NAME			3. स्पलायर की गलती		पीले बिन में रखें	
VISUAL AIDS	AIDS		JIG/FIX NO.	•	,	4. शुद्धिकरण	पीः	पीले बिन का प्रयोग करें	नरें ।
						नोट:– शुद्धिकरण केवल इंजीनियर/सुपरवाईज़र के द्वारा शिफ्ट के अन्त में किया जाए।	इंजीनियर / सुपरवाः जाए।	गर्डज़र के द्वारा शिष् !।	ट के अन्त में किया
S. NO.		OPERATION	POINTS & CONTROL ITEMS	ITEMS RESP	СНЕС	CHECKING METHOD	ALTERNATE CONTROL	INSP. FRQY.	DATA ENTRY
~	क्लच असेंबर्ल लगाकर रोटेश	क्लच असेंबली का एक्सियल लोड लगाकर रोटेशनल मूवमेंट चेक करे	CFD और क्लच प्लेट की लोड लगाने के बाद रोटेशनल मूवमेंट फ्री होनी चाहिर	लगाने के चाहिए		(AXIAL LOAD MACHINE & HANDLE)	ı	100%	N=5/SHIFT & SETUP

N=5/SETUP & SHIFT

100%

देखकर चैक करें।


OPER


CHECK LIFTER FOR BREAKAGE & MARKING GREEN COLOR.

MARKING OF LIFTER

2







DOCUMENT CONTROL STATUS	REV. NO.	REVISION RECORD	DATE	APPROVED BY	CONFIRMED BY	PREPARED BY	ISSUED BY
Maco logative	•			1	/ JA		
CONTROL COPY	(i)	NEW ISSUE	26-Mar-21	125	1	•	9
OPS CONTROL NO.:	\ <u>\</u>	Line No. added for Lot Stamp Process (CSR)	23-Jul-21		3/2 / S		The rainbox
FCC-OS-ASY-KST VA-11A				\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	2)

चाहिए।

CFD और क्लच प्लेट मूव नही होनी

7