

Chino - Setting Display Unit IR-GZ (example with IR-SA series)






IR-VXS1E

Measured value trend display and parameter settings available by connecting to maximum 3 units of IR-SA.



Environment	OS	Windows 2000 / XP / Vista
	Hard drive	Capacity: 20MB or more
	Drive	CD-ROM (use when installation)
Functions	Real time trend display Data storage (CSV type) / replay / printing Parameter setup and readout	
Option	Protocol convertor Communication cable (for protocol convertor and PC)	







Chino - Setting Display Unit IR-GZ (example with IR-SA series)

STRUCTURE

Basic system by IR-GZ



Remote monitoring and data acquisition by PC



Plural units monitoring

