
Sheet1

E	MO	M1	M2	No-zero
0	0	0	0	0.5
		0	1	0.5625
		1	0	0.625
		1	1	0.6875
	1	0	0	0.75
		0	1	0.8125
		1	0	0.875
		1	1	0.9375
1	0	0		1
		0	1	1.125
	U	1	0	1.25
		1	1	1.375
Ι Ι		0		1.5
	1	0	1	1.625
		1	0	1.75
		1	1	1.875
2	0	0	0	2
		0	1	2.25
		1	0	2.5
		1	1	2.75
	1	0	0	3
		0	1	3.25
		1	0	3.5
		1	1	3.75
3	0	0	0	4
		0	1	4.5
		1	0	5
		1	1	5.5
	1	0	0	6
		0	1	6.5
		1	0	7
		1	1	7.5



Page 2

Sheet1

E	M1	M0	No-zero
0	0	0	0.125
	0	1	0.15625
	1		0.1875
	1	1	0.21875
	0	0	0.25
1	0	1	0.3125
	1	0	0.375
	1	1	0.4375
	0		0.5
2	0	1	0.625
_	1	0	0.75
	1	1	0.875
	0	0	1
3	0	1	1.25
3	1	0	1.5
	1	1	1.75
	0	0	2
4	0	1	2.5
4	1	0	3
	1	1	3.5
	0	0	4
_	0	1	5
5	1	0	6
	1	1	7
	0	0	8
6	0	1	10
6	1	0	12
	1	1	14
	0		16
7	0	1	20
'	1		24
	1	1	28

