

Bulletin B522

 RIBMXA 393014C

TYPE F, G, EM For use with:

General Signaling Equip. NM

Dry Indoor Use Smoke Control System

- 1. Start load and let stabilize. 2. Turn screw counterclockwise until LED#1 goes ON
- (may already be ON). 3. Turn screw clockwise until LED#2 goes ON.
- 4. Turn screw counterclockwise until LED#1 goes ON.
- 5. For differential, continue turning screw counterclockwise

(approx. 30% of current per turn).

www.functionaldevices.com

SIGNALING


LISTED

13CY

Functional Devices, Inc. 101 Commerce Drive Sharpsville, IN 46068 Phone: (800) 888-5538

SENSOR OUTPUT Maximum 30Vac/dc Maximum .4A

SENSOR RANGE 0.5-20A. Maximum 20A



CAUTION: RISK OF ELECTRIC SHOCK - MORE THAN ONE DISCONNECT MAY BE REQUIRED TO DEFNERGIZE THE DEVICE BEFORE SERVICING.

Current

Sensor

Status =

Closed

when

OΝ