

South package - inspection retention index

Work rybex-d86cdd4cd0c04dea97da79c382cf790c

Package wp-78e58674787b43ccb8b63571d69e6495

Release 596f7f59-9ff9-4427-b750-9aeca91510ab

Turnover 8a8fd746-0c2f-4039-b2a2-5feb177045ef

Retained source summary

Requirement 414f0882-63ea-4222-9961-f13f4532aea5:

ten installed control points respond to agreed alarm test.

Verified passing inspection: 37bd1b5a-d2a0-43f0-8e3d-915cb925ce10.

The retained source inspection remains the governing review record.

Fictional qualification only. No real customer or engineering approval is claimed.

Source facts are the accepted D5O pilot Work Record and exact reviewed revisions above.