



COPQ REPORT



COPQ là chi phí nhà máy phải chi trả khi có giày lỗi cần sửa chữa, giày phế.

Chi phí này báo gồm: **chi phí nguyên vật liệu, chi phí nhân công.**

Mục đích làm báo cáo này giúp doanh nghiệp nắm bắt được các chi phí phát sinh trong quá trình sản xuất.




LOG INTO

For COPQ include:
in VietNam: VH-VH2-VH3-VH4
in Indonesia: JV-JV2-JVB

→ Log into “Sfc.chingluh.com” → Quality Management System
→ Select Language
→ Select Factory (ex: VH, VH2, JV, JV2..) → Performance Management → COPQ Report

Production Modules

Access key production management modules to monitor and control manufacturing processes.



LOG INTO

Cost Of Poor Quality Report

Input date: 2026-03-13

2026-03-13

1

Factory	Rework	Re-inspectio	1.Report COPQ	Inbound/PI Claim	SGS Fail Retest	Defective Return	Ttl cost
			2.COPQ Data				
			3. COPQ By Monthly				
Shoes	17908			61.27	0	0	18014.88
Factory Sandals	1936			3.86	0	0	1953.82
Stockfitting	0.00	0		0.00	0	0	0
CMP	0.00	0		0.00	0	0	0
DP	0.00	0		0.00	0	0	0
IP	0.00	0		0.00	0	0	0
OS	0.00	41.88		0.00	0	0	41.88
PU	0.00	0		0.00	0	0	0
Total	19,844.00	101.45		65.13	0.00	0.00	20,010.58

- Click excell→choose COPQ data
- Leave blank Category & Type
- Choose date from...to....
- Click
- Choose excell

Report COPQ

清祿

2

3

4

5

Category:

Type:

Input dates: 2026-02-01 2026-02-28

Date	Category	Type	Factory	Fty/Line	Style Nbr	Mold	Model	Defective Qty(Pair)	FOB (\$)	Manpower	Labor cost (\$)	Working hours	SGS Retest Qty (Pic)	SGS Test unit price/	SG
2026-02-02	Internal	Rework		Line 8	CZ5478		NIKE VICTORI ONE SHOWER SLIDE	130.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 1	Line 11	HM9593		W NIKE RUN DEFY	422.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 1	Line 11	IB2766		W NIKE UPLIFT SC	45.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 1	Line 12	HV9272		NIKE AIR WINFLO 12	451.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 1	Line 14	HV9272		NIKE AIR WINFLO 12	305.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 1	Line 15	553558		AIR JORDAN 1 LOW	487.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 1	Line 5	CT3839		AIR FORCE 1 (GS)	365.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 1	Line 5	DH2920		AIR FORCE 1 LE (GS)	35.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 1	Line 6	CJ1677		WMNS NIKE WEARALLDAY	23.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 1	Line 6	CJ1682		NIKE WEARALLDAY	486.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 1	Line 7	554725		AIR JORDAN 1 MID (GS)	406.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	B/C	Factory 1	Line 7	554725		AIR JORDAN 1 MID (GS)	0.5	19.68	0		0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 1	Line 7	DH2920		AIR FORCE 1 LE (GS)	18.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 1	Line 8	IQ6016		JORDAN COURT CONNECT LOW (GS)	485.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 1	Line 9	BQ6472		WMNS AIR JORDAN 1 MID	388.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 1	Line 9	DV0991		WMNS AIR JORDAN 1 MID	72.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 2	Line 1	314870		WMNS CELSO GIRL THONG	275.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 2	Line 1	DC9835		JORDAN PLAY SLIDE	55.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 2	Line 1	HF3263		JORDAN FRANCHISE SLIDE	657.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 2	Line 2	CN9675		NIKE VICTORI ONE SLIDE	52.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 2	Line 2	CN9677		W NIKE VICTORI ONE SLIDE	205.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 2	Line 2	HF3263		JORDAN FRANCHISE SLIDE	630.0	0.0	1	484	0.0	0	0.0	
2026-02-02	Internal	Rework	Factory 2	Line 3	CN9675		NIKE VICTORI ONE SLIDE	1020.0	0.0	1	484	0.0	0	0.0	

CLEAN THE DATA

Cost Of Poor Quality 2026-02-01_2026-02-28.xls [Compatibility Mode] - Ex...

File Home Insert Page Layout Formulas Data Review View Help

Clipboard Font Alignment Number Styles Cells Editing

C10 Rework

1	A	B	C	D	E	F	G	H	I	J	K	L	M	N
1	Cost Of Poor Quality													
3	Date	Category	Type	Factory	Fty/Line	Style Nbr	Mold	Model	Defective Qty(Pair)	FOB (\$)	Manpower	Labor cost (\$)	Working hours	
4	2-Feb-26	Internal	Rework		Line 8	CZ5478		NIKE VICTORI ONE SHOWER SLIDE	130	0	1	484	0	
5	2-Feb-26	Internal	Rework	Factory 1	Line 11	HM9593		W NIKE RUN DEFY	422	0	1	484	0	
6	2-Feb-26	Internal	Rework	Factory 1	Line 11	IB2766		W NIKE UPLIFT SC	45	0	1	484	0	
7	2-Feb-26	Internal	Rework	Factory 1	Line 12	HV9272		NIKE AIR WINFLO 12	451	0	1	484	0	
8	2-Feb-26	Internal	Rework	Factory 1	Line 14	HV9272		NIKE AIR WINFLO 12	305	0	1	484	0	
9	2-Feb-26	Internal	Rework	Factory 1	Line 15	553558		AIR JORDAN 1 LOW	487	0	1	484	0	
10	2-Feb-26	Internal	Rework	Factory 1	Line 5	CT3839		AIR FORCE 1 (GS)	365	0	1	484	0	
11	2-Feb-26	Internal	Rework	Factory 1	Line 5	DH2920		AIR FORCE 1 LE (GS)	35	0	1	484	0	
12	2-Feb-26	Internal	Rework	Factory 1	Line 6	CJ1677		WMNS NIKE WEARALLDAY	23	0	1	484	0	
13	2-Feb-26	Internal	Rework	Factory 1	Line 6	CJ1682		NIKE WEARALLDAY	486	0	1	484	0	
14	2-Feb-26	Internal	Rework	Factory 1	Line 7	554725		AIR JORDAN 1 MID (GS)	406	0	1	484	0	
15	2-Feb-26	Internal	B/C	Factory 1	Line 7	554725		AIR JORDAN 1 MID (GS)	0.5	19.68	0		0	
16	2-Feb-26	Internal	Rework	Factory 1	Line 7	DH2920		AIR FORCE 1 LE (GS)	18	0	1	484	0	
17	2-Feb-26	Internal	Rework	Factory 1	Line 8	IQ6016		JORDAN COURT CONNECT LOW (GS)	485	0	1	484	0	
18	2-Feb-26	Internal	Rework	Factory 1	Line 9	BQ6472		WMNS AIR JORDAN 1 MID	388	0	1	484	0	
19	2-Feb-26	Internal	Rework	Factory 1	Line 9	DV0991		WMNS AIR JORDAN 1 MID	72	0	1	484	0	
20	2-Feb-26	Internal	Rework	Factory 2	Line 1	314870		WMNS CELSO GIRL THONG	275	0	1	484	0	
21	2-Feb-26	Internal	Rework	Factory 2	Line 1	DC9835		JORDAN PLAY SLIDE	55	0	1	484	0	
22	2-Feb-26	Internal	Rework	Factory 2	Line 1	HF3263		JORDAN FRANCHISE SLIDE	657	0	1	484	0	
23	2-Feb-26	Internal	Rework	Factory 2	Line 2	CN0675		NIKE VICTORI ONE SLIDE	52	0	1	484	0	

Cost Of Poor Quality

Ready

100%

Unhide the second row down

CLEAN THE DATA

Cost Of Poor Quality

Type	Factory	Fty/L ine	Style Nbr	Mold	Model	Defective Qty(Pair)	FOB (€)	Manpower	Labor cost (€)	Working hours
Rework		Line 8	CZ5478		NIKE VICTORI ONE SHOWER SLIDE	130	0	1	484	0
Rework	Factory 1	Line 11	HM9593		W NIKE RUN DEFY	422	0	1	484	0
Rework	Factory 1	Line 11	IB2766		W NIKE UPLIFT SC	45	0	1	484	0
Rework	Factory 1	Line 12	HV9272		NIKE AIR WINFLO 12	451	0	1	484	0
Rework	Factory 1	Line 14	HV9272		NIKE AIR WINFLO 12	305	0	1	484	0
Rework	Factory 1	Line 15	553558		AIR JORDAN 1 LOW	487	0	1	484	0
Rework	Factory 1	Line 5	CT3839		AIR FORCE 1 (GS)	365	0	1	484	0
Rework	Factory 1	Line 5	DH2920		AIR FORCE 1 LE (GS)	35	0	1	484	0
Rework	Factory 1	Line 6	CJ1677		WMNS NIKE WEARALLDAY	23	0	1	484	0
Rework	Factory 1	Line 6	CT1692		NIKE WEARALLDAY	486	0	1	484	0

[illegible]

→ Delete the first 2 row

→ Press Ctrl + ↓ → Delete the last row

CLEAN THE DATA

The header of each column

Date
Category
Type
Factory
Fty/Line
Style Nbr
Mold
Model
Defective Qty(Pair)
FOB (\$)
Manpower
Labor cost (\$)
Working hours
SGS Retest Qty (Pic)
SGS Test unit price/pic (\$)
SGS Retest failure C grade
Ttl cost (\$)
PO
Remark
Remark (Re-inspection Station)

File

Home

Insert

Page Layout

Formulas

Data

Review

View

Help

Share

Get Data

From Text/CSV

From Web

From Table/Range

Recent Sources

Existing Connections

Get & Transform Data

Refresh All

Queries & Connections

Properties

Edit Links

Queries & Connections

Sort

Filter

Clear

Reapply

Advanced

Sort & Filter

Text to Columns

Data Tools

What-If Analysis

Forecast Sheet

Forecast

Group

Ungroup

Subtotal

Outline

Data Analysis

Analysis

B4

:

X

✓

fx

Internal

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	
1	Date	Category	Type	Factory	Fty/Line	Style Nbr	Mold	Model			Defective Qty(Pair)	FOB (\$)	Manpower	Labor cost (\$)	Working hours	SGS Retest Qty (Pic)	SGS Test unit price/pic (\$)	SGS Retest failure C grade	Ttl cost (\$)	PO	Remark	Remark (Re-inspection Station)
2	2-Feb-26	Internal	Rework		Line 8	CZ5478		NIKE VICTORI ONE SHOWER SLIDE			130	0	1	484	0	0	0	0	484			
3	2-Feb-26	Internal	Rework	Factory 1	Line 11	HM9593		W NIKE RUN DEFY			422	0	1	484	0	0	0	0	484			
4	2-Feb-26	Internal	Rework	Factory 1	Line 11	IB2766		W NIKE UPLIFT SC			45	0	1	484	0	0	0	0	0			
5	2-Feb-26	Internal	Rework	Factory 1	Line 12	HV9272		NIKE AIR WINFLO 12			451	0	1	484	0	0	0	0	484			
6	2-Feb-26	Internal	Rework	Factory 1	Line 14	HV9272		NIKE AIR WINFLO 12			305	0	1	484	0	0	0	0	484			
7	2-Feb-26	Internal	Rework	Factory 1	Line 15	553558		AIR JORDAN 1 LOW			487	0	1	484	0	0	0	0	484			

Note:

- If the Factory is OS or IP, there must be a Model and Mold Code.
- If the Factory is line, sandals, stockfitting, there must be a Model and Style Nbr.
- Type: There are 3 types: B/C, Reinspection, Rework
 - Reinspection has 2 types: Reinspection and Touch up – paint
 - Touch up – paint will be noted in Remark (Reinspection Station).

CLEAN THE DATA

Click Data → Filter → Check each data column to see if there is any wrong or blanks data.

1 Data 2 Filter 3

EX

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
	Date	Category	Type	Factory	Fty/Line	Style Nbr	Mold		Model	Defective Qty(Pa	FOB	Manpow	Labor cost	Working ho	SGS Retest Qty (Pi	SGS Test unit price/pic	SGS Retest failure C grad	Ttl cost	PO	Remark	Remark (Ke-
1	2-Feb-26	Internal	Rework		Line 8	CZ5478			NIKE VICTORI ONE SHOWER SLIDE	130	0	1	484	0	0	0	0	484			
3	2-Feb-26	Internal	Rework	Factory 1	Line 11	HM9593			W NIKE RUN DEFY				484	0	0	0	0	484			
4	2-Feb-26	Internal	Rework	Factory 1	Line 11	IB2766			W NIKE UPLIFT SC				484	0	0	0	0	0			
5	2-Feb-26	Internal	Rework	Factory 1	Line 12	HV9272			NIKE AIR WINFLO 12				484	0	0	0	0	484			
6	2-Feb-26	Internal	Rework	Factory 1	Line 14	HV9272			NIKE AIR WINFLO 12				484	0	0	0	0	484			
7	2-Feb-26	Internal	Rework	Factory 1	Line 15	553558			AIR JORDAN 1 LOW				484	0	0	0	0	484			

	Date	Category	Type	Factory	Fty/Line	Style Nbr	Mold		Model	Defective Qty(Pa	FOB	Manpow	Labor cost	Working ho	SGS Retest Qty (Pi	SGS Test unit price/pic	SGS Retest failure C grad	Ttl cost	PO	Remark	Remark (Ke-
1	2-Feb-26	Internal	Reinspection	Factory 4	VE - S2 Line 4	IQ5698-003				72	0	5	484	0.3	0	0	0	3.49			HFPA
3	5-Feb-26	Internal	Reinspection	Factory 4	VE - S2 Line 4	IQ5698-003				66	0	5	484	0.3	0	0	0	3.49			HFPA
5	10-Feb-26	Internal	Reinspection	OS						350	0	4	484	2	0	0	0	18.62			Touch-up paint

Possible error cases:

- Have Model but missing Style Nbr, and vice versa.
- Have Model but missing Mold code, and vice versa.
- Missing Type (B/C classification, Reinspection).
- Type is Reinspection but missing defect pairs, manpower, working hours, or Ttl cost.
- Type is B/C but missing pairs or missing Ttl cost.

If any errors are found, please edit data at the system → then download the data again to make the report.

Comparison of BC Defect Pairs: COPQ vs. FTT Data

DOWNLOAD FTT DATA

Production Modules
Access key production management modules to monitor and control manufacturing processes.

- Shoes Factory Planning
Manages production planning for shoe factories
- Bottom Factory Planning
Manages production planning for bottom factories
- Workforce
Manages workforce allocation and attendance
- Station
Oversees production station operations
- Output
Monitors production output metrics
- Replenishment
Manages material replenishment
- Report
Generates production and inventory reports
- Production Analysis
Analyzes production performance
- Quality Management System**
Ensures quality control standards

Quality Management System
VH English Hii Trần Thị Kim Huyền

English VH Home page

- 1. Control Plan
- 2. Basic Information
- 3. QA Document
- 4. Collect Data
- 5. Quality Database
- 6. Performance Management**

Quality Management System
VH English Hii Trần Thị Kim Huyền

English VH Home page Performance Management

- 1. COPQ Report
- 2. Dashboard
- 3. FTT**
- 4. BDTS Report

- Log into “Sfc.chingluh.com” → Quality Management System
- Select Language
- Select Factory (ex: VH, VH2, JV, JV2) which you want to make a report
- Performance Management → FTT

Comparison of BC Defect Pairs: COPQ vs. FTT Data

FTT

Select Station

☒ Cutting

☒ HFPA

☒ Stitching

☒ Assembly IPQC

☒ Assembly

☒ Stockfitting

OK

Cancel


FTT Report: Internal & External

NIKE

Internal

File Name

- Choose date from ...to...
- Click
- Choose 2nd excell:
 - For FTT→ Assembly→ Internal



Comparison of BC Defect Pairs: COPQ vs. FTT Data

1st Pivot Table

3

2

1

Do Not Show Subtotals

Show all Subtotals at Bottom of Group

Show all Subtotals at Top of Group

Include Filtered Items in Totals

Off for Rows and Columns

On for Rows and Columns

On for Rows Only

On for Columns Only

Show in Compact Form

Show in Outline Form

Show in Tabular Form

Repeat All Item Labels

Do Not Repeat Item Labels

FileHomeInsertPage LayoutFormulasDataReviewViewHelpPivotTable AnalyzeDesign

SubtotalsGrand TotalsReport LayoutBlank Rows

Row Headers

Banded Rows

Column Headers

Banded Columns

PivotTable Style Options

PivotTable Styles

P4

Drop Report Filter Fields Here

Date	Factory	FactoryGroup	Plant	Line	Model	Model 2	SO#	Season	Cutting Die	Style Nbr	Colorway Cd	Number of pairs	Station	Metric
02/02/2026	JV	CLG	N1	Line 1	NIKE DL	NIKE DL	N26B31	SU26	L-004-8	HF5441	009	1	Assembly	C/Reject
02/02/2026	JV	CLG	N1	Line 1	NIKE DL	NIKE DL	N26B31	SU26	L-004-8	HF5441	112	0.5	Assembly	C/Reject
02/02/2026	JV	CLG	N1	Line 1	NIKE DL	NIKE DL	N26B31	SU26	L-004-8	HF5441	112	10	Assembly	Multi Rework
02/02/2026	JV	CLG	N1	Line 1	NIKE DL	NIKE DL	N26B31	SU26	L-004-8	HF5441	112	181	Assembly	Rework1
02/02/2026	JV	CLG	N1	Line 1	NIKE DL	NIKE DL	N26B31	SU26	L-004-8	HF5441	112	606	Assembly	AGrade
02/02/2026	JV	CLG	N1	Line 2	NIKE IN	WMNS	N26B21	FA26	NQ-114	394053	100	1	Assembly	C/Reject
02/02/2026	JV	CLG	N1	Line 2	NIKE IN	WMNS	N26B21	FA26	NQ-114	394053	100	20	Assembly	Multi Rework
02/02/2026	JV	CLG	N1	Line 2	NIKE IN	WMNS	N26B21	FA26	NQ-114	394053	100	314	Assembly	Rework1
02/02/2026	JV	CLG	N1	Line 2	NIKE IN	WMNS	N26B21	FA26	NQ-114	394053	100	1064	Assembly	AGrade
02/02/2026	JV	CLG	N1	Line 2	NIKE IN	WMNS	N26B31	FA26	NQ-114	394053	100	5	Assembly	Multi Rework
02/02/2026	JV	CLG	N1	Line 2	NIKE IN	WMNS	N26B31	FA26	NQ-114	394053	100	56	Assembly	Rework1
02/02/2026	JV	CLG	N1	Line 2	NIKE IN	WMNS	N26B31	FA26	NQ-114	394053	100	296	Assembly	AGrade
02/02/2026	JV	CLG	N1	Line 3	NIKE IN	NIKE IN	N26B21	SU26	NQ-113	IB4595	001	7	Assembly	Rework1
02/02/2026	JV	CLG	N1	Line 3	NIKE IN	NIKE IN	N26B21	SU26	NQ-113	IB4595	001	0.5	Assembly	C/Reject
02/02/2026	JV	CLG	N1	Line 3	NIKE IN	NIKE IN	N26B21	SU26	NQ-113	IB4595	001	9	Assembly	Multi Rework
02/02/2026	JV	CLG	N1	Line 3	NIKE IN	NIKE IN	N26B21	SU26	NQ-113	IB4595	001	98	Assembly	Rework1
02/02/2026	JV	CLG	N1	Line 3	NIKE IN	NIKE IN	N26B21	SU26	NQ-113	IB4595	001	212	Assembly	AGrade
02/02/2026	JV	CLG	N1	Line 3	NIKE IN	WMNS	N26B21	SU26	N-114	394053	105	3	Assembly	Multi Rework
02/02/2026	JV	CLG	N1	Line 3	NIKE IN	WMNS	N26B21	SU26	N-114	394053	105	74	Assembly	Rework1
02/02/2026	JV	CLG	N1	Line 3	NIKE IN	WMNS	N26B21	SU26	N-114	394053	105	354	Assembly	AGrade
02/02/2026	JV	CLG	N1	Line 3	NIKE IN	WMNS	N26B21	FA26	NQ-114	394053	100	3	Assembly	Multi Rework
02/02/2026	JV	CLG	N1	Line 3	NIKE IN	WMNS	N26B21	FA26	NQ-114	394053	100	78	Assembly	Rework1
02/02/2026	JV	CLG	N1	Line 3	NIKE IN	WMNS	N26B31	SU26	NQ-114	394053	100	228	Assembly	AGrade
02/02/2026	JV	CLG	N2	Line 5	NIKE IN	NIKE IN	N26B21	SU26	N-113	394055	001	34	Assembly	AGrade
02/02/2026	JV	CLG	N2	Line 5	NIKE IN	NIKE IN	N26B21	SU26	N-113	394055	001	0.5	Assembly	C/Reject
02/02/2026	JV	CLG	N2	Line 5	NIKE IN	WMNS	N26B21	SU26	N-113	394055	001	4	Assembly	Multi Rework
02/02/2026	JV	CLG	N2	Line 5	NIKE IN	NIKE IN	N26B21	SU26	N-113	394055	001	294	Assembly	Rework1
02/02/2026	JV	CLG	N2	Line 5	NIKE IN	NIKE IN	N26B21	SU26	N-113	394055	001	744	Assembly	AGrade
02/02/2026	JV	CLG	N2	Line 5	NIKE IN	NIKE IN	N26B21	SU26	N-113	394055	001	20	Assembly	Rework1
02/02/2026	JV	CLG	N2	Line 5	NIKE IN	NIKE IN	N26B21	SU26	N-113	394055	001	200	Assembly	AGrade
02/02/2026	JV	CLG	N2	Line 5	NIKE IN	NIKE IN	N26B21	SU26	N-113	394055	001	6	Assembly	AGrade
02/02/2026	JV	CLG	N2	Line 5	NIKE IN	WMNS	N25L11	SU26	N-114	394053	105	54	Assembly	Rework1

PivotTable Fields

Choose fields to add to report:

Date

FactoryGroup

Factory

Plant

Line

Model

Model 2

SO#

Season

Cutting Die

Style Nbr

Colorway Cd

Total Pair Produced

Drop Value Fields Here

Filters

Columns

Rows

Values

Defer Layout Update

Update

Row: Date,FactoryGroup , Factory, Plant, Line, Model, Model 2, SO#, Season,Cutting Die, Style Nbr, Colorway Cd, Metric, Number of pairs, Station
(include all duplicate values)

Ctrl + A → Insert → Pivot Table 1st
Design → Report Layout → Repeat All Items Labels
Design → Grand Totals → Off for Rows and Columns
Design → Subtotals → Do Not Show Subtotals

Copy into a new table

Date	Factory	FactoryGr	Plant	Line	Model	Model 2	SO#	Season	Cutting D	Style Nbr	Colorway	Number c	Station	Metric
02/02/2026	JV	CLG	N1	Line 1	NIKE DUN	NIKE DUN	N26B3095	SU26	L-004-82-	HF5441	009	1	Assembly	C/Reject
02/02/2026	JV	CLG	N1	Line 1	NIKE DUN	NIKE DUN	N26B3102	SU26	L-004-82-	HF5441	112	0.5	Assembly	C/Reject
02/02/2026	JV	CLG	N1	Line 1	NIKE DUN	NIKE DUN	N26B3102	SU26	L-004-82-	HF5441	112	10	Assembly	Multi Rework
02/02/2026	JV	CLG	N1	Line 1	NIKE DUN	NIKE DUN	N26B3102	SU26	L-004-82-	HF5441	112	181	Assembly	Rework1
02/02/2026	JV	CLG	N1	Line 1	NIKE DUN	NIKE DUN	N26B3102	SU26	L-004-82-	HF5441	112	606	Assembly	AGrade
02/02/2026	JV	CLG	N1	Line 2	NIKE INITI	WMNS NII	N26B2621	FA26	NQ-114	394053	100	1	Assembly	C/Reject
02/02/2026	JV	CLG	N1	Line 2	NIKE INITI	WMNS NII	N26B2621	FA26	NQ-114	394053	100	20	Assembly	Multi Rework
02/02/2026	JV	CLG	N1	Line 2	NIKE INITI	WMNS NII	N26B2621	FA26	NQ-114	394053	100	314	Assembly	Rework1
02/02/2026	JV	CLG	N1	Line 2	NIKE INITI	WMNS NII	N26B2621	FA26	NQ-114	394053	100	1064	Assembly	AGrade
02/02/2026	JV	CLG	N1	Line 2	NIKE INITI	WMNS NII	N26B3715	FA26	NQ-114	394053	100	5	Assembly	Multi Rework
02/02/2026	JV	CLG	N1	Line 2	NIKE INITI	WMNS NII	N26B3715	FA26	NQ-114	394053	100	56	Assembly	Rework1
02/02/2026	JV	CLG	N1	Line 2	NIKE INITI	WMNS NII	N26B3715	FA26	NQ-114	394053	100	296	Assembly	AGrade
02/02/2026	JV	CLG	N1	Line 3	NIKE INITI	NIKE INITI	N26B2651	SU26	NQ-113-6	IB4595	001	7	Assembly	Rework1
02/02/2026	JV	CLG	N1	Line 3	NIKE INITI	NIKE INITI	N26B2651	SU26	NQ-113-6	IB4595	001	0.5	Assembly	C/Reject
02/02/2026	JV	CLG	N1	Line 3	NIKE INITI	NIKE INITI	N26B2651	SU26	NQ-113-6	IB4595	001	9	Assembly	Multi Rework
02/02/2026	JV	CLG	N1	Line 3	NIKE INITI	NIKE INITI	N26B2651	SU26	NQ-113-6	IB4595	001	98	Assembly	Rework1
02/02/2026	JV	CLG	N1	Line 3	NIKE INITI	NIKE INITI	N26B2651	SU26	NQ-113-6	IB4595	001	212	Assembly	AGrade
02/02/2026	JV	CLG	N1	Line 3	NIKE INITI	WMNS NII	N26B2643	SU26	N-114	394053	105	3	Assembly	Multi Rework
02/02/2026	JV	CLG	N1	Line 3	NIKE INITI	WMNS NII	N26B2643	SU26	N-114	394053	105	74	Assembly	Rework1
02/02/2026	JV	CLG	N1	Line 3	NIKE INITI	WMNS NII	N26B2643	SU26	N-114	394053	105	354	Assembly	AGrade
02/02/2026	JV	CLG	N1	Line 3	NIKE INITI	WMNS NII	N26B2911	FA26	NQ-114	394053	100	3	Assembly	Multi Rework
02/02/2026	JV	CLG	N1	Line 3	NIKE INITI	WMNS NII	N26B2911	FA26	NQ-114	394053	100	78	Assembly	Rework1
02/02/2026	JV	CLG	N1	Line 3	NIKE INITI	WMNS NII	N26B2911	FA26	NQ-114	394053	100	228	Assembly	AGrade
02/02/2026	JV	CLG	N2	Line 5	NIKE DUN	NIKE DUN	N26B3095	SU26	L-004-82-	HF5441	008	34	Assembly	AGrade
02/02/2026	JV	CLG	N2	Line 5	NIKE INITI	NIKE INITI	N26B2615	SU26	N-113	394055	001	0.5	Assembly	C/Reject
02/02/2026	JV	CLG	N2	Line 5	NIKE INITI	NIKE INITI	N26B2615	SU26	N-113	394055	001	4	Assembly	Multi Rework
02/02/2026	JV	CLG	N2	Line 5	NIKE INITI	NIKE INITI	N26B2615	SU26	N-113	394055	001	294	Assembly	Rework1
02/02/2026	JV	CLG	N2	Line 5	NIKE INITI	NIKE INITI	N26B2615	SU26	N-113	394055	001	744	Assembly	AGrade

Comparison of BC Defect Pairs: COPQ vs. FTT Data

Do Not Show Subtotals

Show all Subtotals at Bottom of Group

Show all Subtotals at Top of Group

Include Filtered Items in Totals

Show in Compact Form

Show in Outline Form

Show in Tabular Form

Repeat All Item Labels

Do Not Repeat Item Labels

2

1

FTT

2nd Pivot Table: Insert → Pivot Table

Filter Metric: B Reject & C reject

AN

AO

AP

AQ

AR

Sum of Number of	Model 2	Metric	B/Reject	C/Reject	Grand Total
02/02/2026	AIR JORDAN 1 MID (GS)		0.5		0.5
02/02/2026	JORDAN FLIGHT ORIGIN 3		0.5		0.5
02/02/2026	NIKE SB ZOOM NYJAH 4		0.5		0.5
02/02/2026	NIKE VICTORI ONE SLIDE		0.5		0.5
02/02/2026	WMNS AIR JORDAN 1 LOW SE		0.5		0.5
02/02/2026	WMNS BENASSI JDI		0.5		0.5
02/03/2026	AIR JORDAN 1 LOW		0.5		0.5
02/03/2026	JORDAN COURT CONNECT MID		0.5		0.5
02/03/2026	JORDAN HYDRO IV RETRO		0.5		0.5
02/03/2026	NIKE SB FORCE 58		0.5		1
02/03/2026	NIKE UPLIFT SC		0.5		0.5
02/03/2026	NIKE VICTORI ONE SLIDE		0.5		0.5
02/03/2026	W NIKE RUN DEFY		0.5		0.5
02/03/2026	W NIKE VICTORI ONE SLIDE		0.5		0.5
02/03/2026	WMNS AIR JORDAN 1 LOW SE		0.5		1
02/03/2026	WMNS BENASSI JDI		0.5		0.5
02/03/2026	WMNS CELSO GIRL THONG		0.5		0.5
02/04/2026	AIR JORDAN 1 MID SE		0.5		0.5
02/04/2026	BENASSI JDI		0.5		0.5
02/04/2026	JORDAN COURT CONNECT LOW		0.5		0.5
02/04/2026	JORDAN FLIGHT ORIGIN 3		0.5		0.5
02/04/2026	JORDAN HYDRO 6		0.5		1
02/04/2026	NIKE AIR WINFLO 12		0.5		0.5
02/04/2026	NIKE SB DUNK LOW PRO QS BT		0.5		0.5
02/04/2026	NIKE SB FORCE 58		0.5		2
02/04/2026	NIKE UPLIFT SC		0.5		1
02/04/2026	W NIKE RUN DEFY		0.5		0.5

PivotTable Fields

Choose fields to add to report:

☒ Date

☒ FactoryGroup

☒ Factory

☒ Plant

☒ Line

☒ Model

☒ Model 2

☒ SO#

☒ Season

☒ Cutting Die

☒ Style Nbr

☒ Colorway Cd

☐ Total Pair Produced

Filters

Columns

Rows

Values

Row: Date, Model 2
Filter : Factory
Values: Number of pairs
Columns: Metric

COPQ

Filter Type: BC

Home

Insert

Page Layout

Formulas

Data

Review

View

Help

PivotTable Analyze

Design

Clipboard

Font

Alignment

Number

Sum of Defective Qty(Pair)

1	fty	VH	Type
2	Remark (Re-inspection Station)		
3			
4	Sum of Defective Qty(Pair)	Model	Type
5	Date		B/C
6	2-Feb-26	AIR JORDAN 1 MID (GS)	0.5
7		JORDAN FLIGHT ORIGIN 3	0.5
8		NIKE SB ZOOM NYJAH 4	0.5
9		NIKE VICTORI ONE SLIDE	0.5
10		WMNS AIR JORDAN 1 LOW SE	0.5
11		WMNS BENASSI JDI	0.5
12	3-Feb-26	AIR JORDAN 1 LOW	0.5
13		JORDAN COURT CONNECT MID	0.5
14		JORDAN HYDRO IV RETRO	0.5
15		NIKE SB FORCE 58	1
16		NIKE UPLIFT SC	0.5
17		NIKE VICTORI ONE SLIDE	0.5
18		W NIKE RUN DEFY	0.5
19		W NIKE VICTORI ONE SLIDE	0.5
20		WMNS AIR JORDAN 1 LOW SE	1
21		WMNS BENASSI JDI	0.5
22		WMNS CELSO GIRL THONG	0.5
23	4-Feb-26	AIR JORDAN 1 MID SE	0.5
24		BENASSI JDI	0.5
25		JORDAN COURT CONNECT LOW	0.5
44		BENASSI JDI	1
45		JORDAN ACCESS	0.5
46		JORDAN COURT CONNECT LOW	1
47		JORDAN HYDRO IV RETRO	0.5
48		NIKE SB ZOOM NYJAH 4	0.5
49		W NIKE UPLIFT SC	0.5
50		WMNS JORDAN POINTE	0.5
51	7-Feb-26	AIR JORDAN 1 LOW	0.5
52		BENASSI JDI	0.5
53		NIKE SB DUNK LOW PRO	0.5
54		NIKE SB FORCE 58	1.5
55	9-Feb-26	AIR JORDAN 1 MID SE	1
56		JORDAN ACCESS	0.5
57		JORDAN COURT CONNECT LOW (GS)	0.5
58		JORDAN FLIGHT ORIGIN 3 (GS)	0.5
59		JORDAN HYDRO IV RETRO	0.5

PivotTable Fields

Choose fields to add to report:

☒ Date

☐ Category

☒ Type

☒ fty

☐ Factory

☐ Fty/Line

☐ Style Nbr

☐ Mold

☒ Model

☒ Defective Qty(Pair)

☐ FOB (\$)

☐ Manpower

☐ Labor cost (\$)

Filters

Columns

Rows

Values

Row: FTY, Factory,Date
Filter : Remark (Re-inspection Station)
Values: Defective Qty (pair), Ttl cost.
Columns: Type

Copy into a new table

Copy the COPQ data into the same sheet as the FTT data.

Comparison of BC Defect Pairs: COPQ vs. FTT Data

FEB 2026,COPQ .xls [Compatibility Mode] - Excel									
Page Layout Formulas Data Review View Help									
Font Alignment Number Styles									
=P7=L7									
COPQ			FTT						
Date	Model	B/C	Date	Model 2	Total BC				
2-Feb-26	AIR JORDAN 1 MID (GS)	0.5	02/02/2026	AIR JORDAN 1 MID (GS)	0.5	=P7=L7	TRUE		
	JORDAN FLIGHT ORIGIN 3	0.5	02/02/2026	JORDAN FLIGHT ORIGIN 3	0.5	TRUE	TRUE		
	NIKE SB ZOOM NYJAH 4	0.5	02/02/2026	NIKE SB ZOOM NYJAH 4	0.5	TRUE	TRUE		
	NIKE VICTORI ONE SLIDE	0.5	02/02/2026	NIKE VICTORI ONE SLIDE	0.5	TRUE	TRUE		
	WMNS AIR JORDAN 1 LOW SE	0.5	02/02/2026	WMNS AIR JORDAN 1 LOW SE	0.5	TRUE	TRUE		
	WMNS BENASSI JDI	0.5	02/02/2026	WMNS BENASSI JDI	0.5	TRUE	TRUE		
3-Feb-26	AIR JORDAN 1 LOW	0.5	02/03/2026	AIR JORDAN 1 LOW	0.5	TRUE	TRUE		
	JORDAN COURT CONNECT MID	0.5	02/03/2026	JORDAN COURT CONNECT MID	0.5	TRUE	TRUE		
	JORDAN HYDRO IV RETRO	0.5	02/03/2026	JORDAN HYDRO IV RETRO	0.5	TRUE	TRUE		
	NIKE SB FORCE 58	1	02/03/2026	NIKE SB FORCE 58	1	TRUE	TRUE		
	NIKE UPLIFT SC	0.5	02/03/2026	NIKE UPLIFT SC	0.5	TRUE	TRUE		
	NIKE VICTORI ONE SLIDE	0.5	02/03/2026	NIKE VICTORI ONE SLIDE	0.5	TRUE	TRUE		
	W NIKE RUN DEFY	0.5	02/03/2026	W NIKE RUN DEFY	0.5	TRUE	TRUE		
	W NIKE VICTORI ONE SLIDE	0.5	02/03/2026	W NIKE VICTORI ONE SLIDE	0.5	TRUE	TRUE		
	WMNS AIR JORDAN 1 LOW SE	1	02/03/2026	WMNS AIR JORDAN 1 LOW SE	1	TRUE	TRUE		
	WMNS BENASSI JDI	0.5	02/03/2026	WMNS BENASSI JDI	0.5	TRUE	TRUE		
	WMNS CELSO GIRL THONG	0.5	02/03/2026	WMNS CELSO GIRL THONG	0.5	TRUE	TRUE		
4-Feb-26	AIR JORDAN 1 MID SE	0.5	02/04/2026	AIR JORDAN 1 MID SE	0.5	TRUE	TRUE		
	BENASSI JDI	0.5	02/04/2026	BENASSI JDI	0.5	TRUE	TRUE		
6-Feb-26	AIR FORCE 1 LE (GS)	0.5	02/06/2026	AIR FORCE 1 LE (GS)	0.5	TRUE	TRUE		
	BENASSI JDI	1	02/06/2026	BENASSI JDI	1	TRUE	TRUE		
	JORDAN ACCESS	0.5	02/06/2026	JORDAN ACCESS	0.5	TRUE	TRUE		
	JORDAN COURT CONNECT LOW	1	02/06/2026	JORDAN COURT CONNECT LOW	1	TRUE	TRUE		
	JORDAN HYDRO IV RETRO	0.5	02/06/2026	JORDAN HYDRO IV RETRO	0.5	TRUE	TRUE		
	NIKE SB ZOOM NYJAH 4	0.5	02/06/2026	NIKE SB ZOOM NYJAH 4	0.5	TRUE	TRUE		
	W NIKE UPLIFT SC	0.5	02/06/2026	W NIKE UPLIFT SC	0.5	TRUE	TRUE		
	WMNS JORDAN POINTE	0.5	02/06/2026	WMNS JORDAN POINTE	0.5	TRUE	TRUE		
7-Feb-26	AIR JORDAN 1 LOW	0.5	02/07/2026	AIR JORDAN 1 LOW	0.5	TRUE	TRUE		
	BENASSI JDI	0.5	02/07/2026	BENASSI JDI	0.5	TRUE	TRUE		
	NIKE SB DUNK LOW PRO	0.5	02/07/2026	NIKE SB DUNK LOW PRO	0.5	TRUE	TRUE		
	NIKE SB FORCE 58	1.5	02/07/2026	NIKE SB FORCE 58	1.5	TRUE	TRUE		


→Check each column of COPQ vs. FTT data using the

formula =P7=L7

- **P7: Model (FTT data)**
- **L7: Model (COPQ data)**

→The result is FALSE, send an email to QC to recheck and correct the COPQ data.

ANALYSIS




After checking the data:

If any results are FALSE and QC has updated the data, download the COPQ data again.→ Recheck the data to ensure accuracy.→ Once the data is correct, proceed with COPQ data analysis.

Ctrl + A → Insert → Pivot Table → New worksheet → Ok

	A	B	C	D
1	Remark (Re-inspection Station)	(All)		
2				
3		Type	-T	Data
4		B/C		
5	Qty	Sum of Defective Qty(Pair)	Sum of Working hours	Sum of Ttl cost (\$)
6	JV	346.5	0	5764.71
7	JV2	45	0	753.49
8	VH	73.5	0	1264.52
9	VH2	12	0	232.75
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				
35				
36				
37				
38				
39				
40				
41				



Row: FTY

Filter : Remark (Re-inspection Station)
 Values: Defective Qty (pair), Working
 hours, Ttl cost.
 Columns: Type

ANALYSIS

FILE COPQ DATA

Copy data → Paste 123 in file CoPQ database 25

Filter Type: BC

Remark (Re-inspection Station)	(All)		
	Type	-T	Data
	B/C		
fty	Sum of Defective Qty(Pair)	Sum of Working hours	Sum of Ttl cost (\$)
JV	346.5	0	5764.71
JV2	45	0	753.49
VH	73.5	0	1264.52
VH2	12	0	232.75

**-Filter Type :
Reinspection
-Filter Remark: r
Touch-up paint**

Remark (Re-inspection Station)	(Multiple Items)		
	Type	Data	
	Reinspection		
Qty	Sum of Defective Qty(Pair)	Sum of Working hours	Sum of Ttl cost (\$)
VH3	974	4.5	11.56
VH	14359	149.8	1504.83
JV3	27670	106.6	1318.64
JV2	37692	47.5	428.15
JV	46819	487	1877.75
	43701	157	1551.38

Filter Type :
Reinspection
Filter Remark:
Touch-up paint

A	B	C	D
Remark (Re-inspection Station)	Touch-up paint		
	Type	Data	
fty	Reinspection		
	Sum of Defective Qty(Pair)	Sum of Working hours	Sum of Ttl cost (\$)
JV	7546	77	750.7
VH	6594	41	272.2
VH2	7754	136	1099.6
VH4	13584	333.8	2086.2

[illegible]

ANALYSIS

Copy data → Paste 123 in file CoPQ type analysis

FILE COPQ TYPE ANALYSIS

Remark (Re-inspection Station)	(All)	Filter Type: BC	
	Type	Data	
	B/C		
fty	Sum of Defective Qty(Pair)	Sum of Working hours	Sum of Ttl cost (\$)
JV	346.5	0	5764.71
JV2	45	0	753.49
VH	73.5	0	1264.52
VH2	12	0	232.75

Remark (Re-inspection Station)	(Multiple Items)	-Filter Type : Reinspection -Filter Remark: missing Touch-up paint	
	Type	Data	
	Reinspection		
fty	Sum of Defective Qty(Pair)	Sum of Working hours	Sum of Ttl cost (\$)
VH3	974	4.5	11.56
VH2	14359	149.8	1504.83
VH	27670	106.6	1318.64
JV3	37692	47.5	428.15
JV2	46819	487	1877.75
JV	43701	157	1551.38

A	B	Filter Type : Reinspection Filter Remark: Touch-up paint	
Remark (Re-inspection Station)	Touch-up paint		
	Type	Data	
	Reinspection		
fty	Sum of Defective Qty(Pair)	Sum of Working hours	Sum of Ttl cost (\$)
JV	7546	77	750.76
VH	6594	41	272.25
VH2	7754	136	1099.68
VH4	13584	333.8	2086.25

CoPQ type analysis (1).xlsx - Excel

Le, Thanh-Truc

FileHomeInsertPage LayoutFormulasDataReviewViewHelp

Calibri

11

A⁺

A⁻

</

TOP FACTORY BC GRADE

Remark (Re-inspection Station)	Type	Sum of Defective Qty(Pair)	Sum of Working hours	Sum of Ttl cost (\$)
VH	Factory 1	20.5	0	420.51
	Factory 3	17.5	0	347.07
	Factory 4	15	0	319.21
	Factory 2	20.5	0	177.73

PivotTable Fields

Choose fields to add to report:

Search

☐ Fty/Line

☐ Style Nbr

☐ Mold

☐ Model

☒ Defective Qty(Pair)

☐ FOB (\$)

☐ Manpower

☐ Labor cost (\$)

☒ Working hours

☐ SGS Retest Qty (Pic)

☐ SGS Test unit price/pi...

☐ SGS Retest failure C g...

☒ Ttl cost (\$)

Columns

Type

Rows

Fty

Factory

Σ Values

Sum of Defective Qty(Pair)

Sum of Working hours

Defer Layout Update

Update

Row: FTY, Factory

Filter : Remark (Re-inspection Station)

Values: Defective Qty (pair), Ttl cost.

Columns: Type

File CoPQ analysis

BC Grade	FTY	Factory	Defect Qty	Ttl cost (\$)
	VH	Factory 1	20.5	\$420.51
	VH	Factory 3	17.5	\$347.07
	VH	Factory 4	15	\$319.21
	VH	Factory 2	20.5	\$177.73

TOP FACTORY REINSPECTION

- Filter Type : Reinspection
- Filter Remark: missing Touch-up paint

Remark (Re-inspection Station)	Type	Sum of Defective Qty(Pair)	Sum of Working hours	Sum of Ttl cost (\$)
VH	Factory 1	3761	17.1	261.75
	Factory 2	388	1.9	8.8
	Factory 3	6067	28.4	361.46
	Factory 4	7073	29.6	394.36
	Factory Sandals	4524	20.6	250.35

PivotTable Fields

Choose fields to add to report:

Search

☐ Fty/Line

☐ Style Nbr

☐ Mold

☐ Model

☒ Defective Qty(Pair)

☐ FOB (\$)

☐ Manpower

☐ Labor cost (\$)

☒ Working hours

☐ SGS Retest Qty (Pic)

☐ SGS Test unit price/pi...

☐ SGS Retest failure C g...

☒ Ttl cost (\$)

Columns

Type

Rows

Fty

Factory

Σ Values

Sum of working hours

Sum of Ttl cost (\$)

Row: FTY, Factory

Filter : Remark (Re-inspection Station)

Values: Defective Qty (pair), Ttl cost.

Columns: Type

File CoPQ analysis

Re-inspect	FTY	Factory	Defective Qty(Pair)	Working hours	Ttl cost (\$)
VH	VH	Factory 4	7,073	29.6	\$394.36
VH2	VH	Factory 3	6,067	28.4	\$361.46
VH3	VH	Factory 1	3,761	17.1	\$261.75
JV	VH	Factory Sandals	4,524	20.6	\$250.35
JV2	VH	OS	5,857	9	\$41.88
JVB					

TOP FACTORY TOUCH-UP PAINT

Filter Type : Reinspection
Filter Remark: Touch-up paint

Remark (Re-inspection Station)	Touch-up paint			
fty	Factory	Sum of Defective Qty(Pair)	Sum of Working hours	Sum of Ttl cost (\$)
VH	OS	6594	41	272.25

Sort Descending

PivotTable Fields

Choose fields to add to report:

☐ Date

☐ Category

☒ Type

☒ fty

☒ Factory

☐ Fty/Line

☐ Style Nbr

☐ Mold

☐ Model

☒ Defective Qty(Pair)

☐ FOB (\$)

☐ Manpower

☐ Labor cost (\$)

☒ Working hours

Filters

Remark (Re-inspection Station)

Columns

Type

Rows

fty

Values

Sum of Defective Qty(Pair)

Sum of Working hours

Defer Layout Update

Update

File CoPQ analysis

87	Touch-up	FTY	Factory	Defective Qty(P: Working hours	Ttl cost (\$)
88	VH	VH	OS	6,594	41
89	VH2				
90	VH4				
91	JV				
92	JVB				
93					

Copy & Paste 123

Row: FTY, Factory
Filter : Remark (Re-inspection Station)
Values: Defective Qty (pair), Ttl cost.
Columns: Type

TOP 5 MODEL BC GRADE

Formula:
=TRIM(B51)

1

2

3

Sort ascending

Row: FTY, Model
Filter : Remark (Re-inspection Station)
Values: Defective Qty (pair), Ttl cost.
Columns: Type

Copy & Paste

Model	Sum of Defective Qty(Pair)	Sum of Ttl cost (\$)
JORDAN FRANCHISE SLIDE (GS)	1	7.88
JORDAN ACCESS (PS)	0.5	8.15
JORDAN COURT CONNECT LOW (GS)	0.5	8.81
WMNS CELSO GIRL THONG	1	9.08
WMNS JORDAN COURT CONNECT MID	0.5	9.59
AIR JORDAN 1 MID (GS)	0.5	9.84
AIR JORDAN 1 LOW SE (GS)	0.5	10.42
JORDAN COURT CONNECT MID	2	39.94
AIR JORDAN 1 LOW	2	40.82
JORDAN COURT CONNECT LOW	2.5	45.72
W NIKE RUN DEFY	4	57.37
AIR FORCE 1 LE (GS)	3.5	59.43
WMNS AIR JORDAN 1 LOW SE	5	105.75
NIKE SB FORCE 58	8	144.47
NIKE AIR WINFLO 12	9	222.33

4

5

6

Copy & Paste123

Copy the last 5 rows & Paste 123

model	\Defectiv...	Ttl cost (\$)
JORDAN FRANCHISE SLIDE (GS)	1	7.88
JORDAN ACCESS (PS)	0.5	8.15
JORDAN COURT CONNECT LOW (GS)	0.5	8.81
WMNS CELSO GIRL THONG	1	9.08
WMNS JORDAN COURT CONNECT MID	0.5	9.59
AIR JORDAN 1 MID (GS)	0.5	9.84
AIR JORDAN 1 LOW SE (GS)	0.5	10.42
JORDAN COURT CONNECT MID	1.5	38.61
JORDAN COURT CONNECT LOW	2	39.94
AIR JORDAN 1 LOW	2	40.82
JORDAN COURT CONNECT LOW	2.5	45.72
W NIKE RUN DEFY	4	57.37
AIR FORCE 1 LE (GS)	3.5	59.43
WMNS AIR JORDAN 1 LOW SE	5	105.75
NIKE SB FORCE 58	8	144.47
NIKE AIR WINFLO 12	9	222.33

Row: Model
Values: Defective Qty (pair), Ttl cost.

File CoPQ analysis

BC Grade	FTY	Factory	Defect Qty	Ttl cost (\$)
	VH	Factory 1	20.5	\$420.51
	VH	Factory 3	17.5	\$347.07
	VH	Factory 4	15	\$319.21
	VH	Factory 2	20.5	\$177.73

FTY	Model	Defect Qty	Ttl cost (\$)
VH	W NIKE RUN DEFY	4	\$57.37
VH	AIR FORCE 1 LE (GS)	3.5	\$59.43
VH	WMNS AIR JORDAN 1 LOW SE	5	\$105.75
VH	NIKE SB FORCE 58	8	\$144.47
VH	NIKE AIR WINFLO 12	9	\$222.33

***Note for the Top Model of B/C, Reinspection, and Touch-up Paint:**
→Copy the data from the Pivot Table and paste it into any cell.
→Insert columns and **use the TRIM formula to remove the blank space** after the model.
→Create the Pivot Table again.
→Copy the data into the COPQ Analysis file.

TOP 5 MODEL REINSPECTION

- Filter Type : Reinspection
- Filter Remark: missing Touch-up paint

Sort Descending

Row: FTY, Model
Filter : Remark (Re-inspection Station)
Values: Defective Qty (pair),Working hours, Ttl cost.
Columns: Type

File CoPQ analysis

Re-inspect	FTY	Factory	Defective Qty(Pair)	Working hours	Ttl cost (\$)
VH	VH	Factory 4	7,073	29.6	\$394.36
VH2	VH	Factory 3	6,067	28.4	\$361.46
VH3	VH	Factory 1	3,761	17.1	\$261.75
JV	VH	Factory Sandals	4,524	20.6	\$250.35
JV2	VH	OS	5,857	9	\$41.88
JVB					

Factory	FTY	Model	Defective Qty(Pair)	Working hours	Ttl cost (\$)
VH	VH	NIKE SB FORCE 58	6,699	16.3	\$165.12
VH2	VH	WMNS AIR JORDAN 1 LOW SE	1,775	7.6	\$95.15
VH3	VH	WMNS JORDAN POINTE	1,578	6.2	\$89.57
JV	VH	NIKE UPLIFT SC	1,287	6.2	\$78.40
JV2	VH	WMNS BENASSI JDI	624	6.5	\$76.78
JVB					

- *Note for the Top Model of B/C, Reinspection, and Touch-up Paint:
- Copy the data from the Pivot Table and paste it into any cell.
 - Insert columns and use the TRIM formula to remove the blank space after the model.
 - Create the Pivot Table again.
 - Copy the data into the COPQ Analysis file.

Row: Model
Values: Defective Qty (pair), Ttl cost.
Workinghours

TOP 5 MODEL TOUCH-UP PAINT

The screenshot shows an Excel spreadsheet with the following data:

Remark (Re-inspection Station)	Touch-up paint	Type	Reinspection	Sum of Defective Qty(Pair)	Sum of Working hours	Sum of Ttl cost (\$)
VH	3047	JORDAN MVP 92	6594	41	272.25	

A blue arrow points to the text "Copy & Paste" above the data row. Below the data row, the text "Combine Mold and Model: Mold (M)" is visible, followed by a blue arrow pointing to the right.

Copy & Paste

Combine Mold and Model: Mold (Model)

PivotTable Fields

Choose fields to add to report: 

Search 

☐ Fty/Line

☐ Style Nbr

☒ **Model**

☒ **Defective Qty(Pair)**

☐ FOB (\$)

☐ Manpower

☐ Labor cost (\$)

☒ **Working hours**

☐ SGS Retest Qty (Pic)

☐ SGS Test unit price/pi...

☐ SGS Retest failure C g... 

Drag fields between areas below:

Filters

Remark (Re-inspection Station) 

Columns

Type 

Rows

fty 

Values

Sum of working hours 

Sum of Ttl cost (\$) 

☐ Defer Layout Update 

Row: FTY, Mold ,Model
Filter : Remark (Re-inspection Station)
Values: Defective Qty (pair),Working hours, Ttl cost.
Columns: Type

86					
87	Touch-up	FTY	Factory	Defective Qty(P: Working hours	Ttl co
88	VH	VH	OS	6,594	41
89	VH2				
90	VH4				
91	JV				
92	JVB				
93					
94					
95	Factory	FTY	Model	Defective Qty(P: Working hours	Ttl co
96	VH	VH	3047 (JORDAN MVP 92)	6,594	41
97	VH2	VH			
98	VH4	VH			
99	JV	VH			
100	JVB	VH			
101					

Copy & Paste 123

Sort in descending order and select the top 5 models if there are many models

Continue to remove extra spaces (using TRIM) as done for BC grade and Reinspection (if any).

For JV factory, the Top Models of Touch-up Paint need to be renamed as follows:

NSW AIR MAX 98 MW → NIKE INITIATOR
DOWN SHIFTER (Xcceleration) → NIKE AIR MAX
97

TOP 3 DEFECT OF EACH TOP 3 MODEL BC GRADE

File CoPQ analysis

BC Grade	FTY	Factory	Defect Qty	Ttl cost (\$)
	VH	Factory 1	20.5	\$420.51
	VH	Factory 3	17.5	\$347.07
	VH	Factory 4	15	\$319.21
	VH	Factory 2	20.5	\$177.73
	FTY	Model	Defect Qty	Ttl cost (\$)
	VH	W NIKE RUN DEFY	4	\$57.37
	VH	AIR FORCE 1 LE (GS)	3.5	\$59.43
	VH	WMNS AIR JORDAN 1 LOW SE	5	\$105.75
	VH	NIKE SB FORCE 58	8	\$144.47
	VH	NIKE AIR WINFLO 12	9	\$222.33

NIKE AIR WINFLO 12	B/Wrinkle or Deformed Upper	7	11	63.64%	63.64%
	C/Wrinkle or Deformed Bottom	1	11	9.09%	9.09%
	C/Wrinkle or Deformed Upper	1	11	9.09%	9.09%

DATA FTT

Filter model

Date	(All)
Model 2	NIKE AIR WINFLO 12
Factory	VH

Sum of Issues Q'ty	Total
B/Wrinkle or Deformed Upper	7
C/Wrinkle or Deformed Bottom	1
C/Wrinkle or Deformed Upper	1
C/Contamination	1
C/Material damaged	1
Grand Total	11

PivotTable Fields

Choose fields to add to report:

Search

☒ Date

☐ FactoryGroup

☒ Factory

☐ Plant

☐ Line

☐ Model

☒ Model 2

☐ SO#

☐ Season

☐ Cutting Die

☐ Style Nbr

☐ Colorway Cd

Drag fields between areas below:

Filters

Factory

Columns

Rows

Defect Issues

Values

Sum of Issues Q'ty

Defer La... Update

Row: Station/ Issues
Filters: Model 2/ Factory
Values: Issues Q'ty

This result is used to create a stacked column chart of defects by model.

DR%= ISSUES QTY/TOTAL ISSUES QTY

FILE COPQ DATA

[illegible]

File CoPQ analysis

FileHomeInsertPage LayoutFormulasDataReviewViewHelp

ClipboardFontAlignmentNumberStylesCellsEditing

Calibri11A^A^BIBUFontMerge & CenterAlignmentGeneralNumberStylesCellsEditing

C79

NIKE SB FORCE 58

BC Grade	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Jan	Feb								
VH	Quantity (prs)	68.5	76.5	89.5	92	86.0	81.0	117.0	93.5	93.0	111.0	123.5	126.0	119.5	73.5							
VH2	Quantity (prs)	63	32	41.0	24	18.5	4.5	28.5	39.5	52.5	80.0	12.0	22.5	19.0	12.0							
IV	Quantity (prs)	5,958.0	7,869.5	1,566.0	1391	1,016.5	383.5	545.0	696.5	485.0	753.0	311.5	443.0	73.0	346.5							
IV2	Quantity (prs)	37.5	51.5	31.5	27.5	28.0	30.5	44.5	40.0	48.5	72.0	61.5	61.0	2.5	45.0							
Factory	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Jan	Feb								
VH	Cost (\$)	\$1,270.48	\$1,439.11	\$1,620.60	\$1,726.99	\$1,509.73	\$1,505.94	\$2,409.17	\$1,923.42	\$1,802.29	\$2,063.12	\$2,237.89	\$2,217.23	\$2,133.04	\$1,264.52							
VH2	Cost (\$)	\$1,148.79	\$618.12	\$697.67	\$462.42	\$366.17	\$87.83	\$524.07	\$736.92	\$944.33	\$1,553.89	\$219.42	\$392.82	\$229.05	\$232.75							
IV	Cost (\$)	\$115,145.92	\$150,856.80	\$29,766.09	\$26,792.18	\$19,262.79	\$6,745.05	\$9,631.16	\$12,241.64	\$7,761.64	\$12,046.90	\$5,217.26	\$7,102.09	\$14,030.31	\$5,764.71							
IV2	Cost (\$)	\$729.60	\$1,072.79	\$627.15	\$497.97	\$526.44	\$538.69	\$819.22	\$704.68	\$845.39	\$1,295.75	\$1,023.73	\$1,010.74	\$458.02	\$753.49							
Re-inspect	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Jan	Feb								
VH	Quantity (prs)	21.971	44,470	63,182	57253	42,178	142,231	41,440	49,415	52,198	46,840	65,207	74,082	41,896	27,670							
VH2	Quantity (prs)	29,127	25,164	7,004	28242	37,276	7,526	34,392	49,977	37,119	35,642	14,359	26,960	31,995	14,359							
VH3	Quantity (prs)	1,043	4,745	1,398	150	1,196	7,037	778	3,607	3,157	7,140	24,356	10,461	6,891	974							
IV	Quantity (prs)	51,379	65,277	41,551	42665	42,595	9,683	5,712	3,520	0	17,150	23,417	25,768	22,590	43,701							
IV2	Quantity (prs)	3,351	2,391	2,581	1586	3,550	2,664	3,273	4,836	2,520	5,128	35,914	54,582	48,898	46,819							
IVB	Quantity (prs)	236,662	271,646	91,041	55267	71,373	63,212	82,905	58,625	82,221	77,394	61,025	54,062	57,501	37,692							
Factory	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Jan	Feb								
VH	Cost (\$)	\$1,348.96	\$2,420.01	\$1,916.68	\$2,906.16	\$1,245.89	\$5,394.91	\$1,432.39	\$1,833.49	\$2,805.45	\$2,887.85	\$2,449.76	\$2,977.26	\$1,900.05	\$1,318.64	-\$590.8						
VH2	Cost (\$)	\$695.32	\$479.26	\$218.80	\$746.18	\$1,917.91	\$234.88	\$2,085.48	\$4,177.28	\$1,733.56	\$2,191.50	\$459.97	\$2,080.40	\$2,720.05	\$1,504.83	-\$1,215.3						
VH3	Cost (\$)	\$8.86	\$43.63	\$9.11	\$1.16	\$15.40	\$101.80	\$6.67	\$41.72	\$35.93	\$52.37	\$260.03	\$144.15	\$111.88	\$11.56	-\$101.4						
IV	Cost (\$)	\$3,974.27	\$4,386.88	\$2,862.61	\$2,901.84	\$2,708.62	\$475.86	\$199.54	\$139.66	\$0.00	\$731.17	\$1,741.67	\$1,474.86	\$96.94	\$1,551.38	\$583.9						
IV2	Cost (\$)	\$154.28	\$133.98	\$95.41	\$73.68	\$152.25	\$93.38	\$117.74	\$168.49	\$107.59	\$178.64	\$1,583.40	\$2,356.83	\$1,981.27	\$1,877.75	-\$109.6						
IVB	Cost (\$)	\$2,407.68	\$3,068.21	\$1,193.22	\$768.11	\$1,943.01	\$887.84	\$984.18	\$705.15	\$930.31	\$937.47	\$639.22	\$712.25	\$660.31	\$428.15	-\$237.3						
Touch-up	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Jan	Feb								
VH	Quantity (prs)	61,874	72,029	60,089	31627	10,675	9,329	61,381	27,967	121,780	70,237	21,407	27,362	4,898	6,594							
VH2	Quantity (prs)	139,290	87,980	120,521	114718	125,322	154,113	140,099	113,584	67,759	64,422	33,654	23,360	8,996	7,754							
VH4	Quantity (prs)	15,896	16,549	26,283	25726	25,232	20,564	23,605	25,333	21,994	31,547	29,407	33,961	31,977	13,584							
IV	Quantity (prs)	5,095	5,742	3,836	2781	1,977	3,446	8,377	4,780	6,812	13,200	8,101	8,227	5,990	7,546							
IVB	Quantity (prs)	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A							
Factory	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Jan	Feb								
VH	Cost (\$)	\$5,705.62	\$6,379.23	\$6,433.92	\$5,096.01	\$1,256.54	\$673.60	\$4,393.18	\$2,445.57	\$3,375.20	\$2,352.47	\$1,049.38	\$1,612.56	\$251.21	\$732.25	-\$1,340.3						
VH2	Cost (\$)	\$7,998.10	\$7,951.28	\$9,990.21	\$9,945.19	\$10,346.90	\$10,197.94	\$10,548.81	\$9,350.73	\$8,105.52	\$9,636.72	\$6,636.63	\$1,658.08	\$1,020.05	\$1,099.68	-\$558.4						
VH4	Cost (\$)	\$2,710.63	\$2,658.13	\$3,504.38	\$3,176.88	\$3,408.13	\$3,312.50	\$3,681.25	\$3,581.25	\$3,157.50	\$3,681.88	\$3,445.63	\$3,591.88	\$3,490.31	\$2,086.25	-\$1,505.6						
IV	Cost (\$)	\$314.73	\$604.74	\$386.58	\$257.74	\$219.20	\$349.00	\$1,091.69	\$458.61	\$551.93	\$957.79	\$748.80	\$842.13	\$531.72	\$750.76	-\$91.3						
IVB	Cost (\$)	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A						
BC Grade	FTY	FTY	Factory	Defect Qty	Ttl cost (\$)	FTY	Factory	Defect Qty	Ttl cost (\$)	FTY	Factory	Defect Qty	Ttl cost (\$)	FTY	Factory	Defect Qty	Ttl cost (\$)					
VH	VH	VH2	Factory 5	8.0	\$163.86	JV	Factory 1	180	\$3,349.49	JV2	Factory 2	17.5	\$310.65	JVB	OS	25,744	30	\$29				
VH	VH	VH2	Factory 3	2.5	\$37.83	JV	Factory 3	167	\$2,415.22	JV2	Factory 3	14.0	\$239.76	JVB	IP	11,948	17.5	\$13				
VH	VH	VH2	Factory 1	1.5	\$31.06	JV				JV2	Factory 1	13.5	\$203.08	JVB								
FTY	FTY	FTY	Model	Defect Qty	Ttl cost (\$)	FTY	Model	Defect Qty	Ttl cost (\$)	FTY	Model	Defect Qty	Ttl cost (\$)	FTY	Model	Defect Qty	Ttl cost (\$)					
VH	VH	VH2	NIKE AIR MAX EXCEE	0.5	\$11.04	JV	COURT BOROUGH LOW RECRAT (TD	30	\$299.85	JV2	WMNS NIKE INITIATOR	3.5	\$61.47	JVB	NIKE COURT BOROUGH 1	12,288	14	\$14				
VH	VH	VH2	W NIKE UPFLT SC	1.0	\$13.76	JV	NIKE EBERNON LOW	23	\$345.18	JV2	JORDAN 1 MID (PS)	4.5	\$64.70	JVB	NIKE EBERNON MW	9,094	10	\$10				
VH	VH	VH2	WMNS NIKE ZOOM SPAN 3	1.0	\$17.87	JV	NIKE DUNK LOW RETRO SE	52	\$1,071.21	JV2	NIKE DUNK LOW (GS)	4.5	\$70.11	JVB	JORDAN COURT CONNECT	5,815	8	\$8				
VH	VH	VH2	AIR FORCE 1 LE (GS)	1.5	\$25.41	JV	NIKE DUNK LOW RETRO	63	\$1,107.19	JV2	AIR JORDAN 1 MID SE BG	3.0	\$71.28	JVB	DOWN SHIFTER (Kocoforat	4,638	7.5	\$7.5				
VH	VH	VH2	NIKE AIR WINFLO 12	5.5	\$129.56	JV	WMNS NIKE INITIATOR	65	\$1,138.40	JV2	WMNS NIKE DUNK LOW	5.5	\$100.57	JVB	JORDAN COURT CONNECT	1,495	2	\$2				
Re-inspect	FTY	FTY	Factory	Defective Q	Working hou	Ttl cost (\$)	FTY	Factory	Defective Q	Working hou	Ttl cost (\$)	FTY	Factory	Defective Qty	Workin	Ttl cost (\$)	FTY	Factory	Defective Qty	(Pair	Workin	Ttl cost (\$)
VH	VH	VH2	Factory 1	9,026	96	\$1,041.17	JV	Factory 3	33,182	120.9	\$1,253.47	JV2	Factory 2	20,429	201	\$816.06	JVB	OS	25,744	30	\$29	
VH2	VH	VH2	Factory 3	3,136	40	\$393.74	JV	Factory 1	10,519	36.1	\$297.91	JV2	Factory 3	14,634	174	\$611.03	JVB	IP	11,948	17.5	\$13	
VH3	VH	VH2	Factory 5	2,197	13.8	\$69.92	JV					JV2	Factory 1	11,756	112	\$450.66	JVB					
IV	VH	VH2					JV					JV2					JVB					
IV2	VH	VH2					JV					JV2					JVB					
IVB	VH	VH2					JV					JV2					JVB					
Factory	FTY	FTY	Model	Defective Q	Working hou	Ttl cost (\$)	FTY	Model	Defective Q	Working hou	Ttl cost (\$)	FTY	Model	Defective Qty	Workin	Ttl cost (\$)	FTY	Model	Defective Qty	(Pair	Workin	Ttl cost (\$)
VH	VH	VH2	W AIR MAX BIA SE	3,973	31.5	\$516.77	JV	NIKE COURT VISION LO FL	7,348	22.4	\$333.28	JV2	NIKE DUNK LOW (GS)	6,314	54	\$217.21	JVB	NIKE COURT BOROUGH 1	12,288	14	\$14	
VH2	VH	VH2	NIKE ZOOM SPAN 3	2,154	36	\$305.47	JV	NIKE EBERNON LOW	6,120	22.5	\$262.78	JV2	JORDAN 1 MID (PS)	4,573	53	\$894.73	JVB	NIKE EBERNON MW	9,094	10	\$10	
VH3	VH	VH2	NIKE RUN DEFY	706	11	\$160.38	JV	W NIKE DUNK LOW	8,751	27	\$241.49	JV2	W NIKE DUNK LOW	3,471	38	\$154.28	JVB	JORDAN COURT CONNECT	5,815	8	\$8	
IV	VH	VH2	NIKE AIR MAX EXCEE	1,114	12	\$120.51	JV	W LO-1000 SE	6,177	11	\$174.51	JV2	WMNS NIKE DUNK LOW	3,521	37	\$150.22	JVB	DOWN SHIFTER (Kocoforat	4,638	7.5	\$7.5	
IV2	VH	VH2	AIR MAX SYSTEM (PS) - DQ0285	632	9.5	\$109.46	JV	NIKE COURT VISION LO	5,244	12.5	\$136.97	JV2	WMNS NIKE INITIATOR	3,562	38	\$140.07	JVB	JORDAN COURT CONNECT	1,495	2	\$2	
Touch-up	FTY	FTY	Factory	Defective Q	Working hou	Ttl cost (\$)	FTY	Factory	Defective Q	Working hou	Ttl cost (\$)	FTY	Factory	Defective Qty	Workin	Ttl cost (\$)	FTY	Factory	Defective Qty	(Pair	Workin	Ttl cost (\$)
VH	VH	VH2	OS	7,754	136	\$1,099.68	JV	StockMistg	7,546	77	\$750.76	JV2					JVB					
VH2	VH	VH2					JV					JV2					JVB					
VH4	VH	VH2					JV					JV2					JVB					

THANK YOU