



Clearance Check	False error : 0000	( ) q	JOB NAME	IST8310_DEMOBOARD	
Connectivity Check	False error: 0000	Gao—Fu Technology Corp. http://www.gaofu.com.tw	LAYER	ARTWORM THE STATE OF THE STATE	
Plane Check	False error: 0000	886-3-6682475	DATE	2016.01.21 4 LAYER-A4	



Clearance Check	False error : 0000	( ) q	JOB NAME	IST8310_DEMOBOARD	
Connectivity Check	False error: 0000	Gao—Fu Technology Corp. http://www.gaofu.com.tw	LAYER	SILARORORIN-TOP	
Plane Check	False error: 0000	886–3–6682475	DATE	2016.01.21 4 LAYER-A4	



Clearance Check	False error: 0000	( ) q	JOB NAME	IST8310_DEMOBOARD	
Connectivity Check	False error: 0000	Gao—Fu Technology Corp. http://www.gaofu.com.tw	LAYER		
Plane Check	False error: 0000	Evonne 886-3-6682475	DATE	2016.01.21 4 LAYER-A4	

Comment	Description	Designator	Footprint	LibRef	Quantity
0.1uF/0603/X5R		C1, C2	C0603	CAP NP	2
4.7uF/ 0603/ X5R		C3	C0603	CAP NP	1
0.22uF/ 0603/ X5R		C4	C0603	CAP NP	1
3.3K		R1, R2	R0603	R	2
3.3K/ 0402		R3, R4, R5, R6	R0402	R	4
NC-1X5PIN		T1, T2	HD1X5/P2.54	8X2PIN_1, 8X2PIN_6	2
IST8308		U1	LGA-10	IST8301_5	1