3GPP TS 38.133 V17.3.0 (2021-09)

Technical Specification

3rd Generation Partnership Project; Technical Specification Group Radio Access Network; NR;

Requirements for support of radio resource management (Release 17)





A GLOBAL INITIATIVE

The present document has been developed within the 3rd Generation Partnership Project (3GPP TM) and may be further elaborated for the purposes of 3GPP. The present document has not been subject to any approval process by the 3GPP Organizational Partners and shall not be implemented. This Specification is provided for future development work within 3GPP only. The Organizational Partners accept no liability for any use of this Specification. Specifications and Reports for implementation of the 3GPP TM system should be obtained via the 3GPP Organizational Partners' Publications Offices.

3GPP

Postal address

3GPP support office address

650 Route des Lucioles - Sophia Antipolis Valbonne - FRANCE Tel.: +33 4 92 94 42 00 Fax: +33 4 93 65 47 16

Internet

http://www.3gpp.org

Copyright Notification

No part may be reproduced except as authorized by written permission. The copyright and the foregoing restriction extend to reproduction in all media.

© 2021, 3GPP Organizational Partners (ARIB, ATIS, CCSA, ETSI, TSDSI, TTA, TTC). All rights reserved.

UMTSTM is a Trade Mark of ETSI registered for the benefit of its members 3GPPTM is a Trade Mark of ETSI registered for the benefit of its Members and of the 3GPP Organizational Partners LTETM is a Trade Mark of ETSI registered for the benefit of its Members and of the 3GPP Organizational Partners GSM® and the GSM logo are registered and owned by the GSM Association

Contents

Forew	ord	42
1	Scope	44
2	References	44
3	Definitions, symbols and abbreviations	45
3.1	Definitions	
3.2	Symbols	46
3.3	Abbreviations	47
3.4	Test tolerances	
3.5	Frequency bands grouping	50
3.5.1	Introduction	
3.5.2	NR operating bands in FR1	
3.5.3	NR operating bands in FR2	
3.6	Applicability of requirements in this specification version	
3.6.1	RRC connected state requirements in DRX	
3.6.2	Number of serving carriers	
3.6.2.1	σ	
3.6.2.2		
3.6.2.3		
3.6.2.4	ϵ	
3.6.3	Applicability for intra-band FR2	
3.6.4	Applicability for FR2 UE power classes	
3.6.5	Applicability for SDL bands	
3.6.6	Applicability of requirements for NGEN-DC operation	
3.6.7	Applicability of QCL	
3.6.9	Applicability of requirements for scheduling availability	53
3.6.10	Applicability of requirements for measurement restrictions	33
4	SA: RRC_IDLE state mobility	55
4.1	Cell Selection	
4.2	Cell Re-selection	
4.2.1	Introduction	
4.2.2	Requirements	
4.2.2.1	5 —	
4.2.2.2	ϵ	
4.2.2.3	1 2	
4.2.2.4		
4.2.2.5		
4.2.2.6		
4.2.2.7		
4.2.2.8		63
4.2.2.9	1 0	
	criterion	
4.2.2.9		
4.2.2.9	ϵ	
4.2.2.9		
4.2.2.9		65
4.2.2.1		
4221	criterion	
4.2.2.1		
4.2.2.1	θ	
4.2.2.1	e e	
4.2.2.1		67
4.2.2.1	e	2 0
1221	criterion	
4.2.2.1 4.2.2.1		
4.2.2.1	1.2 Measurements for UE fulfilling low mobility criterion	08

4.2.2.11.3	\mathcal{E}	
4.2.2.11.4	5 · · · · · · · · · · · · · · · · · · ·	
4.2A	Cell Re-selection when subject to CCA	
4.2A.1	Introduction	
4.2A.2	Requirements	
4.2A.2.1	UE measurement capability	
4.2A.2.2	Measurement and evaluation when subject to CCA on the serving cell	/ 1
4.2A.2.3	Measurements of intra-frequency NR cells when subject to CCA on the serving cell and target	70
4.2A.2.4	cell	
4.2A.2.4 4.2A.2.5	Measurements of inter-RAT E-UTRAN cells when subject to CCA on the serving cell	
4.2A.2.5 4.2A.2.6	Maximum interruption in paging reception when subject to CCA on the target cell	
4.2A.2.7	General requirements.	
4.3	Minimization of Drive Tests (MDT)	
4.3.1	Introduction	
4.3.2	Measurement Requirements	
4.3.3	Requirements for Relative Time Stamp Accuracy	
4.3.4	Requirements for Relative Time Stamp Accuracy for RRC Connection Establishment Failure Log	
	Reporting	77
4.3.5	Requirements for Relative Time Stamp Accuracy for Radio Link Failure and Handover Failure Log	
	Reporting	77
4.4	Idle Mode CA/DC Measurements	
4.4.1	Introduction	
4.4.2	Measurement Requirements	
4.4.2.1	Detected cell requirement during state transition and Idle mode	
4.4.2.2	Measurements of inter-frequency CA/DC candidate cells	
4.4.2.3	Measurements on serving cell	
4.4.2.4	Measurements of E-UTRAN inter-RAT DC candidate cells	79
5 SA	A: RRC_INACTIVE state mobility	81
5.1	Cell Re-selection	
5.1.1	Introduction	81
5.1.2	Requirements	81
5.1.2.1	UE measurement capability	
5.1.2.2	Measurement and evaluation of serving cell	
5.1.2.3	Measurements of intra-frequency NR cells	
5.1.2.4	Measurements of inter-frequency NR cells	
5.1.2.5	Measurements of inter-RAT E-UTRAN cells	
5.1.2.6	Maximum interruption in paging reception	
5.1.2.7	General requirements.	
5.1A	Cell Re-selection with CCA	
5.1A.1	Introduction	
5.1A.2 5.1A.2.1	UE measurement capability	
5.1A.2.1 5.1A.2.2	Measurement and evaluation when CCA is used on the serving cell	
5.1A.2.2 5.1A.2.3	Measurements of intra-frequency NR cells when CCA is used on the serving cell and target cell	
5.1A.2.4	Measurements of inter-frequency NR cells when CCA is used on the target cell	
5.1A.2.5	Measurements of inter-RAT E-UTRAN cells when CCA is used on the serving cell	
5.1A.2.6	Maximum interruption in paging reception when CCA is used on the target cell	
5.1A.2.7	General requirements.	
5.2	Void	
5.3	Minimization of Drive Tests (MDT)	82
5.3.1	Introduction	82
5.3.2	Measurement Requirements	83
5.3.3	Requirements for Relative Time Stamp Accuracy	83
5.3.4	Requirements for Relative Time Stamp Accuracy for RRC Connection Establishment Failure Log	
	Reporting	83
5.3.5	Requirements for Relative Time Stamp Accuracy for Radio Link Failure and Handover Failure Log	
	Reporting	
5.3.6	Requirements for Relative Time Stamp Accuracy for RRC Resume Failure Log Reporting	
5.4 5.4.1	Idle Mode CA/DC Measurements	83
3 /I I	ITHT/VHVTION	

5.4.2	Measurement Requirements	
5.4.2.1	Detected cell requirement during state transition and Idle mode	
5.4.2.2	Measurements of inter-frequency CA/DC candidate cells	84
5.4.2.3	Measurements on serving cell	84
5.4.2.4	Measurements on E-UTRAN inter-RAT DC candidate cells	84
с г	DDC CONNECTED state mobility	0.4
	RRC_CONNECTED state mobility	
6.1	Handover	
6.1.1	NR Handover	
6.1.1.1	Introduction	
6.1.1.2	NR FR1 - NR FR1 Handover	
6.1.1.2.1		
6.1.1.2.2	1	
6.1.1.3	NR FR2- NR FR1 Handover	
6.1.1.3.1		
6.1.1.3.2	1	
6.1.1.4	NR FR2- NR FR2 Handover	
6.1.1.4.1	y	
6.1.1.4.2	1	
6.1.1.5	NR FR1- NR FR2 Handover	
6.1.1.5.1	· · · · · · · · · · · · · · · · · · ·	
6.1.1.5.2	T	
6.1.2	NR Handover to other RATs	
6.1.2.1	NR – E-UTRAN Handover	
6.1.2.1.1		88
6.1.2.1.2	2 Handover delay	88
6.1.2.1.3	3 Interruption time	88
6.1.2.2	NR – UTRAN Handover	89
6.1.2.2.1		
6.1.2.2.2	2 Handover delay	89
6.1.2.2.3	3 Interruption time	89
6.1.3	NR DAPS Handover	90
6.1.3.1	Introduction	
6.1.3.2	NR FR1 - NR FR1 DAPS Handover	90
6.1.3.2.1	1 DAPS handover delay	90
6.1.3.2.2	2 Interruption time	91
6.1.3.3	NR FR2- NR FR1 DAPS Handover	93
6.1.3.3.1	1 DAPS handover delay	93
6.1.3.3.2	2 Interruption time	93
6.1.3.4	NR FR1- NR FR2 DAPS Handover	94
6.1.3.4.1	DAPS handover delay	94
6.1.3.4.2	2 Interruption time	94
6.1.4	NR Conditional Handover	95
6.1.4.1	Introduction	95
6.1.4.2	NR FR1 – NR FR1 conditional handover	95
6.1.4.3	NR FR2 – NR FR1 conditional handover	96
6.1.4.4	NR FR2 – NR FR2 conditional handover	97
6.1.4.4.1		
6.1.4.4.2		
6.1.4.4.3		
6.1.4.4.4		
6.1.4.5	NR FR1 – NR FR2 conditional handover	
6.1A	Void	
6.1A.1	Void	
6.1A.1.1		
6.1A.1.2		
6.1A.1.2		
6.1A.1.2		
6.1B	Handover to target cell using CCA	
6.1B.1	NR Handover	
6.1B.1.1		
6.1B.1.1		90

6.1B.1.2.1		
6.1B.1.2.2	r	
6.2	RRC Connection Mobility Control	
6.2.1	SA: RRC Re-establishment	
6.2.1.1	Introduction	
6.2.1.2	Requirements	
6.2.1.2.1	UE Re-establishment delay requirement	
6.2.1A	RRC Re-establishment with CCA	101
6.2.1A.1	Introduction	101
6.2.1A.2	Requirements	102
6.2.1A.2.1	UE Re-establishment with CCA delay requirement	102
6.2.2	Random access	
6.2.2.1	Introduction.	
6.2.2.2	Requirements for 4-step RA type	
6.2.2.2.1	Contention based random access	
6.2.2.2.2	Non-Contention based random access	
6.2.2.2.3	UE behaviour when configured with supplementary UL	
6.2.2.3	Requirements for 2-step RA type	
6.2.2.3.1	Contention based random access	
6.2.2.3.2	Non-Contention based random access	
6.2.2.3.3	UE behaviour when configured with supplementary UL	
6.2.2A	Random access when CCA is used on target frequency	
6.2.2A.1	Introduction.	
6.2.2A.2	Requirements for 4-step RA type	
6.2.2A.2.1	• • •	
6.2.2A.2.2		
6.2.2A.3	Requirements for 2-step RA type	
6.2.2A.3.1	e te	
6.2.2A.3.1		
6.2.3	SA: RRC Connection Release with Redirection	
6.2.3.1	Introduction.	
6.2.3.1	Requirements	
6.2.3.2.1	RRC connection release with redirection to NR	
6.2.3.2.1	RRC connection release with redirection to F-UTRAN	
6.2.3.2.2	RRC connection release with redirection to E-OTRAN	
0.2.3.2.3	RRC connection release with redirection to NR carrier subject to CCA	114
7 Tir	ning	115
7.1	UE transmit timing	
7.1.1	Introduction	
7.1.2	Requirements	
7.1.2.1	Gradual timing adjustment	117
7.1.2.2	Void	
7.2	UE timer accuracy	
7.2.1	Introduction	
7.2.2	Requirements	
7.2.2	Timing advance	
7.3.1	Introduction	
7.3.1	Requirements	
7.3.2.1	Timing Advance adjustment delay	
7.3.2.1	Timing Advance adjustment accuracy	
	Cell phase synchronization accuracy	
7.4.1	Definition	
7.4.1	Minimum requirements.	
	Maximum Transmission Timing Difference	
7.5 7.5.1	<u>C</u>	
	Introduction	
7.5.2		
7.5.2.1	Minimum Requirements for inter-band synchronous EN-DC	
7.5.3	Minimum Requirements for intra-band EN-DC	
7.5.4	Minimum Requirements for NR Carrier Aggregation	
7.5.5	Minimum Requirements for inter-band NE-DC	
7.5.5.1	Minimum Requirements for inter-band synchronous NE-DC	
7.5.6	Minimum Requirements for inter-band NR DC	121

7.6	Maximum Receive Timing Difference	
7.6.1	Introduction	
7.6.2	Minimum Requirements for inter-band EN-DC	122
7.6.2.1	Minimum Requirements for inter-band synchronous EN-DC	122
7.6.3	Minimum Requirements for intra-band EN-DC	123
7.6.4	Minimum Requirements for NR Carrier Aggregation	
7.6.5	Minimum Requirements for inter-band NE-DC	
7.6.5.1	Minimum Requirements for inter-band synchronous NE-DC	
7.6.6	Minimum Requirements for inter-band NR DC	
7.7	deriveSSB-IndexFromCell tolerance	
7.7.1	Minimum requirements	
7.8	Void	126
0 0:		126
,	gnalling characteristics	
8.1	Radio Link Monitoring	
8.1.1	Introduction	
8.1.2	Requirements for SSB based radio link monitoring	127
8.1.2.1	Introduction	127
8.1.2.2	Minimum requirement	
8.1.2.3	Measurement restrictions for SSB based RLM	
8.1.3	Requirements for CSI-RS based radio link monitoring.	
8.1.3.1	Introduction	
8.1.3.2	Minimum requirement	
8.1.3.3	Measurement restrictions for CSI-RS based RLM	
8.1.4	Minimum requirement at transitions.	133
8.1.5	Minimum requirement for UE turning off the transmitter	134
8.1.6	Minimum requirement for L1 indication	
8.1.7	Scheduling availability of UE during radio link monitoring	
8.1.7.1	Scheduling availability of UE performing radio link monitoring with a same subcarrier spacing	
0.1.7.1	as PDSCH/PDCCH on FR1	13/
0173		134
8.1.7.2	Scheduling availability of UE performing radio link monitoring with a different subcarrier	101
	spacing than PDSCH/PDCCH on FR1	
8.1.7.3	Scheduling availability of UE performing radio link monitoring on FR2	135
8.1.7.4	Scheduling availability of UE performing radio link monitoring on FR1 or FR2 in case of FR1-	
	FR2 inter-band CA and NR-DC	135
8.1A	Radio Link Monitoring with CCA on Target Frequency	135
8.1A.1	Introduction	
8.1A.2	Requirements for SSB Based Radio Link Monitoring	
8.1A.2.1	Introduction.	
8.1A.2.2	Minimum Requirement.	
	1	
8.1A.3	Minimum requirement at transitions	
8.1A.4	Minimum requirement for UE turning off the transmitter	
8.1A.5	Minimum requirement for L1 indication	
8.1A.6	Scheduling availability of UE during radio link monitoring	139
8.1A.6.1	Scheduling availability of UE performing radio link monitoring with the same subcarrier spacing	
	as PDSCH/PDCCH	139
8.1A.6.2	Scheduling availability of UE performing radio link monitoring with a different subcarrier	
	spacing than PDSCH/PDCCH	139
8.2	Interruption	
	EN-DC Interruption	
8.2.1	1	
8.2.1.1	Introduction	
8.2.1.2	Requirements	
8.2.1.2.1	Interruptions at transitions between active and non-active during DRX	
8.2.1.2.2	Interruptions at transitions from non-DRX to DRX	140
8.2.1.2.3	Interruptions at SCell addition/release	
8.2.1.2.4	Interruptions at SCell activation/deactivation	
8.2.1.2.5	Interruptions during measurements on SCC	
8.2.1.2.6	Interruptions at UL carrier RRC reconfiguration	
8.2.1.2.7	Interruptions due to Active BWP switching Requirement	
8.2.1.2.8	Interruptions at direct SCell activation and hibernation	
8.2.1.2.9	Interruptions at SCell hibernation	
8.2.1.2.10	Interruptions at SCell activation/deactivation with multiple downlink SCells	146

8.2.1.2.11	Interruptions due to UE-specific CBW change	
8.2.1.2.12	Interruptions at NR SRS carrier based switching	
8.2.1.2.13	Interruptions at E-UTRA SRS carrier based switching	148
8.2.1.2.14	DL Interruptions at switching between two uplink carriers	149
8.2.1.2.15	Interruptions due to SCell dormancy	150
8.2.1.2.16	Interruptions when identifying CGI of an NR cell with autonomous gaps	150
8.2.1.2.17	Interruptions when identifying CGI of an E-UTRA cell with autonomous gaps	151
8.2.2	SA: Interruptions with Standalone NR Carrier Aggregation	
8.2.2.1	Introduction	
8.2.2.2	Requirements	
8.2.2.2.1	Interruptions at SCell addition/release	
8.2.2.2.2	Interruptions at SCell activation/deactivation	
8.2.2.2.3	Interruptions during measurements on deactivated SCC	
8.2.2.2.4	Interruptions at UL carrier RRC reconfiguration	
8.2.2.2.5	Interruptions due to Active BWP switching Requirement	
8.2.2.2.6	Interruptions at inter-frequency SFTD measurement	
8.2.2.2.7	Interruptions at SCell activation/deactivation with multiple downlink SCells	
8.2.2.2.8	Interruptions due to UE-specific CBW change	
8.2.2.2.9	Interruptions at NR SRS carrier based switching.	
8.2.2.2.10	DL Interruptions at UE switching between two uplink carriers	
8.2.2.2.11	Interruptions at direct SCell activation	
8.2.2.2.11		
8.2.2.2.13	Interruptions due to SCell dormancy	
	Interruptions at transitions between active and non-active during DRX	
8.2.2.2.14	Interruptions when identifying CGI of an NR cell with autonomous gaps	
8.2.2.2.15	Interruptions when identifying CGI of an E-UTRA cell with autonomous gaps	
8.2.3	NE-DC Interruptions	
8.2.3.1	Introduction	
8.2.3.2	Requirements	
8.2.3.2.1	Interruptions at transitions between active and non-active during DRX	
8.2.3.2.2	Interruptions at transitions from non-DRX to DRX	
8.2.3.2.3	Interruptions at PSCell/SCell addition/release	
8.2.3.2.4	Interruptions at SCell activation/deactivation	
8.2.3.2.5	Interruptions during measurements on SCC	
8.2.3.2.6	Interruptions at UL carrier RRC reconfiguration	
8.2.3.2.7	Interruptions due to Active BWP switching Requirement	
8.2.3.2.8	Interruptions at direct SCell activation and hibernation	
8.2.3.2.9	Interruptions at SCell hibernation	
8.2.3.2.10	Interruptions at SCell activation/deactivation with multiple downlink SCells	
8.2.3.2.11	Interruptions at NR SRS carrier based switching	168
8.2.3.2.12	Interruptions at E-UTRA SRS carrier based switching	169
8.2.3.2.13	Interruptions due to SCell dormancy	
8.2.3.2.14	Interruptions when identifying CGI of an NR cell with autonomous gaps	
8.2.3.2.15	Interruptions when identifying CGI of an E-UTRA cell with autonomous gaps	171
8.2.4	NR-DC: Interruptions	
8.2.4.1	Introduction	172
8.2.4.2	Requirements	172
8.2.4.2.1	Interruptions at PSCell/SCell addition/release	172
8.2.4.2.2	Interruptions at SCell activation/deactivation	173
8.2.4.2.3	Interruptions during measurements on SCC	
8.2.4.2.4	Interruptions at UL carrier RRC reconfiguration	174
8.2.4.2.5	Interruptions due to Active BWP switching Requirement	
8.2.4.2.6	Interruptions at transitions between active and non-active during DRX	
8.2.4.2.7	Interruptions at transitions from non-DRX to DRX	
8.2.4.2.8	Interruptions at SCell activation/deactivation with multiple downlink SCells	
8.2.4.2.9	Interruptions at NR SRS carrier based switching	
8.2.4.2.10	Interruptions at direct SCell activation	177
8.2.4.2.11	Interruptions when identifying CGI of an NR cell with autonomous gaps	
8.2.4.2.12	Interruptions when identifying CGI of an E-UTRA cell with autonomous gaps	
8.2.4.2.13	Interruptions due to SCell dormancy	
8.2.4.2A	Void	
8.2.4.2A.1	Void	
8.2.4.2A.1	Void	

8.2.4.2A.:	3 Void	.179
8.3	SCell Activation and Deactivation Delay	.179
8.3.1	Introduction	.179
8.3.2	SCell Activation Delay Requirement for Deactivated SCell	
8.3.3	SCell Deactivation Delay Requirement for Activated SCell	
8.3.4	Direct SCell Activation at SCell addition	
8.3.5	Direct SCell Activation at Handover	
8.3.7	SCell Activation Delay Requirement for Deactivated SCell with Multiple Downlink SCells	
8.3.8		
	SCell Deactivation Delay Requirement for Activated SCell with Multiple Downlink SCells	
8.3.9	Direct SCell Activation of Multiple Downlink SCells at SCell addition	
8.3.10	Direct SCell Activation of Multiple Downlink SCells at Handover	
8.3A	SCell Activation and Deactivation Delay in Carriers with CCA	
8.3A.1	Introduction	
8.3A.2	SCell Activation Delay Requirement for Deactivated SCell	
8.3A.3	SCell Deactivation Delay Requirement for Activated SCell	
8.4	UE UL carrier RRC reconfiguration delay	. 197
8.4.1	Introduction	. 197
8.4.2	UE UL carrier configuration delay requirement	. 197
8.4.3	UE UL carrier deconfiguration delay requirement	
8.5	Link Recovery Procedures.	. 197
8.5.1	Introduction	
8.5.2	Requirements for SSB based beam failure detection	
8.5.2.1	Introduction	
8.5.2.2	Minimum requirement	
8.5.2.3	Measurement restriction for SSB based beam failure detection	
8.5.3 8.5.3	Requirements for CSI-RS based beam failure detection	
	<u>*</u>	
8.5.3.1	Introduction	
8.5.3.2	Minimum requirement	
8.5.3.3	Measurement restrictions for CSI-RS beam failure detection	
8.5.4	Minimum requirement for L1 indication	
8.5.5	Requirements for SSB based candidate beam detection	
8.5.5.1	Introduction	
8.5.5.2	Minimum requirement	
8.5.5.3	Measurement restriction for SSB based candidate beam detection	
8.5.6	Requirements for CSI-RS based candidate beam detection	
8.5.6.1	Introduction	.207
8.5.6.2	Minimum requirement	.207
8.5.6.3	Measurement restriction for CSI-RS based candidate beam detection	.209
8.5.7	Scheduling availability of UE during beam failure detection	.210
8.5.7.1	Scheduling availability of UE performing beam failure detection with a same subcarrier spacing as PDSCH/PDCCH on FR1	
8.5.7.2	Scheduling availability of UE performing beam failure detection with a different subcarrier	
	spacing than PDSCH/PDCCH on FR1	.210
8.5.7.3	Scheduling availability of UE performing beam failure detection on FR2	
8.5.7.4	Scheduling availability of UE performing beam failure detection on FR1 or FR2 in case of FR1-	
0.0.7.1	FR2 inter-band CA and NR DC	211
8.5.8	Scheduling availability of UE during candidate beam detection	
8.5.8.1	Scheduling availability of UE performing L1-RSRP measurement with a same subcarrier spacing	. 211
0.5.0.1	as PDSCH/PDCCH on FR1	211
8.5.8.2	Scheduling availability of UE performing L1-RSRP measurement with a different subcarrier	. 411
0.3.6.2		211
0.5.0.2	spacing than PDSCH/PDCCH on FR1	
8.5.8.3	Scheduling availability of UE performing L1-RSRP measurement on FR2	.212
8.5.8.4	Scheduling availability of UE performing L1-RSRP measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA and NR-DC	
8.5.9	Requirements for Beam Failure Recovery in SCell	
8.5.9.1	Introduction	.212
8.5.9.2	Requirement	.213
8.5.10	Minimum requirement at transitions for beam failure detection	.213
8.5A	Link Recovery Procedures when CCA is used on target frequency	.213
8.5A.1	Introduction	
8.5A.2	Requirements for SSB based beam failure detection	
8.5A.2.1	Introduction	

8.5A.2.2	Minimum requirement	21	4
8.5A.2.3	Measurement restriction for SSB based beam failure detection	21	15
8.5A.4	Minimum requirement for L1 indication	21	15
8.5A.5	Requirements for SSB based candidate beam detection	21	15
8.5A.5.1	Introduction		
8.5A.5.2	Minimum requirement		
8.5A.5.3	Measurement restriction for SSB based candidate beam detection	21	16
8.5A.7	Scheduling availability of UE during beam failure detection		
8.5A.7.1	Scheduling availability of UE performing beam failure detection with a same subcarrier spacing		
0.011.771	as PDSCH/PDCCH	21	17
8.5A.7.2	Scheduling availability of UE performing beam failure detection with a different subcarrier		•
0.011.7.2	spacing than PDSCH/PDCCH	2.1	17
8.5A.8	Scheduling availability of UE during candidate beam detection		
8.5A.8.1	Scheduling availability of UE performing L1-RSRP measurement with a same subcarrier spacing		. ,
0.011.0.1	as PDSCH/PDCCH		17
8.5A.8.2	Scheduling availability of UE performing L1-RSRP measurement with a different subcarrier		. ,
0.371.0.2	spacing than PDSCH/PDCCH	21	17
8.6	Active BWP switch delay		
8.6.1	Introduction		
8.6.2	DCI and timer based BWP switch delay on a single CC		
8.6.2A	DCI based BWP switch delay on multiple CCs.		
8.6.2A.1	Simultaneous DCI based BWP switch delay on multiple CCs		
8.6.2A.2	Non-simultaneous DCI based BWP switch delay on multiple CCs		
8.6.2B	Timer based BWP switch delay on multiple CCs		
8.6.2B.1	Simultaneous timer based BWP switch delay on multiple CCs		
8.6.2B.2	Non-simultaneous timer based BWP switch delay on multiple CCs		
8.6.3			
	RRC based BWP switch delay on a single CC		
8.6.3A 8.6.3A.1	RRC based BWP switch delay on multiple CCs		
	Simultaneous RRC based BWP switch delay on multiple CCs		
8.6.3A.2	Non-simultaneous RRC based BWP switch delay on multiple CCs		
8.6.4	BWP switch delay on Consistent UL CCA recovery		
8.7	Void		
8.8	NE-DC: E-UTRAN PSCell Addition and Release Delay		
8.8.1	Introduction		
8.8.2	E-UTRAN PSCell Addition Delay Requirement		
8.8.3	E-UTRAN PSCell Release Delay Requirement		
8.9	NR-DC: PSCell Addition and Release Delay		
8.9.1	Introduction		
8.9.2	PSCell Addition Delay Requirement		
8.9.3	PSCell Release Delay Requirement		
8.10	Active TCI state switching delay		
8.10.4	DCI based TCI state switch delay		
8.10.5	RRC based TCI state switch delay		
8.10.6	Active TCI state list update delay		
8.10A	Active TCI state switching delay with CCA		
8.10A.1	Introduction		
8.10A.2	Known conditions for TCI state		
8.10A.3	MAC-CE based TCI state switch delay		
8.10A.4	DCI based TCI state switch delay		
8.10A.5	RRC based TCI state switch delay		
8.10A.6	Active TCI state list update delay		
8.11	PSCell Change		
8.11A	void		
8.11B	Conditional PSCell Change		
8.11B.1	Introduction		
8.11B.2	Conditoinal PSCell Change delay	23	30
8.11B.2.1	Measurement time		
8.12	Uplink spatial relation switch delay	23	31
8.12.1	Introduction		
8.12.2	Known conditions for spatial relation when associated with DL-RS		
8.12.3	MAC-CE based spatial relation switch delay		
8.12.4	DCI based spatial relation switch delay	23	33

8.12.5	RRC based spatial relation switch delay	233
8.13	UE-specific CBW change	233
8.13.1	Introduction	233
8.13.2	UE-specific CBW change delay	233
8.14	Pathloss reference signal switching delay	233
8.14.1	Introduction	233
8.14.2	Known conditions for pathloss reference signal	234
8.14.3	MAC-CE based pathloss reference signal switch delay	234
0	Massaurant Dussa dans	224
	Measurement Procedure	
9.1 9.1.1	General measurement requirement.	
	Introduction	
9.1.2	Measurement gap	
9.1.2.1 9.1.2.1a	EN-DC: Measurement Gap Sharing	
9.1.2.1		
9.1.2.10		
9.1.2.10	UE Measurement capability	
9.1.3 9.1.3.1	EN-DC: Monitoring of multiple layers using gaps	
9.1.3.1		
9.1.3.1		
9.1.3.1		
9.1.3.10		
9.1.3.2		
9.1.3.2	· · · · · · · · · · · · · · · · · · ·	
9.1.3.2	· · · · · · · · · · · · · · · · · · ·	
9.1.3.2. 9.1A.3.		
9.1.3A	UE Measurement capability under operation mode with CCA	
9.1.3A		
9.1.3A		
9.1.3A.		
9.1A.3.	· · · · · · · · · · · · · · · · · · ·	
9.1.3A.		
9.1.4	Capabilities for Support of Event Triggering and Reporting Criteria	
9.1.4.1	Introduction	
9.1.4.2	Requirements	
9.1.5	Carrier-specific scaling factor	
9.1.5.1	Monitoring of multiple layers outside gaps	
9.1.5.1.	1 EN-DC mode: carrier-specific scaling factor for SSB-based, CSI-RS based L3 measurements	
	and RSSI and channel occupancy measurements performed outside gaps	261
9.1.5.1.	2 SA mode: carrier-specific scaling factor for SSB-based, CSI-RS based L3 measurements and	
	RSSI and channel occupancy measurements performed outside gaps	262
9.1.5.1.	NR-DC mode: carrier-specific scaling factor for SSB-based and CSI-RS based L3	
	measurements performed outside gaps	263
9.1.5.1.		
	performed outside gaps	
9.1.5.2	Monitoring of multiple layers within gaps	265
9.1.5.2.		
	RSSI and channel occupancy measurements performed within gaps	266
9.1.5.2.		
	and channel occupancy measurements performed within gaps	268
9.1.5.2.		
	performed within gaps	269
9.1.5.2.		
0155	performed within gaps	
9.1.5.2.		
9.1.5.2.		
9.1.5.2.		
9.1.6	Minimum requirement at transitions.	
9.2	NR intra-frequency measurements.	
9.2.1	Introduction	214 274
7 /. /.	INVALUE CHICKER ADDITION TO THE CONTRACT OF TH	7.14

9.2.3	Number of cells and number of SSB	
9.2.3.1	Requirements for FR1	
9.2.3.2	Requirements for FR2	
9.2.4	Measurement Reporting Requirements	
9.2.4.1	Periodic Reporting.	
9.2.4.2	Event-triggered Periodic Reporting	
9.2.4.3	Event Triggered Reporting	
9.2.5	Intrafrequency measurements without measurement gaps	
9.2.5.1	Intrafrequency cell identification	
9.2.5.2	Measurement period	
9.2.5.3	Scheduling availability of UE during intra-frequency measurements	
9.2.5.3.1	Scheduling availability of UE performing measurements in TDD bands on FR1	281
9.2.5.3.2	Scheduling availability of UE performing measurements with a different subcarrier spacing	
	than PDSCH/PDCCH on FR1	
9.2.5.3.3	Scheduling availability of UE performing measurements on FR2	281
9.2.5.3.4	Scheduling availability of UE performing measurements on FR1 or FR2 in case of FR1-FR2	
	inter-band CA	
9.2.5.4	SFTD Measurements between PCell and PSCell	
9.2.5.4.1	Introduction	
9.2.5.4.2	•	
9.2.5.4.3	SFTD Measurement Reporting Delay	
9.2.6	Intra-frequency measurements with measurement gaps	
9.2.6.1	Void	
9.2.6.2	Intra-frequency cell identification	
9.2.6.3	Intrafrequency Measurement Period	
9.2A	NR intra-frequency measurements with CCA	
9.2A.1	Introduction	
9.2A.2	Requirements applicability	
9.2A.3	Number of cells and number of SSB	
9.2A.4	Measurement Reporting Requirements	
9.2A.5	Intra-frequency measurements without measurement gaps	
9.2A.5.2		
9.2A.5.3		
9.2A.5.3.		291
9.2A.5.3.	2 Scheduling availability of UE performing measurements with a different subcarrier spacing than PDSCH/PDCCH	200
9.2A.6	Intra-frequency measurements with measurement gaps	
9.2A.6.1	Intra-frequency cell identification	
9.2A.6.1 9.2A.6.2	Intra-frequency Measurement Period	
9.2A.0.2 9.2A.7	Intra-frequency RSSI and Channel occupancy measurements	
9.2A.7 9.2A.7.1	Intra-frequency RSSI measurements	
9.2A.7.1	Intra-frequency Channel occupancy measurements	
9.2A.7.3	Scheduling restriction during RSSI and Channel Occupancy measurements	
9.3	NR inter-frequency measurements	
9.3.1	Introduction	
9.3.2	Requirements applicability	
9.3.2.1	Void	
9.3.2.2	Void	
9.3.3	Number of cells and number of SSB	
9.3.3.1	Requirements for FR1	
9.3.3.2	Requirements for FR2	
9.3.4	Inter-frequency measurement with measurement gaps	
9.3.4.1	Void	
9.3.4.2	Void	
9.3.5	Inter-frequency measurements	
9.3.5.1	Void	
9.3.5.2	Void	
9.3.5.3	Void	
9.3.6	Inter-frequency measurements reporting requirements	
9.3.6.1	Periodic Reporting	
9.3.6.2	Event-triggered Periodic Reporting	
9.3.6.3	Event-triggered Reporting	

9.3.7	Void	
9.3.8	Inter-frequency SFTD measurement requirements	
9.3.8.1	Introduction	
9.3.8.2	SFTD Measurement delay	
9.3.8.3	SFTD Measurement reporting delay	
9.3.9	Inter frequency measurements without measurement gaps	
9.3.9.1	Inter frequency Cell identification	
9.3.9.2	Measurement period	
9.3.9.3	Scheduling availability of UE during inter-frequency measurements	
9.3.9.3.1	Scheduling availability of UE performing measurements in TDD bands on FR1	304
9.3.9.3.2	Scheduling availability of UE performing measurements with a different subcarrier spacing than PDSCH/PDCCH on FR1	305
9.3.9.3.3	Scheduling availability of UE performing measurements on FR2	
9.3.9.3.4	Scheduling availability of UE performing measurements on FR1 or FR2 in case of FR1-FR2	
	inter-band CA	305
9.3A	NR inter-frequency measurements in carrier frequencies with CCA	
9.3A.1	Introduction	
9.3A.2	Requirements applicability	306
9.3A.3	Number of cells and number of SSB	306
9.3A.3.1	Requirements	306
9.3A.4	Inter-frequency cell identification	
9.3A.5	Inter-frequency measurements	
9.3A.6	NR Inter-frequency measurements reporting requirements	
9.3A.6.1	Periodic Reporting.	
9.3A.6.2	Event-triggered Periodic Reporting	
9.3A.6.3	Event-triggered Reporting	
9.3A.8	Inter-frequency RSSI measurements	
9.3A.9	Inter-frequency channel occupancy measurements	
9.4	Inter-RAT measurements	
9.4.1	Introduction	
9.4.2	NR – E-UTRAN FDD measurements	
9.4.2.1	Introduction	
9.4.2.2	Requirements when no DRX is used	
9.4.2.3	Requirements when DRX is used	
9.4.2.4	Measurement reporting requirements	
9.4.2.4.1	Periodic Reporting	
9.4.2.4.2	Event-Triggered Periodic Reporting	314
9.4.2.4.3	Event-Triggered Reporting	314
9.4.3	NR – E-UTRAN TDD measurements	314
9.4.3.1	Introduction	314
9.4.3.2	Requirements when no DRX is used	314
9.4.3.3	Requirements when DRX is used	315
9.4.3.4	Measurement reporting requirements	
9.4.3.4.1	Periodic Reporting	
9.4.3.4.2	Event-Triggered Periodic Reporting	
9.4.3.4.3	Event-Triggered Reporting	317
9.4.4	Inter-RAT RSTD measurements	317
9.4.4.1	NR – E-UTRAN FDD RSTD measurements	317
9.4.4.1.1	Introduction	317
9.4.4.1.2	Requirements	318
9.4.4.2	NR – É-UTRAN TDD RSTD measurements	321
9.4.4.2.1	Introduction	
9.4.4.2.2	Requirements	322
9.4.5	Inter-RAT E-CID measurements	
9.4.5.1	NR-E-UTRAN FDD E-CID RSRP and RSRQ measurements	
9.4.5.1.1	Introduction	
9.4.5.1.2	Requirements	
9.4.5.1.3	Measurement Reporting Delay	
9.4.5.2	NR-E-UTRAN TDD E-CID RSRP and RSRQ measurements	
9.4.5.2.1	Introduction	325
9.4.5.2.2	Requirements	
9.4.5.2.3	Measurement Reporting Delay	

9.4.6	NR – UTRAN FDD measurements	326
9.4.6.1	Introduction	326
9.4.6.2	Requirements when no DRX is used	326
9.4.6.3	Requirements when DRX is used	327
9.4.7	NR – E-UTRAN measurements with autonomous gaps	329
9.4.7.1	CGI identification of an E-UTRA cell with autonomous gaps	329
The requ	irement for identifying a new CGI of an E-UTRA cell within Tidentify_CGI, E-UTRAN is applicable	
	when no DRX is used as well as when any of the DRX cycles specified in TS 38.331 [2] is	
	used.9.4.7.2 CGI	
	reporting delay 329	
9.5	L1-RSRP measurements for Reporting	330
9.5.1	Introduction	330
9.5.2	Requirements applicability	330
9.5.3	Measurement Reporting Requirements	330
9.5.3.1	Periodic Reporting	331
9.5.3.2	Semi-Persistent Reporting	331
9.5.3.3	Aperiodic Reporting	331
9.5.4	L1-RSRP measurement requirements	331
9.5.4.1	SSB based L1-RSRP Reporting	331
9.5.4.2	CSI-RS based L1-RSRP Reporting	333
9.5.4A	Void	336
9.5.4A.1	Void	336
9.5.5	Measurement restriction for CSI-RS and SSB for L1-RSRP measurement	336
9.5.5.1	Measurement restriction for SSB based L1-RSRP	336
9.5.5.2	Measurement restriction for CSI-RS based L1-RSRP	
9.5.6	Scheduling availability of UE during L1-RSRP measurement	337
9.5.6.1	Scheduling availability of UE performing L1-RSRP measurement with a same subcarrier spacing	
	as PDSCH/PDCCH on FR1	337
9.5.6.2	Scheduling availability of UE performing L1-RSRP measurement with a different subcarrier	
	spacing than PDSCH/PDCCH on FR1	
9.5.6.3	Scheduling availability of UE performing L1-RSRP measurement on FR2	338
9.5.6.4	Scheduling availability of UE performing L1-RSRP measurement on FR1 or FR2 in case of	
	FR1-FR2 inter-band CA	
9.5A	L1-RSRP measurements for Reporting under CCA	
9.5A.1	Introduction	
9.5A.2	Requirements applicability	
9.5A.3	Measurement Reporting Requirements	
9.5A.3.1	Periodic Reporting	
9.5A.3.2		
9.5A.3.3	Aperiodic Reporting	
9.5A.4	L1-RSRP measurement requirements	
9.5A.4.1	SSB based L1-RSRP Reporting	
9.5A.5	Measurement restriction for L1-RSRP measurement.	
9.5A.5.1	Measurement restriction for SSB based L1-RSRP	
9.5A.6	Scheduling availability of UE during L1-RSRP measurement	
9.5A.6.1	Scheduling availability of UE performing L1-RSRP measurement with a same subcarrier spacing	
	as PDSCH/PDCCH	342
9.5A.6.2		
	spacing than PDSCH/PDCCH	342
9.5A.6.3	Scheduling availability of UE performing L1-RSRP measurement in case of FR1-FR2 inter-band	
	CA	
9.6	NE-DC: Measurements	
9.6.1	Introduction	
9.6.2	SFTD Measurements	
9.6.2.1	Introduction	
9.6.2.2	SFTD Measurement requirements	
9.7	Cross Link Interference measurements	
9.7.1	Introduction	
9.7.2	SRS-RSRP measurements	
9.7.2.1	Introduction	
9.7.2.2	Requirements applicability	
9.7.2.3	Measurement Reporting Requirements	344

9.7.2.3.1	Periodic Reporting	
9.7.2.3.2	Event-triggered Periodic Reporting	344
9.7.2.3.3	Event Triggered Reporting	344
9.7.2.4	Measurement capability	344
9.7.2.5	SRS-RSRP measurement period	344
9.7.3	CLI-RSSI measurements	345
9.7.3.1	Introduction	345
9.7.3.2	Requirements applicability	345
9.7.3.3	Measurement Reporting Requirements	
9.7.3.3.1	Periodic Reporting	
9.7.3.3.2	Event-triggered Periodic Reporting	
9.7.3.3.3	Event Triggered Reporting	
9.7.3.4	Measurement capability	
9.7.3.5	CLI-RSSI measurement period	
9.7.4	Scheduling availability of UE during CLI measurements	
9.7.4.1	Scheduling availability of UE performing measurement on FR1	
9.7.4.2	Scheduling availability of UE performing measurement on FR2	
9.8	L1-SINR measurements for Reporting	
9.8.1	Introduction	
9.8.2	Requirements applicability	
9.8.3	Measurement Reporting Requirements	
9.8.3.1	Periodic Reporting.	
9.8.3.2	Semi-Persistent Reporting	
9.8.4	L1-SINR measurement requirements.	
9.8.4.1	L1-SINR reporting with CSI-RS based CMR and no dedicated IMR configured	
9.8.4.3	L1-SINR reporting with CSI-RS based CMR and dedicated IMR configured	
9.8.5	Measurement restriction for L1-SINR measurement	
9.8.5.1	Measurement restriction if SSB configured for L1-SINR Measurement	
9.8.5.2	Measurement restriction if CSI-RS configured for L1-SINR measurement	
9.8.5.3	Measurement restriction if CSI-IM configured for L1-SINR measurement	
9.8.6	Scheduling availability of UE during L1-SINR measurement	
0861	Schoduling availability of LIE performing L1 SIND maggurament with a same subservior enocing	
9.8.6.1	Scheduling availability of UE performing L1-SINR measurement with a same subcarrier spacing	
	as PDSCH/PDCCH on FR1	
9.8.6.1 9.8.6.2	as PDSCH/PDCCH on FR1	356
9.8.6.2	as PDSCH/PDCCH on FR1	356 356
	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-	356 356
9.8.6.2 9.8.6.4	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA	356
9.8.6.2 9.8.6.4 9.9	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning	356
9.8.6.2 9.8.6.4 9.9 9.9.1	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning Introduction	356
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning Introduction RSTD measurements	356 357 357 357
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning Introduction RSTD measurements Introduction	356 357 357 358 358
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning Introduction RSTD measurements Introduction. Requirements Applicability	356 357 357 358 358
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning Introduction RSTD measurements Introduction Requirements Applicability Measurement Capability	356 357 357 358 358 358
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3 9.9.2.4	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning Introduction RSTD measurements Introduction Requirements Applicability Measurement Capability Measurement Reporting Requirements	356357357357358358358
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3 9.9.2.4 9.9.2.4.1	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning Introduction RSTD measurements Introduction Requirements Applicability Measurement Capability Measurement Reporting Requirements Void	356357357357358358358358
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3 9.9.2.4 9.9.2.4.1 9.9.2.4.2	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning Introduction RSTD measurements Introduction. Requirements Applicability Measurement Capability Measurement Reporting Requirements. Void Void	356356357357358358358358358
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning Introduction RSTD measurements Introduction. Requirements Applicability Measurement Capability Measurement Reporting Requirements. Void Void Void Void	356356357357358358358358358
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3 9.9.2.5	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning Introduction RSTD measurements Introduction Requirements Applicability Measurement Capability Measurement Reporting Requirements Void Void Void Measurements Period Requirements	356356357357358358358358358358
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3 9.9.2.5 9.9.2.6	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning. Introduction. RSTD measurements Introduction. Requirements Applicability Measurement Capability Measurement Reporting Requirements Void Void Void Measurements Period Requirements Void	356356357357358358358358358358
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3 9.9.2.5 9.9.2.6 9.9.3	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning Introduction RSTD measurements Introduction Requirements Applicability Measurement Capability Measurement Reporting Requirements Void Void Void Measurements Period Requirements Void PRS-RSRP measurements	356357357357358358358358358358358358
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3 9.9.2.5 9.9.2.6 9.9.3 9.9.3.1	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning Introduction RSTD measurements Introduction Requirements Applicability Measurement Capability Measurement Reporting Requirements Void Void Void Neasurements Period Requirements Void PRS-RSRP measurements Introduction.	356356357357358358358358358358358358358
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3 9.9.2.6 9.9.3 9.9.3.1 9.9.3.2	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning. Introduction RSTD measurements Introduction. Requirements Applicability Measurement Capability Measurement Reporting Requirements Void Void Void Measurements Period Requirements Void. PRS-RSRP measurements Introduction. Requirements applicability	356356357357358358358358358358358358358
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3 9.9.2.5 9.9.3 9.9.3.1 9.9.3.2 9.9.3.3	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning. Introduction RSTD measurements Introduction Requirements Applicability Measurement Capability Measurement Reporting Requirements Void Void Void Measurements Period Requirements Void PRS-RSRP measurements Introduction Requirements applicability Measurement Capability Measurements Period Requirements Void PRS-RSRP measurements Introduction Requirements applicability Measurement Capability	356356357357358358358358358358358358358360360
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3 9.9.2.5 9.9.2.6 9.9.3 9.9.3.1 9.9.3.2 9.9.3.3 9.9.3.4	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning. Introduction RSTD measurements Introduction. Requirements Applicability Measurement Capability Measurement Reporting Requirements. Void Void Void Measurements Period Requirements Void. PRS-RSRP measurements Introduction. Requirements applicability Measurement Capability Measurement Reporting Requirements	356356357357358358358358358358358358358358358
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3 9.9.2.5 9.9.2.6 9.9.3 9.9.3.1 9.9.3.2 9.9.3.3 9.9.3.3 9.9.3.5	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning Introduction RSTD measurements Introduction Requirements Applicability Measurement Capability Measurement Reporting Requirements Void Void Void Measurements Period Requirements Void PRS-RSRP measurements Introduction Requirements applicability Measurement Reporting Requirements Void PRS-RSRP measurements Introduction Requirements applicability Measurement Reporting Requirements Measurement Reporting Requirements Measurement Reporting Requirements Measurement Reporting Requirements	356356357357358358358358358358358358358360360361361
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3 9.9.2.5 9.9.2.6 9.9.3 9.9.3.1 9.9.3.2 9.9.3.3 9.9.3.4 9.9.3.5 9.9.4	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning. Introduction RSTD measurements Introduction. Requirements Applicability Measurement Capability Measurement Reporting Requirements. Void Void Void Measurements Period Requirements Void. PRS-RSRP measurements Introduction. Requirements applicability Measurement Reporting Requirements Void PRS-RSRP measurements Introduction. Requirements applicability Measurement Reporting Requirements Void Requirement Reporting Requirements Measurement Reporting Requirements Measurement Reporting Requirements Measurement Period Requirements Measurement Period Requirements	356356357357358358358358358358360360361361363
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3 9.9.2.5 9.9.3 9.9.3.1 9.9.3.2 9.9.3.3 9.9.3.4 9.9.3.5 9.9.4 1 Int	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA NR measurements for positioning Introduction RSTD measurements Introduction Requirements Applicability Measurement Capability Measurement Reporting Requirements Void Void Void Measurements Period Requirements Void PRS-RSRP measurements Introduction Requirements applicability Measurement Reporting Requirements Void PRS-RSRP measurements Introduction Requirements applicability Measurement Reporting Requirements UE Rx-Tx time difference measurements	356356357357358358358358358358360360361361363
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3 9.9.2.5 9.9.3.1 9.9.3.1 9.9.3.2 9.9.3.3 9.9.3.1 9.9.3.2 9.9.3.8 9.9.3.1 9.9.3.2 9.9.3.8	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA. NR measurements for positioning Introduction RSTD measurements Introduction Requirements Applicability Measurement Capability Measurement Reporting Requirements. Void Void Measurements Period Requirements Void PRS-RSRP measurements Introduction Requirements applicability Measurement Capability Measurement Reporting Requirements Void PRS-RSRP measurements Introduction Requirements applicability Measurement Capability Measurement Reporting Requirements. UE Rx-Tx time difference measurements troduction Equirements Applicability	356356357357358358358358358358360361361363363
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3 9.9.2.5 9.9.3.3 9.9.3.1 9.9.3.2 9.9.3.3 9.9.3.4 9.9.3.5 9.9.4 9.9.4.1 Into possible of the possi	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA. NR measurements for positioning Introduction RSTD measurements Introduction. Requirements Applicability Measurement Capability Measurement Reporting Requirements. Void Void Woid Weasurements Period Requirements Void. PRS-RSRP measurements Introduction. Requirements applicability Measurement Reporting Requirements Void UC PRS-RSRP measurements Introduction Requirements applicability Measurement Capability Measurement Reporting Requirements UE Rx-Tx time difference measurements Irroduction Squirements Applicability. Quirements Applicability.	356356357357358358358358358360360361363363363
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.3 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3 9.9.2.5 9.9.3.3 9.9.3.1 9.9.3.2 9.9.3.3 9.9.3.4 9.9.3.5 9.9.4 9.9.4.1 Into possible of the possi	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA. NR measurements for positioning Introduction RSTD measurements Introduction Requirements Applicability Measurement Capability Measurement Reporting Requirements. Void Void Measurements Period Requirements Void PRS-RSRP measurements Introduction Requirements applicability Measurement Capability Measurement Reporting Requirements Void PRS-RSRP measurements Introduction Requirements applicability Measurement Capability Measurement Reporting Requirements. UE Rx-Tx time difference measurements troduction Equirements Applicability	356356357357358358358358358360360361363363363
9.8.6.2 9.8.6.4 9.9 9.9.1 9.9.2 9.9.2.1 9.9.2.2 9.9.2.4 9.9.2.4.1 9.9.2.4.2 9.9.2.4.3 9.9.2.5 9.9.2.6 9.9.3 9.9.3.1 9.9.3.2 9.9.3.3 9.9.3.4 9.9.3.5 9.9.4 9.9.4.1 Int 9.9.4.2 Re 9.9.4.3 M 9.9.4.3 M 9.9.4.4 M	as PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement with a different subcarrier spacing than PDSCH/PDCCH on FR1 Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-FR2 inter-band CA. NR measurements for positioning Introduction RSTD measurements Introduction. Requirements Applicability Measurement Capability Measurement Reporting Requirements. Void Void Woid Weasurements Period Requirements Void. PRS-RSRP measurements Introduction. Requirements applicability Measurement Reporting Requirements Void UC PRS-RSRP measurements Introduction Requirements applicability Measurement Capability Measurement Reporting Requirements UE Rx-Tx time difference measurements Irroduction Squirements Applicability. Quirements Applicability.	356356357357358358358358358358360360361363363363

Measurement Requirements	
Intra-frequency Measurement Requirements	365
• · ·	
Requirements for FR2	368
Measurement Reporting Requirements	369
Periodic Reporting	369
Event-triggered Periodic Reporting	369
Requirements for FR2	372
Measurements reporting requirements	372
Periodic Reporting	372
Inter frequency measurements with measurement gans	373
Inter frequency measurements with measurement gaps	
NR measurements with autonomous gaps	374
NR measurements with autonomous gaps	374 374
NR measurements with autonomous gaps	374 374 374
NR measurements with autonomous gaps	374 374 374
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay	374 374 375
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements	374 374 375 376
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay casurement Performance requirements NR measurements	374 374 375 376
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay casurement Performance requirements NR measurements Introduction	374 374 375 376 376
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1	374 374 375 376 376 376
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements	374 374 375 376 376 376 376
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy	374 374 375 376 376 376 376 376
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy	374 374 375 376 376 376 376 376
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void	374 374 375 376 376 376 376 376 376 377
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void Intra-frequency CSI-RSRP accuracy requirements	374 374 375 376 376 376 376 376 376 378 378
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void	374 374 375 376 376 376 376 376 376 378 378
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void Intra-frequency CSI-RSRP accuracy requirements	374 374 375 376 376 376 376 376 378 378 378
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Relative CSI-RSRP Accuracy Relative CSI-RSRP Accuracy	374 374 375 376 376 376 376 376 376 378 378 378
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Relative CSI-RSRP Accuracy Intra-frequency RSRP accuracy Relative CSI-RSRP Accuracy Relative CSI-RSRP Accuracy	374 374 375 376 376 376 376 376 376 378 378 378 378 378
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Relative CSI-RSRP Accuracy Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements for FR1 for CA/DC Idle Mode Measurements Intra-frequency SS-RSRP accuracy requirements	374 374 375 376 376 376 376 376 376 378 378 378 378 378 378
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps. CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Relative CSI-RSRP Accuracy Intra-frequency RSRP accuracy requirements Absolute CSI-RSRP Accuracy Intra-frequency RSRP accuracy requirements for FR1 for CA/DC Idle Mode Measurements Intra-frequency SS-RSRP accuracy requirements Intra-frequency SS-RSRP accuracy requirements	374 374 375 376 376 376 376 376 376 378 378 378 378 380 380
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Relative CSI-RSRP Accuracy Intra-frequency RSRP accuracy requirements Absolute CSI-RSRP Accuracy Intra-frequency RSRP accuracy requirements for FR1 for CA/DC Idle Mode Measurements Intra-frequency SS-RSRP Accuracy requirements 1 Absolute SS-RSRP Accuracy Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements	374 374 375 376 376 376 376 376 376 378 378 378 380 380 380
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void. Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Relative CSI-RSRP Accuracy Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements for FR1 for CA/DC Idle Mode Measurements Intra-frequency SS-RSRP accuracy requirements 1 Absolute SS-RSRP Accuracy Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements for FR2 Intra-frequency SS-RSRP accuracy requirements	374 374 375 376 376 376 376 376 378 378 378 380 380 380 381
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Relative CSI-RSRP Accuracy Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements Intra-frequency SS-RSRP accuracy requirements Intra-frequency SS-RSRP accuracy requirements Intra-frequency SS-RSRP accuracy requirements 1 Absolute SS-RSRP Accuracy Intra-frequency SS-RSRP accuracy requirements Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP accuracy requirements Absolute SS-RSRP accuracy requirements Absolute SS-RSRP accuracy requirements Absolute SS-RSRP accuracy requirements	374 374 375 376 376 376 376 376 378 378 380 380 380 381 381
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps. CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Relative CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Intra-frequency RSRP accuracy requirements for FR1 for CA/DC Idle Mode Measurements Intra-frequency SS-RSRP accuracy requirements Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP accuracy requirements Absolute SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Relative SS-RSRP Accuracy Relative SS-RSRP Accuracy	374 374 375 376 376 376 376 376 378 378 378 380 380 381 381 381
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps. CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Relative CSI-RSRP Accuracy Intra-frequency RSRP accuracy requirements for FR1 for CA/DC Idle Mode Measurements Intra-frequency RSRP accuracy requirements for FR1 for CA/DC Idle Mode Measurements Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements Absolute SS-RSRP accuracy requirements Absolute SS-RSRP accuracy requirements Relative SS-RSRP Accuracy	374 374 375 376 376 376 376 376 378 378 378 380 380 381 381 381 381
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps. CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void. Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Void. Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Intra-frequency RSRP accuracy requirements for FR1 for CA/DC Idle Mode Measurements Intra-frequency SS-RSRP accuracy requirements Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements Absolute SS-RSRP Accuracy Intra-frequency RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Relative SS-RSRP Accuracy Relative SS-RSRP Accuracy Relative SS-RSRP Accuracy Noid. Intra-frequency CSI-RSRP accuracy requirements	374 374 375 376 376 376 376 376 378 378 378 380 380 380 381 381 381 381
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps. CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void. Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Relative CSI-RSRP Accuracy Intra-frequency RSRP accuracy requirements for FR1 for CA/DC Idle Mode Measurements Intra-frequency RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Relative SS-RSRP Accuracy Void. Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Void. Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy	374 374 375 376 376 376 376 376 378 378 380 380 380 381 381 381 382 383 383
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps. CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy Relative SS-RSRP Accuracy Relative SS-RSRP Accuracy Void Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Intra-frequency CSI-RSRP accuracy Relative CSI-RSRP Accuracy Intra-frequency RSRP accuracy requirements for FR1 for CA/DC Idle Mode Measurements Intra-frequency SS-RSRP accuracy requirements I Absolute SS-RSRP Accuracy Intra-frequency RSRP accuracy requirements I Absolute SS-RSRP accuracy requirements Intra-frequency RSRP accuracy requirements Relative SS-RSRP Accuracy Relative SS-RSRP Accuracy Relative SS-RSRP Accuracy Relative SS-RSRP Accuracy Relative CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Relative CSI-RSRP Accuracy	374 374 375 376 376 376 376 376 376 378 380 380 380 381 381 381 383 383 383
NR measurements with autonomous gaps	374374374375376376376376376376378378380380381381381383383383
NR measurements with autonomous gaps Introduction CGI identification of an NR cell with autonomous gaps CGI reporting delay assurement Performance requirements NR measurements Introduction Intra-frequency RSRP accuracy requirements for FR1 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative SS-RSRP Accuracy Void Intra-frequency CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Relative CSI-RSRP Accuracy Intra-frequency RSRP accuracy requirements Intra-frequency RSRP accuracy requirements for FR1 for CA/DC Idle Mode Measurements Intra-frequency SS-RSRP accuracy requirements Intra-frequency SS-RSRP accuracy requirements for FR2 Intra-frequency SS-RSRP accuracy requirements Absolute SS-RSRP accuracy requirements Absolute SS-RSRP Accuracy Relative CSI-RSRP accuracy requirements Absolute CSI-RSRP Accuracy Relative CSI-RSRP	374374374375376376376376376376378378380380381381381381383383383
NR measurements with autonomous gaps	374374375376376376376376376376378380380381381381381383383383383
	Inter-frequency Measurement Requirements Measurement Reporting Delay CSI-RS based L3 measurements Introduction CSI-RS based intra-frequency measurements Introduction Requirements applicability Number of cells and number of CSI-RS Requirements for FR1 Requirements for FR2 Measurement Reporting Requirements. Periodic Reporting Event-triggered Periodic Reporting Event Triggered Reporting Intra-frequency measurements without measurement gaps. Scheduling availability of UE during CSI-RS based intra-frequency measurements Scheduling availability of UE performing CSI-RS based measurements in TDD bands. Scheduling availability of UE performing CSI-RS based measurements in FR2. CSI-RS based Inter-frequency measurements Introduction. Requirements applicability Number of cells and number of CSI-RS resources Requirements for FR1 Requirements reporting requirements. Periodic Reporting Event-triggered Periodic Reporting Event-triggered Periodic Reporting

10.1.4.1	Inter-frequency SS-RSRP accuracy requirements	
10.1.4.1.1	Absolute Accuracy of SS-RSRP in FR1	385
10.1.4.1.2	Relative Accuracy of SS-RSRP in FR1	386
10.1.4.2	Void	
10.1.4.3	Inter-frequency CSI-RSRP accuracy requirements	387
10.1.4.3.1	Absolute Accuracy of CSI-RSRP in FR1	387
10.1.4.3.2	Relative Accuracy of CS-RSRP in FR1	388
10.1.4B	Inter-frequency RSRP accuracy requirements for FR1 for CA/DC Idle Mode Measurements	389
10.1.4B.1	Inter-frequency SS-RSRP accuracy requirements	
10.1.4B.1.1	Absolute Accuracy of SS-RSRP in FR1	
10.1.5	Inter-frequency RSRP accuracy requirements for FR2	
10.1.5.1	Inter-frequency SS-RSRP accuracy requirements	
10.1.5.1.1	Absolute SS-RSRP Accuracy	
10.1.5.1.2	Relative SS-RSRP Accuracy	
10.1.5.1.2	Void	
10.1.5.2	Inter-frequency CSI-RSRP accuracy requirements	
10.1.5.3	Absolute CSI-RSRP Accuracy	
10.1.5.3.1		
	Relative CSI-RSRP Accuracy	
10.1.5B	Inter-frequency RSRP accuracy requirements for FR2 for CA/DC Idle Mode Measurements	
10.1.5B.1	Inter-frequency SS-RSRP accuracy requirements	
10.1.5B.1.1	Absolute SS-RSRP Accuracy	
	Measurement Report Mapping	
10.1.7	Intra-frequency RSRQ accuracy requirements for FR1	
10.1.7.1	Intra-frequency SS-RSRQ accuracy requirements in FR1	
10.1.7.1.1	Absolute SS-RSRQ Accuracy in FR1	
10.1.7.2	Intra-frequency CSI-RSRQ accuracy requirements	397
10.1.7.2.1	Absolute CSI-RSRQ Accuracy	397
10.1.7B	Intra-frequency RSRQ accuracy requirements for FR1 for CA/DC Idle Mode Measurements	398
10.1.7B.1	Intra-frequency SS-RSRQ accuracy requirements in FR1	398
10.1.7B.1.1	Absolute SS-RSRQ Accuracy in FR1	
10.1.8	Intra-frequency RSRQ accuracy requirements for FR2	
10.1.8.1	Intra-frequency SS-RSRQ accuracy requirements in FR2	
10.1.8.1.1	Absolute SS-RSRQ Accuracy in FR2	
10.1.8.2	Intra-frequency CSI-RSRQ accuracy requirements	
10.1.8.2.1	Absolute CSI-RSRQ Accuracy	
10.1.8B	Intra-frequency RSRQ accuracy requirements for FR2 for CA/DC Idle Mode Measurements	
10.1.8B.1	Intra-frequency SS-RSRQ accuracy requirements in FR2	
10.1.8B.1.1	Absolute SS-RSRQ Accuracy in FR2	
10.1.8 b .1.1	Inter-frequency RSRQ accuracy requirements for FR1	
10.1.9.1	Inter-frequency SS-RSRQ accuracy requirements in FR1	
10.1.9.1.1	Absolute Accuracy of SS-RSRQ in FR1	
10.1.9.1.2	Relative Accuracy of SS-RSRQ in FR1	
10.1.9.2	Inter-frequency CSI-RSRQ accuracy requirements	
10.1.9.2.1	Absolute CSI-RSRQ Accuracy	
10.1.9.2.2	Relative CSI-RSRQ Accuracy	
10.1.9B	Inter-frequency RSRQ accuracy requirements for FR1 for CA/DC Idle Mode Measurements	
10.1.9B.1	Inter-frequency SS-RSRQ accuracy requirements in FR1	
10.1.9B.1.1	Absolute Accuracy of SS-RSRQ in FR1	
10.1.10	Inter-frequency RSRQ accuracy requirements for FR2	
10.1.10.2	Inter-frequency CSI-RSRQ accuracy requirements	
10.1.10.2.1	Absolute CSI-RSRQ Accuracy	409
10.1.10.2.2	Relative CSI-RSRQ Accuracy	
10.1.10B	Inter-frequency RSRQ accuracy requirements for FR2 for CA/DC Idle Mode Measurements	410
10.1.10B.1	Inter-frequency SS-RSRQ accuracy requirements in FR2	
10.1.10B.1.1	Absolute Accuracy of SS-RSRQ in FR2	
10.1.11	RSRQ report mapping.	
10.1.12	Intra-frequency SINR accuracy requirements for FR1	
10.1.12.2	Intra-frequency CSI-SINR accuracy requirements in FR1	
10.1.12.2.1	Absolute CSI-SINR Accuracy in FR1	
10.1.12.2.1	Intra-frequency SINR accuracy requirements for FR2	
10.1.13	Intra-frequency CSI-SINR accuracy requirements in FR2	
10.1.13.2.1	Absolute CSI-SINR Accuracy in FR2	
10.1.12.4.1		

10.1.14	Inter-frequency SINR accuracy requirements for FR1	
10.1.14.2	Inter-frequency CSI-SINR accuracy requirements in FR1	417
10.1.14.2.1	Aboslute Accuracy of CSI-SINR in FR1	
10.1.15	Inter-frequency SINR accuracy requirements for FR2	
10.1.15.2	Inter-frequency CSI-SINR accuracy requirements in FR2	
10.1.15.2.1	Aboslute Accuracy of CSI-SINR in FR2	
10.1.15.2.2	Relative Accuracy of CSI-SINR in FR2	421
10.1.16	SINR report mapping	422
10.1.17	Power Headroom	
10.1.18	$P_{CMAX,c,f}$	
10.1.19	L1-RSRP accuracy requirements for FR1	
10.1.20	L1-RSRP accuracy requirements for FR2	
10.1.21	SFTD accuracy requirements	
10.1.22	CLI measurement accuracy requirements	
10.1.24.3.1	Absolute PRS-RSRP Measurement Report Mapping	
10.1.24.3.2	Differential Report Mapping for PRS-RSRP Measurement	439
10.1.23	RSTD Measurements	
10.1.23.1	Introduction	
10.1.23.2	Measurement Accuracy Requirements	442
10.1.23.3	Report mapping	
10.1.23.3.1	Absolute DL RSTD Measurement Reporting	
10.1.23.3.2	Differential Reporting for DL RSTD Measurement	
10.1.23.3.3	Additional Path Report Mapping for DL RSTD	450
10.1.24	PRS-RSRP Measurements	
10.1.24.1	Introduction	452
10.1.24.2	Measurement Accuracy Requirements	
	Absolute PRS RSRP accuracy	
10.1.24.2.2 I	Relative PRS RSRP accuracy	
10.1.24.3	Report mapping	
10.1.24.3.1	Absolute PRS-RSRP Measurement Report Mapping	
10.1.24.3.2	Differential Report Mapping for PRS-RSRP Measurement	
10.1.25	UE Rx-Tx Time Difference Measurements	459
10.1.25.1	Introduction	
10.1.25.2	Measurement Accuracy Requirements	
10.1.25.3	Report mapping	
10.1.25.3.1	Absolute UE Rx-Tx Measurement Report Mapping	
10.1.25.3.2	Differential UE Rx-Tx Measurement Report Mapping	
10.1.25.3.3	Additional Path Report Mapping for UE Rx-Tx Time Difference	
10.1.26	FR2 P-MPR report	
10.1.26.1	Report mapping	
10.1.27	L1-SINR accuracy requirements for FR1	
10.1.28	L1-SINR accuracy requirements for FR2	
10.1.29	Intra-frequency RSRQ accuracy requirements under CCA	
10.1.29.1	Intra-frequency SS-RSRQ accuracy requirements in FR1	
10.1.29.1.1	Absolute SS-RSRQ Accuracy	
10.1.30	Inter-frequency RSRQ accuracy requirements under CCA	488
10.1.30.1	Inter-frequency SS-RSRQ accuracy requirements in FR1	
10.1.30.1.1	Aboslute Accuracy of SS-RSRQ	
10.1.30.1.2	Relative Accuracy of SS-RSRQ	
10.1.31	Intra-frequency SINR accuracy requirements under CCA	
10.1.31.1	Intra-frequency SS-SINR accuracy requirements in FR1	
10.1.31.1.1	Absolute SS-SINR Accuracy	
10.1.32	Inter-frequency SINR accuracy requirements under CCA	
10.1.32.1	Inter-frequency SS-SINR accuracy requirements in FR1	
10.1.32.1.1	Aboslute Accuracy of SS-SINR	
10.1.32.1.2	Relative Accuracy of SS-SINR	
10.1.33	L1-RSRP accuracy requirements under CCA	
10.1.33.1	SSB based L1-RSRP accuracy requirements in FR1	
10.1.33.1.1	Absolute Accuracy	
10.1.33.1.2	Relative Accuracy	
10.1.34	RSSI measurements under CCA	
10.1.34.1	Intra-frequency absolute RSSI measurement accuracy requirements in FR1	493

10.1.34.2	1 1	
10.1.34.3	RSSI measurement report mapping	493
10.1.35	Channel occupancy measurements under CCA	494
10.1.35.1	Intra-frequency channel occupancy measurement accuracy requirements in FR1	494
10.1.35.2	Inter-frequency channel occupancy measurement accuracy requirements in FR1	494
10.1.36	Intra-frequency RSRP accuracy requirements under CCA	
10.1.36.1		
10.1.36.1		
10.1.36.1	taran da antaran da an	
10.1.37	Inter-frequency RSRP accuracy requirements under CCA	
10.1.37.1		
10.1.37.1	i i i	
10.1.37.1	·	
10.1.37.1	E-UTRAN measurements.	
10.2.1	Introduction	
10.2.1	E-UTRAN RSRP measurements	
10.2.2		
	E-UTRAN RSRQ measurements.	
10.2.4	E-UTRAN RSTD measurements	
10.2.5	E-UTRAN RS-SINR measurements	
10.2.6	E-UTRAN RSRP measurements for CA/DC Idle Mode Measurements	
10.2.7	E-UTRAN RSRQ measurements for CA/DC Idle Mode Measurements	
10.3	UTRAN FDD Measurements	
10.3.1	UTRAN FDD CPICH RSCP	
10.3.2	UTRAN FDD CPICH Ec/No	
10.4	V2X measurements	
10.4.1	Introduction	
10.4.2	Intra-frequency PSBCH-RSRP accuracy requirements for FR1	
10.4.2.1	PSBCH-RSRP Absolute Accuracy	500
10.4.2.2	PSBCH-RSRP Relative Accuracy	
10.4.3	Intra-Frequency SL-RSSI Measurement Accuracy Requirements for FR1	502
10.4.3.1	Absolute SL-RSSI Accuracy	
10.4.4	Intra-Frequency L1 SL-RSRP Measurement Accuracy Requirements for FR1	
10.7.7	Initia-i reduction Li SL-NSINi inicasurcincin Accuracy Reduitements for i Ni	502
10.4.4.1		
10.4.4.1	Absolute L1 SL-RSRP Accuracy	502
10.4.4.1		502
10.4.4.1 11 V	Absolute L1 SL-RSRP Accuracy	502
10.4.4.1 11 V 12 V	Absolute L1 SL-RSRP Accuracyoid	502 503
10.4.4.1 11 V 12 V 12.1	Absolute L1 SL-RSRP Accuracy	502 503 503
10.4.4.1 11 V 12 V 12.1 12.2	Absolute L1 SL-RSRP Accuracy oid	502 503 503 503
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1	Absolute L1 SL-RSRP Accuracy oid 2X Requirements Introduction UE Transmit Timing Introduction	502 503 503 503 503
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2	Absolute L1 SL-RSRP Accuracy oid 2X Requirements Introduction UE Transmit Timing Introduction GNSS as synchronization reference source	502 503 503 503 503 504
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3	Absolute L1 SL-RSRP Accuracy oid	502 503 503 503 503 504 504
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4	Absolute L1 SL-RSRP Accuracy oid 2X Requirements Introduction UE Transmit Timing Introduction GNSS as synchronization reference source NR Cell as synchronization reference source E-URTAN Cell as synchronization reference source	502 503 503 503 503 504 504
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3	Absolute L1 SL-RSRP Accuracy oid 2X Requirements Introduction UE Transmit Timing Introduction GNSS as synchronization reference source NR Cell as synchronization reference source E-URTAN Cell as synchronization reference source SyncRef UE as synchronization reference source	502 503 503 503 503 504 504
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4	Absolute L1 SL-RSRP Accuracy oid 2X Requirements Introduction UE Transmit Timing Introduction GNSS as synchronization reference source NR Cell as synchronization reference source E-URTAN Cell as synchronization reference source SyncRef UE as synchronization reference source Initiation/Cease of SLSS Transmissions	502 503 503 503 503 504 504 504 505
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5	Absolute L1 SL-RSRP Accuracy oid 2X Requirements Introduction UE Transmit Timing Introduction GNSS as synchronization reference source NR Cell as synchronization reference source E-URTAN Cell as synchronization reference source SyncRef UE as synchronization reference source	502 503 503 503 503 504 504 504 505
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3	Absolute L1 SL-RSRP Accuracy. oid	502 503 503 503 503 504 504 504 505 505
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3 12.3.1	Absolute L1 SL-RSRP Accuracy	502 503 503 503 503 504 504 504 505 505
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3 12.3.1 12.3.1.1 12.3.1.2	Absolute L1 SL-RSRP Accuracy oid	502 503 503 503 503 504 504 504 505 505 505
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3 12.3.1 12.3.1.1 12.3.1.2 12.3.1.3	Absolute L1 SL-RSRP Accuracy oid	502 503 503 503 503 504 504 504 505 505 505 505
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3 12.3.1 12.3.1.1 12.3.1.2 12.3.1.3 12.3.1.4	Absolute L1 SL-RSRP Accuracy oid	502 503 503 503 503 504 504 505 505 505 505 505
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3 12.3.1.1 12.3.1.2 12.3.1.3 12.3.1.4 12.4	Absolute L1 SL-RSRP Accuracy	502 503 503 503 503 504 504 504 505 505 505 505 505 507 507
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3 12.3.1 12.3.1.1 12.3.1.2 12.3.1.3 12.3.1.4 12.4 12.5	Absolute L1 SL-RSRP Accuracy	502 503 503 503 503 504 504 504 505 505 505 505 506 507 507
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3.1 12.3.1.1 12.3.1.2 12.3.1.3 12.3.1.4 12.4 12.5 12.5.1	Absolute L1 SL-RSRP Accuracy oid 2X Requirements Introduction UE Transmit Timing Introduction GNSS as synchronization reference source NR Cell as synchronization reference source E-URTAN Cell as synchronization reference source SyncRef UE as synchronization reference source Initiation/Cease of SLSS Transmissions. Introduction Initiation/Cease of SLSS transmissions with NR cell as synchronization reference source. Initiation/Cease of SLSS transmissions with EUTRAN cell as synchronization reference source. Initiation/Cease of SLSS transmissions with GNSS as synchronization reference source. Initiation/Cease of SLSS transmissions with SyncRef UE as synchronization reference source. Initiation/Cease of SLSS transmissions with SyncRef UE as synchronization reference source. Initiation/Cease of SLSS transmissions with SyncRef UE as synchronization reference source. Selection / Reselection of V2X Synchronization Reference Source L1 SL-RSRP measurements Introduction	502 503 503 503 503 504 504 505 505 505 505 505 507 507 508 509
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3.1 12.3.1.1 12.3.1.2 12.3.1.3 12.3.1.4 12.4 12.5 12.5.1 12.5.2	Absolute L1 SL-RSRP Accuracy oid	502 503 503 503 503 504 504 505 505 505 505 507 507 507 509 509
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3.1 12.3.1.1 12.3.1.2 12.3.1.3 12.3.1.4 12.5 12.5.1 12.5.2 12.6	Absolute L1 SL-RSRP Accuracy oid	502 503 503 503 504 504 504 505 505 505 505 507 507 508 509 509
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3 12.3.1.1 12.3.1.2 12.3.1.3 12.3.1.4 12.4 12.5 12.5.1 12.5.2 12.6 12.7	Absolute L1 SL-RSRP Accuracy oid	502 503 503 503 504 504 504 505 505 505 505 507 507 508 509 509
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3 12.3.1.1 12.3.1.2 12.3.1.3 12.3.1.4 12.4 12.5 12.5.1 12.5.2 12.6 12.7 12.7.1	Absolute L1 SL-RSRP Accuracy	502 503 503 503 504 504 504 505 505 505 505 507 507 509 509 509
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3 12.3.1.1 12.3.1.2 12.3.1.3 12.3.1.4 12.4 12.5 12.5.1 12.5.2 12.6 12.7 12.7.1 12.7.2	Absolute L1 SL-RSRP Accuracy	502503503503503504504505505505505507507509509509
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3 12.3.1.1 12.3.1.2 12.3.1.3 12.3.1.4 12.5 12.5.1 12.5.2 12.6 12.7 12.7.1 12.7.2 12.7.3	Absolute L1 SL-RSRP Accuracy	502 503 503 503 504 504 504 505 505 505 505 506 507 507 509 509 509 509
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3 12.3.1.1 12.3.1.2 12.3.1.3 12.3.1.4 12.5 12.5.1 12.5.2 12.6 12.7 12.7.1 12.7.2 12.7.3 12.8	Absolute L1 SL-RSRP Accuracy oid	502503503503503504504505505505505507507508509509509509509509509
10.4.4.1 11 V 12 V 12.1 12.2 12.2.1 12.2.2 12.2.3 12.2.4 12.2.5 12.3 12.3.1.1 12.3.1.2 12.3.1.3 12.3.1.4 12.5 12.5.1 12.5.2 12.6 12.7 12.7.1 12.7.2 12.7.3	Absolute L1 SL-RSRP Accuracy	502503503503503504504505505505505507507509509509509509509509509509

13	Measurement Performance Requirements for NR gNB	
13.1	UL-RTOA	
13.1.1	Report mapping	513
13.2	gNB Rx-Tx time difference	515
13.2.1	1 11 6	
13.2.2	Measurement Accuracy Requirements	517
13.2.2		
13.3	UL SRS RSRP measurement	518
13.3.1	Report mapping	518
13.3.2	Measurement accuracy requirements	519
13.3.2	.1 Introduction	519
13.3.2	.2 Requirements	519
13.4	AoA/ZoA	520
13.4.1	Report mapping	520
		400
Anne	x A (normative): Test Cases	
A.1	Purpose of annex	423
A.2	Requirement classification for statistical testing	423
A.2.1	Types of requirements in TS 38.133	
A.2.1.		
A.3	RRM test configurations	425
A.3.1	Reference measurement channels	425
A.3.1.	1 PDSCH	425
A.3.1.	1.1 FDD	425
A.3.1.	1.2 TDD	426
A.3.1.	2 CORESET for RMSI scheduling	429
A.3.1.	2.1 FDD	429
A.3.1.	2.2 TDD	430
A.3.1.	3 CORESET for RMC scheduling	433
A.3.1.	· · · · · · · · · · · · · · · · · · ·	
A.3.1.	3.2 TDD	434
A.3.1.	4 TDD UL/DL configuration	437
A.3.1		
A.3.1	A.1 PDSCH	
A.3.1	A.1.1 TDD	439
A.3.1		
A.3.1		
A.3.1		
A.3.1	<u> </u>	
A.3.1		
A.3.1	e	
A.3.2.		
A.3.2.	·	
A.3.2.		
A.3.2.		
A.3.2.	1	
A.3.2.		
A.3.3	Reference DRX configurations	
A.3.3.		
A.3.3.		
A.3.3.		
A.3.3.	č ,	
A.3.3.		
A.3.3.		
A.3.3.	•	
A.3.3.	e s	
n.s.s.	bixa Configuration of Dixa Cycle – 320 ms and TAT – milling	++0

A.3.3.9 DRX Configuration 9: DRX cycle = 40 ms and TAT = 500 ms	
A.3.3.10 DRX Configuration 10: DRX cycle = 640 ms and TAT = 500 ms	
A.3.3.11 DRX Configuration 11: DRX cycle = 20 ms and TAT = Infinity	
A.3.3.12 DRX Configuration 12: DRX cycle = 640 ms and TAT = Infinity	
A.3.4 Test Cases with Different Channel Bandwidths	
A.3.4.1 Test Cases with Different E-UTRA Channel Bandwidths	
A.3.4.1.1 Introduction	
A.3.4.1.2 Principle of testing	
A.3.5 Test Cases for Synchronous and Asynchronous DC Operations	450
A.3.5.1 EN-DC Test Cases for Synchronous and Asynchronous EN-DC Operations	
A.3.5.1.1 Introduction	
A.3.5.1.2 Principle of Testing	
A.3.6 Antenna configurations	
A.3.6.1 Antenna configurations for FR1	
A.3.6.1.1 Antenna connection for 4 Rx capable UEs	
A.3.6.1.1.1 Introduction	
A.3.6.1.1.2 Principle of testing	
A.3.6.2 Antenna configurations for FR2	
A.3.6A Antenna configurations with unlicensed bands	
A.3.6A.1 Antenna configurations for FR1	
A.3.6A.1.1 Antenna connection for 4 Rx capable UEs	
A.3.6A.1.1.1 Introduction	
A.3.6A.1.1.2 Principle of testing	
A.3.7 EN-DC test setup	
A.3.7.1 Introduction	
A.3.7.2 E-UTRAN Serving Cell Parameters	
A.3.7.2.1 E-UTRAN Serving Cell Parameters for Tests with NR Cell(s) in FR1	
A.3.7.2.2 E-UTRAN Serving Cell Parameters for Tests with NR Cell(s) in FR2	
A.3.7A NR FR1-FR2 test setup	
A.3.7B EN-DC test setup with unlicensed bands.	
A.3.7B.1 Introduction	
A.3.7B.2 E-UTRAN Serving Cell Parameters	
A.3.7C LTE-FR1/FR2 test setup	
A.3.8.1 Introduction	
A.3.8.2 PRACH configurations in FR1	
A.3.8.2.1 FR1 PRACH configuration 1	
A.3.8.2.2 FR1 PRACH configuration 2	
A.3.8.2.3 FR1 PRACH configuration 3	
A.3.8.2.4 FR1 PRACH configuration 4	
A.3.8.3 PRACH configurations in FR2.	
A.3.8.3.1 FR2 PRACH configuration 1	
A.3.8.3.2 FR2 PRACH configuration 2	
A.3.8.3.3 FR2 PRACH configuration 3	
A.3.8.3.4 FR2 PRACH configuration 4	
A.3.8A PRACH configurations under CCA	
A.3.8A.1 Introduction	
A.3.8A.2 PRACH configurations in FR1	
A.3.8A.2.1 FR1 PRACH configuration 1 under CCA	
A.3.8A.2.2 FR1 PRACH configuration 2 under CCA	
A.3.9 BWP configurations	
A.3.9.1 Introduction	
A.3.9.2 Downlink BWP configurations	
A.3.9.2.1 Initial BWP	
A.3.9.2.2 Dedicated BWP	
A.3.9.3 Uplink BWP configurations	
A.3.9.3.1 Initial BWP	
A.3.9.3.2 Dedicated BWP	471
A.3.10 SSB Configurations.	
A.3.10.1 SSB Configurations for FR1	
A.3.10.1.1 SSB pattern 1 in FR1: SSB allocation for SSB SCS=15 kHz in 10 MHz	471

A.3.10.1.5 S5B pattern 5 in FR1: 55B allocation for 55B 5C5=15 kHz starting from odd 5FN in 10 MHz	4/3
A.3.10A SSB Configurations under CCA	
A.3.10A.1 SSB Configurations under CCA for FR1	478
A.3.10A.1.1 SSB pattern 1 under CCA for semi-static channel access: SSB allocation for SSB SCS=30kHz in 40MHz	
A.3.10A.1.2 SSB pattern 2 under CCA for dynamic channel access: SSB allocation for SSB SCS=30kHz in 40MHz	
A.3.10A.1.3 SSB pattern 3 under CCA for semi-static channel access: SSB allocation for SSB SCS=30 kHz in 40 MHz	
A.3.10A.1.4 SSB pattern 4 under CCA for dynamic channel access: SSB allocation for SSB SCS=30 kHz in 40 MHz	
A.3.11 SMTC Configurations	
A.3.11.1 SMTC pattern 1: SMTC period = 20 ms with SMTC duration = 1 ms	
A.3.11.2 SMTC pattern 2: SMTC period = 20 ms with SMTC duration = 5 ms	
A.3.11.3 SMTC pattern 3: SMTC period = 160 ms with SMTC duration = 1 ms	
A.3.11.4 SMTC pattern 4: SMTC period = 20 ms with SMTC duration = 1 ms	
A.3.11.5 SMTC pattern 5: SMTC period = 20 ms with SMTC duration = 5 ms	
A.3.12 Test Cases with Different CC Configurations.	
A.3.12.1 EN-DC Test Cases with Different EN-DC Configurations	
A.3.12.1.1 Introduction	
A.3.12.1.2 Principle of testing	
A.3.12.2 Carrier Aggregation Test Cases with Different CA Configurations	
A.3.12.2.1 Introduction	
A.3.12.2.2 Principle of testing	
A.3.13 Test Cases in SA and EN-DC Operations	
A.3.13.2 Principle of Testing	
A.3.13A Test Cases involving E-UTRA/FR1 and FR2 carriers	
A.3.13A.1 Introduction	
A.3.13A.2 Principle of Testing in EN-DC	
A.3.13A.3 Principle of Testing in SA	
A.3.13A.4 Principle of Testing in E-UTRA	483
A.3.14 CSI-RS configurations	484
A.3.14.1 FDD	
A.3.14.2 TDD	
A.3.15 Angle of Arrival (AoA) for FR2 RRM test cases	
A.3.15.1 Setup 1: Single AoA in Rx beam peak direction	
A.3.15.2 Setup 2: Single AoA in non Rx beam peak direction	
A.3.15.2.1 Setup 2a: Single AoA in non Rx beam peak direction without change in direction	
A.3.15.2.2 Setup 26. Shigle AoA in holi Rx bealth peak direction with change in direction	
A.3.15.4 Setup 4: 2 AoAs, 1 AoA in Rx beam peak direction, 1 in non Rx beam peak	
A.3.15.4.1 Setup 4a: 2 AoAs, 1 AoA in Rx beam peak direction, 1 in non Rx beam peak without change in	47-
direction	494
A.3.15.4.2 Setup 4b: 2 AoAs, 1 AoA in Rx beam peak direction, 1 in non Rx beam peak with change in direction	407
A.3.16 TCI State Configuration	
A.3.16.1 Introduction	
A.3.16.2 TCI states	
A.3.17 Configurations of CSI-RS for tracking.	
A.3.17.1 Configuration of CSI-RS for tracking for FR1	
A.3.17.1.1 FDD	
A.3.17.1.2 TDD	
A.3.17.2 Configuration of CSI-RS for tracking for FR2	497
A.3.17.2.1 TDD	
A.3.18 Additional definitions related to OTA testing for FR2 RRM test cases	
A.3.18.1 Introduction	
A.3.18.2 PRACH Power Measurement	
A.3.19 Test applicability for DAPS handover	
A.3.19.1 Introduction	
A.3.19.2 Principle of testing	498 100
A 3 /II MINUA CONTOURSHOUS	/101

A.3.20.1 Introduction	
A.3.20.2 MsgA configurations in FR1	
A.3.20.2.1 FR1 MsgA configuration 1	499
A.3.20.2.2 FR1 MsgA configuration 2	
A.3.20.3 MsgA configurations in FR2	
A.3.20.3.1 FR2 MsgA configuration 1	
A.3.20.3.2 FR2 MsgA configuration 2	
A.3.20A MsgA configurations under CCA	
A.3.20A.1 Introduction	
A.3.20A.2 MsgA configurations in FR1	
A.3.20A.2.1 FR1 MsgA configuration 1 under CCA	
A.3.20A.2.2 FR1 MsgA configuration 2 under CCA	
A.3.21 V2X sidelink communication	
A.3.21.1 Introduction	
A.3.21.2 Reference resource pool configurations for V2X Sidelink Communication	
A.3.21.3 Reference measurement channels for V2X Sidelink Communication	
A.3.22 CSI-IM configurations	
A.3.22.1 FDD	
A.3.22.2 TDD	
A.3.23 Spatial Relation Configuration	
A.3.23.1 Introduction	
A.3.23.2 Spatial Relation	
A.3.24 SRS configuration	
A.3.25 Channel bandwidth (CBW) configurations.	
A.3.25.1 DL UE specific CBW	
1	
A.3.26 CCA model	
A.3.26.2 CCA model for operation on a carrier frequency with CCA in FR1	
A.3.26.2.1 DL CCA model	
A.3.26.2.2 UL CCA model	
A.3.27 Test Cases with at Least One Cell on a Carrier Frequency with CCA	
A.3.27.1 Introduction	
A.3.27.2 NR Standalone Tests with NR SCell under CCA and All Other NR Cells in FR1	
A.3.27.3 EN-DC Tests with NR PSCell under CCA and Other NR Cells in FR1	
A.3.27.4 NR Standalone Tests with NR PCell under CCA and Other NR Cells in FR1	
A.3.27.5 E-UTRA Standalone Tests with at Least One NR Cell under CCA	
A.3.28 Discovery Burst Transmission Window configuration under CCA	
A.3.28.1 DBT Window pattern 1: DBT Window period = 20 ms with DBT Window duration = 1 ms	
A.3.29 Testing principles for UE capable of only NR bands with shared spectrum access	
A.3.29.1 Introduction	
A.3.29.2 Principle of testing for UE capable of EN-DC with only NR bands with shared spectrum access	
A.3.29.3 Principle of testing for UE capable of SA operation with only NR bands with shared spectrum	52
access	524
A.3.30 CSI-RS configurations for RRM	
A.3.30.1 FDD	
A.3.30.2 TDD	
A.3.31 PRS Configurations.	
A.3.31.1. PRS Configurations for FR1	
A.3.31.1.1. PRS pattern 1 in FR1: SCS=15 KHz	
A.3.31.1.2. PRS pattern 2 in FR1: SCS=30 KHz	
A.3.31.2. PRS Configurations for FR2	
A.3.31.2.1. PRS pattern 1 in FR2: SCS=120 KHz	
•	
A.4 EN-DC tests with all NR cells in FR1	
A.4.1 Void	
A.4.2 Void	
A.4.3 RRC_CONNECTED state mobility	
A.4.3.1 Void	
A.4.3.2 RRC Connection Mobility Control	
A.4.3.2.1 Void	
A.4.3.2.2 Random Access	530

A.4.3.2.2.1	4-step RA type contention based random access test in FR1 for PSCell in EN-DC	.530
A.4.3.2.2.2	4-step RA type n on-contention based random access test in FR1 for PSCell in EN-DC	
A.4.3.2.2.3	2-step RA type contention based random access test in FR1 for PSCell in EN-DC	
A.4.3.2.2.4	2-step RA type n on-contention based random access test in FR1 for PSCell in EN-DC	
A.4.3.2.3	Void	
A.4.4 Ti	ming	
A.4.4.1	UE transmit timing	
A.4.4.1.1	NR UE Transmit Timing Test for FR1	
A.4.4.1.1.1	Test Purpose and environment	
A.4.4.1.1.2	Test requirements	
A.4.4.2	UE timer accuracy	
A.4.4.3	Timing advance	
A.4.4.3.1	EN-DC FR1 timing advance adjustment accuracy	
A.4.4.3.1.1	Test Purpose and Environment	
A.4.4.3.1.2	Test Parameters	
A.4.4.3.1.3	Test Requirements	
	gnaling characteristics	
A.4.5.1	Radio link Monitoring.	. 554
A.4.5.1.1	Radio Link Monitoring Out-of-sync Test for FR1 PSCell configured with SSB-based RLM RS in non-DRX mode	<i></i>
A.4.5.1.1.1	Test Purpose and Environment	
A.4.5.1.1.1 A.4.5.1.1.2	Test Requirements	
A.4.5.1.1.2 A.4.5.1.2	Radio Link Monitoring In-sync Test for FR1 PSCell configured with SSB-based RLM RS in	. 339
A.4.3.1.2	non-DRX mode	550
A.4.5.1.2.1	Test Purpose and Environment	
A.4.5.1.2.1 A.4.5.1.2.2	Test Requirements	
A.4.5.1.3	Radio Link Monitoring Out-of-sync Test for FR1 PSCell configured with SSB-based RLM RS in	.505
11.4.3.1.3	DRX mode	565
A.4.5.1.3.1	Test Purpose and Environment	
A.4.5.1.3.2	Test Requirements	
A.4.5.1.4	Radio Link Monitoring In-sync Test for FR1 PSCell configured with SSB-based RLM RS in	
	DRX mode	.570
A.4.5.1.4.1	Test Purpose and Environment	
A.4.5.1.4.2	Test Requirements	
A.4.5.1.5	EN-DC Radio Link Monitoring Out-of-sync Test for FR1 PSCell configured with CSI-RS-based	
	RLM in non-DRX mode	
A.4.5.1.5.1	Test Purpose and Environment	
A.4.5.1.5.2	Test Requirements	.581
A.4.5.1.6	EN-DC Radio Link Monitoring In-sync Test for FR1 PSCell configured with CSI-RS-based	
	RLM in non-DRX mode	
A.4.5.1.6.1	Test Purpose and Environment	
A.4.5.1.6.2	Test Requirements	.587
A.4.5.1.7	EN-DC Radio Link Monitoring Out-of-sync Test for FR1 PSCell configured with CSI-RS-based	505
A 4 5 1 7 1	RLM in DRX mode	
A.4.5.1.7.1	Test Purpose and Environment	
A.4.5.1.7.2	Test Requirements	. 592
A.4.5.1.8	EN-DC Radio Link Monitoring In-sync Test for FR1 PSCell configured with CSI-RS-based	502
A 4 5 1 0 1	RLM in DRX mode	
A.4.5.1.8.1	Test Purpose and Environment	
A.4.5.1.8.2 A.4.5.2	Test Requirements	
	Interruption.	. 398
A.4.5.2.1	E-UTRAN – NR FR1 interruptions at transitions between active and non-active during DRX in synchronous EN-DC	508
A.4.5.2.1.1	Test Purpose and Environment	
A.4.5.2.1.1 A.4.5.2.1.2	Test Requirements	
A.4.5.2.1.2 A.4.5.2.2	E-UTRAN – NR FR1 interruptions at transitions between active and non-active during DRX in	.002
11.7.2.2.2	asynchronous EN-DC	602
A.4.5.2.2.1	Test Purpose and Environment	
A.4.5.2.2.2	Test Requirements	
A.4.5.2.3	E-UTRAN – NR FR1 interruptions during measurements on deactivated NR SCC in	. 555
- · · · -	synchronous EN-DC	.606
A.4.5.2.3.1	Test Purpose and Environment	

A.4.5.2.3.2	Test Requirements	610
A.4.5.2.4	E-UTRAN – NR FR1 interruptions during measurements on deactivated NR SCC in	
	asynchronous EN-DC	611
A.4.5.2.4.1	Test Purpose and Environment	
A.4.5.2.4.2	•	
A.4.5.2.5	E-UTRAN – NR FR1 interruptions during measurements on deactivated E-UTRAN SCC in	
	synchronous EN-DC	615
A.4.5.2.5.1	Test Purpose and Environment	
A.4.5.2.5.2		
A.4.5.2.6	E-UTRAN – NR FR1 interruptions during measurements on deactivated E-UTRAN SCC in	
	asynchronous EN-DC	618
A.4.5.2.6.1	Test Purpose and Environment	
A.4.5.2.6.2		
A.4.5.2.7	Void	
A.4.5.2.8	E-UTRAN - NR FR1 interruptions at NR SRS carrier based switching in asynchronous EN-DC	
A.4.5.2.8.1	Test Purpose and Environment	
A.4.5.2.8.2		
A.4.5.2.9	E-UTRAN – NR interruptions at E-UTRA SRS carrier based switching	
A.4.5.2.9.1	Test Purpose and Environment	
A.4.5.2.9.2	<u>*</u>	
A.4.5.3	SCell Activation and Deactivation Delay	
A.4.5.3.1	SCell Activation and deactivation of known SCell in FR1 for 160ms SCell measurement cycle	
A.4.5.3.1.1	Test Purpose and Environment	630
A.4.5.3.1.2		
A.4.5.3.2	SCell Activation and deactivation of known SCell in FR1 for 320 ms SCell measurement cycle	
A.4.5.3.2.1	Test Purpose and Environment	636
A.4.5.3.2.2	Test Requirements	636
A.4.5.3.3	SCell Activation and deactivation of unknown SCell in FR1	636
A.4.5.3.3.1	Test Purpose and Environment	636
A.4.5.3.3.2	1 · · · · · · · · · · · · · · · · · · ·	637
A.4.5.3.4	SCell Activation and deactivation of multiple unknown SCells in FR1 with single	
	activation/deactivation command	
A.4.5.3.4.1	Test Purpose and Environment	637
A.4.5.3.3.2	1	
A.4.5.3.5	Direct SCell activation at SCell addition of known SCell in FR1	
A.4.5.3.5.1	Test Purpose and Environment	
A.4.5.3.5.2	1	
A.4.5.4	UE UL carrier RRC reconfiguration Delay	
A.4.5.4.1	UE UL carrier RRC reconfiguration Delay	645
	Test Purpose and Environment	
A.4.5.4.1.2	1	
A.4.5.5	Beam Failure Detection and Link recovery procedures	655
A.4.5.5.1	EN-DC Beam Failure Detection and Link Recovery Test for FR1 PSCell configured with SSB-	
	based BFD and LR in non-DRX mode	
A.4.5.5.1.1	Test Purpose and Environment	
A.4.5.5.1.2	1	661
A.4.5.5.2	EN-DC Beam Failure Detection and Link Recovery Test for FR1 PSCell configured with SSB-	
	based BFD and LR in DRX mode	
A.4.5.5.2.1	Test Purpose and Environment	
A.4.5.5.2.2	1	667
A.4.5.5.3	EN-DC Beam Failure Detection and Link Recovery Test for FR1 PSCell configured with CSI-	
A 4 5 5 2 1	RS-based BFD and LR in non-DRX mode	
A.4.5.5.3.1	Test Pagyirements	
A.4.5.5.3.2	1	0/3
A.4.5.5.4	EN-DC Beam Failure Detection and Link Recovery Test for FR1 PSCell configured with CSI-	670
A 15511	RS-based BFD and LR in DRX mode	
A.4.5.5.4.1 A.4.5.5.4.2	Test Purpose and Environment Test Requirements	
A.4.5.5.4.2 A.4.5.6	Active BWP switch	
A.4.5.6.1	DCI-based and Timer-based Active BWP Switch	
A.4.3.0.1 A 4 5 6 1 1	E-UTRAN – NR PSCell FR1 DL active BWP switch in non-DRX in synchronous EN-DC	693

A.4.5.6.1.2	E-UTRAN – NR PSCell FR1 DL active BWP switch with FR1 SCell in non-DRX in	
	synchronous EN-DC	
A.4.5.6.2	RRC-based Active BWP Switch	
A.4.5.6.3	Simultaneous DCI-based and Timer-based Active BWP Switch on multiple CCs	. 707
A.4.5.6.3.1	Simultaneous E-UTRAN – NR PSCell FR1 DL active BWP switch in non-DRX in EN-DC	707
A 45 C 2 1 1	on multiple CCs	
A.4.5.6.3.1.1	Test Parsisses and Environment.	
A.4.5.6.3.1.2	1	
A.4.5.6.4	Simultaneous RRC-based Active BWP Switch on multiple CCs	./13
A.4.5.6.4.1	· ·	710
A 45 C 4 1 1	multiple CCs	
A.4.5.6.4.1.1	Test Purpose and Environment	
A.4.5.6.4.1.2	1	
A.4.5.6.5	SCell dormancy switch	
A.4.5.6.5.1	E-UTRAN – NR FR1 PSCell SCell dormancy switch of single FR1 SCell outside active time	
A.4.5.6.5.1.1	Test Purpose and Environment	
A.4.5.6.5.1.2	1	
A.4.5.6.5.2	E-UTRAN – NR FR1 PSCell SCell dormancy switch of two FR1 SCells inside active time	
A.4.5.6.5.2.1	Test Purpose and Environment.	
A.4.5.6.5.2.2	<u>.</u>	
A.4.5.7	PSCell addition and release delay	
A.4.5.7.1	Addition and Release Delay of known NR PSCell	
A.4.5.7.1.1	Test purpose and environment	
A.4.5.7.1.2	Test Requirements	
A.4.5.8	DL Interruptions at switching between two uplink carriers	
A.4.5.8.1	Test Purpose and Environment	
A.4.5.8.2	Test Requirements	
	easurement procedure	
A.4.6.1	Intra-frequency Measurements	
A.4.6.1.1	EN-DC event triggered reporting tests without gap under non-DRX	
A.4.6.1.1.1	Test purpose and Environment	
A.4.6.1.1.2	Test parameters	
A.4.6.1.1.3	Test Requirements	
A.4.6.1.2	EN-DC event triggered reporting tests without gap under DRX	
A.4.6.1.2.1	Test purpose and Environment	
A.4.6.1.2.2	Test parameters	
A.4.6.1.2.2	Test Requirements	
A.4.6.1.3	EN-DC event triggered reporting tests with per-UE gaps under non-DRX	
A.4.6.1.3.1	Test purpose and Environment	
A.4.6.1.3.2	Test parameters	
A.4.6.1.3.3	Test Requirements	
A.4.6.1.4	EN-DC event triggered reporting tests with per-UE gaps under DRX	
A.4.6.1.4.1	Test purpose and Environment	
A.4.6.1.4.2	Test parameters	
A.4.6.1.4.3	Test Requirements	
A.4.6.1.5	EN-DC event triggered reporting tests without gap under non-DRX with SSB index reading	
A.4.6.1.5.1	Test purpose and Environment	
A.4.6.1.5.2	Test parameters	
A.4.6.1.5.3	Test Requirements	
A.4.6.1.6	EN-DC event triggered reporting tests with SSB index reading with per-UE gaps	
A.4.6.1.6.1	Test purpose and Environment	
A.4.6.1.6.2	Test parameters	
A.4.6.1.6.3	Test Requirements	.757
A.4.6.1.7	EN-DC event triggered reporting tests under DRX for UE configured with highSpeedMeasFlag-	
	r16	
A.4.6.1.7.1	Test purpose and Environment	
A.4.6.1.7.2	Test parameters	
A.4.6.1.7.3	Test Requirements	
A.4.6.2	Inter-frequency Measurements	.762
A.4.6.2.1	EN-DC event triggered reporting tests for FR1 cell without SSB time index detection when DRX	
	is not used	.762
A.4.6.2.1.1	Test Purpose and Environment	.762

A.4.6.2.1.2	Test Requirements	766
A.4.6.2.2	EN-DC event triggered reporting tests for FR1 cell without SSB time index detection when DRX	
	is used	
A.4.6.2.2.1	Test Purpose and Environment	
A.4.6.2.2.2	Test Requirements	
A.4.6.2.3	Void	
A.4.6.2.4	Void	771
A.4.6.2.5	EN-DC event triggered reporting tests for FR1 cell with SSB time index detection when DRX is	
	not used	
A.4.6.2.5.1	Test Purpose and Environment	
A.4.6.2.5.2	Test Requirements	//5
A.4.6.2.6	EN-DC event triggered reporting tests for FR1 cell with SSB time index detection when DRX is used	775
A.4.6.2.6.1	Test Purpose and Environment	
A.4.6.2.6.2	Test Requirements	
A.4.6.2.7	Void	
A.4.6.2.8	Void	
A.4.6.3	Void	
A.4.6.4	L1-RSRP measurement for beam reporting	
A.4.6.4.1	SSB based L1-RSRP measurement when DRX is not used.	
A.4.6.4.1.1	Test Purpose and Environment	
A.4.6.4.1.1	•	
A.4.6.4.1.2 A.4.6.4.1.3	Test parameters	
	Test Requirements	
A.4.6.4.2	SSB based L1-RSRP measurement when DRX is used	
A.4.6.4.2.1 A.4.6.4.2.2	Test Purpose and Environment	
111	Test parameters	
A.4.6.4.2.3	Test Requirements	
A.4.6.4.3	CSI-RS based L1-RSRP measurement when DRX is not used	
A.4.6.4.3.1	Test Purpose and Environment	
A.4.6.4.3.2	Test parameters	
A.4.6.4.3.3	Test Requirements	
A.4.6.4.4	CSI-RS based L1-RSRP measurement when DRX is used	
A.4.6.4.4.1	Test Purpose and Environment	
A.4.6.4.4.2	Test parameters	
A.4.6.4.4.3	Test Requirements	795
A.4.6.4.5	SSB based L1-RSRP measurement when DRX is used for UE configured with	70
	highSpeedMeasFlag-r16	
A.4.6.4.5.1	Test Purpose and Environment	
A.4.6.4.5.2	Test parameters	
A.4.6.4.2.3	Test Requirements	
A.4.6.5	CLI measurements	
A.4.6.5.1	SRS-RSRP measurement with non-DRX	
A.4.6.5.1.1	Test Purpose and Environment	
A.4.6.5.1.2	Test Parameters	
A.4.6.5.1.3	Test Requirements	
A.4.6.5.2	CLI-RSSI measurement with non-DRX	
A.4.6.5.2.1	Test Purpose and Environment	
A.4.6.5.2.2	Test Parameters	
A.4.6.5.2.3	Test Requirements	
A.4.6.6.1.2	Test Requirements	
A.4.6.7	L1-SINR measurement for beam reporting	
A.4.6.7.2	L1-SINR measurement with SSB based CMR and dedicated IMR when DRX is used	
A.4.6.7.2.1	Test Purpose and Environment	
A.4.6.7.2.2	Test parameters	
A.4.6.7.2.3	Test Requirements	816
A.4.6.7.3	L1-SINR measurement with CSI-RS based CMR and dedicated IMR configured when DRX is	
	used	
A.4.6.7.3.1	Test Purpose and Environment	
A.4.6.7.3.2	Test parameters	
A.4.6.7.3.3	Test Requirements	
A.4.6.8	CSI-RS based intra-frequency Measurement	
A.4.6.8.1	EN-DC event triggered reporting tests without gap under DRX	819

A.4.6.8.1.1	Test purpose and Environment	
A.4.6.8.1.2	Test Requirements	
A.4.6.9	CSI-RS based inter-frequency Measurement	
A.4.6.9.1	EN-DC event triggered reporting tests for FR1 cell when non-DRX is used	
A.4.6.9.1.1	Test Purpose and Environment	
A.4.6.9.1.2	Test Requirements	
A.4.7 M A.4.7.1	easurement Performance requirements	
	SS-RSRP	
A.4.7.1.1	EN-DC Intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.1.1.1	Test Purpose and Environment	
A.4.7.1.1.2 A.4.7.1.1.3	Test parameters	
A.4.7.1.1.3 A.4.7.1.2	EN-DC inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.1.2 A.4.7.1.2.1	Test Purpose and Environment	
A.4.7.1.2.1 A.4.7.1.2.2	Test parameters	
A.4.7.1.2.2 A.4.7.1.2.3	Test Requirements	
A.4.7.1.2.3 A.4.7.1.3	Void	
A.4.7.2	SS-RSRQ	
A.4.7.2.1	EN-DC Intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.2.1.1	Test Purpose and Environment	
A.4.7.2.1.2	Test Parameters.	
A.4.7.2.1.3	Test Requirements	
A.4.7.2.2	EN-DC Inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.2.2.1	Test Purpose and Environment	
A.4.7.2.2.2	Test Parameters.	
A.4.7.2.2.3	Test Requirements	
A.4.7.3	SS-SINR.	
A.4.7.3.1	EN-DC Intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.3.1.1	Test Purpose and Environment	
A.4.7.3.1.2	Test Parameters	
A.4.7.3.1.3	Test Requirements	
A.4.7.3.2	EN-DC Inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.3.2.1	Test Purpose and Environment	852
A.4.7.3.2.2	Test Parameters	852
A.4.7.3.2.3	Test Requirements	857
A.4.7.4	L1-RSRP measurement for beam reporting	857
A.4.7.4.1	SSB based L1-RSRP measurement	857
A.4.7.4.1.1	Test Purpose and Environment	
A.4.7.4.1.2	Test parameters	858
A.4.7.4.1.3	Test Requirements	
A.4.7.4.2	CSI-RS based L1-RSRP measurement on resource set with repetition off	
A.4.7.4.2.1	Test Purpose and Environment	
A.4.7.4.2.2	Test parameters	
A.4.7.4.2.3	Test Requirements	
A.4.7.5	SFTD accuracy	
A.4.7.5.1	SFTD accuracy	
A.4.7.5.1.1	Test Purpose and Environment	
A.4.7.5.1.2	Test Parameters	
A.4.7.5.1.3	Test Requirements	
A.4.7.5.2	Void	
A.4.7.5.3 A.4.7.6	Void	
A.4.7.6.1	CLI measurements	
A.4.7.6.1 A.4.7.6.1.1	Test Purpose and Environment	
A.4.7.6.1.1 A.4.7.6.1.2	Test parameters	
A.4.7.6.1.2 A.4.7.6.1.3	Test Requirements	
A.4.7.6.2	EN-DC CLI-RSSI measurement accuracy with FR1 serving cell	
A.4.7.6.2.1	Test Purpose and Environment	
A.4.7.6.2.1 A.4.7.6.2.2	Test parameters	
A.4.7.6.2.3	Test Requirements	
A.4.7.7	L1-SINR measurement for beam reporting	
A.4.7.7.2	L1-SINR measurement with SSB based CMR and dedicated IMR	

A.4.7.7.2.1 Test Purpose and Environment	884
A.4.7.7.2.2 Test parameters	884
A.4.7.7.2.3 Test Requirements	888
A.4.7.7.3 L1-SINR measurement with CSI-RS based CMR and dedicated IMR	888
A.4.7.7.3.1 Test Purpose and Environment	888
A.4.7.7.3.2 Test parameters	888
A.4.7.7.3.3 Test Requirements	891
A.4.7.8 CSI-RSRP	
A.4.7.8.1 EN-DC Intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.8.1.1 Test Purpose and Environment	
A.4.7.8.1.2 Test parameters	
A.4.7.8.1.3 Test Requirements	
A.4.7.8.2 EN-DC inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.8.2.1 Test Purpose and Environment	
A.4.7.8.2.2 Test parameters	
A.4.7.8.2.3 Test parameters Test parameters Test parameters	
A.4.7.9 CSI-RSRQ	
A.4.7.9.1 EN-DC Intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
1 · · · · · · · · · · · · · · · · · · ·	
A.4.7.9.1.2 Test Parameters	
A.4.7.9.1.3 Test Requirements	
A.4.7.9.2 EN-DC Inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.9.2.1 Test Purpose and Environment	
A.4.7.9.2.2 Test Parameters	
A.4.7.9.2.3 Test Requirements	
A.4.7.10 CSI-SINR	
A.4.7.10.1 EN-DC Intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.10.1.1 Test Purpose and Environment	
A.4.7.10.1.2 Test Parameters	913
A.4.7.10.1.3 Test Requirements	917
A.4.7.10.2 EN-DC Inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	917
A.4.7.10.2.1 Test Purpose and Environment	
A.4.7.10.2.2 Test Parameters	918
A.4.7.10.2.3 Test Requirements	922
A.4.8 Void	
A.5 EN-DC tests with one or more NR cells in FR2	
A.5.1 Void	
A.5.2 Void	
A.5.3 RRC_CONNECTED state mobility	923
A.5.3.1 Void	923
A.5.3.2 RRC Connection Mobility Control	923
A.5.3.2.1 Void	923
A.5.3.2.2 Random Access	923
A.5.3.2.2.1 4-step RA type c ontention based random access test in FR2 for PSCell/SCell in EN-DC	923
A.5.3.2.2.2 4-step RA type non-contention based random access test in FR2 for PSCell/SCell in EN-D	
A.5.3.2.2.3 2-step RA type contention based random access test in FR2 for PSCell/SCell in EN-DC	
A.5.3.2.2.4 2-step RA type non-contention based random access test in FR2 for PSCell/SCell in EN-D	
A.5.3.2.3 Void	
A.5.4 Timing	
A.5.4.1 UE transmit timing	
A.5.4.1.1 NR UE Transmit Timing Test for FR2	
· · · · · · · · · · · · · · · · · · ·	
A.5.4.1.1.1 Test Purpose and environment	
A.5.4.1.1.2 Test requirements.	
A.5.4.2 UE timer accuracy	
A.5.4.3 Timing advance	
A.5.4.3.1 EN-DC FR2 timing advance adjustment accuracy	
A.5.4.3.1.1 Test Purpose and Environment	
A.5.4.3.1.2 Test Parameters	
A.5.4.3.1.3 Test Requirements	
A.5.5 Signaling characteristics	
A.5.5.1 Radio link Monitoring	947

A.5.5.1.1	Radio Link Monitoring Out-of-sync Test for FR2 PSCell configured with SSB-based RLM RS in	
	non-DRX mode	
A.5.5.1.1.1	Test Purpose and Environment	
A.5.5.1.1.2	Test Requirements	950
A.5.5.1.2	Radio Link Monitoring In-sync Test for FR2 PSCell configured with SSB-based RLM RS in non-DRX mode	951
A.5.5.1.2.1	Test Purpose and Environment	951
A.5.5.1.2.2	Test Requirements	954
A.5.5.1.3	Radio Link Monitoring Out-of-sync Test for FR2 PSCell configured with SSB-based RLM RS in	
	DRX mode	955
A.5.5.1.3.1	Test Purpose and Environment	955
A.5.5.1.3.2	Test Requirements	958
A.5.5.1.4	Radio Link Monitoring In-sync Test for FR2 PSCell configured with SSB-based RLM RS in	
	DRX mode	958
A.5.5.1.4.1	Test Purpose and Environment	
A.5.5.1.4.2	Test Requirements	962
A.5.5.1.5	EN-DC Radio Link Monitoring Out-of-sync Test for FR2 PSCell configured with CSI-RS-based RLM in non-DRX mode	962
A.5.5.1.6	EN-DC Radio Link Monitoring In-sync Test for FR2 PSCell configured with CSI-RS-based	
	RLM in non-DRX mode	968
A.5.5.1.7	EN-DC Radio Link Monitoring Out-of-sync Test for FR2 PSCell configured with CSI-RS-based	
	RLM in DRX mode	973
A.5.5.1.8	EN-DC Radio Link Monitoring In-sync Test for FR2 PSCell configured with CSI-RS-based	
	RLM in DRX mode	
A.5.5.1.8.2	Test Requirements	
A.5.5.1.9	EN-DC Radio Link Monitoring UE Scheduling Restrictions on FR2	986
A.5.5.1.9.1	Test Purpose and Environment	986
A.5.5.1.9.2	Test Requirements	988
A.5.5.2	Interruption	988
A.5.5.2.1	E-UTRAN – NR FR2 interruptions at transitions between active and non-active during DRX in	
	synchronous EN-DC	988
A.5.5.2.1.1	Test Purpose and Environment	988
A.5.5.2.1.2	Test Requirements	991
A.5.5.2.2	E-UTRAN – NR FR2 interruptions at transitions between active and non-active during DRX in	
	asynchronous EN-DC	991
A.5.5.2.2.1	Test Purpose and Environment	
A.5.5.2.2.2	Test Requirements	994
A.5.5.2.3	E-UTRAN – NR FR2 interruptions during measurements on deactivated NR SCC in	
	synchronous EN-DC	
A.5.5.2.3.1	Test Purpose and Environment	
A.5.5.2.3.2	Test Requirements	998
A.5.5.2.4	E-UTRAN - NR FR2 interruptions during measurements on deactivated NR SCC in	
	asynchronous EN-DC	
A.5.5.2.4.1	Test Purpose and Environment	
A.5.5.2.4.2	Test Requirements	1001
A.5.5.2.5	E-UTRAN – NR FR2 interruptions during measurements on deactivated E-UTRAN SCC in synchronous EN-DC	1002
A.5.5.2.5.1	Test Purpose and Environment	
A.5.5.2.5.2	Test Requirements	1005
A.5.5.2.6	E-UTRAN - NR FR2 interruptions during measurements on deactivated E-UTRAN SCC in	
	asynchronous EN-DC	1005
A.5.5.2.6.1	Test Purpose and Environment	1005
A.5.5.2.6.2	Test Requirements	
A.5.5.2.7	E-UTRAN – NR FR2 interruptions at E-UTRA SRS carrier based switching	
A.5.5.2.7.1	Test Purpose and Environment	
A.5.5.2.7.2	Test Requirements	
	-UTRAN – NR FR2 interruptions at NR SRS carrier based switching	
	Test Purpose and Environment	
A.5.5.2.8.3	Test Requirements	
A.5.5.3	SCell Activation and Deactivation Delay	
A.5.5.3.1	SCell Activation and deactivation of SCell in FR2 intra-band	
A.5.5.3.1.1	Test Purpose and Environment	1014

A.5.5.3.1.2	Test Requirements	1017
A.5.5.3.2	SCell Activation and deactivation of known SCell in FR1 for 160ms SCell measurement cycle	1017
A.5.5.3.2.1	Test Purpose and Environment	1017
A.5.5.3.2.2	Test Requirements	
A.5.5.3.3	Void	
A.5.5.3.4	Void	
A.5.5.3.5	SCell Activation and deactivation of SCell in FR2	
A.5.5.3.5.1	Test Purpose and Environment	
A.5.5.3.5.2	Test Requirements	
A.5.5.3.6	Multiple SCell Activation and deactivation of one unknown SCell and one known SCell in FR2	
A.5.5.3.6.1	Test Purpose and Environment	
A.5.5.3.6.2	Test Requirements	
A.5.5.3.7	Direct SCell activation at SCell addition of known SCell in FR2	
A.5.5.3.7.1	Test Purpose and Environment	
A.5.5.3.7.2	Test Requirements	
A.5.5.4	Void	
A.5.5.5	Beam Failure Detection and Link recovery procedures	1034
A.5.5.5.1	EN-DC Beam Failure Detection and Link Recovery Test for FR2 PSCell configured with SSB-	
	based BFD and LR in non-DRX mode	
A.5.5.5.1.1	Test Purpose and Environment	1034
A.5.5.5.1.2	Test Requirements	1040
A.5.5.5.2	EN-DC Beam Failure Detection and Link Recovery Test for FR2 PSCell configured with SSB-	
	based BFD and LR in DRX mode	1040
A.5.5.5.2.1	Test Purpose and Environment	
A.5.5.5.2.2	Test Requirements	
A.5.5.5.3	EN-DC Beam Failure Detection and Link Recovery Test for FR2 PSCell configured with CSI-	10.0
110.000	RS-based BFD and LR in non-DRX mode	1046
A.5.5.5.3.1	Test Purpose and Environment	
A.5.5.5.3.2	Test Requirements	
A.5.5.5.4	EN-DC Beam Failure Detection and Link Recovery Test for FR2 PSCell configured with CSI-	1032
A.J.J.J.4	RS-based BFD and LR in DRX mode	1052
A 5 5 5 4 1		
A.5.5.5.4.1	Test Purpose and Environment	
A.5.5.5.4.2	Test Requirements	1058
A.5.5.5.5	EN-DC scheduling availability restriction during Beam Failure Detection and Link Recovery for	1050
	FR2 PSCell configured with SSB-based BFD and LR in non-DRX mode	
A.5.5.5.5.1	Test Purpose and Environment	
A.5.5.5.5.2	Test Requirements	1064
A.5.5.5.6	EN-DC Beam Failure Detection and Link Recovery Test for FR2 SCell configured with CSI-RS-	
	based BFD and LR in non-DRX mode	1064
A.5.5.5.6.1	Test Purpose and Environment	1064
A.5.5.5.6.2	Test Requirements	1069
A.5.5.5.7	EN-DC Beam Failure Detection and Link Recovery Test for FR2 SCell configured with CSI-RS-	
	based BFD and LR in DRX mode	1069
A.5.5.5.7.1	Test Purpose and Environment	1069
A.5.5.5.7.2	Test Requirements	
A.5.5.6	Active BWP switch	
A.5.5.6.1	DCI-based and Timer-based Active BWP Switch	
A.5.5.6.1.1	E-UTRAN – NR PSCell FR2 DL active BWP switch with non-DRX in synchronous EN-DC.	
A.5.5.6.1.1.1	Test Purpose and Environment	
A.5.5.6.1.1.2	Test Requirements	
A.5.5.6.1.2	E-UTRAN – NR PSCell FR2 with FR2 SCell DL active BWP switch in non-DRX in	10//
A.S.S.0.1.2	synchronous EN-DC	1070
A.5.5.6.2	RRC-based Active BWP Switch	
A.5.5.6.2.1		
	E-UTRAN – NR PSCell FR2 DL active BWP switch with non-DRX in synchronous EN-DC.	
	nultaneous DCI-based and Timer-based Active BWP Switch on multiple CCs	1088
A.5.5.6.3.1	E-UTRAN – NR PSCell FR2 and NR SCell FR2 DL active BWP switch on multiple CCs in	1000
	synchronous EN-DC	
A.5.5.6.3.1.1	Test Purpose and Environment.	
A.5.5.6.3.1.2	Test Requirements	
A.5.5.6.4	SCell dormancy switch	
A.5.5.6.4.1	E-UTRAN – NR FR2 PSCell SCell dormancy switch of single FR2 SCell inside active time	
A.5.5.6.4.1.1	Test Purpose and Environment	1093

A.5.5.6.4.1.2	Test Requirements	
A.5.5.6.4.2	E-UTRAN – NR FR1 PSCell SCell dormancy switch of two FR2 SCells outside active time.	. 1097
A.5.5.6.4.2.1	Test Purpose and Environment	. 1097
A.5.5.6.4.2.2	Test Requirements	
A.5.5.6.5	Simultaneous RRC-based Active BWP Switch on multiple CCs	
A.5.5.6.5.1	E-UTRAN – NR PSCell FR2 and NR SCell FR2 DL active BWP switch on multiple CCs	
11.0.0.0.0.1	with non-DRX in synchronous EN-DC	110/
A 5 5 7		
A.5.5.7	PSCell addition and release delay	
A.5.5.7.1	Addition and Release Delay of NR PSCell	
A.5.5.7.1.1	Test purpose and environment	
A.5.5.7.1.2	Test Requirements	
A.5.5.8	Active TCI state switch delay	
A.5.5.8.1	MAC-CE based active TCI state switch	.1111
A.5.5.8.1.1	E-UTRAN – NR PSCell FR2 active TCI state switch for a known TCI state	.1111
A.5.5.8.1.1.1	Test Purpose and Environment	
A.5.5.8.1.1.2	Test Requirements	
A.5.5.8.2	RRC based active TCI state switch	
A.5.5.8.2.1	E-UTRAN – NR PSCell FR2 active TCI state switch for a known TCI state	
A.5.5.8.2.1.1	Test Purpose and Environment.	
A.5.5.8.2.1.2	Test Requirements	
A.5.5.9	Uplink spatial relation switch delay	
A.5.5.9.1	MAC-CE based uplink spatial relation switch	
A.5.5.9.1.1	E-UTRAN – NR PSCell FR2 uplink spatial relation switch for a known spatial relation	. 1116
A.5.5.9.1.1.1	Test Purpose and Environment	.1116
A.5.5.9.1.1.2	Test Requirements	. 1119
A.5.5.9.2	RRC based spatial relation switch	
A.5.5.9.2.1	E-UTRAN – NR PSCell FR2 spatial relation switch associated with a known DL-RS	
A.5.5.9.2.1.1	Test Purpose and Environment.	
A.5.5.9.2.1.1	Test Requirements	
A.5.5.10	UE specific CBW change.	
A.5.5.10.1	UE specific CBW change on FR2 NR PSCell	
A.5.5.10.1.1	Test Purpose and Environment	
A.5.5.10.1.2	Test Requirements	
A.5.6 Me	easurement procedure	. 1126
A.5.6.1	Intra-frequency Measurements	.1126
A.5.6.1.1	EN-DC event triggered reporting test without gap under non-DRX	.1126
A.5.6.1.1.1	Test purpose and Environment	
A.5.6.1.1.2	Test Requirements	
A.5.6.1.2	EN-DC event triggered reporting test without gap under DRX	
A.5.6.1.2.1	Test purpose and Environment	
A.5.6.1.2.2	Test Requirements	1120
A.5.6.1.3	EN-DC event triggered reporting test with per-UE gaps under non-DRX	
A.5.6.1.3.1	Test purpose and Environment	
A.5.6.1.3.2	Test Requirements	
A.5.6.1.4	EN-DC event triggered reporting test with per-UE gaps under DRX	
A.5.6.1.4.1	Test purpose and Environment	
A.5.6.1.4.2	Test Requirements	. 1140
A.5.6.2	Inter-frequency Measurements	. 1141
A.5.6.2.1	EN-DC event triggered reporting tests for FR2 cell without SSB time index detection when DRX	
	is not used	
A.5.6.2.1.1	Test Purpose and Environment	
A.5.6.2.1.2	Test Purpose and Environment Test Requirements	
A.5.6.2.2	EN-DC event triggered reporting tests for FR2 cell without SSB time index detection when DRX	
A.J.0.2.2		
A 5 6 2 2 1	is used	
A.5.6.2.2.1	Test Purpose and Environment	
A.5.6.2.2.2	Test Requirements	. 1148
A.5.6.2.3	EN-DC event triggered reporting tests for FR2 cell with SSB time index detection when DRX is	
	not used	
A.5.6.2.3.1	Test Purpose and Environment	. 1148
A.5.6.2.3.2	Test Requirements	
A.5.6.2.4	EN-DC event triggered reporting tests for FR2 cell with SSB time index detection when DRX is	
	used	. 1152

A.5.6.2.4.1	Test Purpose and Environment	1152
A.5.6.2.4.2	Test Requirements	
A.5.6.2.5	EN-DC event triggered reporting tests for FR2 cell without SSB time index detection when DR	X
	is not used	
A.5.6.2.5.1	Test Purpose and Environment	1156
A.5.6.2.5.2	Test Requirements	
A.5.6.2.6	EN-DC event triggered reporting tests for FR2 cell without SSB time index detection when DR	
	is used.	
A.5.6.2.6.1	Test Purpose and Environment	
A.5.6.2.6.2	Test Requirements	
A.5.6.2.7	EN-DC event triggered reporting tests for FR2 cell with SSB time index detection when DRX i	
11.0.0.2.7	not used	
A.5.6.2.7.1	Test Purpose and Environment	
A.5.6.2.7.2	Test Requirements	
A.5.6.2.8	EN-DC event triggered reporting tests for FR2 cell with SSB time index detection when DRX i	
11.5.0.2.0	used	
A.5.6.2.8.1	Test Purpose and Environment	
A.5.6.2.8.2	Test Requirements	
A.5.6.3	L1-RSRP measurement for beam reporting	
A.5.6.3.1	SSB based L1-RSRP measurement when DRX is not used	
A.5.6.3.1.1	Test Purpose and Environment	
A.5.6.3.1.1		
	Test parameters	
A.5.6.3.1.3	Test Requirements	
A.5.6.3.2	SSB based L1-RSRP measurement when DRX is used	
A.5.6.3.2.1	Test Purpose and Environment	
A.5.6.3.2.2	Test parameters	
A.5.6.3.2.3	Test Requirements	
A.5.6.3.3	CSI-RS based L1-RSRP measurement when DRX is not used	
A.5.6.3.3.1	Test Purpose and Environment	
A.5.6.3.3.2	Test parameters	
A.5.6.3.3.3	Test Requirements	
A.5.6.3.4	CSI-RS based L1-RSRP measurement when DRX is used	
A.5.6.3.4.1	Test Purpose and Environment	
A.5.6.3.4.2	Test parameters	
A.5.6.3.4.3	Test Requirements	
A.5.6.4	CLI measurements	
A.5.6.4.1	SRS-RSRP measurement with DRX	
A.5.6.4.1.1	Test Purpose and Environment	
A.5.6.4.1.2	Test Parameters	
A.5.6.4.1.3	Test Requirements	
A.5.6.4.2	CLI-RSSI measurement with DRX	1190
A.5.6.4.2.1	Test Purpose and Environment	1190
A.5.6.4.2.2	Test Parameters	1191
A.5.6.4.2.3	Test Requirements	1193
A.5.6.5	Measurements with autonomous gaps	
A.5.6.5.1	EN-DC inter-frequency CGI identification of NR neighbor cell in FR2	1193
A.5.6.5.1.1	Test Purpose and Environment	1193
A.5.6.5.1.2	Test Requirements	
A.5.6.6	L1-SINR measurement for beam reporting	
A.5.6.6.2	L1-SINR measurement with SSB based CMR and dedicated IMR when DRX is not used	
A.5.6.6.2.1	Test Purpose and Environment	
A.5.6.6.2.2	Test parameters	
A.5.6.6.2.3	Test Requirements	
A.5.6.6.3	L1-SINR measurement with CSI-RS based CMR and dedicated IMR configured when DRX is	
	not used.	1203
A.5.6.6.3.1	Test Purpose and Environment	
A.5.6.6.3.2	Test parameters	
A.5.6.6.3.3	Test Requirements	
A.5.6.7	CSI-RS based Intra-frequency Measurements	
A.5.6.7.1	EN-DC event triggered reporting test without gap under non-DRX	
A.5.6.7.1.1	Test purpose and Environment	
A.5.6.7.1.2	Test Requirements	
. 1.0.0.7.1.2	requirement	1200

A.5.6.8	CSI-RS based Inter-frequency Measurements	
A.5.6.8.1	EN-DC event triggered reporting tests for NR FR2 cell when DRX is used	. 1208
A.5.6.8.1.1	Test Purpose and Environment	. 1208
A.5.6.8.1.2	Test Requirements	. 1213
A.5.7 M	leasurement Performance requirements	. 1213
A.5.7.1	SS-RSRP	. 1213
A.5.7.1.1	EN-DC intra-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	. 1213
A.5.7.1.1.1	Test Purpose and Environment	. 1213
A.5.7.1.1.2	Test parameters	. 1214
A.5.7.1.1.3	Test Requirements	. 1216
A.5.7.1.2	EN-DC inter-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	. 1217
A.5.7.1.2.1	Test Purpose and Environment	. 1217
A.5.7.1.2.2	Test parameters	. 1217
A.5.7.1.2.3	Test Requirements	. 1221
A.5.7.1.3	EN-DC inter-frequency measurement accuracy with FR1 serving cell and FR2 target cell	. 1222
A.5.7.1.3.1	Test Purpose and Environment	. 1222
A.5.7.1.3.2	Test parameters	. 1222
A.5.7.1.3.3	Test Requirements	. 1225
A.5.7.2	SS-RSRQ	. 1226
A.5.7.2.1	EN-DC Intra-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell	. 1226
A.5.7.2.1.1	Test Purpose and Environment	. 1226
A.5.7.2.1.2	Test Parameters	. 1226
A.5.7.2.1.3	Test Requirements	. 1229
A.5.7.2.2	EN-DC Inter-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell	. 1229
A.5.7.2.2.1	Test Purpose and Environment	. 1229
A.5.7.2.2.2	Test Parameters	
A.5.7.2.2.3	Test Requirements	. 1231
A.5.7.3	SS-SINR	. 1232
A.5.7.3.1	EN-DC Intra-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell	. 1232
A.5.7.3.1.1	Test Purpose and Environment	. 1232
A.5.7.3.1.2	Test Parameters	. 1232
A.5.7.3.1.3	Test Requirements	. 1235
A.5.7.3.2	EN-DC Inter-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell	. 1235
A.5.7.3.2.1	Test Purpose and Environment	
A.5.7.3.2.2	Test Parameters	. 1235
A.5.7.3.2.3	Test Requirements	. 1237
A.5.7.4	L1-RSRP measurement for beam reporting	. 1237
A.5.7.4.1	SSB based L1-RSRP measurement	. 1237
A.5.7.4.1.1	Test Purpose and Environment	. 1237
A.5.7.4.1.2	Test parameters	. 1238
A.5.7.4.1.3	Test Requirements	. 1240
A.5.7.4.2	CSI-RS based L1-RSRP measurement on resource set with repetition off	. 1241
A.5.7.4.2.1	Test Purpose and Environment	. 1241
A.5.7.4.2.2	Test parameters	. 1241
A.5.7.4.2.3	Test Requirements	. 1243
A.5.7.5	CLI measurements	
A.5.7.5.1	EN-DC SRS-RSRP measurement accuracy with FR2 serving cell	. 1244
A.5.7.5.1.1	Test Purpose and Environment	. 1244
A.5.7.5.1.2	Test parameters	. 1244
A.5.7.5.1.3	Test Requirements	. 1247
A.5.7.5.2	EN-DC CLI-RSSI measurement accuracy with FR2 serving cell	. 1248
A.5.7.5.2.1	Test Purpose and Environment	
A.5.7.5.2.2	Test parameters	
A.5.7.5.2.3	Test Requirements	
A.5.7.6	L1-SINR measurement for beam reporting	
A.5.7.6.2	L1-SINR measurement with SSB based CMR and dedicated IMR	
A.5.7.6.2.1	Test Purpose and Environment	
A.5.7.6.2.2	Test parameters	
A.5.7.6.2.3	Test Requirements	
A.5.7.6.3	L1-SINR measurement with CSI-RS based CMR and dedicated IMR	
A.5.7.6.3.1	Test Purpose and Environment	
A.5.7.6.3.2	Test parameters	. 1257

A.5.7.6.3.3		Requirements	
A.5.7.7			
A.5.7.7.1	EN-DC i	intra-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	1259
A.5.7.7.1.1	Test l	Purpose and Environment	1259
A.5.7.7.1.2	Test p	parameters	1260
A.5.7.7.1.3		Requirements	
A.5.7.7.2	EN-DC i	inter-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	1263
A.5.7.7.2.1	Test l	Purpose and Environment	1263
A.5.7.7.2.2	Test p	parameters	1263
A.5.7.7.2.3	Test l	Requirements	1267
A.5.7.8	CSI-RSRQ		1268
A.5.7.8.1	EN-DC I	Intra-frequency measurement accuracy with FR2 serving cell and FR2 target cell	1268
A.5.7.8.1.1		Purpose and Environment	
A.5.7.8.1.2	Test l	Parameters	1268
A.5.7.8.1.3		Requirements	
A.5.7.8.2	EN-DC I	Inter-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell.	1270
A.5.7.8.2.1		Purpose and Environment	
A.5.7.8.2.2		Parameters	
A.5.7.8.2.3		Requirements	
A.5.7.9			
A.5.7.9.1		Intra-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell.	
A.5.7.9.1.1		Purpose and Environment	
A.5.7.9.1.2		Parameters	
A.5.7.9.1.3		Requirements	
A.5.7.9.2		Inter-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell.	
A.5.7.9.2.1	Test l	Purpose and Environment	1275
A.5.7.9.2.2		Parameters	
A.5.7.9.2.3	Test l	Requirements	1278
A.5.8 V	oid		1278
A.6 NR s	tandalone tes	sts with all NR cells in FR1	1011
		E state mobility	
A.6.1.1		etion to NR	
A.6.1.1.1		election to FR1 intra-frequency NR case	
A.6.1.1.1		Purpose and Environment	
A.6.1.1.1.2		Parameters	
A.6.1.1.1.3		Requirements	
A.6.1.1.2		ection to FR1 inter-frequency NR case	
A.6.1.1.2.1		Purpose and Environment	
A.6.1.1.2.1		Parameters.	
A.6.1.1.2.3		Requirements	
A.6.1.1.3		election to FR1 intra-frequency NR case for UE fulfilling low mobility relaxed	1013
A.0.1.1.3		ment criterion	1010
A.6.1.1.3.1		Purpose and Environment	
A.6.1.1.3.1		Parameters	
A.6.1.1.3.2		Requirements	
A.6.1.1.4		election to FR1 intra-frequency NR case for UE fulfilling not-at-cell edge relaxed	1024
A.0.1.1.4		ment criterionment criterion	102/
A.6.1.1.4.1		Purpose and Environment	
A.6.1.1.4.1 A.6.1.1.4.2		Parameters	
A.6.1.1.4.3		Requirements	
A.6.1.1.5		ection to FR1 inter-frequency NR case for UE fulfilling low mobility relaxed	1027
A.0.1.1.3		ment criterion	1027
A.6.1.1.5.1		Purpose and Environment	
A.6.1.1.5.1 A.6.1.1.5.2		Parameters	
A.6.1.1.5.2 A.6.1.1.5.3		Requirements	
A.6.1.1.6		lection to FR1 inter-frequency NR case for UE fulfilling not-at-cell edge relaxed	1032
11.0.1.1.0		ment criterionment	1033
A.6.1.1.6.1		Purpose and Environment	
A.6.1.1.6.2		Parameters	
A.6.1.1.6.3		Requirements	
4 4.0.1.1.0.0	1 031 1	2.50d WII AIIIAII (1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.	/

A.6.1.1.7	Cell reselection to FR1 intra-frequency NR case for UE configured with highSpeedMeasFlag-	1029
A.6.1.1.7.1		
A.6.1.1.7.2	*	
A.6.1.1.7.3		
A.6.1.2	Inter-RAT E-UTRAN cell re-selection	
A.6.1.2.1	Cell reselection to higher priority E-UTRAN	
A.6.1.2.1.1	The state of the s	
A.6.1.2.1.2		
A.6.1.2.1.3		
A.6.1.2.2	Cell reselection to lower priority E-UTRAN	
A.6.1.2.2.1		
A.6.1.2.2.2	1	
A.6.1.2.2.3		
A.6.1.2.3	Cell reselection to lower priority E-UTRAN for UE fulfilling low mobility relaxed measuremen	
A.0.1.2.3	criterion	
A.6.1.2.3.1		
A.6.1.2.3.2	•	
A.6.1.2.3.3		
A.6.1.2.4	Cell reselection to lower priority E-UTRAN for UE fulfilling not-at-cell edge relaxed	1032
11.0.1.2.4	measurement criterion	1053
A.6.1.2.4.1		
A.6.1.2.4.2		
A.6.1.2.4.3		
A.6.1.2.5	Cell reselection to lower priority E-UTRAN cell for UE configured with highSpeedMeasFlag-	1050
A.0.1.2.3	r16	1057
A.6.1.2.5.1		
A.6.1.2.5.2		
A.6.1.2.5.3		
A.6.1.1.7	Void	
	SA: RRC_INACTIVE state mobility	
	RRC_CONNECTED state mobility	
A.6.3.1	Handover	
A.6.3.1.1	Intra-frequency handover from FR1 to FR1; known target cell	
A.6.3.1.1.1		
A.6.3.1.1.2		
A.6.3.1.1.3	Test Requirements	
A.6.3.1.2	Intra-frequency handover from FR1 to FR1; unknown target cell	
A.6.3.1.2.1	• •	
A.6.3.1.2.2		
A.6.3.1.2.3		
A.6.3.1.3	Inter-frequency handover from FR1 to FR1; unknown target cell	
A.6.3.1.3.1		
A.6.3.1.3.2		
	Test Requirements	
A.6.3.1.4	SA NR - E-UTRAN handover	
A.6.3.1.4.1		
A.6.3.1.4.2		
A.6.3.1.5	SA NR - E-UTRAN handover with unknown target cell	
A.6.3.1.5.1		
A.6.3.1.5.2	1	
A.6.3.1.6	SA NR - UTRAN FDD handover	
A.6.3.1.6.1		
A.6.3.1.6.2		
A.6.3.1.7	Intra-frequency handover in FR1; synchronous scenario	
A.6.3.1.7.1		
A.6.3.1.7.2		
	Test Requirements.	
A.6.3.1.8	Intra-frequency handover in FR1; asynchronous scenario	
A.6.3.1.8.1		
A.6.3.1.8.2	•	
	Test Requirements.	1099

A.6.3.1.9	Intra-band inter-frequency synchronous DAPS handover test in SA for FR1	
A.6.3.1.9.1	Test Purpose and Environment	
A.6.3.1.9.2	Test Parameters	1100
A.6.3.1.9.3 Test	t Requirements	1104
A.6.3.1.10	Intra-band inter-frequency asynchronous DAPS handover test in SA for FR1	1104
A.6.3.1.10.1	Test Purpose and Environment	
A.6.3.1.10.2	Test Parameters	
A 6 3 1 10 3 Te	st Requirements	
A.6.3.1.11	Inter-band inter-frequency synchronous DAPS handover from FR1 to FR1	
A.6.3.1.11	Test Purpose and Environment	
A.6.3.1.11.2	Test Parameters	
	st Requirements	
A.6.3.1.12	Inter-band inter-frequency asynchronous DAPS handover from FR1 to FR1	
A.6.3.1.12.1	Test Purpose and Environment	
A.6.3.1.12.2	Test Parameters	
	st Requirements	
A.6.3.2 R	RC Connection Mobility Control	1122
A.6.3.2.1	SA: RRC Re-establishment	1122
A.6.3.2.1.1	Intra-frequency RRC Re-establishment in FR1	1122
A.6.3.2.1.2	Inter-frequency RRC Re-establishment in FR1	1126
A.6.3.2.1.3	Intra-frequency RRC Re-establishment in FR1 without serving cell timing	
A.6.3.2.2	Random Access	
A.6.3.2.2.1	4-step RA type contention based random access test in FR1 for NR standalone	
A.6.3.2.2.1 A.6.3.2.2.2	4-step RA type non-contention based random access test in FR1 for NR standarone	
	1 71	
A.6.3.2.2.3	2-step RA type contention based random access test in FR1 for NR standalone	
A.6.3.2.2.4	2-step RA type non-contention based test in FR1 for NR standalone	
A.6.3.2.3	SA: RRC Connection Release with Redirection	
A.6.3.2.3.1	Redirection from NR in FR1 to NR in FR1	
A.6.3.2.3.2	Redirection from NR in FR1 to E-UTRAN	1155
A.6.3.3 Condition	onal handover	1162
A.6.3.3.1	Intra-frequency conditional handover from FR1 to FR1	1162
A.6.3.3.1.1	Test Purpose and Environment	1162
A.6.3.3.1.2	Test Parameters	
	t Requirements	
A.6.3.3.2	Inter-frequency conditional handover from FR1 to FR1	
A.6.3.3.2.1	Test Purpose and Environment	
A.6.3.3.2.2	Test Parameters	
	t Requirements	
	ng	
	E transmit timing	
A.6.4.1.1	NR UE Transmit Timing Test for FR1	
A.6.4.1.1.1	Test Purpose and environment	
A.6.4.1.1.2	Test requirements	1174
A.6.4.2 U	Æ timer accuracy	1174
A.6.4.3 T	iming advance	1174
A.6.4.3.1	SA FR1 timing advance adjustment accuracy	
A.6.4.3.1.1	Test Purpose and Environment	
A.6.4.3.1.2	Test Parameters.	
A.6.4.3.1.3	Test Requirements	
	alling characteristics	
C	· ·	
	adio link Monitoring	
A.6.5.1.1	Radio Link Monitoring Out-of-sync Test for FR1 PCell configured with SSB-based RLM RS in	
	non-DRX mode	
A.6.5.1.1.1	Test Purpose and Environment	
A.6.5.1.1.2	Test Requirements	
A.6.5.1.2	Radio Link Monitoring In-sync Test for FR1 PCell configured with SSB-based RLM RS in nor	
	DRX mode	1183
A.6.5.1.2.1	Test Purpose and Environment	
A.6.5.1.2.2	Test Requirements	
A.6.5.1.3	Radio Link Monitoring Out-of-sync Test for FR1 PCell configured with SSB-based RLM RS in	
	DRX mode	
A.6.5.1.3.1	Test Purpose and Environment	

A.6.5.1.3.2	Test Requirements	
A.6.5.1.4	Radio Link Monitoring In-sync Test for FR1 PCell configured with SSB-based RLM RS in DRX	
	mode	
A.6.5.1.4.1	Test Purpose and Environment	
A.6.5.1.4.2	Test Requirements	
A.6.5.1.5	Radio Link Monitoring Out-of-sync Test for FR1 PCell configured with CSI-RS-based RLM in	1201
A.0.J.1.J	non-DRX mode	1201
A C 5 1 5 1		
A.6.5.1.5.1	Test Purpose and Environment	
A.6.5.1.5.2	Test Requirements	1206
A.6.5.1.6	Radio Link Monitoring In-sync Test for FR1 PCell configured with CSI-RS-based RLM in non-DRX mode	1206
A.6.5.1.6.1	Test Purpose and Environment	
A.6.5.1.6.2	Test Requirements	
A.6.5.1.7	Radio Link Monitoring Out-of-sync Test for FR1 PCell configured with CSI-RS-based RLM in	1212
11.0.0.1.7	DRX mode	1212
A.6.5.1.7.1	Test Purpose and Environment	
A.6.5.1.7.2		
	Test Requirements	1210
A.6.5.1.8	Radio Link Monitoring In-sync Test for FR1 PCell configured with CSI-RS-based RLM in DRX	1216
A C 5 1 0 1	mode	
A.6.5.1.8.1	Test Purpose and Environment	
A.6.5.1.8.2	Test Requirements	
A.6.5.2	Interruption	
A.6.5.2.1	Interruptions during measurements on deactivated NR SCC in FR1	
A.6.5.2.1.2	Test Requirements	1226
A.6.5.2.2	SA interruptions at NR SRS carrier based switching	1227
A.6.5.2.2.1	Test Purpose and Environment	1227
A.6.5.2.2.2	Test Parameters	1227
A.6.5.2.2.3	Test Requirements	
A.6.5.3	SCell Activation and Deactivation Delay	
A.6.5.3.1	SCell Activation and deactivation of known SCell in FR1 in non-DRX for 160ms SCell	
11.0.0.0.1	measurement cycle	1230
A.6.5.3.1.1	Test Purpose and Environment	
A.6.5.3.1.2	Test Requirements	
A.6.5.3.2	SCell Activation and deactivation of known SCell in FR1 in non-DRX for 320ms SCell	1233
A.0.3.3.2		1224
A 6 5 2 2 1	measurement cycle	
A.6.5.3.2.1	1	
A.6.5.3.2.2	Test Requirements	
A.6.5.3.3	SCell Activation and deactivation of unknown SCell in FR1 in non-DRX	
A.6.5.3.3.1	Test Purpose and Environment	
A.6.5.3.3.2	Test Requirements	1235
A.6.5.3.4	Direct SCell activation at SCell addition of known SCell in FR1	
A.6.5.3.4.1	Test Purpose and Environment	
A.6.5.3.4.2	Test Requirements	1239
A.6.5.3.5	Direct SCell activation at handover with known SCell in FR1	1239
A.6.5.3.5.1	Test Purpose and Environment	1239
A.6.5.3.5.2	Test Requirements	1243
A.6.5.4	UE UL carrier RRC reconfiguration Delay	
A.6.5.4.1	UE UL carrier RRC reconfiguration Delay	
A.6.5.4.1.1	Test Purpose and Environment	
A.6.5.4.1.2	Test Requirements	
A.6.5.4.2	Void	
A.6.5.5	Beam Failure Detection and Link recovery procedures	
A.6.5.5.1	Beam Failure Detection and Link Recovery Test for FR1 PCell configured with SSB-based BFD	1233
A.0.3.3.1	and LR in non-DRX mode	1255
A.6.5.5.1.1	Test Purpose and Environment	
A.6.5.5.2	Beam Failure Detection and Link Recovery Test for FR1 PCell configured with SSB-based BFD	
	and LR in DRX mode	1260
A.6.5.5.2.1	Test Purpose and Environment	
A.6.5.5.2.2	Test Requirements	
A.6.5.5.3	Beam Failure Detection and Link Recovery Test for FR1 PCell configured with CSI-RS-based	-201
11.0.3.3.3	BFD and LR in non-DRX mode	1267
A.6.5.5.3.1	Test Purpose and Environment	
r.v.J.J.J.1	10st 1 til pose and Environment	120/

A.6.5.5.3.2	Test Requirements	. 1273
A.6.5.5.4	Beam Failure Detection and Link Recovery Test for FR1 PCell configured with CSI-RS-based	
	BFD and LR in DRX mode.	. 1273
A.6.5.5.4.1	Test Purpose and Environment	
A.6.5.5.4.2	Test Requirements	
A.6.5.5.5	Beam Failure Detection and Link Recovery Test for FR1 SCell configured with CSI-RS-based	
11.0.0.0.0	BFD and SSB-based LR in non-DRX mode	1279
A.6.5.5.5.1	Test Purpose and Environment	
A.6.5.5.5.2	•	
	Test Requirements	. 1283
A.6.5.5.6	Beam Failure Detection and Link Recovery Test for FR1 SCell configured with CSI-RS-based	100
	BFD and SSB-based LR in DRX mode	
A.6.5.5.6.1	Test Purpose and Environment	
A.6.5.5.6.2	Test Requirements	
A.6.5.6	Active BWP switch	
A.6.5.6.1	DCI-based and Timer-based Active BWP Switch	. 1288
A.6.5.6.1.1	NR FR1- NR FR1 DL active BWP switch of SCell with non-DRX in SA	. 1288
A.6.5.6.1.2	NR FR1 DL active BWP switch with non-DRX in SA	. 1294
A.6.5.6.2	RRC-based Active BWP Switch	
A.6.5.6.2.1	NR FR1 DL active BWP switch of Cell with non-DRX in SA	
	ultaneous DCI-based and Timer-based Active BWP Switch on multiple CCs	
A.6.5.6.3.1	NR FR1- NR FR1 DL active BWP switch on multiple CCs with non-DRX in SA	
A.6.5.6.3.1.1	Test Purpose and Environment	
A.6.5.6.3.1.2	Test Requirements	
A.6.5.6.4	SCell dormancy switch	
A.6.5.6.4.1	NR FR1 PCell SCell dormancy switch of single FR1 SCell outside active time	
A.6.5.6.4.1.1	Test Purpose and Environment.	
A.6.5.6.4.1.2	Test Requirements	
A.6.5.6.4.2	NR FR1 PCell SCell dormancy switch of two FR1 SCells inside active time	. 1314
A.6.5.6.4.2.1	Test Purpose and Environment	. 1314
A.6.5.6.4.2.2	Test Requirements	. 1318
A.6.5.6.5	Simultaneous RRC-based Active BWP Switch on multiple CCs	. 1318
A.6.5.6.5.1	NR FR1- NR FR1 DL active BWP switch on multiple CCs with non-DRX in SA	
A.6.5.7	DL interruptions at switching between two uplink carriers	
A.6.5.7.1	DL interruptions at switching between two uplink carriers in FDD-TDD CA	
A.6.5.7.1.1	Test Purpose and Environment	
A.6.5.7.1.2	Test Requirements	
A.6.5.7.2	DL interruptions at switching between two uplink carriers in TDD-TDD CA	
A.6.5.7.2.1		
	Test Purpose and Environment	
A.6.5.7.2.2	Test Requirements	. 1330
A.6.5.8.1	UE specific CBW change on PCell in FR1 in non-DRX	
A.6.5.8.1.1	Test Purpose and Environment	
A.6.5.8.1.2	Test Requirements	
A.6.6 Me	asurement procedure	. 1334
A.6.6.1	Intra-frequency Measurements	. 1334
A.6.6.1.1	SA event triggered reporting tests without gap under non-DRX	. 1334
A.6.6.1.1.1	Test purpose and Environment	. 1334
A.6.6.1.1.2	Test parameters	
A.6.6.1.1.3	Test Requirements	
A.6.6.1.2	SA event triggered reporting tests without gap under DRX	
A.6.6.1.2.1	Test purpose and Environment	
A.6.6.1.2.2	Test parameters	
	•	
A.6.6.1.2.3	Test Requirements	
A.6.6.1.3	SA event triggered reporting tests with per-UE gaps under non-DRX	
A.6.6.1.3.1	Test purpose and Environment	
A.6.6.1.3.2	Test parameters	
A.6.6.1.3.3	Test Requirements	
A.6.6.1.4	SA event triggered reporting tests with per-UE gaps under DRX	
A.6.6.1.4.1	Test purpose and Environment	
A.6.6.1.4.2	Test parameters	. 1346
A.6.6.1.4.3	Test Requirements	. 1350
A.6.6.1.5	SA event triggered reporting tests without gap under non-DRX with SSB index reading	
A.6.6.1.5.1	Test purpose and Environment	. 1350

A.6.6.1.5.2	Test parameters	1350
A.6.6.1.5.3	Test Requirements	1352
A.6.6.1.6	SA event triggered reporting tests with per-UE gaps under non-DRX with SSB index reading	1353
A.6.6.1.6.1	Test purpose and Environment	
A.6.6.1.6.2	Test parameters	1353
A.6.6.1.6.3	Test Requirements	
A.6.6.1.7	SA event triggered reporting tests under DRX for UE configured with highSpeedMeasFlag-r16	
A.6.6.1.7.1	Test purpose and Environment	
A.6.6.1.7.2	Test parameters	
A.6.6.1.7.3	Test Requirements	
A.6.6.2	Inter-frequency Measurements	
A.6.6.2.1	SA event triggered reporting tests for FR1 without SSB time index detection when DRX is not	100)
11.0.0.2.1	used	1359
A.6.6.2.1.1	Test Purpose and Environment	
A.6.6.2.1.2	Test Requirements	
A.6.6.2.2	SA event triggered reporting tests for FR1 without SSB time index detection when DRX is used	
A.6.6.2.2.1	Test Purpose and Environment	
A.6.6.2.2.2	Test Requirements	
A.6.6.2.3	Void	
A.6.6.2.4	Void	
A.6.6.2.5	SA event triggered reporting tests for FR1 with SSB time index detection when DRX is not used.	
A.6.6.2.5.1	Test Purpose and Environment	
A.6.6.2.5.1	Test Requirements	
A.6.6.2.6	SA event triggered reporting tests for FR1 with SSB time index detection when DRX is used	
A.6.6.2.6.1	Test Purpose and Environment	
A.6.6.2.6.2	Test Requirements	
A.6.6.2.7	Void	
A.6.6.2.8	Void	
A.6.6.2.9	SA event triggered reporting tests with additional mandatory gap pattern	
A.6.6.2.9.1	Test Purpose and Environment	
A.6.6.2.9.2	Test Requirements	
A.6.6.2.10	SA event triggered reporting tests for FR1 when DRX is used	
A.6.6.2.10.1	Test Purpose and Environment	
A.6.6.2.10.2	Test Requirements	
A.6.6.3	Inter-RAT Measurements.	
A.6.6.3.1	SA NR - E-UTRAN event-triggered reporting in non-DRX in FR1	
A.6.6.3.1.1	Test Purpose and Environment	
A.6.6.3.1.2	Test Requirements	
A.6.6.3.2	SA NR - E-UTRAN event-triggered reporting in DRX in FR1	
A.6.6.3.2.1	Test Purpose and Environment	
A.6.6.3.2.2	Test Requirements	1401
A.6.6.3.3	SA NR - E-UTRAN event-triggered reporting in DRX in FR1 for UE configured with	
	highSpeedMeasFlag-r16	
A.6.6.3.3.1	Test Purpose and Environment	
A.6.6.3.3.2	Test Requirements	
A.6.6.4	L1-RSRP measurement for beam reporting	
A.6.6.4.1	SSB based L1-RSRP measurement when DRX is not used	
A.6.6.4.1.1	Test Purpose and Environment	
A.6.6.4.1.2	Test parameters	
A.6.6.4.1.3	Test Requirements	
A.6.6.4.2	SSB based L1-RSRP measurement when DRX is used	
A.6.6.4.2.1	Test Purpose and Environment	
A.6.6.4.2.2	Test parameters	
A.6.6.4.2.3	Test Requirements	
A.6.6.4.3	CSI-RS based L1-RSRP measurement when DRX is not used	1413
A.6.6.4.3.1	Test Purpose and Environment	
A.6.6.4.3.2	Test parameters	
A.6.6.4.3.3	Test Requirements	
A.6.6.4.4	CSI-RS based L1-RSRP measurement when DRX is used	1417
A.6.6.4.4.1	Test Purpose and Environment	1417
A.6.6.4.4.2	Test parameters	
A.6.6.4.4.3	Test Requirements	

A.6.6.4.5	SSB based L1-RSRP measurement when DRX is used for UE configured with	
	highSpeedMeasFlag-r16	
A.6.6.4.5.1	Test Purpose and Environment	
A.6.6.4.5.2	Test parameters	
A.6.6.4.5.3	Test Requirements	1424
A.6.6.5	1424	
A.6.6.5.1	SA NR - UTRAN FDD event-triggered reporting in non-DRX in FR1	
A.6.6.5.1.1	Test Purpose and Environment	
A.6.6.5.1.2	Test Requirements	
A.6.6.6	CLI measurements	
A.6.6.6.1	SRS-RSRP measurement with DRX	
A.6.6.6.1.1	Test Purpose and Environment	
A.6.6.6.1.2	Test Parameters	
A.6.6.6.1.3	Test Requirements	1432
A.6.6.6.2	CLI-RSSI measurement with DRX	
A.6.6.6.2.1	Test Purpose and Environment	1432
A.6.6.6.2.2	Test Parameters	1433
A.6.6.6.2.3	Test Requirements	1435
A.6.6.7	NR measurements with autonomous gaps	1435
A.6.6.7.1	SA intra-frequency CGI identification of NR neighbor cell in FR1	1435
A.6.6.7.1.1	Test Purpose and Environment	1435
A.6.6.7.1.2	Test Parameters	1435
A.6.6.7.1.3	Test Requirements	
A.6.6.7.2	Identification of a new CGI of inter-RAT E-UTRA cell using autonomous gaps in NR SA	1438
A.6.6.7.2.1	Test Purpose and Environment	1438
A.6.6.7.2.2	Test Requirements	1441
A.6.6.8	L1-SINR measurement for beam reporting	
A.6.6.8.2	L1-SINR measurement with SSB based CMR and dedicated IMR when DRX is not used	
A.6.6.8.2.1	Test Purpose and Environment	
A.6.6.8.2.2	Test parameters	
A.6.6.8.2.3	Test Requirements	
A.6.6.8.3	L1-SINR measurement with CSI-RS based CMR and dedicated IMR configured when DRX is	
	not used	1449
A.6.6.8.3.1	Test Purpose and Environment	
A.6.6.8.3.2	Test parameters	
A.6.6.8.3.3	Test Requirements	
A.6.6.9	Idle Mode CA/DC Measurements	
A.6.6.9.1	SA Idle mode CA/DC measurement for FR1	
A.6.6.9.1.1	Test Purpose and Environment	
A.6.6.9.1.2	Test Requirements	
A.6.6.10	CSI-RS based intra-frequency Measurements	
A.6.6.10.1	SA event triggered reporting tests without gap under non-DRX	
A.6.6.10.1.1	Test purpose and Environment	
A.6.6.10.1.2	Test Requirements	
A.6.6.11	CSI-RS based inter-frequency Measurements	
A.6.6.11.1	SA event triggered reporting tests with gap under DRX	
A.6.6.11.1.1	Test Purpose and Environment	
A.6.6.11.1.2	Test Requirements	
A.6.6.12	RSTD measurements	
A.6.6.12.1	NR RSTD measurement reporting delay test case for single positioning frequency layer in FR1	
A.0.0.12.1	SA	
A.6.6.12.1.1	Test Purpose and Environment	
A.6.6.12.1.1	Test Requirements	
A.6.6.12.1.2 A.6.6.12.2	NR RSTD measurement reporting delay test case for dual positioning frequency layers in FR1	, 1+/2
11.0.0.12.2	SA	1473
A 6 6 12 2 1		
A.6.6.12.2.1 A.6.6.12.2.2	Test Purpose and Environment	
	Test Requirements	
A.6.6.13.1	PRS-RSRP reporting delay test case for single positioning frequency layer	
A.6.6.13.1.1		
A.6.6.13.1.1 A.6.6.13.1.2	Test Paguirements	
A.6.6.13.1.2 A.6.6.13.2	Test Requirements	
$\triangle U.U.I.1.2$	LIND-INDING TEDUCHTING METAY LENG CASE TOL MUAL DOSTLIOHING THEMMETICY TAVEL	1401

A.6.6.13.2.1	Test purpose and Environment	
A.6.6.13.2.2	Test Requirements	1487
A.6.6.14	UE Rx-Tx time difference measurements	
A.6.6.14.1	UE Rx-Tx time difference measurement for single positioning frequency layer in FR1 SA	1487
A.6.6.14.1.1	Test purpose and environment	
A.6.6.14.1.2	Test requirements	
A.6.6.14.2	UE Rx-Tx time difference measurement for dual positioning frequency layers in FR1 SA	1490
A.6.6.14.2.1	Test purpose and environment	1490
A.6.6.14.2.2	Test requirements	1493
A.6.6.15	Idle Mode measurements of inter-RAT CA candidate cells for early reporting	1493
A.6.6.15.1	Test Purpose and Environment	1493
A.6.6.15.2	Test Requirements	1501
A.6.7 Me	easurement Performance requirements	1501
A.6.7.1	SS-RSRP	1502
A.6.7.1.1	SA: intra-frequency case measurement accuracy with FR1 serving cell and FR1 target cell	1502
A.6.7.1.1.1	Test Purpose and Environment	1502
A.6.7.1.1.2	Test parameters	1502
A.6.7.1.1.3	Test Requirements	1507
A.6.7.1.2	SA inter-frequency case measurement accuracy with FR1 serving cell and FR1 target cell	1507
A.6.7.1.2.1	Test Purpose and Environment	1507
A.6.7.1.2.2	Test parameters	
A.6.7.1.2.3	Test Requirements	
A.6.7.1.3	Void	
A.6.7.2	SS-RSRQ	
A.6.7.2.1	SA: Intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.6.7.2.1.1	Test Purpose and Environment	
A.6.7.2.1.2	Test Parameters	
A.6.7.2.1.3	Test Requirements	
A.6.7.2.2	SA Inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.6.7.2.2.1	Test Purpose and Environment	
A.6.7.2.2.2	Test Parameters	
A.6.7.2.2.3	Test Requirements	
A.6.7.3	SS-SINR	
A.6.7.3.1	SA intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.6.7.3.1.1	Test Purpose and Environment	
A.6.7.3.1.2	Test Parameters.	
A.6.7.3.1.3	Test Requirements	
A.6.7.3.2	SA Inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.6.7.3.2.1	Test Purpose and Environment	
A.6.7.3.2.2	Test Parameters	
A.6.7.3.2.3	Test Requirements	
A.6.7.4	L1-RSRP measurement for beam reporting	
A.6.7.4.1	SSB based L1-RSRP measurement	
A.6.7.4.1.1	Test Purpose and Environment	
A.6.7.4.1.2	Test parameters	
A.6.7.4.1.3	Test Requirements	
A.6.7.4.2	CSI-RS based L1-RSRP measurement on resource set with repetition off	
A.6.7.4.2.1	Test Purpose and Environment	
A.6.7.4.2.2	Test parameters	
A.6.7.4.2.3	Test Requirements	
A.6.7.5	E-UTRAN RSRP	
A.6.7.5.1	SA: inter-RAT measurement accuracy with FR1 serving cell	
A.6.7.5.1.1	Test Purpose and Environment	
A.6.7.5.1.2	Test parameters	
A.6.7.5.1.3	Test Requirements	
A.6.7.6	E-UTRAN RSRQ	
A.6.7.6.1	SA: inter-RAT measurement accuracy with FR1 serving cell	
A.6.7.6.1.1	Test Purpose and Environment	
A.6.7.6.1.2	Test parameters	
A.6.7.6.1.3	Test Requirements	
A.6.7.7	E-UTRAN RS-SINR	
A.6.7.7.1	SA: inter-RAT measurement accuracy with FR1 serving cell	

A.6.7.7.1.1	Test Purpose and Environment	
A.6.7.7.1.2	Test parameters	1555
A.6.7.7.1.3	Test Requirements	1560
A.6.7.8	CLI measurements	1561
A.6.7.8.1	SA SRS-RSRP measurement accuracy with FR1 serving cell	1561
A.6.7.8.1.1	Test Purpose and Environment	1561
A.6.7.8.1.2	Test parameters	1561
A.6.7.8.1.3	Test Requirements	1567
A.6.7.8.2	SA CLI-RSSI measurement accuracy with FR1 serving cell	1567
A.6.7.8.2.1	Test Purpose and Environment	1567
A.6.7.8.2.2	Test parameters	
A.6.7.8.2.3	Test Requirements	
A.6.7.9	L1-SINR measurement for beam reporting	
A.6.7.9.2	L1-SINR measurement with SSB based CMR and dedicated IMR	1576
A.6.7.9.2.1	Test Purpose and Environment	
A.6.7.9.2.2	Test parameters	
A.6.7.9.2.3	Test Requirements	
A.6.7.9.3	L1-SINR measurement with CSI-RS based CMR and dedicated IMR	
A.6.7.9.3.1	Test Purpose and Environment	
A.6.7.9.3.2	Test parameters	
A.6.7.9.3.3	Test Requirements	
A.6.7.10	CSI-RSRP	
A.6.7.10.1	SA: intra-frequency case measurement accuracy with FR1 serving cell and FR1 target cell	
A.6.7.9.10.1	Test Purpose and Environment	
A.6.7.9.10.2	Test parameters	
A.6.7.10.1.3	Test Requirements	
A.6.7.10.2	SA inter-frequency case measurement accuracy with FR1 serving cell and FR1 target cell	
A.6.7.9.10.1	Test Purpose and Environment	
A.6.7.10.2.2	Test parameters	
A.6.7.10.2.3	Test Requirements	
A.6.7.11	CSI-RSRQ	
A.6.7.11.1	SA: Intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.6.7.11.1.1	Test Purpose and Environment	
A.6.7.11.1.2	Test Parameters.	
A.6.7.11.1.3	Test Requirements	
A.6.7.11.2	SA Inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.6.7.11.2.1	Test Purpose and Environment	
A.6.7.11.2.2	Test Parameters.	
A.6.7.11.2.3	Test Requirements	
A.6.7.12	CSI-SINR	
A.6.7.12.1	SA intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.6.7.12.1.1	Test Purpose and Environment	
A.6.7.12.1.2	Test Parameters.	
A.6.7.12.1.3	Test Requirements	
A.6.7.12.2	SA Inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.6.7.12.2.1	Test Purpose and Environment	
A.6.7.12.2.2	Test Parameters.	
A.6.7.12.2.3	Test Requirements	
A.6.7.13	RSTD measurements	
A.6.7.13.1	RSTD measurement accuracy test case for single positioning frequency layer	
A.6.7.13.1.1	Test purpose and Environment	
A.6.7.13.1.1 A.6.7.13.1.2	Test Requirements	
A.6.7.13.1.2 A.6.7.13.2	RSTD measurement accuracy test case for dual positioning frequency layer	
A.6.7.13.2.1	Test purpose and Environment	
A.6.7.13.2.1 A.6.7.13.2.2	Test Requirements	
A.6.7.14	PRS-RSRP measurements.	
A.6.7.14 A.6.7.14.1	SA: measurement accuracy with PRS in FR1	
A.6.7.14.1 A.6.7.14.1.1	Test Purpose and Environment	
A.6.7.14.1.1	Test parameters	
A.6.7.14.1.2 A.6.7.14.1.3	Test Requirements	
A.0.7.14.1.3 A 6 7 15	LIE Rx-Tx time difference measurements	1633

A.6.7.15.1	UE Rx-Tx time difference measurement accuracy for single positioning frequency layer in F	
A.6.7.15.1.1	SA Test purpose and environment	
A.6.7.15.1.1 A.6.7.15.1.2	Test parameters	
A.6.7.15.1.2 A.6.7.15.1.3	Test requirements.	
	•	
	andalone tests with one or more NR cells in FR2	
	RRC_IDLE state mobility	
	Cell re-selection to NR	
A.7.1.1.1	Cell reselection to FR2 intra-frequency NR case	
A.7.1.1.1.1	Test Purpose and Environment	
A.7.1.1.1.2	Test Parameters	
A.7.1.1.3	Test Requirements	
A.7.1.1.2	Cell reselection to FR2 inter-frequency NR case	
A.7.1.1.2.1 A.7.1.1.2.2	Test Peremeters	
A.7.1.1.2.2 A.7.1.1.2.3	Test Parameters Test Requirements	
A.7.1.1.2.3 A.7.1.1.3	Cell reselection to FR2 intra-frequency NR case for UE fulfilling low mobility relaxed	104.
A.7.1.1.3	measurement criterion	16/15
A.7.1.1.3.1	Test Purpose and Environment	
A.7.1.1.3.1 A.7.1.1.3.2	Test Parameters.	
A.7.1.1.3.3	Test Requirements	
A.7.1.1.4	Cell reselection to FR2 intra-frequency NR case for UE fulfilling not-at-cell edge relaxed	
21.7.11.1	measurement criterion	1648
A.7.1.1.4.1	Test Purpose and Environment	
A.7.1.1.4.2	Test Parameters.	
A.7.1.1.4.3	Test Requirements	
A.7.1.1.5	Cell reselection to FR2 inter-frequency NR case for UE fulfilling low mobility relaxed	
	measurement criterion	1651
A.7.1.1.5.1	Test Purpose and Environment	1651
A.7.1.1.5.2	Test Parameters	1651
A.7.1.1.5.3	Test Requirements	1654
A.7.1.1.6	Cell reselection to FR2 inter-frequency NR case for UE fulfilling not-at-cell edge relaxed	
	measurement criterion	
A.7.1.1.6.1	Test Purpose and Environment	
A.7.1.1.6.2	Test Parameters	
A.7.1.1.6.3	Test Requirements	
	RRC_INACTIVE state mobility	
	C_CONNECTED state mobility	
	Handover	
A.7.3.1.1	Inter-frequency handover from FR1 to FR2; unknown target cell	
A.7.3.1.1.1	Test Peremeters	
A.7.3.1.1.2 A.7.3.1.1.3	Test Parameters	
A.7.3.1.1.3 A.7.3.1.2	Test Requirements	
A.7.3.1.2.1	Test Purpose and Environment	
A.7.3.1.2.1 A.7.3.1.2.2	Test Parameters.	
A.7.3.1.2.3	Test Requirements	
A.7.3.1.3	Inter-frequency handover from FR2 to FR2; unknown target cell	
A.7.3.1.3.1	Test Purpose and Environment	
A.7.3.1.3.2	Test Parameters.	
	st Requirements	
A.7.3.1.4	Inter-band inter-frequency synchronous DAPS handover from FR1 to FR2	
A.7.3.1.4.1	Test Purpose and Environment	
A.7.3.1.4.2	Test Parameters	
A.7.3.1.4.3 Te	st Requirements	
A.7.3.1.5	Inter-band inter-frequency asynchronous DAPS handover from FR1 to FR2	1674
A.7.3.1.5.1	Test Purpose and Environment	
A.7.3.1.5.2	Test Parameters.	
	st Requirements	
	RRC Connection Mobility Control	
A 7 3 2 1	SA: RRC Re-establishment	1681

A.7.3.2.1.1	Intra-frequency RRC Re-establishment in FR2	
A.7.3.2.1.2	Inter-frequency RRC Re-establishment in FR2	. 1684
A.7.3.2.1.3	Intra-frequency RRC Re-establishment in FR2 without serving cell timing	. 1687
A.7.3.2.1.3.1	Test Purpose and Environment.	
A.7.3.2.1.3.2	Test Requirements	. 1689
A.7.3.2.2	Random Access	
A.7.3.2.2.1	4-step RA type c ontention based random access test in FR2 for NR Standalone	
A.7.3.2.2.2	4-step RA type n on-contention based random access test in FR2 for NR Standalone	
A.7.3.2.2.3	2-step RA type contention based random access test in FR2 for NR Standalone	
A.7.3.2.2.4	2-step RA type n on-contention based random access test in FR2 for NR Standalone	. 1701
A.7.3.2.3	SA: RRC Connection Release with Redirection	. 1704
A.7.3.2.3.1	Redirection from NR in FR2 to NR in FR2	. 1704
A.7.3.3 Cond	litional Handover	
A.7.3.3.1	Intra-frequency conditional handover from FR2 to FR2	. 1708
A.7.3.3.1.1	Test Purpose and Environment	. 1708
A.7.3.3.1.2	Test Parameters	. 1708
A.7.3.3.1.2.3	Test Requirements	. 1711
A.7.3.3.2	Inter-frequency handover from FR2 to FR2; unknown target cell	. 1711
A.7.3.3.2.1	Test Purpose and Environment	. 1711
A.7.3.3.2.2	Test Parameters	. 1711
A.7.3.3.2.3 T	est Requirements	. 1713
A.7.4 Ti	ming	. 1713
A.7.4.1	UE transmit timing	. 1713
A.7.4.1.1	NR UE Transmit Timing Test for FR2	. 1713
A.7.4.1.1.1	Test Purpose and environment.	. 1713
A.7.4.1.1.2	Test requirements	. 1716
A.7.4.2	UE timer accuracy	. 1717
A.7.4.3	Timing advance	
A.7.4.3.1	SA FR2 timing advance adjustment accuracy	
A.7.4.3.1.1	Test Purpose and Environment	
A.7.4.3.1.2	Test Parameters	
A.7.4.3.1.3 T	est Requirements	
	gnaling characteristics	
A.7.5.1	Radio link Monitoring	
A.7.5.1.1	Radio Link Monitoring Out-of-sync Test for FR2 PCell configured with SSB-based RLM RS in	
	non-DRX mode	. 1721
A.7.5.1.1.1	Test Purpose and Environment	
A.7.5.1.1.2	Test Requirements	
A.7.5.1.2	Radio Link Monitoring In-sync Test for FR2 PCell configured with SSB-based RLM RS in non-	
	DRX mode	
A.7.5.1.2.1	Test Purpose and Environment	. 1725
A.7.5.1.2.2	Test Requirements	
A.7.5.1.3	Radio Link Monitoring Out-of-sync Test for FR2 PCell configured with SSB-based RLM RS in	
11,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	DRX mode	1730
A.7.5.1.3.1	Test Purpose and Environment	
A.7.5.1.3.2	Test Requirements	
A.7.5.1.4	Radio Link Monitoring In-sync Test for FR2 PCell configured with SSB-based RLM RS in DRX	
11.7.0.1.1	mode	
A.7.5.1.4.1	Test Purpose and Environment	
A.7.5.1.4.2	Test Requirements	
A.7.5.1.5	Radio Link Monitoring Out-of-sync Test for FR2 PCell configured with CSI-RS-based RLM in	. 1757
A.7.3.1.3	non-DRX mode	1737
A.7.5.1.5.1	Test Purpose and Environment	
A.7.5.1.5.1 A.7.5.1.5.2	Test Requirements	
A.7.5.1.5.2 A.7.5.1.6	Radio Link Monitoring In-sync Test for FR2 PCell configured with CSI-RS-based RLM in non-	, ı / + l
A.1.J.1.0	DRX mode	1741
A.7.5.1.6.1		
A.7.5.1.6.1 A.7.5.1.6.2	Test Purpose and Environment Test Requirements	
	Radio Link Monitoring Out-of-sync Test for FR2 PCell configured with CSI-RS-based RLM in	. 1 /43
A.7.5.1.7		1744
A 7 5 1 7 1	DRX mode	
A.7.5.1.7.1 A.7.5.1.7.2	Test Purpose and Environment Test Requirements	. 1743 . 1748
A. L.J. L. L.Z.	rest reduitements	. ፲ / 4 ሾ

A.7.5.1.8	Radio Link Monitoring In-sync Test for FR2 PCell configured with CSI-RS-based RLM in DRX	
	mode	
A.7.5.1.8.1	Test Purpose and Environment	
A.7.5.1.8.2	Test Requirements	
A.7.5.1.9	UE Radio Link Monitoring Scheduling Restrictions on FR2	
A.7.5.1.9.1	Test Purpose and Environment	
A.7.5.1.9.2	Test Requirements	
A.7.5.2	Interruption	
A.7.5.2.1	Interruptions during measurements on deactivated NR SCC in FR2	
A.7.5.2.1.1	Test Purpose and Environment	
A.7.5.2.1.2	Test Requirements	
A.7.5.2.2	SA interruptions at NR SRS carrier-based switching	
A.7.5.2.2.1	Test Purpose and Environment	1760
A.7.5.2.2.2	Test Parameters	
A.7.5.2.2.3	Test Requirements	
A.7.5.3	SCell Activation and Deactivation Delay	1762
A.7.5.3.1	SCell Activation and deactivation for SCell in FR2 intra-band in non-DRX	
A.7.5.3.1.1	Test Purpose and Environment	
A.7.5.3.1.2	Test Requirements	
A.7.5.3.2	SCell Activation and deactivation for FR1+FR2 inter-band with target SCell in FR2	
A.7.5.3.2.1	Test Purpose and Environment	
A.7.5.3.2.2	Test Requirements	
A.7.5.3.3	SCell Activation and deactivation for SCell in FR2 inter-band in non-DRX	
A.7.5.3.3.1	Test Purpose and Environment	
A.7.5.3.3.2	Test Requirements	
A.7.5.3.4	Direct SCell activation at SCell addition of known SCell in FR2	
A.7.5.3.4.1	Test Purpose and Environment	
A.7.5.3.4.2	Test Requirements	
A.7.5.3.5	Direct SCell activation at handover with known SCell in FR2	
A.7.5.3.5.1	Test Purpose and Environment	
A.7.5.3.5.2	Test Requirements	
A.7.5.4	Void	
A.7.5.5	Beam Failure Detection and Link recovery procedures	1/80
A.7.5.5.1	Beam Failure Detection and Link Recovery Test for FR2 PCell configured with SSB-based BFD and LR in non-DRX mode	1700
A.7.5.5.1.1		
A.7.5.5.1.1 A.7.5.5.1.2	Test Purpose and Environment	
A.7.5.5.1.2 A.7.5.5.2	Beam Failure Detection and Link Recovery Test for FR2 PCell configured with SSB-based BFD	1765
A.1.3.3.2	and LR in DRX mode	1785
A.7.5.5.2.1	Test Purpose and Environment	
A.7.5.5.2.2	Test Requirements	
A.7.5.5.3	Beam Failure Detection and Link Recovery Test for FR2 PCell configured with CSI-RS-based	
	BFD and LR in non-DRX mode	1790
A.7.5.5.3.1	Test Purpose and Environment	1790
A.7.5.5.3.2	Test Requirements	1796
A.7.5.5.4	Beam Failure Detection and Link Recovery Test for FR2 PCell configured with CSI-RS-based	
	BFD and LR in DRX mode	1796
A.7.5.5.4.1	Test Purpose and Environment	1796
A.7.5.5.4.2	Test Requirements	1802
A.7.5.5.5	Scheduling availability restriction during Beam Failure Detection and Link Recovery for FR2	
	PCell configured with SSB-based BFD and LR in non-DRX mode	
A.7.5.5.5.1	Test Purpose and Environment	
A.7.5.5.5.2	Test Requirements	1807
A.7.5.5.6	Beam Failure Detection and Link Recovery Test for FR2 SCell configured with CSI-RS-based	
	BFD and LR in non-DRX mode	
A.7.5.5.6.1	Test Purpose and Environment	
A.7.5.5.6.2	Test Requirements	1812
A.7.5.5.7	Beam Failure Detection and Link Recovery Test for FR2 SCell configured with CSI-RS-based	
	BFD and LR in DRX mode	
A.7.5.5.7.1	Test Purpose and Environment	
A.7.5.5.7.2	Test Requirements	
A.7.5.6	Active BWP switch	1816

A.7.5.6.1	DCI-based and Timer-based Active BWP Switch	. 1816
A.7.5.6.1.1	NR FR2- NR FR2 DL active BWP switch of SCell with non-DRX in SA	. 1816
A.7.5.6.1.2	NR FR1- NR FR2 DL active BWP switch of SCell with non-DRX in SA	. 1821
A.7.5.6.1.3	NR FR2 DL active BWP switch with non-DRX in SA	. 1826
A.7.5.6.1.3.1	Test Purpose and Environment	. 1826
A.7.5.6.1.3.2	Test Requirements	
A.7.5.6.2	RRC-based Active BWP Switch	
A.7.5.6.3 Sim	nultaneous DCI-based and Timer-based Active BWP Switch on multiple CCs	
A.7.5.6.3.1.1	Test Purpose and Environment	
A.7.5.6.3.1.2	Test Requirements	
A.7.5.6.4	SCell dormancy switch	
A.7.5.6.4.1	NR FR2 PCell SCell dormancy switch of single FR2 SCell inside active time	
A.7.5.6.4.1.1	Test Purpose and Environment.	
A.7.5.6.4.1.2	Test Requirements	
A.7.5.6.4.2	NR FR1 PCell SCell dormancy switch of two FR2 SCells outside active time	
A.7.5.6.4.2.1	Test Purpose and Environment	
A.7.5.6.4.2.2	Test Requirements	
A.7.5.6.5	Simultaneous RRC-based Active BWP Switch on multiple CCs	
A.7.5.6.5.1	Active BWP switch on multiple SCells with non-DRX in SA	
A.7.5.0.3.1 A.7.5.7	PSCell addition and release delay	
A.7.5.7 A.7.5.7.1		
	Addition and Release Delay of known NR PSCell	
A.7.5.7.1.1	Test Purpose and Environment	
A.7.5.7.1.2	Test Requirements	
A.7.5.7.2	Addition and Release Delay of unknown NR PSCell	
A.7.5.7.2.1	Test Purpose and Environment	
A.7.5.7.2.2	Test Requirements	
A.7.5.8	Active TCI state switch delay	
A.7.5.8.1	MAC-CE based active TCI state switch	
A.7.5.8.2	RRC based active TCI state switch	
A.7.5.9	Uplink spatial relation switch delay	
A.7.5.9.1.1.1	Test Purpose and Environment.	
A.7.5.9.1.1.2	Test Requirements	. 1864
A.7.5.9.2	RRC based spatial relation switch	. 1864
A.7.5.9.2.1	NR PCell FR2 spatial relation switch associated with a known DL-RS	. 1864
A.7.5.9.2.1.1	Test Purpose and Environment	
A.7.5.9.2.1.2	Test Requirements	
A.7.5.10	UE specific CBW change	
A.7.5.10.1	NR FR2 UE specific CBW change of PCell with non-DRX in SA	
A.7.5.10.1.1	Test Purpose and Environment	
A.7.5.10.1.2	Test Requirements	
	easurement procedure	
A.7.6.1	Intra-frequency Measurements	
A.7.6.1.1	SA event triggered reporting test without gap under non-DRX	
A.7.6.1.1	Test purpose and Environment	
	• •	
A.7.6.1.1.2	Test Requirements	
A.7.6.1.2	SA event triggered reporting test without gap under DRX	
A.7.6.1.2.1	Test purpose and Environment	
A.7.6.1.2.2	Test Requirements	
A.7.6.1.3	SA event triggered reporting test with per-UE gaps under non-DRX	
A.7.6.1.3.1	Test purpose and Environment	
A.7.6.1.3.2	Test Requirements	
A.7.6.1.4	SA event triggered reporting test with per-UE gaps under DRX	
A.7.6.1.4.1	Test purpose and Environment	
A.7.6.1.4.2	Test Requirements	
A.7.6.2	Inter-frequency Measurements	. 1885
A.7.6.2.1	SA event triggered reporting tests For FR2 without SSB time index detection when DRX is not used (PCell in FR2)	. 1885
A.7.6.2.1.1	Test Purpose and Environment	
A.7.6.2.1.2	Test Requirements	
A.7.6.2.2	SA event triggered reporting tests For FR2 without SSB time index detection when DRX is used	
	(PCell in FR2)	
A.7.6.2.2.1	Test Purpose and Environment	. TAXX

A.7.6.2.2.2	Test Requirements	1892
A.7.6.2.3	SA event triggered reporting tests For FR2 with SSB time index detection when DRX is not used	
	(PCell in FR2)	1892
A.7.6.2.3.1	Test Purpose and Environment	.1892
A.7.6.2.3.2	Test Requirements	. 1896
A.7.6.2.4	SA event triggered reporting tests For FR2 with SSB time index detection when DRX is used	
	(PCell in FR2)	1896
A.7.6.2.4.1	Test Purpose and Environment	
A.7.6.2.4.2	Test Requirements	
A.7.6.2.5	SA event triggered reporting tests for FR2 without SSB time index detection when DRX is not	
	used (PCell in FR1)	. 1900
A.7.6.2.5.1	Test Purpose and Environment	
A.7.6.2.5.2	Test Requirements	
A.7.6.2.6	SA event triggered reporting tests for FR2 without SSB time index detection when DRX is used	
	(PCell in FR1)	. 1905
A.7.6.2.6.1	Test Purpose and Environment	
A.7.6.2.6.2	Test Requirements	
A.7.6.2.7	SA event triggered reporting tests for FR2 with SSB time index detection when DRX is not used	
	(PCell in FR1)	1910
A.7.6.2.7.1	Test Purpose and Environment	
A.7.6.2.7.2	Test Requirements	
A.7.6.2.8	SA event triggered reporting tests for FR2 with SSB time index detection when DRX is used	
	(PCell in FR1)	. 1915
A.7.6.2.8.1	Test Purpose and Environment	
A.7.6.2.8.2	Test Requirements	
A.7.6.2.9	SA event triggered reporting tests For FR2 without SSB time index detection when DRX is not	
	used (PCell in FR2) (rel16 additional mandatory gap pattern 17)	1920
A.7.6.2.9.1	Test Purpose and Environment	
A.7.6.2.9.2	Test Requirements	
A.7.6.2.10	SA event triggered reporting test without gap under non-DRX	
A.7.6.2.10.1	Test Purpose and Environment	
A.7.6.2.10.2	Test Requirements	
A.7.6.2.11	SA event triggered reporting test without gap under DRX	
A.7.6.2.11.1	Test Purpose and Environment	
A.7.6.2.11.2	Test Requirements	
A.7.6.3	L1-RSRP measurement for beam reporting	
A.7.6.3.1	SSB based L1-RSRP measurement when DRX is not used	
A.7.6.3.1	SSB based L1-RSRP measurement when DRX is not used	
A.7.6.3.1.1	Test Purpose and Environment	
A.7.6.3.1.2	Test parameters	
A.7.6.3.1.3	Test Requirements	
A.7.6.3.2	SSB based L1-RSRP measurement when DRX is used	
A.7.6.3.2.1	Test Purpose and Environment	
A.7.6.3.2.2	Test parameters	
A.7.6.3.2.3	Test Requirements	
A.7.6.3.3	CSI-RS based L1-RSRP measurement when DRX is not used	
A.7.6.3.3.1	Test Purpose and Environment	
A.7.6.3.3.2	Test parameters	
A.7.6.3.3.3	Test Requirements	
A.7.6.3.4	CSI-RS based L1-RSRP measurement when DRX is used	
A.7.6.3.4.1	Test Purpose and Environment	
A.7.6.3.4.2	Test parameters	
A.7.6.3.3.3	Test Requirements	
A.7.6.4	CLI measurements	
A.7.6.4.1	SRS-RSRP measurement with non-DRX	
A.7.6.4.1.1	Test Purpose and Environment	
A.7.6.4.1.2	Test Parameters.	
A.7.6.4.1.3	Test Requirements	
A.7.6.4.2	CLI-RSSI measurement with non-DRX	
A.7.6.4.2.1	Test Purpose and Environment	
A.7.6.4.2.2	Test Parameters	
A.7.6.4.2.3	Test Requirements	
	•	

	A interfrequency CGI reporting in autonomous gaps test (PCell in FR2)	
A.7.6.5.1.1	Test Purpose and Environment	
A.7.6.5.1.2	Test Requirements	
A.7.6.6	L1-SINR measurement for beam reporting	
A.7.6.6.2	L1-SINR measurement with SSB based CMR and dedicated IMR when DRX is used	
A.7.6.6.2.1	Test Purpose and Environment	. 1952
A.7.6.6.2.2	Test parameters	. 1953
A.7.6.6.2.3	Test Requirements	. 1955
A.7.6.6.3	L1-SINR measurement with CSI-RS based CMR and dedicated IMR configured when DRX is	
	used	
A.7.6.6.3.1	Test Purpose and Environment	. 1955
A.7.6.6.3.2	Test parameters	1956
A.7.6.6.3.3	Test Requirements	1958
A.7.6.7	CSI-RS based intra-frequency Measurements	1958
A.7.6.7.1	SA event triggered reporting test without gap under DRX for CSI-RS based intra-frequency	
	measurement	1958
A.7.6.7.1.1	Test purpose and Environment	1958
A.7.6.7.1.2	Test Requirements	1961
A.7.6.8	CSI-RS based inter-frequency Measurements	1961
A.7.6.8.1	SA event triggered reporting tests for FR2 CSI-RS based measurement when non-DRX is used	
	(PCell in FR2)	1961
A.7.6.8.1.1	Test Purpose and Environment	
A.7.6.8.1.2	Test Requirements	
A.7.6.9	RSTD measurements	
A.7.6.9.1	NR RSTD measurement reporting delay test case for single positioning frequency layer in FR2	
11.7.0.5.1	SA	1964
A.7.6.9.1.1	Test Purpose and Environment	
A.7.6.9.1.2	Test Requirements	
A.7.6.9.2	NR RSTD measurement reporting delay test case for dual positioning frequency layers in FR2	1770
11.7.0.7.2	SA	1970
A.7.6.9.2.1	Test Purpose and Environment	
A.7.6.9.2.2	Test Requirements	
	S-RSRP measurements	
	RS-RSRP reporting delay test case for single positioning frequency layer	
A.7.6.10.11	Test Purpose and Environment	
A.7.6.10.1.1 A.7.6.10.1.2	Test Requirements	
	PRS-RSRP reporting delay test case for dual positioning frequency layer	
A.7.6.10.2		
A.7.6.10.2.1 A.7.6.10.2.2	Test Purpose and Environment	
	Test Requirements	
A.7.6.11	UE Rx-Tx time difference measurements	
A.7.6.11.1	UE Rx-Tx time difference measurements for single positioning frequency layer in FR2 SA	
A.7.6.11.1.1	Test purpose and environment	
A.7.6.11.1.2	Test requirements	
A.7.6.11.2	UE Rx-Tx time difference measurement period for dual positioning frequency layers in FR2 SA	
A.7.6.11.2.1	Test purpose and environment	
A.7.6.11.2.2	Test requirements	
	easurement Performance requirements	
A.7.7.1	SS-RSRP	
A.7.7.1.1	SA intra-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	
A.7.7.1.1.1	Test Purpose and Environment	
A.7.7.1.1.2	Test parameters	
A.7.7.1.1.3	Test Requirements	
A.7.7.1.2	SA inter-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	
A.7.7.1.2.1	Test Purpose and Environment	
A.7.7.1.2.2	Test parameters	. 1995
A.7.7.1.2.3	Test Requirements	
A.7.7.1.3	SA inter-frequency measurement accuracy with FR1 serving cell and FR2 target cell	2000
A.7.7.1.3.1	Test Purpose and Environment	
A.7.7.1.3.2	Test parameters	
A.7.7.1.3.3	Test Requirements	
A.7.7.2	SS-RSRQ	
A.7.7.2.1	SA intra-frequency measurement accuracy with FR2 serving cell and FR2 target cell	

A.7.7.2.1.1	Test Purpose and Environment	
A.7.7.2.1.2	Test Parameters	
A.7.7.2.1.3	Test Requirements	
A.7.7.2.2	SA Inter-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell	
A.7.7.2.2.1	Test Purpose and Environment	
A.7.7.2.2.2	Test Parameters	
A.7.7.2.2.3	Test Requirements	
A.7.7.3	SS-SINR	
A.7.7.3.1	SA intra-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	
A.7.7.3.1.1	Test Purpose and Environment	
A.7.7.3.1.2	Test Parameters	
A.7.7.3.1.3	Test Requirements	
A.7.7.3.2	SA Inter-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell	
A.7.7.3.2.1	Test Purpose and Environment	
A.7.7.3.2.2	Test Parameters	
A.7.7.3.2.3	Test Requirements	
A.7.7.4	L1-RSRP measurement for beam reporting	
A.7.7.4.1	SSB based L1-RSRP measurement	
A.7.7.4.1.1	Test Purpose and Environment	
A.7.7.4.1.2	Test parameters	
A.7.7.4.1.3	Test Requirements	
A.7.7.4.2	CSI-RS based L1-RSRP measurement on resource set with repetition off	
A.7.7.4.2.1	Test Purpose and Environment	
A.7.7.4.2.2	Test parameters	
A.7.7.4.2.3	Test Requirements	
A.7.7.5	CLI measurements	
A.7.7.5.1	SA SRS-RSRP measurement accuracy with FR2 serving cell	
A.7.7.5.1.1	Test Purpose and Environment	
A.7.7.5.1.2	Test parameters	
A.7.7.5.1.3	Test Requirements	
A.7.7.5.2	SA CLI-RSSI measurement accuracy with FR2 serving cell	
A.7.7.5.2.1	Test Purpose and Environment	
A.7.7.5.2.2	Test parameters	
A.7.7.5.2.3	Test Requirements	
A.7.7.6	L1-SINR measurement for beam reporting	
A.7.7.6.2	L1-SINR measurement with SSB based CMR and dedicated IMR	
A.7.7.6.2.1	Test Purpose and Environment	
A.7.7.6.2.2	Test Pagniaments	
A.7.7.6.2.3 A.7.7.6.3	Test Requirements	
A.7.7.6.3.1		
A.7.7.6.3.1 A.7.7.6.3.2	Test permeters	
A.7.7.6.3.2 A.7.7.6.3.3	Test parameters Test Requirements	
A.7.7.7 A.7.7.7	CSI-RSRP	
A.7.7.7 A.7.7.7.1	SA intra-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	= = = =
A.7.7.7.1	Test Purpose and Environment	
A.7.7.7.1.1 A.7.7.7.1.2	Test parameters	
A.7.7.7.1.2 A.7.7.7.1.3	Test Requirements	
A.7.7.7.2	SA inter-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	
A.7.7.7.2.1	Test Purpose and Environment	
A.7.7.7.2.2	Test parameters	
A.7.7.7.2.3	Test Requirements	
A.7.7.8	CSI-RSRQ	
A.7.7.8.1	SA intra-frequency measurement accuracy with FR2 serving cell and FR2 target cell	
A.7.7.8.1.1	Test Purpose and Environment	
A.7.7.8.1.2	Test Parameters.	
A.7.7.8.1.3	Test Requirements	
A.7.7.8.2	SA Inter-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell	
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
A. / . / . ð . Z . l	Test Purpose and Environment	204 <i>6</i>
A.7.7.8.2.1 A.7.7.8.2.2	Test Purpose and Environment Test Parameters	
	Test Purpose and Environment Test Parameters Test Requirements	2046

A.7.7.9.1	SA intra-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	. 2048
A.7.7.9.1.1	Test Purpose and Environment	. 2048
A.7.7.9.1.2	Test Parameters	. 2048
A.7.7.9.1.3	Test Requirements	. 2050
A.7.7.9.2	SA Inter-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell	. 2050
A.7.7.9.2.1	Test Purpose and Environment	. 2050
A.7.7.9.2.2	Test Parameters	. 2051
A.7.7.9.2.3	Test Requirements	. 2053
A.7.7.10	RSTD measurements	. 2053
A.7.7.10.1	RSTD measurement accuracy test case for single positioning frequency layer	. 2053
A.7.7.10.1.1	Test purpose and Environment	. 2053
A.7.7.10.1.2	Test Requirements	
A.7.7.10.2	RSTD measurement accuracy test case for dual positioning frequency layer	
A.7.7.10.2.1	Test purpose and Environment	
A.7.7.10.2.2	Test Requirements	
A.7.7.11	PRS-RSRP measurements.	
A.7.7.11.1	SA measurement accuracy with PRS in FR2	
A.7.7.11.1.1	Test Purpose and Environment	
A.7.7.11.1.2	Test parameters	
A.7.7.11.1.3	Test Requirements	
A.7.7.12	UE Rx-Tx time difference measurements	
A.7.7.12.1	UE Rx-Tx time difference measurement period for single positioning frequency layer in FR2 SA	
A.7.7.12.1.1	Test purpose and environment.	
A.7.7.12.1.2	Test parameters	
A.7.7.12.1.3	Test requirements.	
	•	
	RA standalone tests for NR RRM	
A.8.1 Vo	oid	. 2064
A.8.2 RF	RC_IDLE state mobility	. 2064
A.8.2.1	Inter-RAT NR Cell re-selection.	. 2064
A.8.2.1.1	E-UTRA Cell reselection to higher priority NR target Cell in FR1	. 2064
A.8.2.1.1.1	Test Purpose and Environment	. 2064
A.8.2.1.1.2	Test Requirements	. 2069
A.8.2.1.2	E-UTRA Cell reselection to lower priority NR target Cell in FR1 for UE configured with	
	highSpeedInterRAT-NR-r16	.2070
A.8.2.1.2.1	Test Purpose and Environment	.2070
A.8.2.1.2.2	Test Requirements	.2073
A.8.2.2	E-UTRA – NR Inter-RAT Early Measruement Reporting	. 2074
A.8.2.2.1	E-UTRA – NR Early Measruement Reporting for NR in FR1	
A.8.2.2.1.1	Test Purpose and Environment	. 2074
A.8.2.2.1.2	Test Requirements	.2077
A.8.3 RF	RC_CONNECTED state mobility	
A.8.3.1	Handover	
A.8.3.1.1	E-UTRAN - NR handover in FR1	.2078
A.8.3.1.1.1	Test Purpose and Environment	
A.8.3.1.1.2	Test Requirements	
A.8.4 Me	easurement procedure	
A.8.4.1	E-UTRA – NR Inter-RAT SFTD Measurement Delay	
A.8.4.1.1	E-UTRA – NR Inter-RAT SFTD Measurement Delay in non-DRX	
A.8.4.1.1.1	Test Purpose and Environment	
A.8.4.1.1.2	Test Requirements	
A.8.4.1.2	E-UTRA – NR Inter-RAT SFTD Measurement Delay in DRX	
A.8.4.1.2.1	Test Purpose and Environment	
A.8.4.1.2.2	Test Requirements	
A.8.4.2	E-UTRA – NR Inter-RAT Measurements.	.2087
A.8.4.2.1	NR Inter-RAT event triggered reporting tests for FR1 without SSB time index detection when	. 2007
11.0. 1.2.1	DRX is not used	2087
A.8.4.2.1.1	Test Purpose and Environment	
A.8.4.2.1.1 A.8.4.2.1.2	Test Requirements	
A.8.4.2.1.2 A.8.4.2.2	NR Inter-RAT event triggered reporting tests for FR1 without SSB time index detection when	. 2072
11.0.7.2.2	DRX is used	.2092
A.8.4.2.2.1	Test Purpose and Environment	
1 1. U. T. Z. Z. I	1 cot 1 di pose and Environment	. 2092

A.8.4.2.2.2	Test Requirements	2096
A.8.4.2.3	NR Inter-RAT event triggered reporting tests for FR1 with SSB time index detection when	DRX
	is not used	
A.8.4.2.3.1	Test Purpose and Environment	
A.8.4.2.3.2	Test Requirements	
A.8.4.2.4	NR Inter-RAT event triggered reporting tests for FR1 with SSB time index detection when	
	is used	
A.8.4.2.4.1	Test Purpose and Environment	
A.8.4.2.4.2	Test Requirements	
A.8.4.2.5	NR Inter-RAT event triggered reporting tests for FR2 without SSB time index detection wh	
A.O.4.2.3	DRX is not used	
A.8.4.2.5.1	Test Purpose and Environment	
A.8.4.2.5.2	Test Requirements	
A.8.4.2.5.2 A.8.4.2.6	NR Inter-RAT event triggered reporting tests for FR2 without SSB time index detection wh	
A.0.4.2.0		
101261	DRX is used	
A.8.4.2.6.1	Test Purpose and Environment	
A.8.4.2.6.2	Test Requirements	
A.8.4.2.7	NR Inter-RAT event triggered reporting tests for FR2 with SSB time index detection when	
	is not used	
A.8.4.2.7.1	Test Purpose and Environment	
A.8.4.2.7.2	Test Requirements	
A.8.4.2.8	NR Inter-RAT event triggered reporting tests for FR2 with SSB time index detection when	
	is used	
A.8.4.2.8.1	Test Purpose and Environment	2114
A.8.4.2.8.2	Test Requirements	
A.8.4.2.9	NR Inter-RAT event triggered reporting tests for FR1 with SSB time index detection in DR	X for
	UE configured with highSpeedInterRAT-NR-r16	2117
A.8.4.2.9.1	Test Purpose and Environment	
A.8.4.2.9.2	Test Requirements	
A.8.5 Mea	asurement performance	
	SFTD accuracy	
A.8.5.1.1	SFTD accuracy	
A.8.5.1.1.1	Test Purpose	
A.8.5.1.1.2	Test Environment.	
A.8.5.1.1.3	Test Requirements	
	E-UTRA – NR Inter-RAT Measurement Performance requirements	
A.8.5.2.1.1	E-UTRAN – NR inter-RAT measurements with FR1 target cell	
A.8.5.2.1.1 A.8.5.2.1.2	E-UTRAN – NR inter-RAT measurements with FR2 target cell	
A.8.5.2.1.2 A.8.5.2.1.2.1		
	Test Purpose and Environment	
A.8.5.2.1.2.2	Test Parameters	
A.8.5.2.1.2.3	Test Requirements	
A.8.5.2.2	SS-RSRQ	
A.8.5.2.2.1	E-UTRAN – NR inter-RAT measurements with FR1 target cell	
A.8.5.2.2.2	E-UTRAN – NR inter-RAT measurements with FR2 target cell	
A.8.5.2.2.2.1	Test Purpose and Environment	
A.8.5.2.2.2.2	Test Parameters	
A.8.5.2.2.2.3	Test Requirements	2142
A.8.5.2.3	SS-SINR	2142
A.8.5.2.3.1	E-UTRAN – NR inter-RAT measurements with FR1 target cell	2142
A.8.5.2.3.2	E-UTRAN – NR inter-RAT measurements with FR2 target cell	2146
A.8.5.2.3.2.1	Test Purpose and Environment	
A.8.5.2.3.2.2	Test Parameters	
A.8.5.2.3.2.3	Test Requirements	
	•	
	Cests	
A.9.1 V22	X Tests in FR1	2149
A.9.1.1	Test for V2X UE Transmit Timing	2149
	for GNSS as Synchronization Reference Source	
A.9.1.1.1.1	Test Purpose and Environment	
A.9.1.1.1.2	Test requirements	
A.9.1.1.2	Test for SyncRef UE as Synchronization Reference Source	
A.9.1.1.2.1	Test Purpose and Environment	2149

A.9.1.1.2.2 Test requirements	2150
A.9.1.1.3 Test for FR1 NR Cell as Synchronization Reference Source	2150
A.9.1.1.3.1 Test Purpose and Environment	
A.9.1.1.3.2 Test requirements	
A.9.1.2 Test for Initiation/Cease of SLSS Transmission with V2X Sidelink Communication	
A.9.1.2.1 Test for FR1 NR Cell as synchronization reference source without gap under the synchronization reference source with the synchronization reference source without gap under the synchronization reference source with the synchronization r	
A.9.1.2.1.1 Test Purpose and Environment	
A.9.1.2.1.2 Test Requirements	
A.9.1.2.2 Test for SyncRef UE as synchronization reference source	
A.9.1.2.2.1 Test Purpose and Environment	
A.9.1.2.2.2 Test Requirements	
A.9.1.3 Test for V2X Synchronization Reference Selection/Reselection	2158
A.9.1.3.1 Test for GNSS configured as the highest priority	2158
A.9.1.3.1.1 Test Purpose and Environment	
A.9.1.3.1.2 Test Requirements	2160
A.9.1.3.2 Test for FR1 NR Cell configured as the highest priority	
A.9.1.3.2.1 Test Purpose and Environment	
A.9.1.3.2.2 Test Requirements	
A.9.1.4 Test for L1 SL-RSRP Measurement	
A.9.1.4.1 Test for V2X UE Autonomous Resource Selection/Reselection	
A.9.1.4.1.1 Test Purpose and Environment	
A.9.1.4.1.2 Test Requirements	
A. 9.1.4.2 Test for V2X UE Resource Pre-emption	
A. 9.1.4.2.1 Test Purpose and Environment	2166
A.9.1.4.2.2 Test Requirements	2170
A.9.1.4.3 Test for V2X UE Resource Re-evaluation	
A.9.1.4.3.1 Test Purpose and Environment	
A.9.1.4.3.2 Test Requirements	
A.9.1.5 Test for Congestion Control Measurement	
A.9.1.5.1 Test Purpose and Environment	
1	
*	
A.9.1.6.1 Test for Interruption to WAN due to V2X Sidelink Communication	
A.9.1.6.1.1 Test Purpose and Environment	
A.9.1.6.1.2 Test Requirements	2181
A.10 EN-DC Tests with NR PSCell under CCA and Other NR Cells in FR1	2181
A.10.1.1 RRC connection mobility control	
A.10.1.1.1 Random Access	
A.10.1.1.1.1 4-step RA type contention-based random access for NR PSCell with CCA	
A.10.1.1.1.1 Test Purpose and Environment	
A.10.1.1.1.2 Test Requirements	2184
A.10.1.1.1.2.1 Random Access Preamble Transmission	2184
A.10.1.1.1.2.2 Random Access Response Reception	
A.10.1.1.1.2.3 No Random Access Response Reception	
A.10.1.1.1.2.4 Receiving an UL grant for msg3 retransmission	
A.10.1.1.1.2.5 Contention Resolution Timer expiry	
A.10.1.1.1.2 4-step RA type non-contention based random access for NR PSCell with C	
1	
A.10.1.1.1.2.2 Test Requirements	
A.10.1.1.1.2.2.1 SSB-based Random Access Preamble Transmission	
A.10.1.1.1.2.2.2 Random Access Response Reception	
A.10.1.1.1.2.2.3 No Random Access Response Reception	
A.10.1.1.1.3 2-step RA type contention-based random access for NR PSCell with CCA	2190
A.10.1.1.3.1 Test Purpose and Environment	
A.10.1.1.1.3.2 Test Requirements	
A.10.1.1.3.2.1 MsgA Transmission	
A.10.1.1.1.3.2.2 MsgB Reception	
A.10.1.1.1.3.2.2 No MsgB Reception	
A.10.1.1.1.4 2-step RA type non-contention based random access for NR PSCell with C	⁷ CΔ 2105
A.10.1.1.1.4.1 Test Purpose and Environment	
73.10.1.1.1.7.1 105t 1 ti pose and Environment	

A.10.1.1.1.4.2	1	
A.10.1.1.1.4.2	2.1 MsgA Transmission	. 2199
A.10.1.1.1.4.2	2.2 MsgB Reception	. 2200
A.10.1.1.1.4.2	No MsgB Reception	. 2200
A.10.2 Tir	ning	. 2201
A.10.2.1	UE transmit timing	. 2201
A.10.2.1.1	UE Transmit Timing Test with PSCell under DL CCA	. 2201
A.10.2.1.1.1		. 2201
A.10.2.1.1.2	Test requirements	. 2204
A.10.2.2	UE timing advance	
A.10.2.2.1	UE Timing Advance Adjustment Accuracy with PSCell under DL CCA	
A.10.2.2.1.1	Test Purpose and Environment	
A.10.2.2.1.2	Test Parameters.	
A.10.2.2.1.3	Test Requirements	
	gnalling characteristics	
A.10.3 Sig	Radio link monitoring	
A.10.3.1 A.10.3.1.1	Introduction	
A.10.3.1.1 A.10.3.1.2	Radio link monitoring out-of-sync test for PSCell configured with SSB-based RLM RS in non-	. 2203
A.10.3.1.2		. 2210
A.10.3.1.2.1		
A.10.3.1.2.1 A.10.3.1.2.2		
	Test requirements.	. 2214
A.10.3.1.3	Radio link monitoring in-sync test for PSCell configured with SSB-based RLM RS in non-DRX	221/
A 10 2 1 2 1	mode	
A.10.3.1.3.1	Test purpose and environment	
A.10.3.1.3.2	Test requirements	. 2220
A.10.3.1.4	Radio link monitoring out-of-sync test for PSCell configured with SSB-based RLM RS in DRX	
A.10.3.1.4.1		. 2220
A.10.3.1.4.2	Test requirements	. 2220
A.10.3.1.5	Radio link monitoring in-sync test for PSCell configured with SSB-based RLM RS in DRX	
	mode	
A.10.3.1.5.1	Test purpose and environment	
A.10.3.1.5.2	1 1	. 2220
A.10.3.2	Interruption	
A.10.3.2.1	E-UTRAN – NR interruptions during SCell operations with CCA	. 2220
A.10.3.2.1.1	Test Purpose and Environment	. 2220
A.10.3.2.1.2	Test Requirements	. 2225
A.10.3.3	SCell activation and deactivation delay	. 2225
A.10.3.3.1	SCell Activation and Deactivation of known NR SCell with NR PSCell and NR SCell under	
	CCA, 160 ms SCell measurement cycle	. 2225
A.10.3.3.1.1	Test Purpose and Environment	
A.10.3.3.1.2	Test Requirements	
	Cell Activation and Deactivation of known NR SCell with NR PSCell and NR SCell under CCA, 320	
		. 2230
A.10.3.3.2.1	· · · · · · · · · · · · · · · · · · ·	. 2230
A.10.3.3.2.2		. 2231
A.10.3.3.3	SCell Activation and Deactivation of unknown NR SCell with NR PSCell and NR SCell under	
11.10.5.5.5		. 2231
A.10.3.3.3.1	Test Purpose and Environment	
A.10.3.3.3.2	Test Requirements	
A.10.3.3.4	Beam failure detection and link recovery procedures	
A.10.3.4.1	EN-DC Beam Failure Detection and Link Recovery Test for FR1 PSCell configured with SSB-	. 4434
A.10.3.4.1		222
A.10.3.4.1.1		2232
	Test Paguirements	
A.10.3.4.1.2	Test Requirements	. 4458
A.10.3.4.2	EN-DC Beam Failure Detection and Link Recovery Test for FR1 PSCell configured with SSB-	2226
A 10 2 4 2 1		. 2238
A.10.3.4.2.1	*	. 2238
A.10.3.4.2.2	4	. 2245
A.10.3.5	C	. 2245
A.10.3.5.1	UL active BWP switch delay with consistent UL LBT failure on PSCell subject to UL CCA in	2245

A.10.3.5.1.2	Test Requirements	2250
A.10.3.5.2	DCI-based and Timer-based Active BWP Switch	
A.10.3.5.2.1	E-UTRAN - NR PSCell FR1 DL active BWP switch in non-DRX in synchronous EN-DC.	2251
A.10.3.5.2.2	E-UTRAN – NR PSCell FR1 DL active BWP switch with FR1 SCell in non-DRX in	
	synchronous EN-DC	2254
A.10.3.5.3	RRC-based Active BWP Switch	
A.10.3.5.3.1	E-UTRAN - NR PSCell FR1 DL active BWP switch in non-DRX in synchronous EN-DC.	
A.10.3.6	PSCell addition and release delay	
A.10.3.6.1	Addition and Release Delay of known NR PSCell on the carrier under CCA	
A.10.3.6.1.1	Test purpose and environment	
A.10.3.6.1.2	Test Requirements	
A.10.3.7	Active TCI state switching delay	
	easurement procedure	
A.10.4 NA A.10.4.1	Intra-frequency measurements	
A.10.4.1 A.10.4.1.1	Event-triggered reporting tests on PSCC without gaps under non-DRX	
A.10.4.1.1.1	Test purpose and environment	
A.10.4.1.1.2	Test parameters	
A.10.4.1.1.3	Test Requirements	
A.10.4.1.2	Event-triggered reporting tests on PSCC without gaps under DRX	
A.10.4.1.2.1	Test purpose and environment	
A.10.4.1.2.2	Test parameters	
A.10.4.1.2.3	Test Requirements	
A.10.4.1.3	Event-triggered reporting tests on PSCC with per-UE gaps under non-DRX	
A.10.4.1.3.1	Test purpose and environment	
A.10.4.1.3.2	Test parameters	
A.10.4.1.3.3	Test Requirements	
A.10.4.1.4	Event-triggered reporting tests on PSCC with per-UE gaps under DRX	2269
A.10.4.1.4.1	Test purpose and environment	2269
A.10.4.1.4.2	Test parameters	2269
A.10.4.1.4.3	Test Requirements	2269
A.10.4.1.5	Event-triggered reporting tests on SCC without gaps under non-DRX	2269
A.10.4.1.5.1	Test purpose and environment	2269
A.10.4.1.5.2	Test parameters	
A.10.4.1.5.3	Test Requirements	
A.10.4.1.6	Event-triggered reporting tests on SCC without gaps under DRX	
A.10.4.1.6.1	Test purpose and environment	
A.10.4.1.6.2	Test parameters	
A.10.4.1.6.3	Test Requirements	
A.10.4.1.7	Event-triggered reporting tests on SCC with per-UE gaps under non-DRX	
A.10.4.1.7.1	Test purpose and environment	
A.10.4.1.7.2	Test parameters	
A.10.4.1.7.3	Test Requirements	
A.10.4.1.8	Event-triggered reporting tests on SCC with per-UE gaps under DRX	
A.10.4.1.8.1	Test purpose and environment	
A.10.4.1.8.1 A.10.4.1.8.2	Test parameters	
A.10.4.1.8.2 A.10.4.1.8.3		
A.10.4.1.8.3 A.10.4.1.9	Test Requirements	
	RSSI measurement reporting on PSCC	
A.10.4.1.9.1	Test purpose and environment	
A.10.4.1.9.2	Test parameters	
A.10.4.1.10	Channel occupancy measurement reporting on PSCC	
A.10.4.1.10.1	1 1	
A.10.4.1.10.2	1	
A.10.4.1.11	RSSI measurement reporting on SCC	
A.10.4.1.11.1	1 1	
A.10.4.1.11.2	P	
A.10.4.1.12	Channel occupancy measurement reporting on SCC	
A.10.4.1.12.1	1 1	
A.10.4.1.12.2	Test parameters	2273
A.10.4.2	Inter-frequency measurements	2273
A.10.4.2.1	RSSI measurement reporting	2273
A.10.4.2.1.1	Test purpose and environment	
A.10.4.2.1.2	Test parameters.	2273

A.10.4.2.2	Channel occupancy measurement reporting.	. 2274
A.10.4.2.2.1	Test purpose and environment	. 2274
A.10.4.2.2.2	Test parameters	. 2274
A.10.4.2.3	EN-DC event triggered reporting tests for FR1 with CCA cell without SSB time index detection when DRX is not used	2274
A.10.4.2.3.1	Test Purpose and Environment	
A.10.4.2.3.2	Test Requirements	
A.10.4.2.4	EN-DC event triggered reporting tests for FR1 cell with CCA without SSB time index detection	
. 10 1 2 1 1	when DRX is used	
A.10.4.2.4.1	Test Purpose and Environment	
A.10.4.2.4.2	Test Requirements	. 2284
A.10.4.2.5	EN-DC event triggered reporting tests for FR1 cell with CCA with SSB time index detection when DRX is not used	. 2285
A.10.4.2.5.1	Test Purpose and Environment	. 2285
A.10.4.2.5.2	Test Requirements	
A.10.4.2.6	EN-DC event triggered reporting tests for FR1 cell with CCA with SSB time index detection when DRX is used	
A.10.4.2.6.1	Test Purpose and Environment	
A.10.4.2.6.2	Test Requirements	
A.10.4.2.7	EN-DC event triggered reporting tests for FR1 cell without SSB time index detection when DRX	
A.10.4.2.7	is not used	
A.10.4.2.7.1	Test Purpose and Environment	
A.10.4.2.7.2	Test Requirements	
A.10.4.2.8	EN-DC event triggered reporting tests for FR1 cell without SSB time index detection when DRX	
	is used	
A.10.4.2.8.1	Test Purpose and Environment	. 2301
A.10.4.2.8.2	Test Requirements	. 2307
A.10.4.2.9	EN-DC event triggered reporting tests for FR1 cell with SSB time index detection when DRX is not used	2308
A.10.4.2.9.1	Test Purpose and Environment	
A.10.4.2.9.1 A.10.4.2.9.2	Test Requirements	
A.10.4.2.9.2 A.10.4.2.10	EN-DC event triggered reporting tests for FR1 cell with SSB time index detection when DRX is	. 2313
A.10.4.2.10	used	. 2313
A.10.4.2.10.1		
A.10.4.2.10.2	•	
A.10.4.3	L1-RSRP measurements for beam reporting	
A.10.4.3.1	SSB based L1-RSRP measurement on PSCC when DRX is not used	
A.10.4.3.1.1	Test Purpose and Environment	
A.10.4.3.1.2	Test parameters	
A.10.4.3.1.3	Test Requirements	
A.10.4.3.2	SSB based L1-RSRP measurement on PSCC when DRX is used	. 2323
A.10.4.3.2.1	Test Purpose and Environment	
A.10.4.3.2.2	Test parameters	
A.10.4.3.2.3	Test Requirements	
A.10.4.3.3	SSB based L1-RSRP measurement on SCC when DRX is not used	. 232 <i>6</i>
A.10.4.3.3.1	Test Purpose and Environment	
A.10.4.3.3.2	Test parameters	
A.10.4.3.3.3	Test Requirements	
A.10.4.3.4	SSB based L1-RSRP measurement on SCC when DRX is used	2330
A.10.4.3.4.1	Test Purpose and Environment	
A.10.4.3.4.2	Test parameters	
A.10.4.3.4.3	Test Requirements	
A.10.4.4	E-UTRAN–NR inter-RAT measurements on NR carrier frequency under CCA	
A.10.4.4 A.10.4.4.1	E-UTRA-NR inter-RAT measurements on NR carrier frequency under CCA	. 2334
	detection when DRX is not used	. 2334
A.10.4.4.1.1	Test Purpose and Environment	
A.10.4.4.1.2	Test Requirements	
A.10.4.4.2 A.10.4.4.2	E-UTRA-NR inter-RAT event triggered reporting tests for FR1 without SSB time index	
	detection when DRX is used	. 2339
A.10.4.4.2.1	Test Purpose and Environment	. 2339
A.10.4.4.2.2	Test Requirements	. 2344

A.10.4.4.3	NR Inter-RAT event triggered reporting tests for FRT with SSB time index detection when DRA	2245
. 10 1 1 2 1	is not used	
A.10.4.4.3.1	Test Purpose and Environment	
A.10.4.4.3.2	Test Requirements	
A.10.4.4.4	NR Inter-RAT event triggered reporting tests for FR1 with SSB time index detection when DRX	
	is used	
A.10.4.4.1	Test Purpose and Environment	
A.10.4.4.4.2	Test Requirements	
A.10.5 Me	easurement performance	
A.10.5.1	SS-RSRP	. 2356
A.10.5.1.1	Intra-frequency measurement accuracy on a CCA serving cell	. 2356
A.10.5.1.1.1	Test Purpose and Environment	. 2356
A.10.5.1.1.2	Test parameters	
A.10.5.1.1.3	Test Requirements	
A.10.5.1.2	Inter-frequency measurement accuracy with FR1 CCA serving cell and FR1 CCA target cell	
A.10.5.1.2.1	Test Purpose and Environment	
A.10.5.1.2.2	Test parameters	
A.10.5.1.2.3	Test Requirements	
A.10.5.1.2.3 A.10.5.2	SS-RSRQ	
A.10.5.2.1	Intra-frequency measurement accuracy with FR1 CCA serving cell and FR1 CCA target cell	
A.10.5.2.1 A.10.5.2.1.1	Test Purpose and Environment	
	•	
A.10.5.2.1.2	Test Parameters	
A.10.5.2.1.3	Test Requirements	
A.10.5.2.2	Inter-frequency measurement accuracy with FR1 CCA serving cell and FR1 CCA target cell	
A.10.5.2.2.1	Test Purpose and Environment	
A.10.5.2.2.2	Test Parameters	
A.10.5.2.2.3	Test Requirements	
A.10.5.3	SS-SINR	
A.10.5.4	L1-RSRP measurement for beam reporting with CCA serving cell	
A.10.5.4.1	SSB based L1-RSRP measurement	. 2368
A.10.5.4.1.1	Test Purpose and Environment	. 2368
A.10.5.4.1.2	Test parameters	. 2368
A.10.5.4.1.3	Test Requirements	. 2371
A.10.5.5	RSSI	. 2371
A.10.5.5.1	RSSI measurement accuracy on PSCC with CCA	. 2371
A.10.5.5.1.1	Test Purpose and Environment	
A.10.5.5.1.2	Test parameters	
A.10.5.5.1.3	Test Requirements	
A.10.5.5.2	RSSI measurement accuracy on SCC with CCA	
A.10.5.5.2.1	Test Purpose and Environment	
A.10.5.5.2.2	Test parameters	
A.10.5.5.2.2 A.10.5.5.2.3	Test Requirements	
A.10.5.5.2.3 A.10.5.5.3	•	
	Inter-frequency RSSI measurement accuracy on a carrier with CCA	
A.10.5.5.3.1	Test Purpose and Environment	
A.10.5.5.3.2	Test parameters	
A.10.5.5.3.3	Test Requirements	
A.10.5.6	Channel occupancy	
A.10.5.6.1	Channel occupancy measurement accuracy on PSCC with CCA	
A.10.5.6.1.1	Test Purpose and Environment	
A.10.5.6.1.2	Test parameters	. 2380
A.10.5.6.1.3	Test Requirements	
A.10.5.6.2	Channel occupancy measurement accuracy on SCC with CCA	. 2384
A.10.5.6.2.1	Test Purpose and Environment	. 2384
A.10.5.6.2.2	Test parameters	. 2384
A.10.5.6.2.3	Test Requirements	
A.10.5.6.3	Inter-frequency channel occupancy measurement accuracy on a carrier with CCA	
A.10.5.6.3.1	Test Purpose and Environment	
A.10.5.6.3.2	Test parameters	
A.10.5.6.3.3	Test Requirements	
	tandalone Tests with NR PCell under CCA and Other NR Cells in FR1	
A.11.1 RF	C_IDLE state mobility	. 2391

A.11.1.1	Cell re-selection with both source and target NR carrier frequencies under CCA	
A.11.1.1.1	Cell reselection to FR1 intra-frequency NR cells when subject to CCA on the serving and targ	get
	cell	2391
A.11.1.1.1	Test Purpose and Environment	2391
A.11.1.1.1.2	Test Parameters	
A.11.1.1.3	Test Requirements	
A.11.1.1.2	Cell reselection to FR1 inter-frequency NR case when subject to CCA on the serving and targ	
	cell	
A.11.1.1.2.1	Test Purpose and Environment	
A.11.1.1.2.1 A.11.1.1.2.2	Test Parameters.	
A.11.1.1.2.2 A.11.1.1.2.3		
	Test Requirements	
A.11.1.2	Cell re-selection to NR with source NR carrier frequency under CCA	
A.11.1.2.1	Cell reselection to FR1 inter-frequency NR case when serving cell is subject to CCA	
A.11.1.2.1.1	Test Purpose and Environment	
A.11.1.2.1.2	Test Parameters	
A.11.1.2.1.3	Test Requirements	
A.11.1.3	Cell re-selection from NR carrier with target NR carrier frequency under CCA	2406
A.11.1.3.1	Cell reselection to FR1 inter-frequency NR case when target cell is subject to CCA	2406
A.11.1.3.1.1	Test Purpose and Environment	2406
A.11.1.3.1.2	Test Parameters	2406
A.11.1.3.1.3	Test Requirements	2412
A.11.1.4	Inter-RAT cell re-selection to E-UTRAN with source NR carrier frequency under CCA	
A.11.1.4.1	Cell reselection to higher priority E-UTRAN when serving cell is subject to CCA	
A.11.1.4.1.1	Test Purpose and Environment	
A.11.1.4.1.2	Test Parameters.	
A.11.1.4.1.2 A.11.1.4.1.3	Test Requirements	
	Cell reselection to lower priority E-UTRAN when serving cell is subject to CCA	
A.11.1.4.2		
A.11.1.4.2.1	Test Purpose and Environment	
A.11.1.4.2.2	Test Requirements	
	RC_CONNECTED state mobility	
A.11.2.1	Handover	
A.11.2.1.1	Intra-frequency handover from FR1 carrier under CCA to FR1 carrier under CCA; known targ	
	cell	
A.11.2.1.1.1	Test Purpose and Environment	2421
A.11.2.1.1.2	Test Parameters	2421
A.11.2.1.1.3	Test Requirements	2424
A.11.2.1.2	Intra-frequency handover from FR1 carrier under CCA to FR1 carrier under CCA; unknown	
	target cell	2424
A.11.2.1.2.1	Test Purpose and Environment	
A.11.2.1.2.2	Test Parameters	
A.11.2.1.2.3	Test Requirements	
A.11.2.1.3	Inter-frequency handover from FR1 carrier under CCA to FR1 carrier under CCA; unknown	2 127
A.11.2.1.3		2427
A 11 2 1 2 1	target cell	
A.11.2.1.3.1	Test Purpose and Environment Test Parameters	
A.11.2.1.3.2	Lest Parameters	242 /
		2 4 2 0
	Test Requirements	
A.11.2.1.4	Test Requirements	2430
A.11.2.1.4 A.11.2.1.4.1	Test Requirements Inter-frequency handover from FR1 carrier under CCA to FR1; known target cell Test Purpose and Environment	2430 2430
A.11.2.1.4	Test Requirements	2430 2430
A.11.2.1.4 A.11.2.1.4.1 A.11.2.1.4.2	Test Requirements Inter-frequency handover from FR1 carrier under CCA to FR1; known target cell Test Purpose and Environment	2430 2430 2430
A.11.2.1.4 A.11.2.1.4.1 A.11.2.1.4.2	Test Requirements	2430 2430 2430
A.11.2.1.4 A.11.2.1.4.1 A.11.2.1.4.2 A.11.2.1.4.3	Test Requirements	2430 2430 2434 2435
A.11.2.1.4 A.11.2.1.4.1 A.11.2.1.4.2 A.11.2.1.4.3 A.11.2.1.5	Test Requirements	2430 2430 2434 2435 2435
A.11.2.1.4 A.11.2.1.4.1 A.11.2.1.4.2 A.11.2.1.4.3 A.11.2.1.5 A.11.2.1.5.1 A.11.2.1.5.2	Test Requirements Inter-frequency handover from FR1 carrier under CCA to FR1; known target cell Test Purpose and Environment Test Parameters Test Requirements Inter-frequency handover from FR1 carrier under CCA to FR1; unknown target cell Test Purpose and Environment Test Parameters	2430 2430 2434 2435 2435
A.11.2.1.4 A.11.2.1.4.1 A.11.2.1.4.2 A.11.2.1.4.3 A.11.2.1.5 A.11.2.1.5.1 A.11.2.1.5.2 A.11.2.1.5.3	Test Requirements	2430 2430 2434 2435 2435 2438
A.11.2.1.4 A.11.2.1.4.1 A.11.2.1.4.2 A.11.2.1.4.3 A.11.2.1.5 A.11.2.1.5.1 A.11.2.1.5.2 A.11.2.1.5.3 A.11.2.1.6	Test Requirements	2430 2430 2434 2435 2435 2438 2439
A.11.2.1.4 A.11.2.1.4.1 A.11.2.1.4.2 A.11.2.1.4.3 A.11.2.1.5 A.11.2.1.5.1 A.11.2.1.5.2 A.11.2.1.5.3 A.11.2.1.6 A.11.2.1.6.1	Test Requirements	2430 2430 2434 2435 2435 2438 2439 2439
A.11.2.1.4 A.11.2.1.4.1 A.11.2.1.4.2 A.11.2.1.4.3 A.11.2.1.5 A.11.2.1.5.1 A.11.2.1.5.2 A.11.2.1.6 A.11.2.1.6.1 A.11.2.1.6.2	Test Requirements. Inter-frequency handover from FR1 carrier under CCA to FR1; known target cell Test Purpose and Environment Test Requirements Inter-frequency handover from FR1 carrier under CCA to FR1; unknown target cell Test Purpose and Environment Test Parameters Test Requirements Inter-frequency handover from FR1 to FR1 carrier under CCA; unknown target cell Test Requirements Inter-frequency handover from FR1 to FR1 carrier under CCA; unknown target cell Test Purpose and Environment Test Parameters	2430 2430 2434 2435 2435 2438 2439 2439
A.11.2.1.4 A.11.2.1.4.1 A.11.2.1.4.2 A.11.2.1.4.3 A.11.2.1.5 A.11.2.1.5.1 A.11.2.1.5.3 A.11.2.1.6 A.11.2.1.6.1 A.11.2.1.6.2 A.11.2.1.6.3	Test Requirements	2430243024342435243524392439
A.11.2.1.4 A.11.2.1.4.1 A.11.2.1.4.2 A.11.2.1.5 A.11.2.1.5 A.11.2.1.5.2 A.11.2.1.5.3 A.11.2.1.6.1 A.11.2.1.6.2 A.11.2.1.6.3 A.11.2.1.6.3	Test Requirements	24302430243424352435243924392439
A.11.2.1.4 A.11.2.1.4.1 A.11.2.1.4.2 A.11.2.1.4.3 A.11.2.1.5 A.11.2.1.5.1 A.11.2.1.5.3 A.11.2.1.6.1 A.11.2.1.6.2 A.11.2.1.6.3 A.11.2.1.6.3 A.11.2.1.7 A.11.2.1.7	Test Requirements. Inter-frequency handover from FR1 carrier under CCA to FR1; known target cell Test Purpose and Environment Test Requirements Inter-frequency handover from FR1 carrier under CCA to FR1; unknown target cell Test Purpose and Environment Test Parameters Test Requirements Inter-frequency handover from FR1 to FR1 carrier under CCA; unknown target cell Test Purpose and Environment Test Purpose and Environment Test Parameters Test Requirements SA NR FR1 carrier under CCA - E-UTRAN handover with known target cell Test Purpose and Environment	24302430243424352435243924392439
A.11.2.1.4 A.11.2.1.4.1 A.11.2.1.4.2 A.11.2.1.5 A.11.2.1.5 A.11.2.1.5.2 A.11.2.1.5.3 A.11.2.1.6.1 A.11.2.1.6.2 A.11.2.1.6.3 A.11.2.1.6.3	Test Requirements	243024302434243524352439243924392443

A.11.2.1.8.1	Test Purpose and Environment	2449
A.11.2.1.8.2	Test Requirements	2454
A.11.2.2 RRC	C connection mobility control	2454
A.11.2.2.1 F	RRC re-establishment	2454
A.11.2.2.1.1	Intra-frequency RRC Re-establishment with CCA in FR1	2454
A.11.2.2.1.2	Inter-frequency RRC Re-establishment with CCA in FR1	
A.11.2.2.1.4	Inter-frequency RRC Re-establishment from NR FR1 carrier without CCA to NR FR1 carrier	
	under CCA	
A.11.2.2.2 F	Random Access	
A.11.2.2.2.1	4-step RA type contention-based random access for NR PCell with CCA	
A.11.2.2.2.1.1	Test Purpose and Environment	
A.11.2.2.2.1.2	Test Requirements	
A.11.2.2.2.1.2.1	Random Access Preamble Transmission	
A.11.2.2.2.1.2.2	Random Access Response Reception	
A.11.2.2.2.1.2.3	No Random Access Response Reception	
A.11.2.2.2.1.2.4	Receiving an UL grant for msg3 retransmission	
A.11.2.2.2.1.2.5	Reception of an Incorrect Message over Temporary C-RNTI	
A.11.2.2.2.1.2.6	Reception of a Correct Message over Temporary C-RNTI	
A.11.2.2.2.1.2.7	Contention Resolution Timer expiry	
A.11.2.2.2.2	4-step RA type non-contention based random access for NR PSCell with CCA	
A.11.2.2.2.2.1	Test Purpose and Environment	
A.11.2.2.2.2.1 A.11.2.2.2.2.2	Test Requirements	
A.11.2.2.2.2.2 A.11.2.2.2.2.2.1	SSB-based Random Access Preamble Transmission	
A.11.2.2.2.2.2.1 A.11.2.2.2.2.2.2	Random Access Response Reception	
A.11.2.2.2.2.2.3 A.11.2.2.2.2.2.3		
A.11.2.2.2.3 A.11.2.2.2.3	No Random Access Response Reception	2470 2470
A.11.2.2.2.3 A.11.2.2.2.3.1		
	Test Purpose and Environment.	
A.11.2.2.2.3.2	Test Requirements	
A.11.2.2.2.3.2.1	MsgA Transmission	
A.11.2.2.2.3.2.2	MsgB Reception	
A.11.2.2.2.3.2.3	No MsgB Reception	2483
A.11.2.2.2.4	2-step RA type non-contention-based random access for NR PCell with CCA	
A.11.2.2.2.4.1	Test Purpose and Environment	
A.11.2.2.2.4.2	Test Requirements	
A.11.2.2.2.4.2.1	MsgA Transmission	
A.11.2.2.2.4.2.2	MsgB Reception	
A.11.2.2.2.4.2.3	No MsgB Reception	
	RRC connection release with redirection	
A.11.2.2.3.1	Redirection from NR FR1 carrier under CCA to NR FR1 carrier under CCA	
A.11.2.2.3.2	Redirection from NR FR1 carrier without CCA to NR FR1 carrier with CCA	
	transmit timing	
	JE Transmit Timing Test with PCell under DL CCA	
A.11.3.1.1.1	Test Purpose and environment	
A.11.3.1.1.2	Test requirements	
	timing advance	
	JE Timing Advance Adjustment Accuracy with PCell under DL CCA	
A.11.3.2.1.1	Test Purpose and Environment	2502
A.11.3.2.1.2	Test Parameters.	2502
A.11.3.2.1.3	Test Requirements	2506
	ng characteristics	2506
A.11.4.1 Radi	io link monitoring	2506
	ntroduction	2506
A.11.4.1.2 F	Radio link monitoring out-of-sync test for PCell configured with SSB-based RLM RS in non-	
	DRX mode	
A.11.4.1.2.1	Test purpose and environment	2507
A.11.4.1.2.2	Test requirements	2511
	Radio link monitoring in-sync test for PCell configured with SSB-based RLM RS in non-DRX	
r	node	
A.11.4.1.3.1	Test purpose and environment	2511
A 11 4 1 3 2	Test requirements	2517

A.11.4.1.4	Radio link monitoring out-of-sync test for PCell configured with SSB-based RLM RS in DRX mode	2517
A.11.4.1.4.1		
A.11.4.1.4.2		
A.11.4.1.5	Radio link monitoring in-sync test for PCell configured with SSB-based RLM RS in DRX mode.	
A.11.4.1.5.1		
A.11.4.1.5.2		
A.11.4.2	Interruption	
A.11.4.2.1	NR interruptions during Scell operations with CCA on PCell and SCell	
A.11.4.2.1.1	Test Purpose and Environment.	
A.11.4.2.1.2	•	
A.11.4.3	SCell activation and deactivation delay	
A.11.4.3.1	SCell Activation and Deactivation of known SCell with PCell and SCell under CCA, 160 ms	
	SCell measurement cycle	2522
A.11.4.3.1.1	· · · · · · · · · · · · · · · · · · ·	
A.11.4.3.1.2		2527
A.11.4.3.2	SCell Activation and Deactivation of known SCell with PCell and SCell under CCA, 320 ms	
	SCell measurement cycle	2527
A.11.4.3.2.1		
A.11.4.3.2.2		
A.11.4.3.3	SCell Activation and Deactivation of unknown SCell with PCell and SCell under CCA	
A.11.4.3.3.1		
A.11.4.3.3.2	•	
A.11.4.4	Beam failure detection and link recovery procedures	
A.11.4.4.1	Beam Failure Detection and Link Recovery Test for FR1 PCell configured with SSB-based BFD	
		2529
A.11.4.4.1.1		
A.11.4.4.1.2	•	
A.11.4.4.2	Beam Failure Detection and Link Recovery Test for FR1 PCell configured with SSB-based BFD	
	and LR in DRX mode	2535
A.11.4.4.2.1		
A.11.4.4.2.2	•	
A.11.4.5	Active BWP switching	
A.11.4.5.1	UL active BWP switch delay with consistent UL LBT failure on PCell subject to UL CCA	
A.11.4.5.1.1		
A.11.4.5.1.2		
A.11.4.5.2	DCI-based and Timer-based Active BWP Switch.	
A.11.4.5.2.1		
A.11.4.5.2.2		
A.11.4.5.3	RRC-based Active BWP Switch	
A.11.4.5.3.1		
A.11.4.6	Active TCI state switching delay	
	leasurement procedure	
A.11.5.1	Intra-frequency measurements	
A.11.5.1.1	Event-triggered reporting tests on PCC without gaps under non-DRX	
A.11.5.1.1		
A.11.5.1.1.2		
A.11.5.1.1.3		
A.11.5.1.1.3 A.11.5.1.2	Event-triggered reporting tests on PCC without gaps under DRX	
A.11.5.1.2.1		
A.11.5.1.2.2	• •	
A.11.5.1.2.2 A.11.5.1.2.3	<u>•</u>	
A.11.5.1.3	Event-triggered reporting tests on PCC with per-UE gaps under non-DRX	
A.11.5.1.3.1		
A.11.5.1.3.1 A.11.5.1.3.2		
A.11.5.1.3.2 A.11.5.1.3.3		
A.11.5.1.3.3 A.11.5.1.4	Event-triggered reporting tests on PCC with per-UE gaps under DRX	
A.11.5.1.4 A.11.5.1.4.1		
A.11.5.1.4.1 A.11.5.1.4.2		
A.11.5.1.4.2 A.11.5.1.4.3		
A.11.5.1.4.5 A.11.5.1.5	Event-triggered reporting tests on SCC without gaps under non-DRX	
A.11.5.1.5 A.11.5.1.5.1		. 2560

A.11.5.1.5.2	Test parameters	
A.11.5.1.6	Event-triggered reporting tests on SCC without gaps under DRX	. 2560
A.11.5.1.6.1	Test purpose and environment	. 2560
A.11.5.1.6.2	Test parameters	. 2560
A.11.5.1.6.3	Test Requirements	.2560
A.11.5.1.7	Event-triggered reporting tests on SCC with per-UE gaps under non-DRX	. 2561
A.11.5.1.7.1	Test purpose and environment	. 2561
A.11.5.1.7.2	Test parameters	.2561
A.11.5.1.7.3	Test Requirements	
A.11.5.1.8	Event-triggered reporting tests on SCC with per-UE gaps under DRX	
A.11.5.1.8.1	Test purpose and environment	
A.11.5.1.8.2	Test parameters	
A.11.5.1.8.3	Test Requirements	
A.11.5.1.9	RSSI measurement reporting on PCC	
A.11.5.1.9.1	Test purpose and environment	
A.11.5.1.9.2	Test parameters	
A.11.5.1.10	Channel occupancy measurement reporting on PCC	
A.11.5.1.10.1	Test purpose and environment	
A.11.5.1.10.2	Test parameters	
A.11.5.1.11	RSSI measurement reporting on SCC	
A.11.5.1.11	Test purpose and environment	
A.11.5.1.11.2		
A.11.5.1.11.2 A.11.5.1.12	Channel occupancy measurement reporting on SCC	
A.11.5.1.12.1 A.11.5.1.12.2	Test purpose and environment	
	Test parameters	
	Inter-frequency measurements	
A.11.5.2.1	RSSI measurement reporting	
A.11.5.2.1.1	Test purpose and environment	
A.11.5.2.1.2	Test parameters	
A.11.5.2.2	Channel occupancy measurement reporting	
A.11.5.2.2.1	Test purpose and environment	
A.11.5.2.2.2	Test parameters	. 2564
A.11.5.2.3	Event triggered reporting tests for FR1 with CCA without SSB time index detection when DRX	
	is not used	
A.11.5.2.3.1	Test Purpose and Environment	
A.11.5.2.3.2	Test Requirements	. 2568
A.11.5.2.4	Event triggered reporting tests for FR1 with CCA without SSB time index detection when DRX	
	is used	
A.11.5.2.4.1	Test Purpose and Environment	
A.11.5.2.4.2	Test Requirements	. 2573
A.11.5.2.5	Event triggered reporting tests for FR1 with CCA with SSB time index detection when DRX is	
	not used	. 2574
A.11.5.2.5.1	Test Purpose and Environment	.2574
A.11.5.2.5.2	Test Requirements	.2578
A.11.5.2.6	Event triggered reporting tests for FR1 with CCA with SSB time index detection when DRX is	
	used	.2579
A.11.5.2.6.1	Test Purpose and Environment	
A.11.5.2.6.2	Test Requirements	
A.11.5.2.7	Event triggered reporting tests for FR1 without SSB time index detection when DRX is not used	
A.11.5.2.7.1	Test Purpose and Environment	
A.11.5.2.7.2	Test Requirements	
A.11.5.2.8	Event triggered reporting tests for FR1 without SSB time index detection when DRX is used	
A.11.5.2.8.1	Test Purpose and Environment	
A.11.5.2.8.1 A.11.5.2.8.2	Test Purpose and Environment Test Requirements	
A.11.5.2.8.2 A.11.5.2.9	Event triggered reporting tests for FR1 with SSB time index detection when DRX is not used	
A.11.5.2.9 A.11.5.2.9.1	Test Purpose and Environment	
A.11.5.2.9.1 A.11.5.2.9.2	Test Purpose and Environment Test Requirements	
A.11.5.2.9.2 A.11.5.2.10	Event triggered reporting tests for FR1 with SSB time index detection when DRX is used	
A.11.5.2.10.1	Test Pagyirement	
A.11.5.2.10.2	Test Requirements	
	Inter-RAT E-UTRAN measurements	
A.11.5.4	L1-RSRP measurements for beam reporting	. 2606

A.11.5.4.1	SSB based L1-RSRP measurement when DRX is not used	2606
A.11.5.4.1.1	Test Purpose and Environment	2606
A.11.5.4.1.2	Test parameters	2606
A.11.5.4.1.3	Test Requirements	
A.11.5.4.2	SSB based L1-RSRP measurement when DRX is used	2608
A.11.5.4.2.1	Test Purpose and Environment	2608
A.11.5.4.2.2	Test parameters	
A.11.5.4.2.3	Test Requirements	
A.11.5.4.3	SSB based L1-RSRP measurement on SCC when DRX is not used	
A.11.5.4.3.1	Test Purpose and Environment	
A.11.5.4.3.2	Test parameters	
A.11.5.4.3.3	Test Requirements	
A.11.5.4.4	SSB based L1-RSRP measurement on SCC when DRX is used	
A.11.5.4.4.1	Test Purpose and Environment	
A.11.5.4.4.1 A.11.5.4.4.2	Test parameters	
A.11.5.4.4.2 A.11.5.4.4.3		
	Test Requirements	
	easurement performance	
A.11.6.1	SS-RSRP	
A.11.6.1.1	Intra-frequency measurement accuracy on a carrier frequency with CCA	
A.11.6.1.1.1	Test Purpose and Environment	
A.11.6.1.1.2	Test parameters	
A.11.6.1.1.3	Test Requirements	
A.11.6.1.2	Intra-frequency measurement accuracy on SCC on a carrier frequency with CCA	
A.11.6.1.2.1	Test Purpose and Environment	2622
A.11.6.1.2.2	Test parameters	2622
A.11.6.1.2.3	Test Requirements	2624
A.11.6.2	SS-RSRQ	2624
A.11.6.3	SS-SINR.	
A.11.6.4	L1-RSRP measurement for beam reporting with CCA serving cell	
A.11.6.4.1	SSB based L1-RSRP measurement	
A.11.6.4.1.1	Test Purpose and Environment	
A.11.6.4.1.2	Test parameters	
A.11.6.4.1.3	Test Requirements	
A.11.6.5	RSSI	
A.11.6.5.1	Intra-frequency RSSI measurement accuracy on PCC with CCA	
A.11.6.5.1	Test Purpose and Environment	
	Test parameters	
A.11.6.5.1.2	1	
A.11.6.5.1.3	Test Requirements	
A.11.6.5.2	Intra-frequency RSSI measurement accuracy on SCC with CCA	
A.11.6.5.2.1	Test Purpose and Environment	
A.11.6.5.2.2	Test parameters	
A.11.6.5.2.3	Test Requirements	
A.11.6.5.3	Inter-frequency RSSI measurement accuracy on a carrier with CCA	
A.11.6.5.3.1	Test Purpose and Environment	2633
A.11.6.5.3.2	Test parameters	2633
A.11.6.5.3.3	Test Requirements	2636
A.11.6.6	Channel occupancy	
A.11.6.6.1	Intra-frequency channel occupancy measurement accuracy on PCC with CCA	
A.11.6.6.1.1	Test Purpose and Environment	
A.11.6.6.1.2	Test parameters	
A.11.6.6.1.3	Test Requirements	
A.11.6.6.2	Intra-frequency channel occupancy measurement accuracy on SCC with CCA	
A.11.6.6.2.1	Test Purpose and Environment	
A.11.6.6.2.2	Test parameters	
A.11.6.6.2.3	Test Requirements	
A.11.6.6.3	Inter-frequency channel occupancy measurement accuracy on a carrier with CCA	
A.11.6.6.3.1	Test Purpose and Environment	
A.11.6.6.3.2	Test parameters	
A.11.6.6.3.3	Test Requirements	
A.11.6.7	E-UTRAN RSRP	
A.11.6.8	E-UTRAN RSRQ	
A.11.6.9	E-UTRAN SINR	2645

A.12 E-UTRA Standalone Tests with at Least One NR Cell under CCA	2645
A.12.1 RRC_IDLE state mobility	
A.12.1.1 Inter-RAT cell re-selection to NR on a carrier frequency with CCA	. 2645
A.12.1.1.1 E-UTRA Cell reselection to higher priority NR target Cell in FR1 when target cell is subject to CCA	
A.12.1.1.1 Test Purpose and Environment	
A.12.1.1.1.2 Test Requirements	
A.12.2 RRC_CONNECTED state mobility	
A.12.2.1 Handover	
A.12.2.1.1 E-UTRAN - NR with CCA handover	
A.12.2.1.1.1 Test Purpose and Environment	
A.12.2.1.1.2 Test rupose and Environment Test rupose and Environment Test rupose and Environment	
A.12.3 Signalling characteristics	
A.12.3.1 Interruptions	
A.12.4 Measurement procedure	
A.12.4.1 E-UTRAN–NR inter-RAT SFTD measurements	
A.12.4.1.1 E-UTRA – NR Inter-RAT SFTD Measurement Delay with NR under CCA in non-DRX	
The state of the s	
1	
A.12.4.2 E-UTRAN-NR inter-RAT measurements on NR carrier frequency under CCA	. 2661
A.12.4.2.1 E-UTRA-NR inter-RAT event triggered reporting tests for FR1 without SSB time index	21
detection when DRX is not used	
A.12.4.2.1.1 Test Purpose and Environment	
A.12.4.2.1.2 Test Requirements	. 2665
A.12.4.2.2 E-UTRA-NR inter-RAT event triggered reporting tests for FR1 without SSB time index	
detection when DRX is used	
A.12.4.2.2.1 Test Purpose and Environment	
A.12.4.2.2.2 Test Requirements	
A.12.4.2.3 NR Inter-RAT event triggered reporting tests for FR1 with SSB time index detection when DRX	
is not used	
A.12.4.2.3.1 Test Purpose and Environment	
A.12.4.2.3.2 Test Requirements	
A.12.4.2.4 NR Inter-RAT event triggered reporting tests for FR1 with SSB time index detection when DRX	
is used	. 2675
A.12.4.2.4.1 Test Purpose and Environment	. 2675
A.12.4.2.4.2 Test Requirements	. 2679
A.12.4.2.5 RSSI measurement reporting	. 2679
A.12.4.2.5.1 Test purpose and environment	. 2679
A.12.4.2.5.2 Test parameters	. 2679
A.12.4.2.6 Channel occupancy measurement reporting	. 2680
A.12.4.2.6.1 Test purpose and environment	. 2680
A.12.4.2.6.2 Test parameters	. 2680
A.12.5 Measurement performance	.2680
A.12.5.1 E-UTRAN-NR SFTD	.2680
A.12.5.1.1 Inter-RAT SFTD accuracy with NR target cell under CCA	.2680
A.12.5.1.1.1 Test Purpose	.2680
A.12.5.1.1.2 Test Environment	
A.12.5.1.1.3 Test Requirements	
A.12.5.2 E-UTRAN-NR SS-RSRP	
A.12.5.3 E-UTRAN-NR SS-RSRQ	
A.12.5.4 E-UTRAN-NR SS-SINR	
A.12.5.6 E-UTRAN-NR channel occupancy	. 2686
A.13 NR Standalone Tests with NR SCell under CCA and All Other NR Cells in FR1	
A.13.1 Timing	
A.13.1.1 UE transmit timing	
A.13.1.2 Timing advance	
A.13.2 Signalling characteristics	
A.13.2.1 Interruption	
A.13.2.1.1 NR interruptions during SCell operations with CCA on SCell	. 2686

A.13.2.1.1.1	Test Purpose and Environment	
A.13.2.1.1.2	Test Requirements	
A.13.2.2	SCell activation and deactivation delay	. 2690
A.13.2.2.1	SCell Activation and Deactivation of known SCell under CCA, 160 ms SCell measurement cycle	2690
A.13.2.2.1.1	Test Purpose and Environment	. 2690
A.13.2.2.1.2	Test Requirements	. 2695
A.13.2.2.2 SO	Cell Activation and Deactivation of known SCell under CCA, 320 ms SCell measurement cycle	. 2695
A.13.2.2.2.1	Test Purpose and Environment	. 2695
A.13.2.2.2.2	Test Requirements	
A.13.2.2.3	SCell Activation and Deactivation of unknown SCell under CCA	
A.13.2.2.3.1	Test Purpose and Environment	. 2696
A.13.2.2.3.2	Test Requirements	
A.13.2.3	Active TCI state switching delay	
A.13.3 Me	easurement procedure	
A.13.3.1	Intra-frequency measurements	
A.13.3.1.1	Event-triggered reporting tests on SCC without gaps under non-DRX	
A.13.3.1.1.1	Test purpose and environment	
A.13.3.1.1.2	Test parameters	
A.13.3.1.1.3	Test Requirements	
A.13.3.1.2	Event-triggered reporting tests on SCC without gaps under DRX	
A.13.3.1.2.1	Test purpose and environment	
A.13.3.1.2.2	Test parameters	
A.13.3.1.2.3	Test Requirements	
A.13.3.1.3	Event-triggered reporting tests on SCC with per-UE gaps under non-DRX	
A.13.3.1.3.1	Test purpose and environment	
A.13.3.1.3.2	Test parameters	
A.13.3.1.3.3	Test Requirements	
A.13.3.1.4	Event-triggered reporting tests on SCC with per-UE gaps under DRX	
A.13.3.1.4.1	Test purpose and environment	
A.13.3.1.4.2	Test parameters	
A.13.3.1.4.3	Test Requirements	
A.13.3.1.5	RSSI measurement reporting on SCC	
A.13.3.1.5.1	Test purpose and environment	
A.13.3.1.5.2	Test parameters	
A.13.3.1.6	Channel occupancy measurement reporting on SCC	
A.13.3.1.6.1	Test purpose and environment	
A.13.3.1.6.2	Test parameters	
A.13.3.2	Inter-frequency measurements	
A.13.3.2.1	RSSI measurement reporting	
A.13.3.2.1.1	Test purpose and environment	
A.13.3.2.1.2	Test parameters	
A.13.3.2.2	Channel occupancy measurement reporting	
A.13.3.2.2.1	Test purpose and environment	
A.13.3.2.2.2	Test parameters	
A.13.3.2.3	Event triggered reporting tests for FR1 with CCA without SSB time index detection when DRX	. 2117
11.13.3.2.3	is not used	. 2719
A.13.3.2.3.1	Test Purpose and Environment	
A.13.3.2.3.1 A.13.3.2.3.2	Test Requirements	
A.13.3.2.4	Event triggered reporting tests for FR1 with CCA without SSB time index detection when DRX	. 2127
71.13.3.2.4	is used	2724
A.13.3.2.4.1	Test Purpose and Environment	
A.13.3.2.4.2	Test Requirements	
A.13.3.2.4.2 A.13.3.2.5	Event triggered reporting tests for FR1 with CCA with SSB time index detection when DRX is	. 212)
A.13.3.2.3	not used	
A.13.3.2.5.1	Test Purpose and Environment	
A.13.3.2.5.2	Test Requirements	. 2735
A.13.3.2.6	Event triggered reporting tests for FR1 with CCA with SSB time index detection when DRX is used	. 2735
A.13.3.2.6.1	Test Purpose and Environment	
A.13.3.2.6.2	Test Requirements	
A.13.3.2.0.2 A.13.3.3	L1-RSRP measurements for beam reporting	
A.13.3.3.1	SSB based L1-RSRP measurement when DRX is not used	
1 1.1 2 . 2 . 2 . 1	552 0050 21 1010 incubitorion when 2101 is not used	, ¬∠

A.13.3.3.	1.1 Test Purpose and Environment	2742
A.13.3.3. A.13.3.3.		
A.13.3.3. A.13.3.3.		
A.13.3.3. A.13.3.3.	•	
A.13.3.3.	1	
A.13.3.3.	1	
A.13.3.3.	1	
A.13.4	Measurement performance	
A.13.4.1	SS-RSRP	
A.13.4.1.		
A.13.4.1.	1.1 Test Purpose and Environment	2750
A.13.4.1.	1.2 Test parameters	2750
A.13.4.1.	1.3 Test Requirements	2752
A.13.4.2	SS-RSRQ	
A.13.4.3	SS-SINR	
A.13.4.4	L1-RSRP measurement for beam reporting with CCA serving cell	
A.13.4.4.	· · ·	
A.13.4.4.		
A.13.4.4.		
A.13.4.4.		
A.13.4.5	RSSI	
A.13.4.5.	1 1 1	
A.13.4.5.		
A.13.4.5.		
A.13.4.5.	- · · · · · · · · · · · · · · · · · · ·	
A.13.4.5.	1	
A.13.4.5.		
A.13.4.5.	2.2 Test parameters	2760
A.13.4.5.	2.3 Test Requirements	2764
A.13.4.6	Channel occupancy	2764
A.13.4.6.	Intra-frequency channel occupancy measurement accuracy on SCC with CCA	2764
A.13.4.6.		
A.13.4.6.		
A.13.4.6.	· ·	
A.13.4.6.		
	3 (normative): Conditions for RRM requirements applicability for operating bands	1787
B.1 Co	onditions for NR RRC_IDLE state mobility	1787
B.1.1	Introduction	
B.1.2	Conditions for measurements on NR intra-frequency cells for cell re-selection	1787
B.1.3	Conditions for measurements on NR inter-frequency cells for cell re-selection	1788
	onditions for UE measurements procedures and performance requirements in	
	RC_CONNECTED state	
B.2.1	Introduction	1788
B.2.1.1	General	
B.2.1.2	Derivation of Minimum SSB_RP values for FR1	1789
B.2.1.3	Derivation of Minimum SSB_RP values for FR2	1789
B.2.1.3.1	Minimum SSB_RP values for Rx Beam Peak angle of arrival	
B.2.1.3.2	Minimum SSB_RP values for angle of arrival within Spherical coverage	
B.2.1.4	Gain to SS-RSRP and CSI-RSRP measurement point for FR1	
B.2.1.5	Gain to SS-RSRP and CSI-RSRP measurement point for FR2	
B.2.1.5.1	Gain to SS-RSRP and CSI-RSRP measurement point for Rx Beam Peak angle of arrival	
B.2.1.6	Gain to PRS-RSRP measurement point for FR2	
B.2.1.6.1	Gain to PRS-RSRP measurement point for Rx Beam Peak angle of arrival	
B.2.1.0.1	Conditions for NR intra-frequency measurements	
B.2.3	Conditions for NR inter-frequency measurements.	
B.2.3 B.2.4	Conditions for NR L1-RSRP reporting	
12.4.4	CONGRESSION TO TAKE LITERAL TODOLUNG	1 / 94

B.2.4.1	Conditions for SSB based L1-RSRP reporting	1794	
B.2.4.2	Conditions for CSI-RS based L1-RSRP reporting	1795	
B.2.5	Conditions for RRC connection release with redirection to NR	1796	
B.2.6	Void	1798	
B.2.6.1	Void	1798	
B.2.6.2	Void	1798	
B.2.8	Conditions for NR L1-SINR reporting	1799	
B.2.8.1	Conditions for L1-SINR reporting with CSI-RS based CMR and no dedicated IMR configured	1799	
B.2.8.2	Conditions for L1-SINR reporting with SSB based CMR and dedicated IMR configured	1800	
B.2.8.2.1	L1-SINR reporting with SSB based CMR and dedicated ZP-IMR configured	1800	
B.2.8.2.2	L1-SINR reporting with SSB based CMR and dedicated NZP-IMR configured	1800	
B.2.8.3	Conditions for L1-SINR reporting with CSI-RS based CMR and dedicated IMR configured		
B.2.8.3.1			
B.2.8.3.2	5 T		
B.2.9	Conditions for NR intra-frequency measurements under CCA		
B.2.10	Conditions for NR inter-frequency measurements under CCA		
B.2.11	Conditions for NR L1-RSRP reporting under CCA	1804	
B.2.11.1	Conditions for SSB based L1-RSRP reporting		
B.2.12	Conditions for NR CSI-RS based intra-frequency measurements.		
B.2.13	Conditions for NR CSI-RS based inter-frequency measurements		
B.2.14	Conditions for NR PRS-based measurements	1808	
B.3 R	RM Requirements Exceptions	1809	
B.3.1	Introduction		
B.3.2	Receiver sensitivity relaxation for CA		
B.3.2.1	Receiver sensitivity relaxation for UE supporting CA in FR1		
B.3.2.2	Receiver sensitivity relaxation for UE configured with CA in FR1		
B.3.2.2.1	·		
B.3.2.2.2	• • • • • • • • • • • • • • • • • • • •		
B.3.2.2.3			
B.3.2.3	Receiver sensitivity relaxation for UE supporting CA in FR2		
B.3.2.4	Receiver sensitivity relaxation for UE configured with CA in FR2		
B.3.2.4.1	· · · · · · · · · · · · · · · · · · ·		
B.3.2.4.2	9 9 9		
B.3.3	Receiver sensitivity relaxation for DC		
B.3.3.1	Receiver sensitivity relaxation for EN-DC	1811	
B.3.3.2	Receiver sensitivity relaxation for NE-DC	1811	
B.3.4	Receiver sensitivity relaxation for SUL	1811	
B.3.4.1	Receiver sensitivity relaxation for UE supporting SUL in FR1	1811	
B.3.4.2	Receiver sensitivity relaxation for UE configured with SUL in FR1		
B.3.4.2.1	Reference sensitivity exceptions due to UL harmonic interference for SUL	1811	
B.4 C	onditions for V2X	1811	
B.4.1	Test parameters for GNSS signals		
B.4.2	Conditions for PSBCH-RSRP Accuracy Requirements		
B.4.3	Conditions for Selection/Reselection to Intra-frequency SyncRef UE		
B.4.4	Conditions for L1 SL-RSRP Accuracy Requirements		
Annex (Annex C (informative): Change history		