



Measured 2026-09-07, interior stud face to stud face, inches
Dashed not yet measured (TBD)
Origin interior corner, left of door walking in


1 PLAN



2 SECTION



3 DOOR / FLOOR RAISE



Gap now	3/8"
Any raise $R > 3/8"$	in-swing door hits new floor; cut slab $R - 3/8"$ or re-hang
Ceiling after raise	$93.5 - R$
Door clear height after raise	slab H $- R + 3/8$ (slab H TBD)