Machine Design Final Exam

August 1, 2022

Gabe Morris

```
[1]: # Notebook Preamble
     import sympy as sp
     import matplotlib.pyplot as plt
     from IPython.display import display
     plt.style.use('maroon_ipynb.mplstyle')
     def sub_return(expression, substitution, sym=None):
         Displays a substituted expression and returns the value.
         :param expression: Symbolic expression
         :param substitution: A list of tuples to be passed into the .sub method
         :param sym: An optional symbol to display prior to operations
         :return: A simplified value of what is substituted.
         HHHH
         with sp.evaluate(False):
             expr_sub = expression.subs(substitution)
         simp = expr_sub.doit().n()
         if sym is None:
             lev1 = sp.Eq(expression, expr_sub)
             lev2 = sp.Eq(lev1, simp, evaluate=False)
             display(lev2)
         else:
             lev1 = sp.Eq(sym, expression)
             lev2 = sp.Eq(lev1, expr_sub, evaluate=False)
             lev3 = sp.Eq(lev2, simp, evaluate=False)
             display(lev3)
         return simp
     def get_principal(s_x, s_y, t_xy):
         Shows the principal stress calculations for a 2D element.
         :param s_x: normal stress along the x-axis
         :param s_y: normal stress along the y-axis
```


```
:param t_xy: shear stress on face x in the direction of y
    :return: principal stresses
    s_x_, s_y_, t_xy_ = sp.symbols(r'\sigma_x \sigma_y \tau_{xy}')
    symbols_ = sp.symbols(r'\sigma_1 \sigma_2 \tau_1 \tau_2')
    expr1_ = (s_x_ + s_y_)/2 + sp.sqrt(((s_x_ - s_y_)/2)**2 + t_xy_**2)
    expr2_ = (s_x_ + s_y_)/2 - sp.sqrt(((s_x_ - s_y_)/2)**2 + t_xy_**2)
    expr3_ = sp.sqrt(((s_x_ - s_y_)/2)**2 + t_xy_**2)
    expr4_ = -sp.sqrt(((s_x_ - s_y_)/2)**2 + t_xy_**2)
    sub_list = [(s_x, s_x), (s_y, s_y), (t_xy, t_xy)]
    ans = \Pi
    for sym_, expr_ in zip(symbols_, [expr1_, expr2_, expr3_, expr4_]):
        ans.append(sub_return(expr_, sub_list, sym=sym_))
    return ans
def von_mises(s_x, s_y, s_z, t_xy, t_yz, t_zx):
   return 1/sp.sqrt(2)*sp.sqrt((s_x - s_y)**2 + (s_y - s_z)**2 + (s_z -
 \Rightarrows_x)**2 + 6*(t_xy**2 + t_yz**2 + t_zx**2))
def log10(x_):
    return sp.log(x_)/sp.log(10)
```

Contents

| 1 | Problem 3-83 | | | | | | | 4 |
|---|---------------|-------------------------|--|---|---|---|-----|---|
| | 1.1 | Given | | | | | | 4 |
| | 1.2 | Find | | | | | | 4 |
| | 1.3 | Solution | | | | | | 5 |
| | | 1.3.1 Part A and Part B | | | | | | 5 |
| | | 1.3.2 Part C | | | | | . ' | 6 |
| | | 1.3.3 Part D | | | | | . ' | 6 |
| | | 1.3.4 Part E | | | | | . ' | 7 |
| 2 | Pro | blem 5-36 | | | | | í | 8 |
| | 2.1 | Given | | | | | | 8 |
| | 2.2 | Find | | | | | | 8 |
| | 2.3 | Solution | | | | | | 8 |
| | | 2.3.1 Element A | | | | | | 8 |
| | | 2.3.2 Element B | | | | | | |
| 3 | D | No | | | | | 1, | ^ |
| 3 | | blem 6-62 Given | | | | | 10 | |
| | 3.1 | | | | | | | |
| | 3.2 | Find | | | | | | |
| | 3.3 | Solution | | | | | | |
| | | 3.3.1 Part A | | | | | | |
| | | 3.3.2 Part B | | • | • | • | . 1 | 1 |
| 4 | Pro | blem 8-26 | | | | | 1: | 2 |
| | 4.1 | Given | | | | | . 1 | 2 |
| | 4.2 | Find | | | | | . 1 | 2 |
| | 4.3 | Solution | | | | | . 1 | 2 |
| | | 4.3.1 Part A | | | | | . 1 | 2 |
| | | 4.3.2 Part B | | | | | . 1 | 3 |
| _ | _ | | | | | | _ | |
| 5 | | blem 9-13 | | | | | 1 | |
| | 5.1 | Given | | | | | | |
| | 5.2 | Find | | | | | | |
| | 5.3 | Solution | | • | ٠ | | . 1 | 4 |
| 6 | Problem 11-34 | | | | | | | 5 |
| | 6.1 | Given | | | | | . 1 | 5 |
| | 6.2 | Find | | | | | . 1 | 5 |
| | 6.3 | Solution | | | | | . 1 | 5 |
| | | 6.3.1 Bearing O | | | | | . 1 | 6 |
| | | 6.3.2 Bearing B | | | | | | 6 |

1 Problem 3-83

1.1 Given



A gear reduction unit uses the countershaft shown in the figure above. Gear A receives power from another gear with a transmitted force F_A applied at the 20° pressure angle as shown. The power is transmitted through the shaft and delivered through gear B through a transmitted force F_B at the pressure angle shown.

1.2 Find

- a. Determine the force F_B , assuming the shaft is running at a constant speed.
- b. Find the bearing reaction forces, assuming the bearings act as simple supports.
- c. Draw a shear-force and bending moment diagrams for the shaft. If needed, make one set for the horizontal plane and another set for the vertical plane.
- d. At the point of maximum bending moment, determine the bending stress and the torsional shear stress.
- e. At the point of maximum bending moment, determine the principal stresses and the maximum shear stress.

1.3 Solution


1.3.1 Part A and Part B

 F_B and the reaction forces may be found by summing the forces and taking the moments about the point O.

```
[2]: # Using matrices takes less thinking and more letting python do the work.
     Oy, Oz, Cy, Cz, F_B = sp.symbols('O_y O_z C_y C_z F_B')
     zero = sp.ZeroMatrix(3, 1)
     F_A_mat = sp.Matrix([0, 300*sp.cos(sp.rad(20)), -300*sp.sin(sp.rad(20))])
     F_B_mat = sp.Matrix([0, -F_B*sp.sin(sp.rad(20)), F_B*sp.cos(sp.rad(20))])
     0 = sp.Matrix([0, 0y, 0z])
     C = sp.Matrix([0, Cy, Cz])
     # Sum forces
     sys1 = sp.Eq(0 + F_A_mat + F_B_mat + C, zero)
     # Sum moments about O
     rA = sp.Matrix([16, 0, 10])
     rC = sp.Matrix([16 + 14, 0, 0])
     rB = sp.Matrix([16 + 14 + 9, 4, 0])
     sys2 = sp.Eq(rA.cross(F_A_mat) + rC.cross(C) + rB.cross(F_B_mat), zero)
     sol = sp.solve([sys1, sys2], dict=True)[0]
     for key, value in sol.items():
         display(sp.Eq(key, value.n())) # lbf
    C_y = 183.118820416782
    C_z = -861.477082334154
    F_{\rm R} = 750.0
    O_y = -208.511499158303
```

 $O_z = 259.313659742423$ The reaction forces above assume all positive directions.

1.3.2 Part C



1.3.3 Part D

The magnitudes of the moment at section A and section C must be compared.

```
[3]: M_A = sp.sqrt(sp.S('3336.18399')**2 + sp.S('4149.01856')**2)

M_C = sp.sqrt(sp.S('6342.92519')**2 + sp.S('2308.63597')**2)

display(M_A, M_C)
```

5323.95328927262

6750.00000058625

```
[4]: # M_C is the greater value
M_C = sp.S(6750) # in*lbf
d = sp.S('1.25')
sig = M_C*32/(sp.pi*d**3) # psi
T = 300*sp.cos(sp.rad(20))*10 # static torque
tau = T*16/(sp.pi*d**3) # psi
display(sig.n(), tau.n())
```

35202.5269328378


7351.01217595663

1.3.4 Part E

$$\begin{split} &\sigma_1 = \frac{\sigma_x}{2} + \frac{\sigma_y}{2} + \sqrt{\tau_{xy}^2 + \left(\frac{\sigma_x}{2} - \frac{\sigma_y}{2}\right)^2} = \frac{1}{2} \cdot 0 + \frac{1}{2} \cdot 35203.0 + \sqrt{7351.0^2 + \left(\left(-\frac{1}{2}\right)0 + \frac{1}{2} \cdot 35203.0\right)^2} = \\ &36675.875 \\ &\sigma_2 = \frac{\sigma_x}{2} + \frac{\sigma_y}{2} - \sqrt{\tau_{xy}^2 + \left(\frac{\sigma_x}{2} - \frac{\sigma_y}{2}\right)^2} = -\sqrt{7351.0^2 + \left(\left(-\frac{1}{2}\right)0 + \frac{1}{2} \cdot 35203.0\right)^2 + \frac{1}{2} \cdot 0 + \frac{1}{2} \cdot 35203.0} = \\ &-1473.375 \\ &\tau_1 = \sqrt{\tau_{xy}^2 + \left(\frac{\sigma_x}{2} - \frac{\sigma_y}{2}\right)^2} = \sqrt{7351.0^2 + \left(\left(-\frac{1}{2}\right)0 + \frac{1}{2} \cdot 35203.0\right)^2} = 19074.625 \\ &\tau_2 = -\sqrt{\tau_{xy}^2 + \left(\frac{\sigma_x}{2} - \frac{\sigma_y}{2}\right)^2} = -\sqrt{7351.0^2 + \left(\left(-\frac{1}{2}\right)0 + \frac{1}{2} \cdot 35203.0\right)^2} = -19074.625 \end{split}$$

2 Problem 5-36

2.1 Given



The figure above illustrates that the factor of safety for a machine element depends on the particular point selected for analysis. The bar is made of AISI 1006 cold-drawn steel and is loaded by the forces $F = 0.55 \, kN$, $P = 4.0 \, kN$, and $T = 25 \, N \cdot m$.

2.2 Find

Find the factor of safety for both elements using the distortion energy method.

2.3 Solution

The yield strength is $S_y=280\,MPa.$

2.3.1 Element A

```
[6]: P = sp.S(4_{000})

Sy = sp.S(280e6)

T = sp.S(25)

d = sp.S('0.015')

F = sp.S('0.55e3')

1 = sp.S('0.1')
```

```
sig_x = 4*P/(sp.pi*d**2)
      tau_xy = 16*T/(sp.pi*d**3) - 4*sp.S('0.55e3')/(3*(sp.pi/4)*(sp.S('0.015')**2))
      display(sig_x.n(), tau_xy.n()) # Pa
     22635369.6841807
     33575798.364868
 [7]: sig_prime = von_mises(sig_x, 0, 0, tau_xy, 0, 0)
      sig_prime.n() # Pa
 [7]: 62404828.8857068
 [8]: (Sy/sig_prime).n()
 [8]: 4.48683226922735
     2.3.2 Element B
 [9]: sig_x = 32*F*1/(sp.pi*d**3) + 4*P/(sp.pi*d**2)
      tau_xy = 16*T/(sp.pi*d**3)
      display(sig_x.n(), tau_xy.n()) # Pa
     188628080.701506\\
     37725616.1403011
[10]: sig_prime = von_mises(sig_x, 0, 0, tau_xy, 0, 0)
      sig_prime.n() # Pa
[10]: 199625196.727842
```

- [11]: (Sy/sig_prime).n()
- $[11]: \underbrace{1.40262854884865}$

ME 4403 Final Exam Gabe Morris gnm54

3 Problem 6-62

3.1 Given

The material properties of a machine part are $S_{ut}=85\,ksi,\ f=0.86,$ and a fully corrected endurance limit of $S_e=45\,ksi.$ The part is to be cycled at $\sigma_a=35\,ksi$ and $\sigma_m=30\,ksi$ for $12\cdot 10^3$ cycles.

3.2 Find

Using the Goodman criterion, estimate the new endurance limit after cycling.

- a. Use Miner's method.
- b. Use Manson's method.

3.3 Solution

3.3.1 Part A

```
[12]: Se = sp.S(45)
Sut = sp.S(85)
sig_a = sp.S(35)
sig_m = sp.S(30)
N = sp.S(12_000)
# f = sp.S('1.06') - sp.S('2.8e-3')*Sut + sp.S('6.9e-6')*Sut**2
f = sp.S('0.86')

sig_ar = sig_a/(1 - (sig_m/Sut)) # 6-59
sig_ar.n() # ksi
```

[12]: 54.0909090909091

```
[13]: a = (f*Sut)**2/Se
b = -sp.Rational(1, 3)*log10(f*Sut/Se)
display(a, b.n())
```

118.746888888889

-0.0702349543941723

The total number of cycles needs to be calculated, then the remaining number of cycles may be found.

```
[14]: N1 = (sig_ar/a)**(1/b)
N1.n()
```

[14]: 72815.2378713139

```
[15]: N_remaining = N1 - N
N_remaining.n()
[15]: 60815.2378713139
[16]: a_prime = sig_ar/(N_remaining**b)
    Se_prime = a_prime*1e6**b
    Se_prime.n() # ksi
[16]: 44.4344130331323

    3.3.2 Part B
    See p. 355.
[17]: Sf = f*Sut
    b_prime = log10(Sf/sig_ar)/log10(1e3/N_remaining)
    a_prime = sig_ar/(N_remaining**b_prime)
    Se_prime = a_prime*1e6**b_prime
    Se_prime.n() # ksi
[17]: 44.0529868187135
```

4 Problem 8-26

4.1 Given

A $\frac{3}{4}$ in-16 UNF series SAE grade 5 bolt has a $\frac{3}{4}$ -in ID steel tube 10 in long, clamped between washer faces of bolt and nut by turning the nut snug and adding one-third of a turn. The tube OD is the washer face diameter $d_w=1.5d=1.5(0.75)=1.125$ in.

4.2 Find

- a. Determine the bolt stiffness, the tube stiffness, and the joint constant C.
- b. When the one-third turn of the nut is applied, what is the initial tension F_i in the bolt?

4.3 Solution

4.3.1 Part A

The bolt stiffness comes from Eq. 8-17.

[18]: 10.640625

```
[19]: d = sp.S('0.75')
L = sp.S('10.75') # to the nearest quarter inch
LT = 2*d + sp.S('0.5')
ld = L - LT
lt = l - ld
Ad = sp.pi*d**2/4
At = sp.S('0.373') # table 8-2
E = sp.S(30e6) # psi (Table A-5)
kb = Ad*At*E/(Ad*lt + At*ld)
kb.n() # psi
```

[19]: 1295495.93286476

The stiffness the member may be calculated as a long bar (Eq. 4-4),

$$k = \frac{AE}{l}$$

```
[20]: km = sp.pi/4*(sp.S('1.125')**2 - sp.S('0.75')**2)*E/1

km.n()
```

[20]: 1656699.25091649

On p. 448, the joint constant is

$$C = \frac{k_b}{k_b + k_m}$$

[21]:
$$C = kb/(kb + km)$$

 $C.n()$

 $\hbox{\tt [21]:} 0.43882462107585$

4.3.2 Part B


The total displacement may be described as,

$$\delta = \delta_b + \delta_m = \frac{N_{turns}}{N_{threads}}$$

$$F_i = \frac{N_t k_b k_m}{N\left(k_b + k_m\right)} = \frac{1}{3} \cdot 1.2955 \cdot 10^6 \cdot 1.6567 \cdot 10^6 \cdot \frac{1}{16} \cdot \frac{1}{1.2955 \cdot 10^6 + 1.6567 \cdot 10^6} = \frac{15145.84375}{1.2955 \cdot 10^6 + 1.6567 \cdot 10^6} = \frac{1}{15145.84375} \cdot \frac{1}{1000} = \frac{1}{1000} = \frac{1}{1000} \cdot \frac{1}{1000} = \frac{1}{1000} = \frac{1}{1000} \cdot \frac{1}{1000} = \frac{1}{1000} \cdot \frac{1}{1000} = \frac{1}{1000} \cdot \frac{1}{1000} = \frac{1}{1000} =$$

5 Problem 9-13

5.1 Given



A steel bar of thickness h is welded to a vertical support as shown in the figure above.

b = 50 mm d = 50 mm h = 5 mm F = 100 kN

5.2 Find

What is the shear stress in the throat of the welds due to the force F?

5.3 Solution


Use Eq. 9-3

```
[23]: F = sp.S(100_000)
h = sp.S('0.005')
l = sp.S('0.2')
tau = sp.sqrt(2)*F/(h*1)
tau.n() # Pa
```

[23]: 141421356.23731

6 Problem 11-34

6.1 Given



The figure above is a geared countershaft with an overhanging pinion at C. The force on gear A is $F_A = 600\,lbf$, and the shaft is to run at a speed of 420 rpm. The solution of the statics problem gives the force of the bearings against the shaft at O as $R_O = -387j + 467k\,lbf$, and at B as $R_B = 316j - 1615k\,lbf$.

6.2 Find

Select an angular contact ball bearing from Table 11-2 for mounting at O and an O2-series cylindrical roller bearing from Table 11-3 for mounting at B. Specify the bearings required, using an application factor of 1.2, a desired life of 40,000 hours, and a combined reliability goal of 0.95, assuming distribution data from manufacturer 2 in Table 11-6.

6.3 Solution

[24]:

6.3.1 Bearing O

```
[25]: x0, theta = sp.S('0.02'), sp.S('4.459')
b = sp.S('1.483')
RD = sp.sqrt(sp.S('0.95'))

kN = sp.S('4.44822')/sp.S(1000)

a = sp.S(3)
af = sp.S('1.2')
FD = sp.sqrt(sp.S(-387)**2 + sp.S(467)**2)
C10 = af*FD*(xD/(x0 + (theta - x0)*(sp.log(1/RD))**(1/b)))**(1/a)
(C10*kN).n() # kN
```

[25]: 44.2269113767268

For bearing O, select the 02-55 mm angular contact bearing with a rating of 46.2 kN.

6.3.2 Bearing B

```
[26]: a = sp.Rational(10, 3)

af = sp.S('1.2')

FD = sp.sqrt(sp.S(316)**2 + sp.S(-1615)**2)

C10 = af*FD*(xD/(x0 + (theta - x0)*(sp.log(1/RD))**(1/b)))**(1/a)

(C10*kN).n() # kN
```

[26]: 92.3909500897365

For bearing B, select the 02-75 mm with a rating of 93.1 kN.