TEMPORARY CHANGE REQUESTTCR NO. TCR-QA-005,R3-001

(e.g., TCR-ENG-021,R1-001)

The Temporary Change Request (TCR) Form is to be used to process <u>urgent or minor changes</u> for PPPL Policies, Organization/Mission Statements and Procedures. The TCR should be used when changes are:

- 1) urgent, and can not wait the 2-4 week period for Department Head review/comment, or
- 2) minor, and do not warrant Department Head review.

Person Requesting Change:	Frank Malinowski	_		
Department Name: Best Practice	es & External Affairs	Phone Ext: 2203		
Document Number: <u>QA-005</u>	Revision No.: 3			
Document Title: Control of None	conformances			
Reason for change: To have Supp	olier nonconformances tr	ansmitted by Procure	ment.	
Change description: (Summarize	and attach changed page	es, with changes clear	ly indicated)	
Section B Steps 1 & 2 all				ent.
Steps 6 & 7 change trans	smittal from QA	to Procurement	<u>.</u>	
1. Does this TCR significantly alte	er the intent or scope of the	he document?	YES:_	NO: <u>X</u>
2. Does this TCR significantly imp	oact ES&H?	YES:	NO: <u>X</u>	
If 1 or 2 is YES , Explain why	the changes should not b	e routed for Departme	ent Head revie	w:
	are changes should not s	o routed for Departme	0110 110uu 10 110	
J. Malsbury		<u>07/8</u>	/08	
Department/Division Head Appr	roval	Date		
J. DeLooper			11/08	
Associate Director, Best Practice	es and External Affairs	Date		
Release/Effective date of this TCR	· 7/11/0Q			
		_		
Incorporate this TCR into next rev				

PPPL	PRINCETON PLASMA PHYSICS LABORATORY	PROCED	No. QA-005 Rev 3 Page 1 of 5
Subject:		Effective Date:	Initiated by:
Contro	l of Nonconformances	March 30, 2007	Head, Quality Assurance
		Supersedes: TCR QA-005-001,	Approved:
		QA-005 Rev. 2	Director

Applicability

This procedure provides guidelines for items and services that fail to meet specified standards.

Introduction

Items, services, or activities that fail to conform to specified requirements shall be controlled to prevent their inadvertent installation or continued use. Provisions shall be made to identify, evaluate, and disposition such nonconformances. Provisions shall also be made to segregate the item or to stop the specific nonconforming activity or condition causing the nonconformance. Organizations affected by the discrepant item or activity shall be notified.

Section A addresses processing of PPPL-generated nonconformances, both those associated with items and services provided by suppliers and those associated with work performed in-house. Section B addresses processing of supplier-generated nonconformance documentation.

Reference Documents

Institutional QA Plan.
DOE O 414.1, *Quality Assurance*10 CFR 830.120, *Quality Assurance*QA-004 PPPL Site Inspection Program

Definitions

Refer to Attachment 1 for definitions of terms used within this procedure.

PROCEDURE

Section A: PPPL-generated Nonconformance Reports

Responsibility Action

Any PPPL Employee 1. Identifies a potentially nonconforming condition. Notifies Quality Assurance (QA).

PRINCETON PLASMA PHYSICS LABORATORY

PROCEDURE

No. QA-005 Rev 3 Page 2 of 5

TCR-QA-005, R3-001

Quality Assurance

2. Reviews potential nonconformances for validity and, if valid, notifies Cognizant Individual of the nonconformance. Generates a Risk Assessment Plan (RAP), also known as a Quality Inspection Plan, if one does not already exist for the work in question, a Nonconformance Report (NCR) and, when determined by QA to be appropriate, a "Hold" tag(s).

Note: Documentation for the NCR should include any relevant photographs, sketches, references to specifications, or engineering requirements. Supporting evidence should also include a description of the method of inspection.

3. Issues NCR to the Cognizant Individual. Includes appropriate Procurement and Accounting representatives on the distribution for supplier-related nonconformances.

Procurement

4. If supplier-related, notifies the appropriate supplier of any nonconforming conditions. Requests the supplier's recommended disposition and forwards it to the Cognizant Individual and QA. If required, negotiates NCR resolution with supplier, Cognizant Individual, and QA.

Cognizant Individual

5. Reviews NCR and evaluates the nonconforming condition. If a supplier-related NCR, either concurs with the supplier's recommendation or discusses concerns with QA and Procurement. If an NCR related to internal work, provides a disposition within 10 working days. If a disposition cannot be provided within 10 working days, notifies QA and provides an estimated time to complete the disposition. The disposition must include technical justification and fall into one of the following categories, as defined in Attachment 1:

- a. Rework (reprocessing to bring the item back into conformance see Attach. 1)
- b. Reject (not suitable for be use in the intended application)
- c. Repair (added processing to bring the item acceptably close to conformance see Attach. 1)
- d. Use-as-is

PROCEDURE

No. QA-005 Rev 3 Page 3 of 5

TCR-OA-005, R3-001

Note: The justification, if related to an item or process, must identify the governing document, specification, or technical reference supporting the Cognizant Individual's disposition.

Cognizant Individual

- 6. Considers and includes, when applicable, actions to prevent recurrence. Considers and addresses, when applicable, similar items that should be checked for the same condition(s). Lists any documents that require revision as a result of the disposition and ensures that these revisions are made.
- 7. Provides a cost estimate for dispositions requiring rework or repair by PPPL staff. Signs and dates NCR.
- 8. Forwards the NCR to the Responsible Line Manager (RLM). If the RLM is the Cognizant Individual, forwards to next higher level manager for signature.

Responsible Line Manager

- 9. Reviews the disposition and ensures that both the action to correct and the action(s) to prevent recurrence are appropriate. Ensures that the disposition complies with steps 5, 6, & 7 above. Indicates approval by signing and dating the NCR.
- 10. Forwards NCR to the Head of Engineering & Technical Infrastructure.

Note: In some instances additional management reviews are required prior to obtaining Head of Engineering concurrence. For example, NCR's related to, but not limited to NCSX, radwaste shipments, or fire protection systems (including penetrations) require additional review, approval and or distribution. These additional requirements can be found at

http://www-local.pppl.gov/QA/MiscPub/AddlMgmtRvw.pdf

Head, Engineering and Technical Infrastructure

11. Reviews NCR's disposition and indicates approval by signing and dating the NCR. Forwards the NCR to QA.

QA

12. Reviews the disposition for inconsistencies. If inconsistencies are identified, addresses them with the Cog. If disposition is acceptable, signs the NCR.

PRINCETON PLASMA PHYSICS LABORATORY

PROCEDURE

No. QA-005 Rev 3 Page 4 of 5

TCR-QA-005, R3-001

QA

- 13. For Use-As-Is disposition, removes any Hold tag(s). For rejected items the QA inspector determines if there is a benefit to applying a Reject tag. Unless not practical, rejected items retained for use shall be tagged or marked with the NCR number to ensure awareness of the nonconforming condition.
- 14. Verifies, for internal work, that the nonconformance has been satisfactorily resolved. Removes any Hold tag.
- 15. When satisfactorily resolved, closes the NCR and maintains official version in associated RAP folder on the QA Server. When the RAP and all associated NCR's are closed, forwards paper copies of the RAP and NCR's to the Operations Center to be maintained as backup copies.
- 16. Provides, as a minimum, copies of the closed NCR to the Cognizant Individual, his/her supervisor, Engineering Department Head, Senior QA Inspector and the Quality Assurance Division Head. Additional requirements regarding distribution of NCR's, including those that are supplier-related, can be found at http://www-local.pppl.gov/QA/MiscPub/AddlMgmtRvw.pdf

Section B: Supplier-generated Nonconformance Reports

Responsibility

Action

QA or **Procurement**

 Receives NCR (supplier designations will vary and may include Deficiency Report, Request for Waiver, or similar form names) documenting a nonconforming condition identified during processing or inspection. Forwards NCR to Cognizant Individual and QA or Procurement. TCR-QA-005, R3-001

QA

2. Tracks PPPL processing of NCR. TCR-QA-005, R3-001

PRINCETON PLASMA PHYSICS LABORATORY

3.

PROCEDURE

No. QA-005 Rev 3 Page 5 of 5

TCR-OA-005, R3-001

Cognizant Individual

Reviews nonconforming condition against requirements and evaluates the Supplier's disposition. Either concurs with the supplier's recommendation and signs NCR or discusses concerns with QA and Procurement, who will work with the supplier and Cognizant Individual to get an acceptable resolution.

Cognizant Individual

4. Forwards the signed NCR to the Responsible Line Manager (RLM). If the RLM is the Cognizant Individual, forwards to next higher level manager.

Responsible Line Manager

5. Signs indicating concurrence with the disposition or returns NCR to Cognizant Individual to obtain an acceptable disposition. Forwards signed NCR to QA.

Note: Supplier forms will vary and may not have clearly delineated spaces for two customer signatures. Signatures should be identified as PPPL Concurrence and added wherever there is space on the form, preferably near the disposition.

QA

6. Reviews the disposition for inconsistencies. If inconsistencies are identified, addresses them with the Cog. If disposition is acceptable, forwards the NCR to Procurement. TCR-QA-005, R3-001

Procurement

7. Returns signed NCR to Supplier for inclusion in the Processing History.

Cognizant Individual

8. Provides a copy of the NCR, with the Processing history, to the Operations Center or Project's designated records repository.

Attachments

- 1. Definitions
- 2. Sample NCR Form
- 3. Sample Hold and Reject Tags

_	_	_	_
_	_	_	

PRINCETON PLASMA PHYSICS LABORATORY

PROCEDURE

No. QA-005 Rev 3 Page 1 of 1

Definitions Attachment 1

TCR-QA-005, R3-001

DEFINITIONS

HOLD Tag: A means of identifying that an item is not to be used until the

nonconforming condition is corrected.

Risk Assessment Plan (RAP): The RAP, also known as Quality Inspection Plan, is a

document used by QA/QC to plan inspections. It is generated using the QA RAP/NCR/PQA Database. The structure of this

database requires that a RAP exist for all NCR's. See

procedure QA-004 for further information and a sample RAP.

Reject: An unacceptable item that is subject to be scrapped or

returned to the supplier. A rejected item may also be used,

with or without modification, for a different application.

REJECT Tag: The reject tag indicates that the item is "Rejected" and is not

to be used.

Repair: The process of restoring an item's nonconforming

characteristic to a condition such that the capability of that item to function reliably and safely is unimpaired, even though the item might still not conform to the original

requirement.

Rework: The process by which an item is made to conform to original

requirements by completion or corrective action.

Use-as-is: A disposition permitted for a nonconforming item when it

can be established that the item is fully satisfactory for its

intended use.

PRINCETON PLASMA PHYSICS LABORATORY

PROCEDURE

No. QA-005 Rev 3 Page 1 of 1

Sample Nonconformance Report Form

Attachment 2

TCR-QA-005, R3-001

PPPL NONCONFORMANCE RE		T		Open Date	-
Donastmant		Trend			-
Source/Org		DIVISION			
Item Drawing/Part#	Procurement #		Cost	Center	
RAP # Job Doc#		Vendor			
RAP Title:					
Hold Tag Applied					
Nonconforming Condition in	nclude requirements	violated:			
Lot Size Recd Sa	ample Size Insp		Lot Rejecte	d # Rejected	
	Validated By	Return To		Scrap*	
Reported By	" Use As Is*		Vendor*	Scrap*	
Reported By Disposition: Rework* Repair For rework or repair of vendor s	" Use As Is*	in informat \$G&A	Vendor*		
Reported By Disposition: Rework* Repair For rework or repair of vendor s #Hours \$Es	upplied equipments, fill	in informat	Vendor*	Scrap*	
Possition: Rework* Repair For rework or repair of vendor s #Hours \$Es \$Material \$B	upplied equipments, fill	in informat \$G&A	Vendor*	Scrap*	
Possition: Rework* Repair For rework or repair of vendor s #Hours \$Es \$Material \$B	upplied equipments, fill	in informat \$G&A \$Total	ion below:	Distribution Cog	
For rework or repair of vendor s #Hours \$Es \$Material \$B Disposition By Supervisor's Concur	upplied equipments, fill	in informat \$G&A \$Total	ion below:	Distribution Cog	
Por rework or repair of vendor s #Hours \$Es	upplied equipments, fill	in informat \$G&A \$Total Date Date	ion below:	Distribution Cog Insp Proj. Doc Contro (when closed) QC Files	
For rework or repair of vendor s #Hours \$Es \$Material \$B Disposition By Supervisor's Concur Eng. Dept. Head Concur	upplied equipments, fill	in informat \$G&A \$Total Date Date	ion below:	Distribution Cog Insp Proj. Doc Contro (when closed)	

P	P	P	T
_	_	_	

PRINCETON PLASMA PHYSICS LABORATORY

PROCEDURE

No. QA-005 Rev 3 Page 1 of 1

Sample Hold Tag & Sample Reject Tag

Attachment 3

TCR-QA-005, R3-001

QA INSPECTION HOLD				
Date	NCR No			
SPEC/DW'G/P.O.# COMMENTS				
QA	Engr			

(Yellow) HOLD Tag

QA INSPECTION REJECT		
Date	NCR No	
SPEC/DW'G/P.O. COMMENTS	#	
QA	Engr	

(Red) REJECT Tag