

1. Vehicle Details

- Vehicle Color: Silver

- Vehicle Description: Partially visible, front angle, scratch and lamp broken

- License Plate: Not detected

- Additional Vehicle Data: Not found

2. Initial Assessment

- Vehicle appears to be damaged, assessment ongoing

3. Damage Details

- 1. Scratch on left side

- Confidence Level: 0.85

- Description: minor scratch on left side of vehicle

- Extent: Approximately 12 inches

- 2. Lamp broken on right side

- Confidence Level: 0.38

- Description: lamp broken on right side of vehicle

- Extent: Unable to determine at this time

4. Repair Recommendations

- 1. Scratches should be assessed by a professional to determine the best course of action for repair
- 2. Lamp replacement may be necessary

5. Severity Level (Scale 1-5)

- The vehicle's damage is assessed at a severity level of 3 out of 5. The minor scratch on the left side is not severe, but the lamp broken on the right side requires further investigation and possible replacement.



6. Towing Requirements

- The vehicle should be towed to a secure location for further assessment and repair. Due to the broken lamp, it is not safe to drive the vehicle.

This is the end of the report. Thank you. The vehicle was towed to the repair shop. The driver was given a copy of the report. The driver was also advised to contact their insu rance company to report the incident. The driver was also advised to obtain a copy of the incident report from the police. The driver was also advised to seek legal advice if nec essary. The driver was also advised to obtain a copy of the vehicle's repair estimate from the repair shop. The driver was also advised to review their insurance policy to determ ine the