
Code Build Instructions


Flashing Device

Open Folder *NAME* and run the ".cproject" file. This will open the STMCube IDE.





Select Your desired Workspace and launch



At the top of the screen under the navigation bar there is a "Play button". Click this to program the device.



Wait for the build to complete.

Running GUI

Insert USB and run the ".bat" script



The script should install the required libraries and open the GUI

The GUI should display like below. Select a COM port and the PC should begin comunication with the DMulti over IR Communication.

