HOUSTON POWER SAVERS



TACLB020326E

10222 INWOOD DR. HOUSTON, TEXAS 77042 OFFICE # (832) 968-0000

DATE: **INVOICE** # September 24, 2021

FOR:

Estimate

South Acres Ranch 11409 Scott Street Houston, TX, 77047 (713) 731-2800 southacresranchmgr@hettig-kahn.com

DESCRIPTION	AMOUNT
2 bags of 12" flex	
subtotal	\$ 297.00
2 bags of 8" flex	
subtotal	\$ 247.00
2 bags of 6" flex	
subtotal	\$ 237.00
New box and all new collars and dampers	
subtotal	\$ 97.00
Replace all duct work from attic to downstairs (living room, kitchen, etc)	
*gut and remove old duct	
*run new duct throughout downstairs system	
*strap to code	
*reseal openings with hardcast	
labor subtotal	\$ 1,297.00
Notes:	
Need to confirm house number	
TOTAL	\$ 2,175.00

THANK YOU FOR YOUR BUSINESS!