## **Houston Power Savers**

**INVOICE** 

**TACLB020326E** 

Code: iccf414

DATE:

: November 1, 2021

INVOICE #

FOR: Estimate

10222 Inwood Dr Houston,Texas 77042 Office: (832) 968-0000

www.HoustonPowerSavers.com

Steve Hartwig 664 W Forest Dr Houston, TX , 77079 (713) 962-9170 Schartwig@sbcglobal.net

DESCRIPTION	AMOUNT
Install new 4 ton evaporator slab coil	
M/N: / S/N:	
*vacuum time, ~1 hr	
*reseal openings with hardcast	
subtota	\$ 2,875.00
Install new 48k BTU gas furnace	
M/N: / S/N:	
*reseal openings with hardcast	
*new roofjack	
*new supply plenum	
*new double wall vent pipe	
*rewire controls to furnace	
subtota	\$ 3,675.00
All new duct work	
*all new collars and dampers	
*15 bags of R8 flex	
subtota	\$ 1,800.00
Install new return air system	
*sheet metal can	
*18 inch flex and 2 18" collars	
subtota	\$ 975.00
Labor cost	
subtota	\$ 1,047.00
Note: 10 yr warranty on parts. 20 yr warranty on heat exchanger	
HPS Provides a 2 yr. labor warranty	
TOTAL	\$ 10,372.00

If you have any questions concerning this invoice, Kenneth Longoria 713-3062694

## THANK YOU FOR YOUR BUSINESS!