HOUSTON POWER SAVERS



TACLB020326E

10222 INWOOD DR. HOUSTON, TEXAS 77042 OFFICE # (832) 968-0000

DATE: INVOICE # September 1, 2021

FOR:

Estimate

Connie Seegmiller 5715 Tangle Circle Ln Houston, TX 77057

DESCRIPTION		AMOUNT
Install new 5 ton 14 SEER condensing unit		
M/N: / S/N:		
*pull vacuum		
*vacuum time; ~1 HR		
*flush copper lines with R-11		
subtota	۱ _{\$}	2,549.00
Install new 5 ton evaporator slab coil		
M/N: / S/N:		
*reseal openings with hardcast		
subtota	1 \$	1,949.00
Labor cost		
subtota	I \$	975.00
Cost of freon to recharge system		
subtota	I \$	500.00
Notes: Email manufacturer warranty information to equipment owner.		
HPS provides a two-year labor warranty		
TOTAL	\$	5,973.00

Make all checks payable to Houston Power Savers

If you have any questions concerning this invoice, contact: Kenneth Longoria, (713) 306-2694