Houston Power Savers

INVOICE

TACLB020326E

10222 Inwood Dr Houston,Texas 77042 Office: (832) 968-0000

www.HoustonPowerSavers.com

 Code:
 CODE

 DATE:
 December 29, 2021

 INVOICE #
 00211229

 FOR:
 Low on freon

Steve Strake 10714 Old Coach Ln Houston, TX 77024 (713) 851-8585 Sstrake@hightoweradvisors.com

| DESCRIPTION | AMOUNT |
|---|-----------|
| Added 3 lbs. R-22 freon to system–150.00 ea | |
| subtotal | \$ 450.00 |
| Serviced evaporator coil | |
| *cleaned coil with brush and cleaner | |
| *blew out drainlines | |
| *cleared main drain | |
| *took apart p-trap and cleaned | |
| *added clorox and pan tabs | |
| subtotal | \$ 197.00 |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| Notes: | |
| Recommend replacing next time system is low w/ R-410 system | |
| Will check again in the Spring | |
| TOTAL | \$ 647.00 |

Make all checks payable to Houston Power Savers
If you have any questions concerning this invoice, Kenneth Longoria 713-3062694