## **Houston Power Savers**

**INVOICE** 

**TACLB020326E** 

10222 Inwood Dr **DATE:** October 27, 2021

Houston,Texas 77042 INVOICE #

Office: (832) 968-0000 FOR: Estimate

www.HoustonPowerSavers.com

Charlotte Hickey 6050 Crab Orchard Rd Houston, TX , 77057 (713) 291-2889 charlottehickey@comcast.net

| DESCRIPTION   |          | ļ  | AMOUNT    |
|---|----------|----|-----------|
| Install new 3 ton box coil–2350.00 ea                       |          |    |           |
| M/N: American Standard                                      |          |    |           |
| *pull vacuum, ~1 hr   |          |    |           |
| *resolder copper lines                                      |          |    |           |
| *reseal openings with hardcast                              |          |    |           |
| Install new 3 ton 50k BTU gas furnace–2875.00 ea            | subtotal | \$ | 5,700.00  |
| M/N: American Standard                                      |          |    |           |
| *reseal openings with hardcast                              |          |    |           |
| *rewire controls to furnace                                 |          |    |           |
| rewire controls to furnace                                  | subtotal | \$ | 6,750.00  |
| Install new double wall exhaust vent pipe                   |          | •  | -,        |
|   | subtotal | \$ | 275.00    |
| Add drain pan and float switch                              |          |    |           |
|   | subtotal | \$ | 197.00    |
| Additional duct work modifications for new system           |          | _  |           |
| Doofooloo fi oolo in atallati oo                            | subtotal | \$ | 697.00    |
| Roofer/roofjack installation                                | subtotal | \$ | 497.00    |
| Run new return air box and duct at master bedroom           | Subtotal | Ψ  | 407.00    |
|   | subtotal | \$ | 1,178.00  |
| Run new wire and install thermostat to master bedroom       |          |    |           |
|   | subtotal | \$ | 697.00    |
| Notes: HPS offers a 2-year labor warranty                   |          |    |           |
| Gas/plumbing and disconnect of old boiler coil not included |          |    |           |
| ,   | TOTAL    | \$ | 15,991.00 |

Make all checks payable to Houston Power Savers
If you have any questions concerning this invoice, Kenneth Longoria 713-3062694

## THANK YOU FOR YOUR BUSINESS!