Houston Power Savers

INVOICE

TACLB020326E

 Code:
 CODE

 10222 Inwood Dr
 DATE:
 December 7, 2021

 Houston,Texas 77042
 INVOICE #
 00211207

 Office: (832) 968-0000
 FOR:
 Description

 www.HoustonPowerSavers.com
 Description

May Cahill 1123A Banks St Houston, TX 77006 (832) 459-7972 maycahill@juno.com

DESCRIPTION		AMOUNT
Checked freon levels to condensing unit–low		
*added 6 lbs R-410A–80.00 ea		
	subtotal	\$ 480.00
Took apart coil and looked for freon leak		
*used leak detector inside coil		
	subtotal	\$ 297.00
Notes: Advise replacing coil		
	TOTAL	\$ 777.00

Make all checks payable to Houston Power Savers
If you have any questions concerning this invoice, Kenneth Longoria 713-3062694