Houston Power Saver

INVOICE

TACLB020326E

10222 Inwood Dr Houston,Texas 77042 Office: (832) 968-0000

www.HoustonPowerSavers.com

DATE: September 10, 2021
INVOICE # 00210910
FOR: Service/maintenance

Mitchell Berg 1037 East 28th Street Houston, TX 77009 (832) 724-5683

DESCRIPTION	AMOUNT
<u>Diagnosis</u>	
Auxiliary drainpan leaking water	
*male nipples were stripped on auxiliary and main drain	
Liner inside box coil detached and fell into the coil	
Repair	
Replaced box coil male nipples	
Reattached liner with hardcast and glue	
parts and labor	\$ 297.00
Notes:	
Pan is cracked; the coil needs to be replaced. Left verbal	
estimate for replacement	
TOTAL	\$ 297.00

Make all checks payable to Houston Power Savers
If you have any questions concerning this invoice, Kenneth Longoria 713-3062694

THANK YOU FOR YOUR BUSINESS!