## **Houston Power Savers**

INVOICE

**TACLB020326E** 

Code: iccf414

DATE:

November 5, 2021

INVOICE #

Estimate FOR:

10222 Inwood Dr Houston, Texas 77042 Office: (832) 968-0000

www.HoustonPowerSavers.com

Steve Hartwig 664 W Forest Dr Houston, TX, 77079 (713) 962-9170 Schartwig@sbcglobal.net

DESCRIPTION		AMOUNT
Install new 5 ton evaporator slab coil		
M/N: / S/N:		
*vacuum time, ~1 hr		
*reseal openings with hardcast		
subtota	ıl \$	3,275.00
Install new 100k BTU gas furnace		
M/N: / S/N:		
*reseal openings with hardcast		
*new roofjack		
*new supply plenum *new heater stands		
*new double wall vent pipe		
*rewire controls to furnace		
subtota	ıl \$	3,875.00
All new duct work		
*all new collars and dampers		
*15 bags of R8 flex		
subtota	al \$	1,800.00
Pick-up/installation of 2 new media filters–325.00 ea		
*filters for upstairs and downstairs systems		
subtota	ıl \$	700.00
Labor cost		
subtota	al \$	975.00
Note: 10 yr warranty on parts. 20 yr warranty on heat exchanger		
HPS Provides a 2 yr. labor warranty		
TOTAL	\$	10,625.00

If you have any questions concerning this invoice, Kenneth Longoria 713-3062694

## THANK YOU FOR YOUR BUSINESS!