## **HOUSTON POWER SAVERS**



**TACLB020326E** 

10222 INWOOD DR. **HOUSTON, TEXAS** 77042

INVOICE # OFFICE # (832) 968-0000

June 16, 2021

FOR: Estimate

DATE:

**Gonzalez Family Medicine** 

11040 East Freeway Houston, TX 77029 (713) 453-8328

DESCRIPTION		AMOUNT
Replace 5 ton electric heat air handler/fan coil		
M/N: / S/N:		
*rewire/reconfigure to system		
*reseal openings with hardcast		
	subtotal	\$2,875.00
Installation labor cost		
installation labor cost	subtotal	\$475.00
		<b>4 3 3</b>
Notes:		
1	TOTAL	\$ 3,350.00

## **THANK YOU FOR YOUR BUSINESS!**