## **Houston Power Savers**

**INVOICE** 

**TACLB020326E** 

 Code:
 iccf514

 10222 Inwood Dr
 DATE:
 January 14, 2022

Houston,Texas 77042 INVOICE #

Office: (832) 968-0000 **FOR:** *Estimate* 

www.HoustonPowerSavers.com

Katie Fields 13510 Indian Creek Rd Houston, TX 77079 (713) 818-1579 fields.kt@gmail.com

DESCRIPTION	AMOUNT
Install new 5 ton 14 SEER condensing unit	
M/N: AMERICAN STANDARD	
*pull vacuum	
*vacuum time; ~1 HR	
*new UltraLite pad	
*flush copper lines with R-11	
*recharge with R-410A	
subtota	\$ 4,183.16
Install new 5 ton evaporator slab coil	
M/N: AMERICAN STANDARD	
*reseal openings with hardcast	
subtota	\$ 2,578.70
Install new 100k BTU 5 ton drive gas furnace	
M/N: AMERICAN STANDARD	
*reseal openings with hardcast	
*rewire controls to furnace	
subtota	\$ 3,913.14
Notes:	
Email manufacturer warranty information to equipment owner.	
HPS provides a 2-year labor warranty	
TOTAL	\$ 10,675.00

## THANK YOU FOR YOUR BUSINESS!