HOUSTON POWER SAVERS



TACLB020326E

10222 INWOOD DR. HOUSTON,TEXAS 77042 OFFICE # (832) 968-0000 DATE: INVOICE #

September 2, 2021

00210902

FOR:

Called to replace txv but txv was fine; just low on

freon

Jane Cizik Garden Place 1839 Jacqueline Dr, #302 Houston, TX 77055

DESCRIPTION		AMOUNT
Serviced 1 air conditioning system		
*cleaned evaporator coils		
*blew out/vacuumed drainlines		
*added clorox/pan tabs		
*checked freon levels–low 4 lbs.		
*washed down condensers		
*checked filters–good		
subtota	\$	147.00
Added 4 lbs. R-410A–80.00 ea		
subtota	1 \$	320.00
Labor charge		
subtota	1 \$	697.00
Notes: Email manufacturer warranty information to equipment owner. HPS provides a two-year labor warranty		
TOTAL	\$	1,164.00

THANK YOU FOR YOUR BUSINESS!