Houston Power Savers

INVOICE

TACLB020326E

 Code:
 CODE

 10222 Inwood Dr
 DATE:
 January 23, 2022

 Houston,Texas 77042
 INVOICE # 01220123

 Office: (832) 968-0000
 FOR:
 Repair

 www.HoustonPowerSavers.com

Sharon Lundgren 8609 Lupton Ln Houston, TX 77055 (713) 465-8820 sltrial@sbcglobal.net

DESCRIPTION	AMOUNT
A/C not cooling	
Reset circuit board	
Tightened wires at air handler	
service fee	\$ 97.50
 -	
TOTAL	\$ 97.50

Make all checks payable to Houston Power Savers
If you have any questions concerning this invoice, Kenneth Longoria 713-3062694