## **Houston Power Savers**

**INVOICE** 

TACLB020326E

10222 Inwood Dr **DATE:** October 26, 2021

Houston,Texas 77042 INVOICE #

Office: (832) 968-0000 FOR: Estimate

www.HoustonPowerSavers.com

Charlotte Hickey 6050 Crab Orchard Rd Houston, TX , 77057 (713) 291-2889 charlottehickey@comcast.net

DESCRIPTION		4	AMOUNT
Install new 3 ton box coil–2350.00 ea			
M/N: Ameristar			
*pull vacuum, ~1 hr			
*resolder copper lines			
*reseal openings with hardcast			
Install new 3 ton 50k BTU gas furnace–2875.00 ea	subtotal	\$	4,700.00
M/N: Ameristar			
*reseal openings with hardcast			
*rewire controls to furnace	subtotal	\$	5,750.00
Install new double wall exhaust vent pipe			·
Add drain pan and float switch	subtotal	\$	275.00
	subtotal	\$	197.00
Additional duct work modifications for new system			
	subtotal	\$	697.00
Roofer/roofjack installation	o ubtotal	Φ	407.00
Run new return air box and duct at master bedroom	subtotal	\$	497.00
	subtotal	\$	1,178.00
Run new wire and install thermostat to master bedroom	subtotal	\$	697.00
	Subtotal	Ψ	031.00
Notes: HPS offers a 2-year labor warranty			
Gas/plumbing and disconnect of old boiler coil not included			
	TOTAL	\$	13,991.00

Make all checks payable to Houston Power Savers
If you have any questions concerning this invoice, Kenneth Longoria 713-3062694

## THANK YOU FOR YOUR BUSINESS!