Electrical Rules Check Report

Class	Document	Massaga
		Message
Warning	Thermistors Array SchDoc	Net A1 has no driving source (Pin J1-2, Pin R1-2)
Warning	Thermistors Array.SchDoc	Net A2 has no driving source (Pin J1-3, Pin R2-2)
Warning	Thermistors Array.SchDoc	Net A3 has no driving source (Pin J1-4, Pin R3-2)
Warning	Thermistors Array SchDoc	Net A4 has no driving source (Pin J1-5, Pin R4-2)
Warning	Thermistors Array.SchDoc	Net A5 has no driving source (Pin J1-6, Pin R5-2)
Warning	Thermistors Array.SchDoc	Net A6 has no driving source (Pin J1-7, Pin R6-2)
Warning	Thermistors Array.SchDoc	Net A7 has no driving source (Pin J1-8, Pin R7-2)
Warning	Thermistors Array.SchDoc	Net A8 has no driving source (Pin J1-9, Pin R8-2)
Warning	Thermistors Array.SchDoc	Net A10 has no driving source (Pin J1-11, Pin R9-2)
Warning	Thermistors Array.SchDoc	Net A11 has no driving source (Pin J1-12, Pin R10-2)
Warning	Thermistors Array.SchDoc	Net A12 has no driving source (Pin J1-13, Pin R11-2)
Warning	Thermistors Array.SchDoc	Net A13 has no driving source (Pin J1-14, Pin R12-2)
Warning	Thermistors Array.SchDoc	Net A14 has no driving source (Pin J1-15, Pin R13-2)
Warning	Thermistors Array.SchDoc	Net A15 has no driving source (Pin J1-16, Pin R14-2)
Warning	Thermistors Array.SchDoc	Net A16 has no driving source (Pin J1-17, Pin R15-2)
Warning	Thermistors Array.SchDoc	Net A17 has no driving source (Pin J1-18, Pin R16-2)
Warning	Thermistors Array.SchDoc	Net B1 has no driving source (Pin J2-2, Pin R17-2)
Warning	Thermistors Array.SchDoc	Net B2 has no driving source (Pin J2-3, Pin R18-2)
Warning	Thermistors Array.SchDoc	Net B3 has no driving source (Pin J2-4, Pin R19-2)
Warning	Thermistors Array.SchDoc	Net B4 has no driving source (Pin J2-5, Pin R20-2)
Warning	Thermistors Array.SchDoc	Net B5 has no driving source (Pin J2-6, Pin R21-2)
Warning	Thermistors Array.SchDoc	Net B6 has no driving source (Pin J2-7, Pin R22-2)
Warning	Thermistors Array.SchDoc	Net B7 has no driving source (Pin J2-8, Pin R23-2)
Warning	Thermistors Array.SchDoc	Net B8 has no driving source (Pin J2-9, Pin R24-2)
Warning	Thermistors Array.SchDoc	Net B10 has no driving source (Pin J2-11, Pin R25-2)
Warning	Thermistors Array.SchDoc	Net B11 has no driving source (Pin J2-12, Pin R26-2)
Warning	Thermistors Array.SchDoc	Net B12 has no driving source (Pin J2-13, Pin R27-2)
Warning	Thermistors Array.SchDoc	Net B13 has no driving source (Pin J2-14, Pin R28-2)
Warning	Thermistors Array.SchDoc	Net B14 has no driving source (Pin J2-15, Pin R29-2)
Warning	Thermistors Array.SchDoc	Net B15 has no driving source (Pin J2-16, Pin R30-2)
Warning	Thermistors Array.SchDoc	Net B16 has no driving source (Pin J2-17, Pin R31-2)
Warning	Thermistors Array.SchDoc	Net B17 has no driving source (Pin J2-18, Pin R32-2)
Warning	Thermistors Array.SchDoc	Net C1 has no driving source (Pin J3-2, Pin R33-2)
Warning	Thermistors Array.SchDoc	Net C2 has no driving source (Pin J3-3, Pin R34-2)
Warning	Thermistors Array.SchDoc	Net C3 has no driving source (Pin J3-4, Pin R35-2)
Warning	Thermistors Array.SchDoc	Net C4 has no driving source (Pin J3-5, Pin R36-2)
Warning	Thermistors Array.SchDoc	Net C5 has no driving source (Pin J3-6, Pin R37-2)
Warning	Thermistors Array.SchDoc	Net C 6 has no driving source (Pin J3-7, Pin R38-2)
Warning	Thermistors Array.SchDoc	Net C7 has no driving source (Pin J3-8, Pin R39-2)
Warning	Thermistors Array.SchDoc	Net C8 has no driving source (Pin J3-9, Pin R40-2)
Warning	Thermistors Array.SchDoc	Net C10 has no driving source (Pin J3-11, Pin R41-2)
Warning	Thermistors Array.SchDoc	Net C11 has no driving source (Pin J3-12, Pin R42-2)
Warning	Thermistors Array . SchDoc	Net C12 has no driving source (Pin J3-13, Pin R43-2)
		1. 1. 2. 1. 2. 1. 2. 1. 2. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.

Page 1 of 2

Class	Document	Message
Warning	Thermistors Array.SchDoc	Net C13 has no driving source (Pin J3-14, Pin R44-2)
Warning	Thermistors Array.SchDoc	Net C14 has no driving source (Pin J3-15, Pin R45-2)
Warning	Thermistors Array.SchDoc	Net C15 has no driving source (Pin J3-16, Pin R46-2)
Warning	Thermistors Array.SchDoc	Net C16 has no driving source (Pin J3-17, Pin R47-2)
Warning	Thermistors Array.SchDoc	Net C17 has no driving source (Pin J3-18, Pin R48-2)
Warning	Thermistors Array.SchDoc	Net D1 has no driving source (Pin J4-2, Pin R49-2)
Warning	Thermistors Array.SchDoc	Net D2 has no driving source (Pin J4-3, Pin R50-2)
Warning	Thermistors Array.SchDoc	Net D3 has no driving source (Pin J4-4, Pin R51-2)
Warning	Thermistors Array.SchDoc	Net D4 has no driving source (Pin J4-5, Pin R52-2)
Warning	Thermistors Array.SchDoc	Net D5 has no driving source (Pin J4-6, Pin R53-2)
Warning	Thermistors Array.SchDoc	Net D6 has no driving source (Pin J4-7, Pin R54-2)
Warning	Thermistors Array.SchDoc	Net D7 has no driving source (Pin J4-8, Pin R55-2)
Warning	Thermistors Array.SchDoc	Net D8 has no driving source (Pin J4-9, Pin R56-2)
Warning	Thermistors Array.SchDoc	Net D10 has no driving source (Pin J4-11, Pin R57-2)
Warning	Thermistors Array.SchDoc	Net D11 has no driving source (Pin J4-12, Pin R58-2)
Warning	Thermistors Array.SchDoc	Net D12 has no driving source (Pin J4-13, Pin R59-2)
Warning	Thermistors Array.SchDoc	Net D13 has no driving source (Pin J4-14, Pin R60-2)
Warning	Thermistors Array.SchDoc	Net D14 has no driving source (Pin J4-15, Pin R61-2)
Warning	Thermistors Array.SchDoc	Net D15 has no driving source (Pin J4-16, Pin R62-2)
Warning	Thermistors Array.SchDoc	Net D16 has no driving source (Pin J4-17, Pin R63-2)
Warning	Thermistors Array.SchDoc	Net D17 has no driving source (Pin J4-18, Pin R64-2)
Warning	Thermistors Array.SchDoc	Unconnected line (50.8mm,38.35mm) To (63.5mm,84.07mm)
Warning	Thermistors Array.SchDoc	Unconnected line (50.8mm,114.3mm) To (63.5mm,160.02mm)
Warning	Thermistors Array.SchDoc	Unconnected line (101.6mm,40.64mm) To (111.76mm,104.14mm)
Warning	Thermistors Array.SchDoc	Unconnected line (101.6mm,116.84mm) To (111.76mm,180.34mm)
Warning	Thermistors Array.SchDoc	Unconnected line (182.88mm,40.64mm) To (195.58mm,83.82mm)
Warning	Thermistors Array.SchDoc	Unconnected line (182.88mm,116.84mm) To (195.58mm,160.02mm)
Warning	Thermistors Array.SchDoc	Unconnected line (233.68mm, 40.64mm) To (243.84mm, 104.14mm)
Warning	Thermistors Array.SchDoc	Unconnected line (233.68mm, 162.56mm) To (243.87mm, 180.37mm)

mardi 21 mars 2023 5:04:29 PN