EX.No.2.1 CREATE A 3D SOLID MODEL FROM ISOMETRIC DRAWING

Date:

AIM

To create a 3Dmodel from the given isometric drawing using fusion 360 tool.

REQUIREMENTS

- 1. Autodesk fusion 360
- 2. Windows 10
- 3. 16 GB of RAM (integrated graphics recommend 1 GB or more)
- 4. 2.5 Mbps or faster download; 500 Kbps or faster upload

PROCEDURE

STEP-1: Start the sketch command

Select Sketch > Create Sketch.

STEP-2: Select the Sketch Plane

Select the Front (XZ) Plane

STEP-3: Create a Rectangle

- 1. Select Sketch > Rectangle > Center Rectangle.
- 2. Now hover over the origin (center) of the sketch. You should see the cursor snap to this location.
- 3. Click once to begin placing the rectangle.
- 4. Type the Tab button and enter the values 100 mm and 60mm for the width and height respectively.
- 5. Click again to place the rectangle.
- 6. Click Finish Sketch after completing.

STEP-4: Extrude Rectangle in XZ Plane

- 1. Select Extrude.
- 2. Select the Rectangle sketch.
- 3. Click again to place the value.
- 4. Type in the value of 30mm.
- 5. Press ENTER to accept the value.

STEP-5: Start the sketch command

Select Sketch > Create Sketch.

STEP-6: Select the Sketch Plane

Select the FRON SURFACE of rectangular block

STEP-7: Create a CIRCLE

- 1. Select Sketch > CIRCLE > CENTER CIRCLE.
- 2. Now hover over the origin (center) of the sketch. You should see the cursor snap to this location.
- 3. Click once to begin placing the CIRCLE.
- 4. Type the Tab button and enter the value DIA 100mm.
- 5. Click again to place the circle.

6. Click Finish Sketch after completing.

STEP-8: Extrude CIRCLE

- 1. Select Extrude.
- 2. Select the Rectangle sketch.
- 3. Click again to place the value.
- 4. Type in the value of 20mm.
- 5. Press ENTER to accept the value.

STEP-9: Start the sketch command

Select Sketch > Create Sketch.


STEP-10: Select the Sketch Plane

Select the TOP SURFACE OF RECTANGLE.


STEP-11: Create a line

- 1. Select Line command.
- 2. Draw the projections in the diagram
- 3. Click Finish Sketch.
- 4. extrude the sketch.

INPUT



Q



RESULT:

Thus, the 3D model is created from given isometric drawing.