RTCA, Inc.

1828 L Street, NW Suite 805

Washington, DC 20036

DO-160G

Environmental Conditions and Test Procedures for Airborne Equipment

Appendix C
Change Coordinators

Date of Issue:
December 8, 2010

Supersedes: DO-160F/ED14F
Prepared by: RTCA SC-135

Copyright RTCA, Inc.
Provided by IHS under license with RTCA, Inc.
No reproduction or networking permitted without license from IHS

Order Number: 02093010
Sold to:ETIHAD AIRWAYS ENGINEERING [048289110575] - MKURUVILLA@ETIHAD.AE,
Not for Resale,2016-02-16 13:45:42 UTC

This Page Intentionally Left Blank.

Copyright RTCA, Inc.
Provided by IHS under license with RTCA, Inc.
No reproduction or networking permitted without license from IHS

Order Number: 02093010
Sold to:ETIHAD AIRWAYS ENGINEERING [048289110575] - MKURUVILLA@ETIHAD.AE,
Not for Resale,2016-02-16 13:45:42 UTC

SC-135 / WG-14 Change Coordinators and Assignments

Section	Section Title	US Change Coordinator, Address, Phone / Fax / e-mail	EU Change Coordinator, Address, Phone / Fax / e-mail
1.0	Purpose and Applicability	Jim Lyall Embry-Riddle Aeronautical University 3700 North Willow Creek Road Prescott, AZ 86301 (P) 928-777-3833 (F) 928-777-6945 (E) lyallj@erau.edu	Marc Ponçon Eurocopter Marseille Provence Intl Airport (P) 33 4 42 85 7252 (F) 33 4 42 85 8765 (E) marc.poncon@eurocopter.com
2.0	Definitions of Terms	Jim Lyall	Marc Ponçon
3.0	Conditions of Test	Jim Lyall	Marc Ponçon
4.0	Temperature and Altitude	Jeff Dinsmore Honeywell, Inc. Aerospace Electronic Systems 8840 Evergreen Blvd., M/S MN 51-1305 Minneapolis, MN 55433-0640 (P) 763-957-4582 (F) 763-957-4731 (E) jeff.dinsmore@honeywell.com	Arnaud Ledreux Aeroconseil Immeuble Le Château 3, rue Dieudonné Costes BP 800 75 31703 Blagnac cedex FRANCE (P) 33 5 67 20 91 22 (F) 33 5 67 20 90 41 (E) arnaud.ledreux@aeroconseil.com
5.0	Temperature Variation	Jeff Dinsmore	Arnaud Ledreux
6.0	Humidity	Richard Errhalt Electronic Proving Ground Electromagnetics and Environmental Division - ETF Bldg. 82812, Arizona St. Fort Huachuca, Arizona 85613-7063 (P) 520-538-3928 (F) (E) richard.errhalt@us.army.mil	
7.0	Shock	Merrill Vaughan Boeing Commercial Airplane Company P.O. Box 3707, MS 03-KR Seattle, WA 98124 (P) 425-342-2277 (F) 425-717-0422 (E) merrill.d.vaughan@boeing.com	Marc Ponçon
8.0	Vibration	Merrill Vaughan	Marc Ponçon
9.0	Explosive Atmosphere	Gary Smith Honeywell International, Inc. 1300 W. Warner Rd Tempe, AZ 85284 (P) 480-592-3517 (F) 480-592-4906 (E) gary.smith7@honeywell.com	
10.0	Waterproofness	Gary Smith	

© 2010 RTCA, Inc

Copyright RTCA, Inc.
Provided by IHS under license with RTCA, Inc.
No reproduction or networking permitted without license from IHS

Order Number: 02093010
Sold to:ETIHAD AIRWAYS ENGINEERING [048289110575] - MKURUVILLA@ETIHAD.AE,
Not for Resale,2016-02-16 13:45:42 UTC

11.0	Fluids Susceptibility	Gary Smith	
12.0	Sand and Dust	Richard Errhalt	
13.0	Fungus Resistance	Richard Errhalt	
14.0	Salt Spray	Richard Errhalt	
15.0	Magnetic Effect	Kenneth J. Webb Rockwell Collins 400 Collins Road, NE, M/S 106-183 Cedar Rapids, IA 52498 (P) 319-295-8667 (F) 319-295-0654 (E) kjwebb@rockwellcollins.com	Gilles Crousier Turbomeca Usine de bordes 64511 Bordes Cedex France (P) 33 5 59 12 58 26 (F) 33 5 59 12 51 48 (E) gilles.crousier@turbomeca.fr
16.0	Power Input	Paul Schwerman Honeywell, Inc. 21111 N. 19th Ave. Phoenix, AZ 85027 (P) 602-822-3691 (E) paul.schwerman@honeywell.com	C.Bertran Airbus France S.A.S 31060 Toulouse cedex France (P) (0)5 62 11 07 88 (F) (0)5 61 93 46 40 (E) christian.bertran@airbus.com
17.0	Voltage Spike Conducted	John Covell Goodrich Corporation Fuel and Utility Systems Vergennes, Vermont (P) 802-877-4594 (F) 802-877-4444 (E) john.covell@goodrich.com	Philippe Leroux Sagem (E) philippe.leroux@sagem.com
18.0	Audio Frequency Conducted Susceptibility	Ken Cechura Rockwell Collins 400 Collins Road, NE, M/S 106-183 Cedar Rapids, IA 52498 (P) 319-295-8494 (F) 319-295-0654 (E) krcechur@rockwellcollins.com	Henning Stöfen Airbus Deutschland GmbH Kreetslag 10, 21129 Hamburg, Germany (P): 49 40 743 69011 (F): 49 (0)40 743 870 69011 Email: henning.stoefen@airbus.com
19.0	Induced Signal Susceptibility	Jim Hatlestad The Boeing Company P.O. Box 3707, MC 03-CM Seattle, WA 98124-2207 (P) 425-266-1916 (F) 425-294-0830 (E) james.r.hatlestad@boeing.com	Tim Noad Qinetiq Cody Technology Park Ively Road, Farnborough Hants, GU14 0LX UK Tel: +44 1252 393382 Fax: +44 1252 397058 Email: tnoad@QinetiQ.com
20.0	RF Susceptibility (Radiated and Conducted)	Jim Hatlestad	Tim Noad

© 2010 RTCA, Inc

Copyright RTCA, Inc.
Provided by IHS under license with RTCA, Inc.
No reproduction or networking permitted without license from IHS

Order Number: 02093010
Sold to:ETIHAD AIRWAYS ENGINEERING [048289110575] - MKURUVILLA@ETIHAD.AE,
Not for Resale,2016-02-16 13:45:42 UTC

21.0	Emission of Radio Frequency Energy	Matthew Wills National Institute for Aviation research Wichita State University 1845 Fairmont St Wichita, KS 67260-0093 (P) 316-987-5776 (E) mwills@niar.wichita.edu	Henning Stöfen
22.0	Lightning Induced Transient Susceptibility	Erik J. Borgstrom Environ Laboratories LLC 9725 Girard Avenue South Bloomington, MN 55431 (P) (952) 888-7795 (F) Fax (952) 888-6345 (E) ejb@environlab.com	Jean.Patrick Moreau Dassault Aviation (E) jean-patrick.moreau@dassault-aviation.com
23.0	Lightning Direct Effects	Allan Meyer Rockwell Collins 400 Collins Road, NE Cedar Rapid, IA 52498 (P) 319-295-1528 (F) 319-295-3661 (E) ajmeyer@rockwellcollins.com	Jean.Patrick Moreau
24.0	Icing	Alan G. Thompson Environ Laboratories LLC 9725 Girard Avenue South Bloomington, MN 55431 (P) (952) 888-7795 (F) Fax (952) 888-6345 (E) agt@environlab.com	
25.0	Electro-Static Discharge	Erik J. Borgstrom	
26.0	Fire, Flammability	Alan G. Thompson	Sant-Anna Philippe Airbus France S.A.S 31060 Toulouse cedex France (P) 33 5 61 18 64 29 (F) 33 5 61 18 78 96 (E) philippe.sant-anna@airbus.com
Appendix A	Environmental Test Identification	Jim Lyall	Marc Ponçon
SC-135 / WG-14	Chairman	Bradley Green Honeywell International, Inc. Aerospace 23500 W. 105th St. Olathe, KS 66061 (P) 913-712-2674 (F) 913-712-2674 (E) bradf.green@honeywell.com	Marc Ponçon

© 2010 RTCA, Inc

Copyright RTCA, Inc.
Provided by IHS under license with RTCA, Inc.
No reproduction or networking permitted without license from IHS

Order Number: 02093010
Sold to:ETIHAD AIRWAYS ENGINEERING [048289110575] - MKURUVILLA@ETIHAD.AE,
Not for Resale,2016-02-16 13:45:42 UTC

SC-135	Secretary	Leo Makowski HV Technologies, Inc. 8515 Rixlew Lane Manassas, VA 20109 (P) 703- 365-2330 (F) 703- 365-2331 (E) makowski@hvtechnologies.com	Tim Noad
SC-135	Designated Federal Representative	Lee Nguyen Avionics Systems Branch FAA/AIR-130 800 Independence Ave, SW Washington, DC 20591-0004 (P) (202)385-4676 (F) (202)385-4651 (E) lee.nguyen@faa.gov	
RTCA	Program Director	Harold Moses 1828 L Street, NW, Suite 805 Washington, DC 20036 (P) 202-330-0654 (F) 202-833-9434 (E) hmoses@rtca.org	

© 2010 RTCA, Inc

Copyright RTCA, Inc.
Provided by IHS under license with RTCA, Inc.
No reproduction or networking permitted without license from IHS

Order Number: 02093010
Sold to:ETIHAD AIRWAYS ENGINEERING [048289110575] - MKURUVILLA@ETIHAD.AE,
Not for Resale,2016-02-16 13:45:42 UTC