
EWMA Convergence Chart
Summary Statistics
Iteration Number
−10
−20
−30
−40
−50
0
50
100
150
200
250
300
Yi
Zi Violation
Zi Control Limit
Control Window Boundary