
EWMA Convergence Chart
Summary Statistics
Iteration Number
−4
−6
−8
−10
−12
0
50
100
150
200
Yi
Zi Violation
Zi Control
Control Limit
Control Window Boundary