
EWMA Convergence Chart
Summary Statistics
Iteration Number
0
−2
−4
−6
−8
−10
0
50
100
150
200
Yi
Zi Violation
Zi Control
Control Limit
Control Window
Boundary