

Wali-Mitter Authorized Auto Care

MOTOR INSURANCE REPAIR ESTIMATE

Estimate No: REP-EST-43289

Vehicle Reg No: MH 34 KI 5974

Chassis No: MAT863161VO498351

Date: 09/12/2025

Policy No: POL-MOT-86559156

Insured: Vanya Din

SI	Repair Item Description	Part / Labour	Amount (INR)
1	Front Bumper Assembly Replacement	Parts	14,500.00
2	Headlight RH Projector LED Unit	Parts	18,200.00
3	Fender Panel RH Alignment & Paint	Parts	6,500.00
4	Radiator Grille Frame	Parts	4,200.00
5	Labour: Dismantling & Refitting	Labour	5,500.00
Subtotal:			48,900.00
GST (18%):			8,802.00
Total Estimate:			57,702.00

Estimate in Words: Fifty Seven Thousand Seven Hundred Two Rupees Only