Assignment No: 4-3/4



						10
0.1	lict	dann	10	DYXDX	messages	Code.
3	F101	11000	TO	60000		

	E CONTRACTOR DE			
11	404	Not found response status code		
	100	Loader available waiting time out.		
37	101	Loader available waiting time out. Unloader available waiting time out.		
4)	102	Product input waiting time out.		
5)	103	Product input waiting time out. Press unit action waiting timeout.		
6)	104	Product out waiting time out.		
7)	105	Bypass error.		
8)	105	Door is opened.		
	107	motor low speed waiting time out.		
10)	108	Product is unlocated.		
11)	109	stopper action vaiting time out.		
12)	110	conveyer action waiting time out		
13)	111	Repeat cycle end.		
14)	112	Error Flag set.		
15)	113	Two boards error		
167	114	Unknown error		
171	115	next station error.		
187	116	No Hardware Detected.		
197	117	product Position Error.		
201	118	Barcode Error.		