Berita Acara Serah Terima Unit

Unit Handover Report: the unit below has been repaired and is Ready For Use (RFU).

Work Order	WO-202609-0022
Unit	DT 106 (DT-006) · Dump Truck
Driver / Operator	Eko Purnomo
PIC Mechanic	Dedi Kurniawan
Repair Category	Brake System
Problem Reported	Brake pedal feels soft, long stopping distance
Repair Period	29/09/26, 16:47 – 30/09/26, 05:11
Result	**Unit Ready For Use (RFU)**

Repair steps

#	Step	PIC	Start	Finish	Duration
1	Unit Breakdown	Dedi Kurniawan	29/09/26, 16:47	29/09/26, 17:51	1h 4m
2	Service Request	Dedi Kurniawan	29/09/26, 17:51	29/09/26, 18:55	1h 4m
3	Inspection Activity	Dedi Kurniawan	29/09/26, 19:30	29/09/26, 20:26	56m
4	Inspection Report Readiness	Dedi Kurniawan	29/09/26, 20:26	29/09/26, 21:22	56m
5	Spareparts Request	Dedi Kurniawan	29/09/26, 21:31	29/09/26, 22:47	1h 16m
6	Supply Spareparts Remarks: Checked OK	Dedi Kurniawan	29/09/26, 22:47	30/09/26, 00:02	1h 16m
7	Repair Process Remove faulty component · Install / repair component Remarks: Part replaced	Dedi Kurniawan	30/09/26, 00:23	30/09/26, 01:46	1h 23m
8	Ground Test	Dedi Kurniawan	30/09/26, 02:12	30/09/26, 03:11	58m
9	RFU (Ready For Use)	Dedi Kurniawan	30/09/26, 03:44	30/09/26, 05:11	1h 27m

Handed over by (Mechanic)	Checked by (Admin Plant)	Received by (Driver / Operator)
Dedi Kurniawan	**Admin Plant**	**Eko Purnomo**