Berita Acara Serah Terima Unit

Unit Handover Report: the unit below has been repaired and is Ready For Use (RFU).

Work Order	WO-202609-0017
Unit	DT 109 (DT-009) · Dump Truck
Driver / Operator	Wahyu Hidayat
PIC Mechanic	Dedi Kurniawan
Repair Category	Suspension
Problem Reported	Abnormal noise from rear suspension
Repair Period	23/09/26, 11:33 – 23/09/26, 20:57
Result	**Unit Ready For Use (RFU)**

Repair steps

#	Step	PIC	Start	Finish	Duration
1	Unit Breakdown	Dedi Kurniawan	23/09/26, 11:33	23/09/26, 11:51	18m
2	Service Request	Dedi Kurniawan	23/09/26, 11:51	23/09/26, 12:09	18m
3	Inspection Activity	Dedi Kurniawan	23/09/26, 12:32	23/09/26, 12:43	11m
4	Inspection Report Readiness Remarks: Part replaced	Dedi Kurniawan	23/09/26, 12:43	23/09/26, 12:53	11m
5	Spareparts Request	Dedi Kurniawan	23/09/26, 13:08	23/09/26, 14:58	1h 50m
6	Supply Spareparts Remarks: Checked OK	Dedi Kurniawan	23/09/26, 14:58	23/09/26, 16:49	1h 50m
7	Repair Process Remove faulty component · Install / repair component Remarks: Need follow-up next service	Dedi Kurniawan	23/09/26, 17:11	23/09/26, 18:42	1h 31m
8	Ground Test	Dedi Kurniawan	23/09/26, 18:57	23/09/26, 19:20	24m
9	RFU (Ready For Use) Remarks: Need follow-up next service	Dedi Kurniawan	23/09/26, 19:45	23/09/26, 20:57	1h 12m

Handed over by (Mechanic)	Checked by (Admin Plant)	Received by (Driver / Operator)
Dedi Kurniawan	**Admin Plant**	**Wahyu Hidayat**