Berita Acara Serah Terima Unit

Unit Handover Report: the unit below has been repaired and is Ready For Use (RFU).

Work Order	WO-202609-0019
Unit	DT 102 (DT-002) · Dump Truck
Driver / Operator	Joko Susilo
PIC Mechanic	Budi Santoso
Repair Category	Hydraulic
Problem Reported	Oil leak at hydraulic cylinder seal
Repair Period	25/09/26, 09:25 – 25/09/26, 23:08
Result	**Unit Ready For Use (RFU)**

Repair steps

#	Step	PIC	Start	Finish	Duration
1	Unit Breakdown	Budi Santoso	25/09/26, 09:25	25/09/26, 10:06	41m
2	Service Request	Budi Santoso	25/09/26, 10:06	25/09/26, 10:47	41m
3	Inspection Activity	Budi Santoso	25/09/26, 11:02	25/09/26, 11:39	36m
4	Inspection Report Readiness	Budi Santoso	25/09/26, 11:39	25/09/26, 12:15	36m
5	Spareparts Request	Budi Santoso	25/09/26, 12:42	25/09/26, 15:33	2h 51m
6	Supply Spareparts	Budi Santoso	25/09/26, 15:33	25/09/26, 18:24	2h 51m
7	Repair Process Remove faulty component · Install / repair component	Budi Santoso	25/09/26, 18:48	25/09/26, 20:29	1h 41m
8	Ground Test Remarks: Need follow-up next service	Budi Santoso	25/09/26, 20:37	25/09/26, 21:15	38m
9	RFU (Ready For Use)	Budi Santoso	25/09/26, 21:46	25/09/26, 23:08	1h 22m

Handed over by (Mechanic)	Checked by (Admin Plant)	Received by (Driver / Operator)
Budi Santoso	**Admin Plant**	**Joko Susilo**