WO

PT Inline Technology International
Work Order Service · Plant Maintenance

WO-202609-0020
28/09/26, 01:35

Berita Acara Serah Terima Unit

Unit Handover Report: the unit below has been repaired and is Ready For Use (RFU).

Work Order	WO-202609-0020
Unit	DT 102 (DT-002) · Dump Truck
Driver / Operator	Hendra Wijaya
PIC Mechanic	Rudi Hartono
Repair Category	Engine
Problem Reported	Engine hard to start in the morning
Repair Period	27/09/26, 10:17 – 28/09/26, 01:35
Result	**Unit Ready For Use (RFU)**

Repair steps

#	Step	PIC	Start	Finish	Duration
1	Unit Breakdown	Rudi Hartono	27/09/26, 10:17	27/09/26, 10:33	15m
2	Service Request	Rudi Hartono	27/09/26, 10:33	27/09/26, 10:48	15m
3	Inspection Activity	Rudi Hartono	27/09/26, 11:02	27/09/26, 11:33	32m
4	Inspection Report Readiness	Rudi Hartono	27/09/26, 11:33	27/09/26, 12:05	32m
5	Spareparts Request	Rudi Hartono	27/09/26, 12:12	27/09/26, 16:25	4h 13m
6	Supply Spareparts	Rudi Hartono	27/09/26, 16:25	27/09/26, 20:37	4h 13m
7	Repair Process Remove faulty component · Install / repair component Remarks: Checked OK	Rudi Hartono	27/09/26, 20:43	27/09/26, 21:19	36m
8	Ground Test	Rudi Hartono	27/09/26, 21:46	27/09/26, 23:43	1h 56m
9	RFU (Ready For Use) Remarks: Done as per SOP	Rudi Hartono	27/09/26, 23:48	28/09/26, 01:35	1h 47m

Handed over by (Mechanic)	Checked by (Admin Plant)	Received by (Driver / Operator)
Rudi Hartono	**Admin Plant**	**Hendra Wijaya**

Example document generated from the WOS demo data for testing the proof upload.