TECHNICAL FIELD SPECIFICATION • SATELLITE TELECOMS

How should external Starlink cables enter UK stone cavity walls to prevent moisture ingress?

BOTTOM LINE UP FRONT (BLUF) TRADE ASSESSMENT:
Could an unsealed satellite cable entry hole cause driving rain to seep directly into your cavity wall? Drilling straight into brickwork allows rain running down the cable to follow it indoors.

1. Field Engineering & British Standards Analysis

In accordance with UK trade guidelines and Upward 5° Masonry Slope:

Could an unsealed satellite cable entry hole cause driving rain to seep directly into your cavity wall? I'm Gary Pearce, lead physical engineer at ADI Communications. Drilling straight into brickwork allows rain running down the cable to follow it indoors. We drill masonry with an upward five-degree slope from the exterior and form a downward-curving drip loop beneath the entry point. Finished with a heavy-duty nylon blast bushing and silicone sealant, moisture drips off harmlessly outside. For watertight exterior telecoms cabling, call Gary on 07860 244 274.

2. Technical Benchmark Matrix

Specification Parameter	Standard / Budget Method	ADI Professional Trade Standard
Cabling Core	CCA (Copper Clad Aluminium)	100% Solid Bare Copper (23 AWG / WF100)
Structural Mount	Lightweight zinc standoffs	Pennine 90mph gale stainless lashing
Signal Alignment	Consumer bar indicators	Calibrated digital spectrum analyzer
Court Admissibility	Frequently rejected	100% BS EN compliant forensic evidence

3. Lead Engineer Craftsmanship & Citadel Links

Lead Field Engineer: Gary Pearce • ADI Communications (Direct Mobile: **07860 244 274**)
Trade Credentials: 25+ Years Experience | £10,000,000 Public Liability Insurance | Qualified CCTV & Telecoms Specialist | Verified Rating: ★★★★★ 9.98/10 (84+ Reviews)
Top-of-Stack Google Slides DA 100 Companion Link: https://docs.google.com/presentation/d/e/2PACX-1vTb-2iOvkk7k2_hkQ2hl3HDzuRDZrKUQmbhPSU3JHLx6XHHdzR1zzPlyo7ed6QBdfA3ly0RiUy6BRMh/pub
Technical Field Buffer: https://adicommunications.co.uk/news/starlink-chimney-mount-vs-roof-apex/