#### **NAME**

```
gbz80 — CPU opcode reference
```

## DESCRIPTION

This is the list of opcodes supported by rgbasm(1), including a short description, the number of bytes needed to encode them and the number of CPU cycles at 1MHz (or 2MHz in GBC dual speed mode) needed to complete them.

Note: All arithmetic/logic operations that use register A as destination can omit the destination as it is assumed to be register A by default. The following two lines have the same effect:

```
OR A,B
OR B
```

#### **LEGEND**

List of abbreviations used in this document.

```
Any of the 8-bit registers (A, B, C, D, E, H, L).
```

- r16 Any of the general-purpose 16-bit registers (**BC**, **DE**, **HL**).
- *n8* 8-bit integer constant.
- *n*16 16-bit integer constant.
- *e8* 8-bit offset (**-128** to **127**).
- *u3* 3-bit unsigned integer constant (**0** to **7**).
- cc Condition codes:

Z Execute if Z is set.
NZ Execute if Z is not set.
C Execute if C is set.

**NC** Execute if C is not set.

vec One of the **RST** vectors (0x00, 0x08, 0x10, 0x18, 0x20, 0x28, 0x30, and 0x38).

## INSTRUCTION OVERVIEW

# 8-bit Arithmetic and Logic Instructions

```
ADC A,r8
```

ADC A,[HL]

ADC A,n8

ADD A,r8

ADD A,[HL]

ADD A,n8

AND A,r8

AND A,[HL]

AND A,n8

CP A,r8

CP A,[HL]

CP A,n8

DEC r8

DEC [HL]

INC r8

```
INC [HL]
OR A,r8
OR A,[HL]
OR A,n8
SBC A,r8
SBC A,[HL]
SBC A,n8
SUB A,r8
SUB A,[HL]
SUB A,n8
XOR A,r8
XOR A,r8
```

#### **16-bit Arithmetic Instructions**

ADD HL,r16 DEC r16 INC r16

# **Bit Operations Instructions**

BIT u3,r8
BIT u3,[HL]
RES u3,r8
RES u3,[HL]
SET u3,r8
SET u3,[HL]
SWAP r8
SWAP [HL]

## **Bit Shift Instructions**

RL r8 RL [HL] **RLA** RLC r8 RLC [HL] **RLCA** RR r8 RR [HL] RRA RRC r8 RRC [HL] **RRCA** SLA r8 SLA [HL] SRA r8 SRA [HL] SRL r8 SRL [HL]

## **Load Instructions**

LD r8,r8

LD r8,n8

LD r16,n16

LD [HL],r8

LD [HL],n8

LD r8,[HL]

LD [r16],A

LD [n16],A

LDH [n16],A

LDH [C],A

LD A,[r16]

LD A,[n16]

LD A,[III0]

LDH A,[n16]

LDH A,[C]

LD [HLI],A

LD [HLD],A

LD A,[HLI]

LD A,[HLD]

# **Jumps and Subroutines**

CALL n16

CALL cc,n16

JP HL

JP n16

JP cc,n16

JR e8

JR cc,e8

RET cc

RET

**RETI** 

RST vec

# **Stack Operations Instructions**

ADD HL,SP

ADD SP,e8

**DEC SP** 

INC SP

LD SP,n16

LD [n16],SP

LD HL,SP+e8

LD SP,HL

POP AF

POP r16

**PUSH AF** 

PUSH r16

# **Miscellaneous Instructions**

**CCF** 

```
CPL
DAA
DI
EI
HALT
NOP
SCF
STOP
```

# INSTRUCTION REFERENCE

## ADC A,r8

Add the value in r8 plus the carry flag to **A**.

Cycles: 1
Bytes: 1
Flags:

**Z** Set if result is 0.

**N** (

H Set if overflow from bit 3.C Set if overflow from bit 7.

## ADC A,[HL]

Add the byte pointed to by **HL** plus the carry flag to **A**.

Cycles: 2 Bytes: 1

Flags: See ADC A,r8

### ADC A,n8

Add the value n8 plus the carry flag to A.

Cycles: 2 Bytes: 2

Flags: See ADC A,r8

## ADD A,r8

Add the value in r8 to **A**.

Cycles: 1
Bytes: 1
Flags:

**Z** Set if result is 0.

N (

H Set if overflow from bit 3.C Set if overflow from bit 7.

# ADD A,[HL]

Add the byte pointed to by HL to A.

```
Cycles: 2
    Bytes: 1
    Flags: See ADD A,r8
ADD A,n8
    Add the value n8 to A.
    Cycles: 2
    Bytes: 2
    Flags: See ADD A,r8
ADD HL,r16
    Add the value in r16 to HL.
    Cycles: 2
    Bytes: 1
    Flags:
    \mathbf{N}
             Set if overflow from bit 11.
    H
    \mathbf{C}
             Set if overflow from bit 15.
ADD HL,SP
    Add the value in SP to HL.
    Cycles: 2
    Bytes: 1
    Flags: See ADD HL,r16
ADD SP,e8
    Add the signed value e8 to SP.
    Cycles: 4
    Bytes: 2
    Flags:
    \mathbf{Z}
             0
    \mathbf{N}
    H
             Set if overflow from bit 3.
    \mathbf{C}
             Set if overflow from bit 7.
AND A,r8
    Bitwise AND between the value in r8 and A.
    Cycles: 1
    Bytes: 1
```

Flags:

 $\mathbf{Z}$ 

Set if result is 0.

```
N 0
H 1
C 0
```

## AND A,[HL]

Bitwise AND between the byte pointed to by **HL** and **A**.

Cycles: 2 Bytes: 1

Flags: See AND A,r8

#### AND A,n8

Bitwise AND between the value in n8 and A.

Cycles: 2 Bytes: 2

Flags: See AND A,r8

#### BIT u3,r8

Test bit u3 in register r8, set the zero flag if bit not set.

Cycles: 2
Bytes: 2
Flags:

**Z** Set if the selected bit is 0.

**N** 0 **H** 1

# BIT u3,[HL]

Test bit u3 in the byte pointed by **HL**, set the zero flag if bit not set.

Cycles: 3 Bytes: 2

Flags: See BIT u3,r8

#### CALL n16

Call address n16. This pushes the address of the instruction after the CALL on the stack, such that **RET** can pop it later; then, it executes an implicit **JP n16**.

Cycles: 6
Bytes: 3

Flags: None affected.

# CALL cc,n16

Call address n16 if condition cc is met.

Cycles: 6 taken / 3 untaken

Bytes: 3

```
Flags: None affected.
```

## **CCF**

```
Complement Carry Flag.
```

Cycles: 1

Bytes: 1

Flags:

 $\mathbf{N}$  0

 $\mathbf{H} = 0$ 

C Inverted.

## CP A,r8

Subtract the value in r8 from **A** and set flags accordingly, but don't store the result. This is useful for Com-Paring values.

Cycles: 1

Bytes: 1

Flags:

**Z** Set if result is 0.

 $\mathbf{N}$ 

**H** Set if borrow from bit 4.

C Set if borrow (i.e. if r8 > A).

# CP A,[HL]

Subtract the byte pointed to by **HL** from **A** and set flags accordingly, but don't store the result.

Cycles: 2

Bytes: 1

Flags: See CP A,r8

## CP A,n8

Subtract the value n8 from A and set flags accordingly, but don't store the result.

Cycles: 2

Bytes: 2

Flags: See CP A,r8

### **CPL**

ComPLement accumulator  $(A = \tilde{A})$ .

Cycles: 1

Bytes: 1

Flags:

N 1

**H** 1

```
DAA
```

Decimal Adjust Accumulator to get a correct BCD representation after an arithmetic instruction.

Cycles: 1 Bytes: 1

Flags:

**Z** Set if result is 0.

 $\mathbf{H}$ 

C Set or reset depending on the operation.

## DEC r8

Decrement value in register r8 by 1.

Cycles: 1
Bytes: 1
Flags:

**Z** Set if result is 0.

N 1

**H** Set if borrow from bit 4.

# DEC [HL]

Decrement the byte pointed to by **HL** by 1.

Cycles: 3 Bytes: 1

Flags: See DEC r8

# DEC r16

Decrement value in register r16 by 1.

Cycles: 2 Bytes: 1

Flags: None affected.

# **DEC SP**

Decrement value in register **SP** by 1.

Cycles: 2 Bytes: 1

Flags: None affected.

# DI

Disable Interrupts by clearing the IME flag.

Cycles: 1 Bytes: 1

Flags: None affected.

#### $\mathbf{EI}$

Enable Interrupts by setting the IME flag. The flag is only set after the instruction following EI.

Cycles: 1 Bytes: 1

Flags: None affected.

#### **HALT**

Enter CPU low-power consumption mode until an interrupt occurs. The exact behavior of this instruction depends on the state of the **IME** flag.

**IME** set The CPU enters low-power mode until *after* an interrupt is about to be serviced. The handler is executed normally, and the CPU resumes execution after the **HALT** when that returns.

#### IME not set

The behavior depends on whether an interrupt is pending (i.e. [IE] & [IF] is non-zero).

#### None pending

As soon as an interrupt becomes pending, the CPU resumes execution. This is like the above, except that the handler is *not* called.

# Some pending

The CPU continues execution after the **HALT**, but the byte after it is read twice in a row (**PC** is not incremented, due to a hardware bug).

Cycles: Bytes: 1

Flags: None affected.

#### INC r8

Increment value in register r8 by 1.

Cycles: 1
Bytes: 1
Flags:

**Z** Set if result is 0.

N (

**H** Set if overflow from bit 3.

# INC [HL]

Increment the byte pointed to by HL by 1.

Cycles: 3 Bytes: 1

Flags: See INC r8

#### INC r16

Increment value in register r16 by 1.

Cycles: 2

```
Bytes: 1
```

Flags: None affected.

#### INC SP

Increment value in register **SP** by 1.

Cycles: 2

Bytes: 1

Flags: None affected.

#### JP n16

Jump to address n16; effectively, store n16 into **PC**.

Cycles: 4
Bytes: 3

Flags: None affected.

#### JP cc,n16

Jump to address n16 if condition cc is met.

Cycles: 4 taken / 3 untaken

Bytes: 3

Flags: None affected.

#### JP HL

Jump to address in **HL**; effectively, load **PC** with value in register **HL**.

Cycles: 1

Bytes: 1

Flags: None affected.

#### JR e8

Relative Jump by adding e8 to the address of the instruction following the **JR**. To clarify, an operand of 0 is equivalent to no jumping.

Cycles: 3

Bytes: 2

Flags: None affected.

# JR cc,e8

Relative Jump by adding e8 to the current address if condition cc is met.

Cycles: 3 taken / 2 untaken

Bytes: 2

Flags: None affected.

## LD r8,r8

Load (copy) value in register on the right into register on the left.

Cycles: 1 Bytes: 1

Flags: None affected.

#### LD r8.n8

Load value n8 into register r8.

Cycles: 2 Bytes: 2

Flags: None affected.

#### LD r16.n16

Load value n16 into register r16.

Cycles: 3
Bytes: 3

Flags: None affected.

## LD [HL],r8

Store value in register r8 into byte pointed to by register **HL**.

Cycles: 2 Bytes: 1

Flags: None affected.

# LD [HL],n8

Store value n8 into byte pointed to by register **HL**.

Cycles: 3 Bytes: 2

Flags: None affected.

## LD r8,[HL]

Load value into register r8 from byte pointed to by register **HL**.

Cycles: 2 Bytes: 1

Flags: None affected.

# LD [r16],A

Store value in register A into byte pointed to by register r16.

Cycles: 2 Bytes: 1

```
Flags: None affected.
```

## LD [n16],A

GBZ80(7)

Store value in register A into byte at address n16.

Cycles: 4

Bytes: 3

Flags: None affected.

## LDH [n16],A

Store value in register **A** into byte at address *n*16, provided it is between \$FF00 and \$FFFF.

Cycles: 3

Bytes: 2

Flags: None affected.

This is sometimes written as LDIO [n16], A, or LD [\$FF00+n8], A.

### LDH [C],A

Store value in register **A** into byte at address FF00+C.

Cycles: 2

Bytes: 1

Flags: None affected.

This is sometimes written as LDIO [C], A, or LD [\$FF00+C], A.

### LD A,[r16]

Load value in register A from byte pointed to by register r16.

Cycles: 2

Bytes: 1

Flags: None affected.

## LD A,[n16]

Load value in register **A** from byte at address n16.

Cycles: 4

Bytes: 3

Flags: None affected.

### LDH A,[n16]

Load value in register A from byte at address n16, provided it is between \$FF00 and \$FFFF.

Cycles: 3

Bytes: 2

Flags: None affected.

This is sometimes written as LDIO A, [n16], or LD A, [\$FF00+n8].

#### LDH A,[C]

Load value in register **A** from byte at address FF00+c.

Cycles: 2
Bytes: 1

Flags: None affected.

This is sometimes written as LDIO A, [C], or LD A, [\$FF00+C].

#### LD [HLI],A

Store value in register A into byte pointed by HL and increment HL afterwards.

Cycles: 2

Bytes: 1

Flags: None affected.

This is sometimes written as LD [HL+], A, or LDI [HL], A.

## LD [HLD],A

Store value in register A into byte pointed by HL and decrement HL afterwards.

Cycles: 2

Bytes: 1

Flags: None affected.

This is sometimes written as LD [HL-], A, or LDD [HL], A.

## LD A,[HLD]

Load value into register A from byte pointed by HL and decrement HL afterwards.

Cycles: 2

Bytes: 1

Flags: None affected.

This is sometimes written as LD A, [HL-], or LDD A, [HL].

### LD A,[HLI]

Load value into register A from byte pointed by HL and increment HL afterwards.

Cycles: 2

Bytes: 1

Flags: None affected.

This is sometimes written as LD A, [HL+], or LDI A, [HL].

#### LD SP,n16

Load value n16 into register SP.

Cycles: 3
Bytes: 3

```
Flags: None affected.
```

# LD [n16],SP

Store **SP & \$FF** at address n16 and **SP** >> **8** at address n16 + 1.

Cycles: 5

Bytes: 3

Flags: None affected.

## LD HL,SP+e8

Add the signed value e8 to SP and store the result in HL.

Cycles: 3

Bytes: 2

Flags:

**Z** 0 **N** 0

H Set if overflow from bit 3.

**C** Set if overflow from bit 7.

# LD SP,HL

Load register HL into register SP.

Cycles: 2

Bytes: 1

Flags: None affected.

# NOP

No OPeration.

Cycles: 1

Bytes: 1

Flags: None affected.

## OR A,r8

Store into A the bitwise OR of the value in r8 and A.

Cycles: 1

Bytes: 1

Flags:

**Z** Set if result is 0.

N 0 H 0 C 0

# OR A,[HL]

Store into **A** the bitwise OR of the byte pointed to by **HL** and **A**.

```
Cycles: 2

Bytes: 1

Flags: See OR A,r8

OR A,n8

Store into A the bitwise OR of n8 and A.
```

Cycles: 2

Bytes: 2

Flags: See OR A,r8

#### POP AF

Pop register AF from the stack. This is roughly equivalent to the following *imaginary* instructions:

```
ld f, [sp] ; See below for individual flags
inc sp
ld a, [sp]
inc sp
```

Cycles: 3

Bytes: 1

Flags:

**Z** Set from bit 7 of the popped low byte.

**N** Set from bit 6 of the popped low byte.

**H** Set from bit 5 of the popped low byte.

C Set from bit 4 of the popped low byte.

## POP r16

Pop register r16 from the stack. This is roughly equivalent to the following *imaginary* instructions:

```
ld LOW(r16), [sp] ; C, E or L
inc sp
ld HIGH(r16), [sp] ; B, D or H
inc sp
```

Cycles: 3

Bytes: 1

Flags: None affected.

## **PUSH AF**

Push register **AF** into the stack. This is roughly equivalent to the following *imaginary* instructions:

```
dec sp
  ld [sp], a
  dec sp
  ld [sp], flag_Z << 7 | flag_N << 6 | flag_H << 5 | flag_C << 4
Cycles: 4
Bytes: 1</pre>
```

Flags: None affected.

#### PUSH r16

Push register r16 into the stack. This is roughly equivalent to the following *imaginary* instructions:

```
dec sp
ld [sp], HIGH(r16); B, D or H
dec sp
ld [sp], LOW(r16); C, E or L

Cycles: 4

Bytes: 1

Flags: None affected.
```

#### RES u3,r8

Set bit u3 in register r8 to 0. Bit 0 is the rightmost one, bit 7 the leftmost one.

Cycles: 2 Bytes: 2

Flags: None affected.

### RES u3,[HL]

Set bit u3 in the byte pointed by **HL** to 0. Bit 0 is the rightmost one, bit 7 the leftmost one.

Cycles: 4 Bytes: 2

Flags: None affected.

#### RET

Return from subroutine. This is basically a **POP PC** (if such an instruction existed). See**POP r16** for an explanation of how **POP** works.

Cycles: 4
Bytes: 1
Flags: None affected.

## RET cc

Return from subroutine if condition cc is met.

Cycles: 5 taken / 2 untaken Bytes: 1

Flags: None affected.

#### **RETI**

Return from subroutine and enable interrupts. This is basically equivalent to executing **EI** then **RET**, meaning that **IME** is set right after this instruction.

Cycles: 4

```
Bytes: 1
```

Flags: None affected.

#### RL r8

Rotate bits in register r8 left through carry.

Cycles: 2

Bytes: 2

Flags:

**Z** Set if result is 0.

**N** 0

 $\mathbf{H} = 0$ 

**C** Set according to result.

# RL [HL]

Rotate byte pointed to by **HL** left through carry.

Cycles: 4

Bytes: 2

Flags: See RL r8

## **RLA**

Rotate register A left through carry.

Cycles: 1

Bytes: 1

Flags:

 $\mathbf{Z}$  0

 $\mathbf{N} = 0$ 

H (

C Set according to result.

# RLC r8

Rotate register r8 left.

Cycles: 2

Bytes: 2

Flags:

**Z** Set if result is 0.

 $\mathbf{N}$  0

 $\mathbf{H} = 0$ 

C Set according to result.

# RLC [HL]

Rotate byte pointed to by HL left.

Cycles: 4

Bytes: 2

Flags: See RLC r8

# **RLCA**

Rotate register A left.

Cycles: 1

Bytes: 1

Flags:

 $\mathbf{Z}$  0

 $\mathbf{N}$  0

**H** (

**C** Set according to result.

## RR r8

Rotate register r8 right through carry.

$$C \rightarrow [7 \rightarrow 0] \rightarrow C$$

Cycles: 2

Bytes: 2

Flags:

**Z** Set if result is 0.

 $\mathbf{N}$  0

 $\mathbf{H} = 0$ 

C Set according to result.

# RR [HL]

Rotate byte pointed to by HL right through carry.

$$C \rightarrow [7 \rightarrow 0] \rightarrow C$$

Cycles: 4

Bytes: 2

Flags: See RR r8

# RRA

Rotate register A right through carry.

$$C \rightarrow [7 \rightarrow 0] \rightarrow C$$

```
Cycles: 1

Bytes: 1

Flags:

Z 0

N 0

H 0

C Set according to result.
```

# RRC r8

Rotate register r8 right.

$$[0] \rightarrow [7 \rightarrow 0] \rightarrow C$$

Cycles: 2 Bytes: 2

Flags:

**Z** Set if result is 0.

**N** 0 **H** 0

**C** Set according to result.

# RRC [HL]

Rotate byte pointed to by HL right.

$$[0] \rightarrow [7 \rightarrow 0] \rightarrow C$$

Cycles: 4 Bytes: 2

Flags: See RRC r8

# **RRCA**

Rotate register A right.

$$[0] \rightarrow [7 \rightarrow 0] \rightarrow C$$

Cycles: 1

Bytes: 1

Flags:

**Z** 0 **N** 0 **H** 0

C Set according to result.

### RST vec

Call address vec. This is a shorter and faster equivalent to CALL for suitable values of vec.

Cycles: 4

Bytes: 1

Flags: None affected.

```
SBC A,r8
```

```
Subtract the value in r8 and the carry flag from A.
```

Cycles: 1

Bytes: 1

Flags:

**Z** Set if result is 0.

N

**H** Set if borrow from bit 4.

C Set if borrow (i.e. if (r8 + carry) > A).

# SBC A,[HL]

Subtract the byte pointed to by **HL** and the carry flag from **A**.

Cycles: 2

Bytes: 1

Flags: See SBC A,r8

#### SBC A,n8

Subtract the value n8 and the carry flag from A.

Cycles: 2

Bytes: 2

Flags: See SBC A,r8

## **SCF**

Set Carry Flag.

Cycles: 1

Bytes: 1

Flags:

**N** 0 **H** 0

**C** 1

#### SET u3,r8

Set bit u3 in register r8 to 1. Bit 0 is the rightmost one, bit 7 the leftmost one.

Cycles: 2

Bytes: 2

Flags: None affected.

# SET u3,[HL]

Set bit u3 in the byte pointed by **HL** to 1. Bit 0 is the rightmost one, bit 7 the leftmost one.

Cycles: 4

Bytes: 2

Flags: None affected.

## SLA r8

Shift Left Arithmetic register r8.

$$C \leftarrow [7 \leftarrow 0] \leftarrow 0$$

Cycles: 2

Bytes: 2

Flags:

 $\mathbf{Z}$ Set if result is 0.

N Н 0

 $\mathbf{C}$ Set according to result.

# SLA [HL]

Shift Left Arithmetic byte pointed to by HL.

Cycles: 4

Bytes: 2

Flags: See SLA r8

## SRA r8

Shift Right Arithmetic register r8.

$$[7] \rightarrow [7 \rightarrow 0] \rightarrow C$$

Cycles: 2

Bytes: 2

Flags:

 $\mathbf{Z}$ Set if result is 0.

N

Н 0

Set according to result.  $\mathbf{C}$ 

# SRA [HL]

Shift Right Arithmetic byte pointed to by HL.

$$[7] -> [7 -> 0] -> C$$

Cycles: 4

Bytes: 2

Flags: See SRA r8

# SRL r8

Shift Right Logic register r8.

$$0 \rightarrow [7 \rightarrow 0] \rightarrow C$$

```
Cycles: 2

Bytes: 2

Flags:

Z Set if result is 0.

N 0

H 0

C Set according to result.
```

## SRL [HL]

Shift Right Logic byte pointed to by HL.

$$0 \rightarrow [7 \rightarrow 0] \rightarrow C$$

Cycles: 4 Bytes: 2

Flags: See SRA r8

#### **STOP**

Enter CPU very low power mode. Also used to switch between double and normal speed CPU modes in GBC.

Cycles: -

Bytes: 2

Flags: None affected.

# SUB A,r8

Subtract the value in r8 from A.

Cycles: 1

Bytes: 1

Flags:

**Z** Set if result is 0.

N :

**H** Set if borrow from bit 4. **C** Set if borrow (set if r8 > A).

# SUB A,[HL]

Subtract the byte pointed to by HL from A.

Cycles: 2 Bytes: 1

Flags: See SUB A,r8

## SUB A,n8

Subtract the value n8 from A.

Cycles: 2 Bytes: 2

```
Flags: See SUB A,r8
```

## SWAP r8

Swap upper 4 bits in register r8 and the lower 4 ones.

Cycles: 2 Bytes: 2

Flags:

**Z** Set if result is 0.

N 0 H 0 C 0

## SWAP [HL]

Swap upper 4 bits in the byte pointed by **HL** and the lower 4 ones.

Cycles: 4 Bytes: 2

Flags: See SWAP r8

# XOR A,r8

Bitwise XOR between the value in r8 and A.

Cycles: 1
Bytes: 1
Flags:

**Z** Set if result is 0.

**N** 0 **H** 0 **C** 0

# XOR A,[HL]

Bitwise XOR between the byte pointed to by HL and A.

Cycles: 2 Bytes: 1

Flags: See XOR A,r8

### XOR A,n8

Bitwise XOR between the value in n8 and A.

Cycles: 2 Bytes: 2

Flags: See XOR A,r8

## SEE ALSO

rgbasm(1), rgbds(7)

# **HISTORY**

**rgbds** was originally written by Carsten Sørensen as part of the ASMotor package, and was later packaged in RGBDS by Justin Lloyd. It is now maintained by a number of contributors at .: **https://github.com/gbdev/rgbds**