
pcb_a_display / PLACEMENT STUDY 0.1



UNROUTED — TBD outlines are NOT validated footprints

USB access from rear / side service space