

Device and circuit simulations



2. Schematic / Layout




Extract test points and measurement settings




4. Validate

Design Feedback

GDS FACTORY



3. Verifyate (DRC, LVS)



1. Load PDK

Layer thickness, materials ...

