Weekly Status Report

Date of submission: 13-06-2014

Mode of Preparation : Single

Submitted to: balachandra.k@iiitb.org, mr@iiitb.ac.n

Week Summary	Redesigned Ultrasonic Sensor Block to be more intuitive Redesigned Motor Blocks to be more intuitive. Implementation of IR Sensor Block Implementation of Buzzer Block. Implementation of OLED Block.
Time Spent (hrs)	15
Plan for next week	Testing of the blocks, Incorporate Review Comments
Estimated total remaining time	24
Status	On Track
Problems faced	
Solution	