# GEORGIA INSTITUTE OF TECHNOLOGY SCHOOL of ELECTRICAL and COMPUTER ENGINEERING

# ECE 2026 Spring 2018 Lab #2: Using Complex Exponentials

Date: 29 Jan. - 1 Feb. 2018

You should read the Pre-Lab section of the lab and do all the exercises in the Pre-Lab section before your assigned lab time.

**ITS:** When you come to the lab, you **must** answer the online ITS questions. You can use MATLAB or any notes you might have but you cannot discuss the exercises with any other students.

**Verification:** The In-Lab Exercise section of each lab must be completed **during your assigned Lab time** and the steps marked *Instructor Verification* must also be signed off **during the lab time**. When you have completed a step that requires verification, simply raise your hand and demonstrate the step to the TA or instructor. After completing the warm-up section, turn in the verification sheet to your TA *before leaving the lab*.

It is only necessary to turn in Section 4 as the lab homework for this lab. More information on the lab report format can be found on t-square under the **INFO** link. Please **label** the axes of your plots and include a title for every plot. In order to reduce "orphan" plots, include each plot as a figure *embedded* within your report. For more information on how to include figures and plots from MATLAB in your report file, consult the **INFO** link on t-square, or ask your TA for details.

Forgeries and plagiarism are a violation of the honor code and will be referred to the Dean of Students for disciplinary action. You are allowed to discuss lab exercises with other students, but you cannot give or receive any written material or electronic files. In addition, you are not allowed to use or copy material from old lab reports from previous semesters. Your submitted work must be your own original work.

Due Date: The lab report will be due during the period 22–25 Jan. at the start of your lab.

# 1 Introduction and Overview

The goal of this laboratory is to gain familiarity with complex numbers and their use in representing sinusoidal signals such as  $x(t) = A\cos(\omega t + \varphi)$  as complex exponentials  $z(t) = Ae^{j\varphi}e^{j\omega t}$ . The key is to use the complex amplitude,  $X = Ae^{j\varphi}$ , and then the real part operator applied to Euler's formula:

$$x(t) = \Re\{Xe^{j\omega t}\} = \Re\{Ae^{j\varphi}e^{j\omega t}\} = A\cos(\omega t + \varphi)$$

Manipulating sinusoidal functions using complex exponentials turns trigonometric problems into simple arithmetic and algebra. In this lab, we first review the complex exponential signal and the phasor addition property needed for adding cosine waves. Then we will use MATLAB to make plots of phasor diagrams that show the vector addition needed when combining sinusoids.

## 1.1 Complex Numbers in MATLAB

MATLAB can be used to compute complex-valued formulas and also to display the results as vector or "phasor" diagrams. For this purpose several new MATLAB functions have been written and are available on the *SP First CD-ROM*. Make sure that this toolbox has been installed by doing help on the new M-files:



<sup>&</sup>lt;sup>1</sup>Correct installation means that the spfirst directory will be on the MATLAB path. Try help path if you need more information.

SP First MATLAB 700/box 700/

zvect, zcat, ucplot, zcoords, and zprint. Each of these functions can plot (or print) several complex numbers at once, when the input is formed into a vector of complex numbers. For example, try the following function call and observe that it will plot five vectors all on one graph:

$$zvect([1+j, j, 3-4*j, exp(j*pi), exp(2j*pi/3)])$$

Here are some of MATLAB's complex number operators:

conj Complex conjugate

abs Magnitude

angle Angle (or phase) in radians

real Real part

imag Imaginary part

i,j pre-defined as  $\sqrt{-1}$ x = 3 + 4i i suffix defines imaginary constant (same for j suffix)

exp(j\*theta) Function for the complex exponential  $e^{j\theta}$ 

Each of these functions takes a vector (or matrix) as its input argument and operates on each element of the vector. Notice that the function names mag() and phase() do not exist in MATLAB.<sup>2</sup>



Finally, there is a complex numbers drill program called:

which uses a GUI to generate complex number problems and check your answers. *Please spend some time* with this drill since it is very useful in helping you to get a feel for complex arithmetic.

When unsure about a command, use help.

#### 1.2 Sinusoid Addition Using Complex Exponentials

Recall that sinusoids may be expressed as the real part of a complex exponential:

$$x(t) = A\cos(2\pi f_0 t + \varphi) = \Re\left\{Ae^{j\varphi}e^{j2\pi f_0 t}\right\}$$
(1)

The *Phasor Addition Rule* presented in Section 2.6.2 of the text shows how to add several sinusoids:

$$x(t) = \sum_{k=1}^{N} A_k \cos(2\pi f_0 t + \varphi_k)$$
(2)

assuming that each sinusoid in the sum has the *same* frequency,  $f_0$ . This sum is difficult to simplify using trigonometric identities, but it reduces to an algebraic sum of complex numbers when solved using complex exponentials. If we represent each sinusoid with its *complex amplitude* 

$$X_k = A_k e^{j\varphi_k} \tag{3}$$

Then the complex amplitude of the sum  $X_s$  is

$$X_s = \sum_{k=1}^{N} X_k = A_s e^{j\varphi_s} \tag{4}$$

<sup>&</sup>lt;sup>2</sup>In the latest release of MATLAB a function called phase() is defined in a seldom used toolbox; it does more or less the same thing as angle() but also attempts to add multiples of  $2\pi$  when processing a vector.

Based on this complex number manipulation, the *Phasor Addition Rule* implies that the amplitude and phase of x(t) in (2) are  $A_s$  and  $\varphi_s$ , so

$$x(t) = A_s \cos(2\pi f_0 t + \varphi_s) \tag{5}$$

We see that the sum signal x(t) in (2) and (5) is a single sinusoid that still has the same frequency,  $f_0$ , and it is periodic with period  $T_0 = 1/f_0$ .

## 1.3 Harmonic Sinusoids

There is an important extension where x(t) is the sum of N cosine waves whose frequencies  $(f_k)$  are different. If we concentrate on the case where the frequencies  $(f_k)$  are all multiples of one basic frequency  $f_0$ , i.e.,

$$f_k = k f_0$$
 (HARMONIC FREQUENCIES)

then the sum of N cosine waves becomes

$$x_h(t) = \sum_{k=1}^{N} A_k \cos(2\pi k f_0 t + \varphi_k) = \Re\left\{\sum_{k=1}^{N} X_k e^{j2\pi k f_0 t}\right\}$$
 (6)

This signal  $x_h(t)$  has the property that it is also periodic with period  $T_0 = 1/f_0$ , because each of the cosines in the sum repeats with period  $T_0$ . The frequency  $f_0$  is called the *fundamental frequency*, and  $T_0$  is called the *fundamental period*. (Unlike the single frequency case, there is no phasor addition theorem to combine the harmonic sinusoids.)

# 2 Pre-Lab

Please do the exercises in this section prior to coming to lab.

# 2.1 Complex Numbers

This section will test your understanding of complex numbers when plotted as vectors. Use  $z_1 = 2e^{j\pi/4}$  and  $z_2 = -\sqrt{3} + j$  for all parts of this section.

(a) Enter the complex numbers  $z_1$  and  $z_2$  in MATLAB, then plot them with zvect(), and also print them with zprint().

#### When unsure about a command, use help.

Whenever you make a plot with zvect() or zcat(), it is helpful to provide axes for reference. An x-y axis and the unit circle can be superimposed on your zvect() plot by doing the following: hold on, zcoords, ucplot, hold off

- (b) Compute the conjugate  $z^*$  and the inverse 1/z for both  $z_1$  and  $z_2$  and plot the results as vectors. In MATLAB, see help conj. Display the results numerically with zprint.
- (c) The function zcat() can be used to plot vectors in a "head-to-tail" format. Execute the statement zcat([1+j,-2+j,1-2j]); to see how zcat() works when its input is a vector of complex numbers.
- (d) Compute  $z_1 + z_2$  and plot the sum using zvect(). Then use zcat() to plot  $z_1$  and  $z_2$  as 2 vectors head-to-tail, thus illustrating the vector sum. Use hold on to put all 3 vectors on the same plot. If you want to see the numerical value of the sum, use zprint() to display it.
- (e) Compute  $z_1z_2$  and  $z_2/z_1$  and plot the answers using zvect() to show how the angles of  $z_1$  and  $z_2$  determine the angles of the product and quotient. Use zprint() to display the results numerically.

(f) Make a  $2 \times 2$  subplot that displays four plots in one window, similar to the four operations done previously: (i)  $z_1$ ,  $z_2$ , and the sum  $z_1 + z_2$  on a single plot; (ii)  $z_2$  and  $z_2^*$  on the same plot; (iii)  $z_1$  and  $1/z_1$  on the same plot; and (iv)  $z_1z_2$ . Add a unit circle and x-y axis to each plot for reference.

#### 2.2 Z-Drill

Work a few problems generated by the complex number drill program. To start the program simply type zdrill; if necessary, install the GUI and add zdrill to MATLAB's path. Use the buttons on the graphical user interface (GUI) to produce different problems.

#### 2.3 Cell Mode in MATLAB

MATLAB has a formatting syntax that allows you to produce documentation at the same time that you make an M-file. A quick summary is that double percent signs followed by a space (%%\_) are interpreted as sections in cell mode so that your code is broken into natural blocks that can be run individually. In addition, the M-file can be "published" to an HTML file and then viewed as a nicely formatted web page. There are several sources with information about cell mode:

#### 1. Videos:

```
https://www.youtube.com/watch?v=CWg15Y1ltxk
https://www.youtube.com/watch?v=_TWBG95mCQU
and https://www.mathworks.com/help/matlab/matlab_prog/run-sections-of-programs.html
```

Please watch the videos, especially the first one, and read some of the documentation.

The MATLAB code in the following section uses cell mode. It can be published to HTML, and displayed in a web browser (the default is MATLAB's internal browser).

#### 2.4 Vectorization

The power of MATLAB comes from its matrix-vector syntax. In most cases, loops can be replaced with vector operations because functions such as exp() and cos() are defined for vector inputs, e.g.,

```
cos(vv) = [cos(vv(1)), cos(vv(2)), cos(vv(3)), ... cos(vv(N))]
```

where vv is an N-element row vector. Vectorization can be used to simplify your code. If you have the following code that plots the signal in the vector yy,

```
M = 200;
for k=1:M
    x(k) = k;
    yy(k) = cos( 0.001*pi*x(k)*x(k) );
end
plot( x, yy, 'ro-')
```

then you can replace the for loop with one line and get the same result with four lines of code:

```
M = 200;
x = 1:M;
yy = cos( 0.001*pi*x.*x );
plot( x, yy, 'ro-' )
```

Run these two programs to see that they give identical results, but note that the vectorized version runs much faster.

#### 2.5 Vectorizing a 2-D Evaluation

You can also vectorize 2D functions. Suppose that you want to plot  $f(u,v) = u^2 + v^2$  versus (u,v) over the domain  $[-20,20] \times [-20,20]$ . The result should be a parabolic surface. To avoid having nested for loops, we can use meshgrid instead:

```
u = -20:0.5:20;
v = -20:0.5:20;
[uu,vv] = meshgrid(u,v);
mesh(u,v,uu.*uu + vv.*vv)
```

The meshgrid function generates all the pairs (u, v) for the domain.

#### 2.6 Functions

Functions are a special type of M-file that can accept inputs (matrices, vectors, structures, etc.) and also return outputs. The keyword function must appear as the first non-comment word in the M-file that defines the function, and that line of the M-file defines how the function will pass input and output arguments. The file extension must be lower case "m" as in my\_func.m. See Section B-6 in Appendix B of the text for more discussion.

The following function has several mistakes (there are at least four). Before looking at the correct one below, try to find these mistake(s):

The corrected function should look something like:

```
function [xx,tt] = goodcos(ff,dur)
tt = 0:1/(100*ff):dur;  %-- gives 100 samples per period
xx = real(exp(2i*pi*ff*tt));
```

Notice that the word function must be at the beginning of the first line. Also, the exponential needs to have an imaginary exponent, and the variable freeq must be defined before being used. Finally, the function has xx as an output, so the variable xx must appear on the left-hand side of at least one assignment line within the function body. In other words, the function name is *not* used to hold values produced in the function.

#### 2.7 Structures in MATLAB

MATLAB can do structures. Structures are convenient for grouping information together. For example, we can group all the information about a sinusoid into a single structure with fields for amplitude, frequency and phase. We could also add fields for other attributes such as a signal name, the signal values, and so on. To see how a structure might be used, run the following program which plots a sinusoid:

Notice that the fields in the structure can contain different types of variables: scalars, vectors or strings.

You can also have arrays of structures. For example, if xx is array of sinusoid-structures with the same fields as above, you would reference one of the sinusoids via:

```
xx(3).name, xx(3).Amp, xx(3).freq, xx(3).phase
%
plot(xx(3).times, xx(3).values)
title([xx(3).name,' Amp=',num2str(xx(3).Amp),' Phase=',num2str(xx(3).phase)])
```

Notice that the array name is xx, so the array index, 3, is associated with xx, e.g., xx(3).

# 3 In-lab Exercise: Complex Exponentials

In the Pre-Lab section of this lab, you saw examples of function M-files. In this section, you will write functions that can generate sinusoids, or sums of sinusoids.

For the instructor verification, you will have to demonstrate that you understand everything in a given subsection. It is not necessary to do everything in the subsections; skip parts that you already know. The Instructor Verification is usually placed close to the most important item, i.e., the most likely one to generate questions from the TAs.

# 3.1 Intelligent Tutoring System (ITS)

During this lab you should run ITS and answer the questions (see the instructions below). In general, ITS will be used throughout the semester to measure progress on the basic concepts covered in ECE-2026.

- 1. The ITS should now be accessible from anywhere on the web.
- 2. The link to ITS is: http://quid.gatech.edu. To open ITS, login with your AD username and password (same as for T-square)

**Instructor Verification** (separate page)

#### 3.2 Vectorization

Use the vectorization idea to write 1 or 2 lines of code that will perform the *same task as the inner loop* of the following MATLAB script without using a for loop. If you are ambitious, try to replace both loops with some vectorized code.

```
%--- make a plot of sum of cosines
dt = 1/800;
XX = rand(1,3).*exp(2i*pi*rand(1,3)); %--Random amplitude and phases
freq = 20;
ccsum = zeros(1,500);
for kx = 1:length(XX)
    for kt = 1:500
        t = kt*dt;
        Ak = abs(XX(kx));
        phik = angle(XX(kx));
        ccsum(kt) = ccsum(kt) + Ak*cos(2*pi*freq*t + phik);
        tt(kt) = t;
    end
end
                 %-- Plot the sum sinusoid
plot(tt,ccsum)
grid on, zoom on, shg
```

**Instructor Verification** (separate page)

#### 3.3 M-file to Generate One Sinusoid

Write a function that will generate a **single** sinusoid,  $x(t) = A\cos(2\pi ft + \varphi)$ . The function should have the following input arguments: a sinusoid-structure with two fields for the frequency (f) in Hz, the complex amplitude  $(X = Ae^{j\varphi})$ , and then three other arguments: a duration argument (dur), followed by an argument for the starting time (tstart), and then a final argument which is the spacing between times,  $\Delta t$ .

The function should return a structure having both of the fields of the input structure plus two new fields: the vector of values of the sinusoidal signal (x) along with the corresponding vector of times (t) at which the sinusoid values are known. The spacing between times in the time-vector,  $\Delta t$ , is a constant, but make sure that it is small enough so that there are at least 32 time points per period of the sinusoid. Call this function makeCosVals(). Hint: use goodcos() from the Pre-Lab part as a starting point. Here is a suggested template that needs to be completed for the M-file:

```
function sigOut = makeCosVals(sigIn, dur, tstart, dt )
%
freq = sigIn.freq;
X = sigIn.complexAmp;
%
%...(Fill in several lines of code)...
%
tt = tstart: dt : ???;  %-- Create the vector of times
xx = A*cos(...???;  %-- Vectorize the cosine evaluation
sigOut.times = ???;  %-- Put vector of times into the output structure
sigOut.values = ???;  %-- Put values into the output structure
```

Plot the result from the following call to test your function.

```
mySig.freq = 2;  %-- (in hertz)
mySig.complexAmp = 5*exp(j*pi/4);
dur = 2;
start = -1;
dt = 1/(32*mySig.freq);
mySigWithVals = makeCosVals( mySig, dur, start, dt );
%- Plot the values in sigWithVals
```

**Instructor Verification** (separate page)

## 3.4 Sinusoidal Synthesis with an M-file: Different Frequencies

Since we will generate many functions that are a *sum of sinusoids*, it will be convenient to have a MATLAB function for this operation. To be general, we should allow the frequency of each component  $(f_k)$  to be different. The following expressions are equivalent if we define the complex amplitude  $X_k$  as  $X_k = A_k e^{j\varphi_k}$ .

$$x(t) = \Re\left\{\sum_{k=1}^{N} X_k e^{j2\pi f_k t}\right\} = \Re\left\{\sum_{k=1}^{N} (A_k e^{j\varphi_k}) e^{j2\pi f_k t}\right\}$$
 (7)

$$x(t) = \sum_{k=1}^{N} A_k \cos(2\pi f_k t + \varphi_k)$$
(8)

#### 3.4.1 Write a Sum of Sinusoids M-file

Write an M-file called addCosVals.m that will synthesize a waveform in the form of (7) using  $X_k$  defined in (3). The result is not a sinusoid unless all the frequencies are the same, so the output signal has to be represented by its values over some (finite) time interval.

Even though for loops are rather inefficient in MATLAB, you must write the function with one outer loop in this lab. The inner loop should be vectorized. The first few statements of the M-file are the comment lines—they should look like:

```
sigOut = addCosVals( cosIn, dur, tstart, dt )
function
%ADDCOSVALS Synthesize a signal from sum of sinusoids
                (do not assume all the frequencies are the same)
%
% usage:
            sigOut = addCosVals( cosIn, dur, tstart, dt )
%
%
   cosIn = vector of structures; each one has the following fields:
%
       cosIn.freq = frequency (in Hz), usually none should be negative
%
       cosIn.complexAmp = COMPLEX amplitude of the cosine
%
%
    dur = total time duration of all the cosines
    start = starting time of all the cosines
    dt = time increment for the time vector
% The output structure has only signal values because it is not necessarily a sinusoid
       sigOut.values = vector of signal values at t = sigOut.times
%
       sigOut.times = vector of times, for the time axis
%
%
     The sigOut.times vector should be generated with a small time increment that
%
          creates 32 samples for the shortest period, i.e., use the period
%
          corresponding to the highest frequency cosine in the input array of structures.
```

In order to verify that this M-file can synthesize *harmonic* sinusoids, try the following test:

```
ss(1).freq = 21; ss(1).complexAmp = exp(j*pi/4);
ss(2).freq = 15; ss(2).complexAmp = 2i;
ss(3).freq = 9; ss(3).complexAmp = -4;
%
dur = 1;
tstart = -0.5;
dt = 1/(21*32); %-- use the highest frequency to define delta_t
%
ssOut = addCosVals( ss, dur, tstart, dt );
%
plot( ssOut.????, ssOut.???? )
%
```

Use MATLABto make a plot of ssOut. Notice that the waveform is periodic. Measure its period and state how the period is related to the fundamental frequency which is 3 Hz in this case.

# Lab #2 ECE-2026 Spring-2018 INSTRUCTOR VERIFICATION SHEET

Turn this page in to your lab instructors before the end of your lab period.

Name:	Date of Lab:
Part 3.1 Answered ITS questions:	
Verified:	Date/Time:
Part 3.2 Replace the inner for loop w MATLAB code in the space below:	vith only one or two lines of vectorized MATLAB code. Write the
Verified:	Date/Time:
Part 3.3 and other places: Learn to pub doing the Instructor Verifications.	lish MATLAB's script capability to create and save the plots when
Verified:	Date/Time:
<del>-</del>	.m function is correct by running the test in Section 3.4.1 and plotting in the structure ssOut, and explain its relationship to the fundamen-
Verified:	Date/Time:

# Lab #2 ECE-2026 Spring-2018 LAB REPORT QUESTIONS

Name:	Date of Lab:
1 (41114)	

**Student Work**: We can generate some interesting waveforms by summing up the harmonics of a single sinusoids. The following code uses the addCosVals function created in Lab 02 to create a square wave.

```
close all
clear all
num_sinusoid = [1 3 10 50];
f0 = 1; %fundamental freq = 1 Hz
for jj = 1:length(num_sinusoid)
    clear cosAdd
    for kk = 1:num_sinusoid(jj) %calculate the freq and amp of each harmonic
        cosAdd(kk).freq = kk*f0;
        cosAdd(kk).complexAmp = ((1-(-1)^kk)/(pi*kk))*exp(j/2*pi);
    end
    dur = 3;
    dt = 0.05;
    tstart = 0;
    a(jj) = addCosVals(cosAdd, dur, tstart, dt);
    subplot(2,2,jj)
    plot(a(jj).times, a(jj).values)
    title(sprintf('Sum of %d sinusoids',num_sinusoid(jj)))
```

- 1. State what happens to the approximation as the number of sinusoids increase in the sum.
- 2. Generate the plot below with sum of 10 sinusoids. Turn in your code and plot. (Hint: You will essentially need to add one line of code by changing the center DC value from 0 to 0.5).

