
# Lab2\_CN

Familiarization with Transmission media and tools: Co-axial cable, UTP cable, Crimping tool, Connectors etc. Preparing the UTP cable for cross and direct connection using crimping tool.



### **Tools & Materials Needed:**

- ✓ UTP Cable (Cat5e, Cat6, etc.)
- **✓** RJ45 Connectors
- ✔ Crimping Tool
- ✓ Cable Stripper
- ✓ Cable Tester (Optional but recommended)

# 1. Understanding Wiring Standards

There are two main wiring standards for Ethernet cables:

- T568A
- T568B

# **Straight-Through (Direct) Connection:**

Used for connecting different types of devices (e.g., PC to Switch, Router to Switch).

# T568B (Common Standard):

### T568B (Other End):

mathematica

1. White-Orange
2. Orange
3. White-Green
4. Blue
5. White-Blue
6. Green
7. White-Brown
8. Brown

## **Crossover Connection:**

Used for connecting similar devices (e.g., PC to PC, Switch to Switch).

### T568A:

# mathematica 1. White-Green 2. Green 3. White-Orange 4. Blue 5. White-Blue 6. Orange 7. White-Brown 8. Brown

### T568B (Other End):

mathematica

1. White-Orange
2. Orange
3. White-Green
4. Blue
5. White-Blue
6. Green
7. White-Brown
8. Brown